E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

North 168th Street	Kempten 0 CSW-2021 4/27/20			Stage 1	
North 168th Street	CSW-2021			1	
North 168th Street	4/27/20				
North 168th Street a		4/27/2024			
	North 168th Street and Bennington Road - Bennington, NE (Douglas County)				
100%			Τ		
100%					
100%					
90%					
40%					
15%					
30%					
Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time	
					Veek
0.00"					
0.00"					
0.00"	4/23/2024	Sunny 64	2:25 PM		
-					
0.00"					
	100% 100% 90% 40% 15% 30% Amount in tenths 0.00" 0.00"	100% 100% 90% 40% 15% 30% Amount in tenths Date inspected 0.00" 0.00" 4/23/2024 0.00" 0.24" 0.91"	100% 100% 90% 40% 15% 30%	100% 100%	100%

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began (11/14/23). Paving and construction ceased on site (1/2/24). Utility installation began on site (4/2/24).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began (11/14/23). Paving and construction ceased on site (1/2/24). Utility installation began on site (4/2/24).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (11/29/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, See findings section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? Create Corrective Action? N/A Are construction entrances and adjacent streets being maintained adequately? Yes Create Corrective Action? N/A Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A Comments: Comments: The site was inactive during the last inspection. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section at this time. 2.) All bare areas on-site that have been inactive for 14 days should be seeded. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection. K2 Construction was reminded on 2/15/24, 3/21/24 **Unique Name** Projected Install Date Maintenance

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	X-11		Removed		
Current Condition:	Removed - Echo Valley paved all entrances prior to the inspection on 12/5/23.					
D1	Diversion	D-8 to K-8	5/23/2023	Active	No	
Current Condition:	Good Condition - HRC Development installed the diversion prior to the inspection on 5/23/23.					
D2	Diversion	East of SB B	5/23/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Developments of the diversion for subjections of the diversion for subjection should be reinstalled. K2 Construction was informed.	canitary sewer installation of where removed for said	n prior to the inspection on	8/29/23.		
	reminded on 10/18/23, 11/16/				ı	
D3	Diversion	Southeast of SB A		Removed		
Current Condition:	Removed - Due to paving the	diversion is no longer r	necessary as of the 4/16/24	inspection.		
D4	Diversion	South of SB A	5/23/2023	Active	Yes	
	sections of the diversion for some diversion should be reinstalled K2 Construction was informed reminded on 10/18/23, 11/16/	ed where removed for sa	anitary installation.		truction was	
ET 1	Erosion Control Terraces	B-9 to G-10	6/6/2023	Active	No	
Current Condition:	Good Condition - HRC Devel	opment installed the ero	sion control terrace prior to	the inspection on	6/6/23.	
ET 2	Erosion Control Terraces	B-9 to I-10	6/6/2023	Active	No	
Current Condition:	Good Condition - HRC Devel	opment installed the erc	sion control terrace prior to	the inspection on	6/6/23.	
ET 3	Erosion Control Terraces	B-7 to K-10	6/6/2023	Active	No	
Current Condition:	Good Condition - HRC Devel	opment installed the erc	sion control terrace prior to	the inspection on	6/6/23.	
ET 4	Erosion Control Terraces	I-7 to M-10	6/6/2023	Active	No	
Current Condition:	Good Condition - HRC Development installed the erosion control terrace prior to the inspection on 6/6/23.					
ET 5	Erosion Control Terraces	Q-10 to Q-8	6/6/2023	Active	No	
Current Condition:	Good Condition - HRC Devel	opment installed the ero	sion control terrace prior to	the inspection on	6/6/23.	
ET 6	Erosion Control Terraces	R-10 to R-7	6/6/2023	Active	No	
Current Condition:	Good Condition - HRC Devel	opment installed the ero	sion control terrace prior to	the inspection on	6/6/23.	
ET 7	Erosion Control Terraces	S-7 to U-10	6/6/2023	Active	No	
Current Condition:	Good Condition - HRC Devel	opment installed the ero	sion control terrace prior to	the inspection on	6/6/23.	
FT 1	Fuel Tank	On site	12/6/2022	Active	Yes	

Current Condition:	Fair Condition - Ruff Grading brought a fuel tank on site prior to the inspection on 12/6/22. Ruff Grading removed the fuel tank from site during the inspection on 3/28/23. Ruff Grading installed a fuel tank and secondary containment prior to the inspection on 4/11/23. Ruff Grading moved the fuel tank to the Morgan Ridge subdivision prior to the inspection on 5/2/23. Cedar Construction installed a single walled fuel tank on site prior to the inspection on 4/23/24. A secondary containment berm should be installed around the fuel tank. Cedar Construction was informed to complete by 4/30/24.					
MS 1	Material Storage Area	On site	11/4/2022	Active	No	
Current Condition:	Good Condition-Material and					
PB 1	Portable toilet	On site	4/11/2023	Pending	No	
Current Condition:	Pending - Ruff Grading insta secured the portable toilet du subdivision prior to the inspe inspection on 8/29/23. K2 Co Echo Valley installed and se portable toilet from the site p	uring the inspection on 4 ection on 5/2/23. K2 Consonstruction removed the cured a portable toilet or	/18/23. Ruff Grading move struction installed and secu portable toilet from the site a site prior to the inspection	d the portable toilet ired a portable toile prior to the inspect	to the Morgan Ridge on site prior to the ion on 10/24/23.	
SB A	Sediment Basin	Z-9	11/14/2023	Active	Yes	
	Development was in the process of installing the riser and outfall pipe during the inspection on 11/7/23. HRC Development installed the riser prior to the inspection on 11/14/23. E&A inspector painted the cleanout mark on the rise during the inspection on 11/28/23. Dewatering holes should be installed in the riser. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection. HRC Development was reminded on 2/15/24, 3/21/24					
SB B	Sediment Basin	L-7	3/21/2023	Active	No	
Current Condition:	Good Condition - 5% filled - Development repaired the er installed the riser prior to the inspection.	osion on the outer bank inspection on 2/13/24. I	of the basin prior to the ins	spection on 12/12/23	HRC Developmen	
SF 1 Current Condition:	Silt fence Good Condition - HRC Deve cleaned out the silt fence in i	multiple locations prior to	the inspection on 3/6/23.			
SF 2	Silt fence	West edge of site	11/29/2022	Active	No	
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 11/29/22. HRC Development trenched in the silt fence where undermined prior to the inspection on 3/6/23. HRC Development repaired the silt fence prior to the inspection on 3/28/23. HRC Development repaired the entire run of silt fence prior to the inspection on 12/12/23.					
SF 3	Silt fence	East edge of site	3/14/2023	Active	No	
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 3/14/23. Due to the grade silt fen along the edge of the site near Daniel Street is no longer necessary as of 5/23/23.					
WO 1	Concrete Washout	On site	11/21/2023	Pending	No	
Current Condition:	Pending - Echo Valley install second concrete washout pit on site and pile up concrete	t with liner prior to the ins	spection on 12/5/23. Echo	on on 11/21/23. Ech Valley removed the		
WS 1	Waste Storage Area	On site	11/4/2022	Pending	No	
Current Condition:	Pending - There is currently generated or stored on-site;	the E&A inspector will co		e due to no waste r	naterials being	
STR	Streets	Bennington Road, N. 168th Street	11/4/2022	Active	No .	
Current Condition:	Good Condition - HRC Deve	opment was cleaning al		s during the inspect	ion on 12/19/23.	
CIVIDED C:	OWDDD Neticle of the Other	1				
SWPPP Sign Current Condition:	SWPPP Notification Sign Good Condition - SWPPP in	Adjacent to CE 1	11/4/2022	Active	No	

Certification Statement:	properly gathered and evaluate persons who manage the systhe information submitted is, am aware that there are sign	direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."				
Inspector Signature:	Brya M Waght		Reviewed Bv:	Post Sul		