E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dent Manager

Engineering Answers

Environmental Services D	ept. Manager			Liigineerii	ig Aliswers
		E&A- P2	020.056.003		
Inspector: Alex Brown					Stage
		Ds Transportat	ion Trucking Termi	nal	1
Ducia at Name:	i				
Project Name:	+		E4504		
For Week Ending:	4/23/2022				51501
Project Location:	Southwest of S 291				
Grading:	100%	,			
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%)			
Seeding:	0%	,			
Utilities:	100%				
Overall Development:	94%				
	1	T			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week
Sunday	0.00"				
Monday	0.00"				
Tuesday	0.00"	4/19/2022	Cloudy 52/29	10:15 AM	
Wednesday	0.01"				
Thursday	0.07"				
Friday	0.11"				
Saturday	0.00"				
Complaints	None				
Complaints:					
				<u> </u>	
Construction Sequencing	:				

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21). Grading and sidewalk installation (12/14/21). Grading along the northern perimeter ROW (3/1/22). Grading ceased (3/8/22). Minor excavation for sprinkler system (4/12).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21). Grading and sidewalk installation (12/14/21). Grading along the northern perimeter ROW (3/1/22). Grading ceased (3/8/22). Minor excavation for sprinkler system (4/12).

Existing vegetation (6/29/21)

Checklist Questions

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Yes		
Create	Corrective	Action?

N/A

- Comments:
- 1.) Site was active for sprinkler installation during the last inspection.
 2.) Rich Engdahl began shaping the PCSMP basin on the western portion of the site during the inspection on 7/20/21.
 Findings / Corrective Actions (Date):

- Findings / Corrective Actions (Date):

 1.) No maintenance is required in the BMP section.
- 2.) All non-paved portions of the site are disturbed and should be stabilized. Rich Engdahl was informed to stabilize the site as soon as possible on 3/11/22. Rich Engdahl informed the E&A inspector on 3/11/22 that the site will be stabilized within approximately three weeks. E&A inspector will continue to monitor for stabilization.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CE 01	Construction Entrance	J3	Frojecteu mstan Date	Removed	Maintenance
Current Condition:	Removed - Rich Engdahl		the inspection on 12/21/21		
CE 02	Construction Entrance	Z7	tile ilispeditori ori 12/2 1/2	Removed	
Current Condition:	Removed - Rich Engdahl p		l rance prior to the inspection		
CW 01	Concrete Washout	On Site		Removed	
Current Condition:	Removed - Rich Engdahl r		nout prior to the inspection		
D 01	Diversion Check	Z6 to Z8	<u>'</u>	Removed	
Current Condition:	Removed - The diversion of		o the inspection on 8/10/21		
IP 01	Inlet Protection	F13	8/29/2021	Active	No
Current Condition:	Active - Rich Engdahl insta recommended at this time.			to the area being paved, i	nlet protection is not
IP 02	Inlet Protection	F3	6/29/2021	Active	No
Current Condition:	Good Condition - This is an inspection.	n existing inlet located off o	of 21st Avenue. Rich Engda	ahl installed inlet protection	prior to the 3/22/22
IP 03	Inlet Protection	F2	6/29/2021	Active	No
Current Condition:	Active - This is an existing	inlet located off of 21st Av	enue. Due to the location o	f the inlet no BMP recomn	nendation is needed
IP 04	time. E&A inspector will co	ntinue to monitor. M4	8/29/2021	Active	No
Current Condition:	Active - Rich Engdahl insta				
	recommended at this time.	E&A inspector will continu	ue to monitor.		
IP 05 Current Condition:	Inlet Protection	P3	6/29/2021	Active	No
	Good Condition - This is an inspection.				prior to the 3/22/22
IP 06	Inlet Protection	P2	6/29/2021	Active	No
Current Condition:	Active - This is an existing time. E&A inspector will co			of the inlet no BMP recomn	nendation is needed
IP 07	Inlet Protection	Q4	10/5/2021	Active	No
Current Condition:	Active - Rich Engdahl insta recommended at this time.			to the area being paved, i	nlet protection is not
IP 08	Inlet Protection	U4	10/5/2021	Active	No
Current Condition:	Good Condition - Rich Eng	dahl installed the inlet and			
IP 09	Inlet Protection	X3	6/29/2021	Active	No
Current Condition:	Good Condition - This is an inspection.	n existing inlet located off o	of 21st Avenue. Rich Engda	ahl installed inlet protectior	prior to the 3/22/22
IP 10	Inlet Protection	X2	6/29/2021	Active	No
Current Condition:	Active - This is an existing time. E&A inspector will co				
IP 11	Inlet Protection	Y6	10/5/2021	Active	No
Current Condition:	Good Condition - Rich Eng				
IP 12 Current Condition:	Inlet Protection	Y7	10/5/2021	Active	No
current Condition:	Active - Rich Engdahl insta protection prior to the inspe- inspector will continue to m	ection on 11/23/21. Due to			
IP 13	Inlet Protection	Y8	10/5/2021	Active	No
Current Condition:		ection on 11/23/21. Due to	ection prior to the inspection the area being paved, rein		
	inspector will continue to m				1
IP 14	Inlet Protection	Y11	10/5/2021	Active	No
Current Condition:		<u> </u>	l inlet protection prior to the		
PB 01	Portable toilet	On Site	7/6/2021	Active	No on 7/6/21 Bigh End
Current Condition:	· 1	t just south of CE 2 prior to	ortable toilet adjacent to Cf to the inspection on 11/23/2 he portable toilet to the par	 Rich Engdahl secured the 	ne portable toilet prid
SF 01 - SF 06	Silt Fence	G3 to B15		Removed	
Current Condition:	Removed - The city inspect 10/05/21. Rich Engdahl rer approved silt fence remova	ctor pre-approved removal moved the remaining secti	of SF 3-6 on 9/23/21. SF 3 on of SF 6 prior to the insp installation. Rich Engdahl r	and 4 were removed prio ection on 11/30/21. As of 1	1/30/21, the City ha
	12/14/21.				

Current Condition:	Removed - As of 11/30/21, the City has approved silt fence removal in this area. Rich Engdahl removed a majority of SF 7 - 12 prior to the inspection on 12/7/21. Rich Engdahl removed the remainder of SF 7 - 12 prior to the inspection on 3/8/22.					
SF 13 - SF 17	Silt Fence	S12 to Z5		Removed		
Current Condition:	Removed - As of 11/30/21	, the City has approved silt	fence removal in this area	. Rich Engdahl removed S	F 13 and SF 14 prior to	
	the inspection on 12/7/21. Rich Engdahl removed SF 15 - 17 prior to the inspection on 3/8/22.					
SF 18 - SF 22	Silt Fence	Z3 to K3		Removed		
Current Condition:	Removed - Rich Engdahl removed the silt fence posts from SF 18 - 22 prior to the inspection on 12/14/21. Rich Engdahl removed the trenched silt fence fabric prior to the inspection on 3/1/22.					
STR	Streets	On Site	6/29/2021	Active	No	
Current Condition:	Good Condition - Rich Engdahl cleaned up the trackout on 21st Ave. prior to the inspection on 9/7/21. Rich Engdahl cleaned up trackout around CE 1 prior to the inspection on 10/12/21. Rick Engdahl cleaned up trackout around CE 02 prior to the inspection on 11/2/21. Minor sedimentation was observed around CE 1 during the 12/14/21 inspection. Rich Engdahl cleaned up the sediment around CE 1 prior to the 12/28/21 inspection. Rich Engdahl cleaned 21st Avenue prior to the 3/22/22 inspection.					
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	8/3/2021	Active	No	
Current Condition:	Good Condition - The E&A inspector installed the SWPPP sign adjacent to CE 01 during the inspection on 8/3/21. The E&A inspector reinstalled the SWPPP sign during the 2/1/22 inspection.					
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
Inspector Signature:				Reviewed By:	- See	