E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

Dept. Manager			Eligineeri	ng Answers
	E&A- P2	020.056.003		
				Stage
5	Ds Transportati	ion Trucking Termi	inal	4
		1		
		51501		
100%				
100%				
100%				
100%				
0%				
100%				
94%				
Amount in tenths	Date inspected	Weather Conditions	Time	
				Week
0.00"				
0.00"				
0.00"	4/26/2022	Sunny 72/30	9:55 AM	
0.00"				
0.00"				
0.50"				
0.17"				
•				
None				
:				
	Southwest of S 29th 100% 100% 100% 100% 100% 100% 94% Amount in tenths 0.00" 0.00" 0.00" 0.00" 0.00" 0.17" None	5Ds Transportati IA - 39 4/3 Southwest of S 29th Street and 21st Avei 100% 100% 100% 0% 100% 94% Amount in tenths Date inspected 0.00" 0.00" 0.00" 0.00" 0.00" 0.17" None	## Factor	SDS Transportation Trucking Terminal IA - 39263 - 38898 4/30/2022 Southwest of S 29th Street and 21st Avenue in Council Bluffs, IA (Pottawattamie County) 100%

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21). Grading and sidewalk installation (12/14/21). Grading along the northern perimeter ROW (3/1/22). Grading ceased (3/8/22). Minor excavation for sprinkler system (4/12/22). Fine grading (4/26/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21). Grading and sidewalk installation (12/14/21). Grading along the northern perimeter ROW (3/1/22). Grading ceased (3/8/22). Minor excavation for sprinkler system (4/12/22). Fine grading (4/26/22).

Existing vegetation (6/29/21)

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

/es	<u> </u>	A . (* O
create	Corrective	Action?

N/A

Comments:

- 1.) Site was active during the last inspection.
- 2.) Rich Engdahl began shaping the PCSMP basin on the western portion of the site during the inspection on 7/20/21.

Findings / Corrective Actions (Date):

- Findings / Corrective Actions (Date):

 1.) No maintenance is required in the BMP section.
- 2.) All non-paved portions of the site are disturbed and should be stabilized. Rich Engdahl was informed to stabilize the site as soon as possible on 3/11/22. Rich Engdahl informed the E&A inspector on 3/11/22 that the site will be stabilized within approximately three weeks. E&A inspector will continue to monitor for stabilization.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CE 01	Construction Entrance	J3	Frojecteu mstan Date	Removed	Maintenance
Current Condition:	Removed - Rich Engdahl		the inspection on 12/21/21		
CE 02	Construction Entrance	Z7	tile ilispeditori ori 12/2 1/2	Removed	
Current Condition:	Removed - Rich Engdahl p		l rance prior to the inspection		
CW 01	Concrete Washout	On Site		Removed	
Current Condition:	Removed - Rich Engdahl r		nout prior to the inspection		
D 01	Diversion Check	Z6 to Z8	<u>'</u>	Removed	
Current Condition:	Removed - The diversion of		o the inspection on 8/10/21		
IP 01	Inlet Protection	F13	8/29/2021	Active	No
Current Condition:	Active - Rich Engdahl insta recommended at this time.			to the area being paved, i	nlet protection is not
IP 02	Inlet Protection	F3	6/29/2021	Active	No
Current Condition:	Good Condition - This is an inspection.	n existing inlet located off o	of 21st Avenue. Rich Engda	ahl installed inlet protection	prior to the 3/22/22
IP 03	Inlet Protection	F2	6/29/2021	Active	No
Current Condition:	Active - This is an existing	inlet located off of 21st Av	enue. Due to the location o	f the inlet no BMP recomn	nendation is needed
IP 04	time. E&A inspector will co	ntinue to monitor. M4	8/29/2021	Active	No
Current Condition:	Active - Rich Engdahl insta				
	recommended at this time.	E&A inspector will continu	ue to monitor.		
IP 05 Current Condition:	Inlet Protection	P3	6/29/2021	Active	No
	Good Condition - This is an inspection.				prior to the 3/22/22
IP 06	Inlet Protection	P2	6/29/2021	Active	No
Current Condition:	Active - This is an existing time. E&A inspector will co			of the inlet no BMP recomn	nendation is needed
IP 07	Inlet Protection	Q4	10/5/2021	Active	No
Current Condition:	Active - Rich Engdahl insta recommended at this time.			to the area being paved, i	nlet protection is not
IP 08	Inlet Protection	U4	10/5/2021	Active	No
Current Condition:	Good Condition - Rich Eng	dahl installed the inlet and			
IP 09	Inlet Protection	X3	6/29/2021	Active	No
Current Condition:	Good Condition - This is an inspection.	n existing inlet located off o	of 21st Avenue. Rich Engda	ahl installed inlet protectior	prior to the 3/22/22
IP 10	Inlet Protection	X2	6/29/2021	Active	No
Current Condition:	Active - This is an existing time. E&A inspector will co				
IP 11	Inlet Protection	<u>Y6</u>	10/5/2021	Active	No
Current Condition:	Good Condition - Rich Eng				
IP 12 Current Condition:	Inlet Protection	Y7	10/5/2021	Active	No
current Condition:	Active - Rich Engdahl insta protection prior to the inspe- inspector will continue to m	ection on 11/23/21. Due to			
IP 13	Inlet Protection	Y8	10/5/2021	Active	No
Current Condition:		ection on 11/23/21. Due to	ection prior to the inspection the area being paved, rein		
	inspector will continue to m				1
IP 14	Inlet Protection	Y11	10/5/2021	Active	No
Current Condition:		<u> </u>	l inlet protection prior to the		
PB 01	Portable toilet	On Site	7/6/2021	Active	No on 7/6/21 Bigh End
Current Condition:	· 1	t just south of CE 2 prior to	ortable toilet adjacent to Cf to the inspection on 11/23/2 he portable toilet to the par	 Rich Engdahl secured the 	ne portable toilet prid
SF 01 - SF 06	Silt Fence	G3 to B15		Removed	
Current Condition:	Removed - The city inspect 10/05/21. Rich Engdahl rer approved silt fence remova	ctor pre-approved removal moved the remaining secti	of SF 3-6 on 9/23/21. SF 3 on of SF 6 prior to the insp installation. Rich Engdahl r	and 4 were removed prio ection on 11/30/21. As of 1	1/30/21, the City ha
	12/14/21.				

Current Condition:	Removed - As of 11/30/21, the City has approved silt fence removal in this area. Rich Engdahl removed a majority of SF 7 - 12 prior to the inspection on 12/7/21. Rich Engdahl removed the remainder of SF 7 - 12 prior to the inspection on 3/8/22.					
SF 13 - SF 17	Silt Fence	S12 to Z5		Removed		
Current Condition:	Removed - As of 11/30/21, the City has approved silt fence removal in this area. Rich Engdahl removed SF 13 and SF 14 prior to the inspection on 12/7/21. Rich Engdahl removed SF 15 - 17 prior to the inspection on 3/8/22.					
SF 18 - SF 22	Silt Fence	Z3 to K3		Removed		
Current Condition:	Removed - Rich Engdahl r	removed the silt fence posts	s from SF 18 - 22 prior to t	he inspection on 12/14/21.	Rich Engdahl removed	
	the trenched silt fence fabric prior to the inspection on 3/1/22.					
STR	Streets	On Site	6/29/2021	Active	No	
Current Condition:	Good Condition - Rich Engdahl cleaned up the trackout on 21st Ave. prior to the inspection on 9/7/21. Rich Engdahl cleaned up trackout around CE 1 prior to the inspection on 10/12/21. Rick Engdahl cleaned up trackout around CE 02 prior to the inspection					
		ion was observed around C 2/28/21 inspection. Rich En				
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	8/3/2021	Active	No	
Current Condition:	Good Condition - The E&A	A inspector installed the SW	/PPP sign adjacent to CE	01 during the inspection or	n 8/3/21. The E&A	
	inspector reinstalled the SWPPP sign during the 2/1/22 inspection. Rich Engdahl relocated the SWPPP sign S 21st Avenue					
	anticipation of fine gradi	ng / sodding prior to the 4	4/26/22 inspection.			
Certification Statement	accordance with a system Based on my inquiry of the information, the informatio	law, that this document and designed to assure that que person or persons who man submitted is, to the best or submitting false information	alified personnel properly ganage the system or those of my knowledge and belie	gathered and evaluated the persons directly responsib f, true, accurate, and comp	e information submitted. ble for gathering the blete. I am aware that there	
Inspector Signature:	h_			Reviewed By:	- Su	