E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

| Inspector: Alex Brown |                                       |  | Stage |
|-----------------------|---------------------------------------|--|-------|
| Project Name:         | -                                     | ation Trucking Terminal<br>39263 - 38898           | 1     |
| For Week Ending:      |                                       | 8/13/2022  | 51501 |
| Project Location:     | Southwest of S 29th Street and 21st A | venue in Council Bluffs, IA (Pottawattamie County) |       |
| Grading:              | 100%                                  |  |       |
| Sanitary Sewer:       | 100%                                  |  |       |
| Storm Sewer:          | 100%                                  |  |       |
| Paving:               | 100%                                  |  |       |
| Seeding:              | 100%                                  |  |       |
| Utilities:            | 100%                                  |  |       |
| Overall Development:  | 100%                                  |  |       |

E&A- P2020.056.003

| RAIN FALL AMOUNTS | Amount in tenths | Date inspected | Weather Conditions | Time    |        |
|-------------------|------------------|----------------|--------------------|---------|--------|
|                   |                  |                |                    |         | Week 1 |
| Sunday            | 0.13"            |                |                    |         |        |
| Monday            | 0.75"            |                |                    |         |        |
| Tuesday           | 0.00"            | 8/9/2022       | Sunny 86/58        | 2:45 PM |        |
| Wednesday         | 0.00"            |                |                    |         |        |
| Thursday          | 0.00"            |                |                    |         |        |
| Friday            | 0.00"            |                |                    |         |        |
| Saturday          | 0.00"            |                |                    |         |        |
|                   |                  |                |                    |         |        |

|             | None |
|-------------|------|
| Complaints: |      |
|             |      |

## Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21). Grading and sidewalk installation (12/14/21). Grading along the northern perimeter ROW (3/1/22). Grading ceased (3/8/22). Minor excavation for sprinkler system (4/12/22). Fine grading (4/26/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21). Grading and sidewalk installation (12/14/21). Grading along the northern perimeter ROW (3/1/22). Grading ceased (3/8/22). Minor excavation for sprinkler system (4/12/22). Fine grading (4/26/22).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/29/21). Seeding / matting PCSMP basin (5/10/22). Sodding throughout the site (5/17/22).

**Checklist Questions:** 

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

## Create Corrective Action?

## Comments:

Comments:

1.) Site is in use as a trucking terminal.

| 2.) Rich Engdahl began shaping the PCSMP basin on the western portion of the site during the inspection on 7/20/21. Rich Engdahl see | eded / matted the basin |
|--|-------------------------|
| prior to the 5/10/22 inspection.   |                         |

## Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is required in the BMP section.

2.) Rich Engdahl seeded / matted the basin prior to the 5/10/22 inspection. Rich Engdahl sodded the remainder of the site prior to the 5/17/22 inspection. E&A inspector will continue to monitor for vegetative growth in the PCSMP basin. The PCSMP basin is vegetated save for the northeast corner. David H. with E&A and Mark A. with the City met on-site on 7/26/22 to discuss closure. Per the city inspector's advisement, 3-inch limestone will be installed in the area before the Notice of Termination is filed. E&A inspector will continue to monitor for installation.

| Unique Name                 | Туре  | Location  | Projected Install Date           | Status                       | Maintenance              |  |
|-----------------------------|---|---|----------------------------------|------------------------------|--------------------------|--|
| CE 01                       | Construction Entrance   | J3  |                                  | Removed                      |                          |  |
| Current Condition:          | Removed - Rich Engdahl  | paved the entrance prior t                          | o the inspection on 12/21/2      | 1.                           |                          |  |
| CE 02                       | Construction Entrance   | Z7  |                                  | Removed                      |                          |  |
| Current Condition:          | Removed - Rich Engdahl  | paved the construction en                           | trance prior to the inspectio    | n on 12/14/21.               | •                        |  |
| CW 01                       | Concrete Washout  | On Site   |                                  | Removed                      |                          |  |
| Current Condition:          | Removed - Rich Engdahl  | removed the concrete was                            | shout prior to the inspection    | on 3/1/22.                   | •                        |  |
| D 01                        | Diversion Check   | Z6 to Z8  |                                  | Removed                      |                          |  |
| Current Condition:          |   |   | to the inspection on 8/10/27     |                              | 1                        |  |
| IP 01                       | Inlet Protection  | F13   | 8/29/2021                        | Active                       | No                       |  |
| Current Condition:          |   |   | nspection on 12/21/21. Due       |                              | , inlet protection is no |  |
|                             | recommended at this time  | <ul> <li>E&amp;A inspector will continue</li> </ul> | nue to monitor.                  |                              |                          |  |
| IP 02                       | Inlet Protection  | F3  | 6/29/2021                        | Active                       | No                       |  |
| Current Condition:          | Active - This is an existing  | g inlet located off of 21st A                       | venue. Rich Engdahl install      | ed inlet protection prior to | o the 3/22/22 inspection |  |
|                             |   |   | ne 6/7/22 inspection. Constr     | ruction is complete and the  | ne area is sodded, so    |  |
|                             | reinstallation will not be re   | commended.  |                                  |                              |                          |  |
| IP 03                       | Inlet Protection  | F2  | 6/29/2021                        | Active                       | No                       |  |
| Current Condition:          | Active - This is an existing  | inlet located off of 21st A                         | venue. Due to the location of    | of the inlet no BMP recon    | nmendation is needed     |  |
|                             | this time. E&A inspector w  | •   |                                  |                              |                          |  |
| IP 04                       | Inlet Protection  | M4  | 8/29/2021                        | Active                       | No                       |  |
| Current Condition:          | Active - Rich Engdahl inst  | alled the inlet prior to the i                      | nspection on 10/26/21. Due       | e to the area being paved    | , inlet protection is no |  |
|                             | Active - Rich Engdahl installed the inlet prior to the inspection on 10/26/21. Due to the area being paved, inlet protection is not recommended at this time. E&A inspector will continue to monitor. |   |                                  |                              |                          |  |
| IP 05                       | Inlet Protection  | P3  | 6/29/2021                        | Active                       | No                       |  |
| Current Condition:          | Active - This is an existing  |   | venue. Rich Engdahl install      | ed inlet protection prior to |                          |  |
| current condition.          |   |   |                                  |                              |                          |  |
|                             | Rich Engdahl removed the inlet protection prior to the 6/7/22 inspection. Construction is complete and the area is sodded, so reinstallation will not be recommended.                                 |   |                                  |                              |                          |  |
|                             |   |   |                                  |                              | 1                        |  |
| IP 06                       | Inlet Protection  | P2  | 6/29/2021                        | Active                       | No                       |  |
| Current Condition:          |   |   | venue. Due to the location of    | of the inlet no BMP recon    | nmendation is needed     |  |
|                             | this time. E&A inspector w  | vill continue to monitor.                           |                                  |                              |                          |  |
| IP 07                       | Inlet Protection  | Q4  | 10/5/2021                        | Active                       | No                       |  |
| Current Condition:          |   |   | nspection on 10/05/21. Due       | e to the area being paved    | , inlet protection is no |  |
|                             | recommended at this time  | <ul> <li>E&amp;A inspector will contir</li> </ul>   | ue to monitor.                   |                              |                          |  |
| IP 08                       | Inlet Protection  | U4  | 10/5/2021                        | Active                       | No                       |  |
| Current Condition:          | Active - Rich Engdahl inst  | alled the inlet and inlet pro                       | ptection prior to the inspection | on on 10/05/21. Rich Eng     | dahl removed the inle    |  |
|                             | protection prior to the 6/7/22 inspection. Construction is complete and the area is sodded, so reinstallation will not be   |   |                                  |                              |                          |  |
|                             | recommended.  |   |                                  |                              |                          |  |
| IP 09                       | Inlet Protection  | X3  | 6/29/2021                        | Active                       | No                       |  |
| Current Condition:          | Active - This is an existing  | inlet located off of 21st A                         | venue. Rich Engdahl install      | ed inlet protection prior to | the 3/22/22 inspection   |  |
|                             | Rich Engdahl removed the inlet protection prior to the 6/7/22 inspection. Construction is complete and the area is sodded, so   |   |                                  |                              |                          |  |
|                             | reinstallation will not be re   |   |                                  |                              | ,,,                      |  |
| IP 10                       | Inlet Protection  | X2  | 6/29/2021                        | Active                       | No                       |  |
| Current Condition:          | Active - This is an existing  | inlet located off of 21st A                         | venue. Due to the location       | of the inlet no BMP recon    | nmendation is needed     |  |
|                             | this time. E&A inspector will continue to monitor.  |   |                                  |                              |                          |  |
| IP 11                       | Inlet Protection  | Y6  | 10/5/2021                        | Active                       | No                       |  |
| Current Condition:          | Active - Rich Engdahl inst  | alled the inlet and inlet pro                       | tection prior to the inspection  | on on 10/05/21. Rich Eng     | dahl removed the inle    |  |
|                             | protection prior to the 6/7/22 inspection. Construction is complete and the area is sodded, so reinstallation will not be   |   |                                  |                              |                          |  |
|                             | recommended.  | -   | -                                |                              |                          |  |
| IP 12                       | Inlet Protection  | Y7  | 10/5/2021                        | Active                       | No                       |  |
| Current Condition:          | Active - Rich Engdahl inst  | alled the inlet and inlet pro                       | ptection prior to the inspection | on on 10/05/21. Rich Eng     | dahl removed the inle    |  |
|                             | protection prior to the inspection on 11/23/21. Due to the area being paved, reinstallation is not recommended at this time. E&A  |   |                                  |                              |                          |  |
|                             | inspector will continue to r  | monitor.  |                                  |                              |                          |  |
| IP 13                       | Inlet Protection  | Y8  | 10/5/2021                        | Active                       | No                       |  |
| Current Condition:          |   |   | tection prior to the inspection  |                              |                          |  |
|                             |   |   | o the area being paved, reir     |                              |                          |  |
|                             | inspector will continue to r  |   | 0, .,                            |                              |                          |  |
|                             | Inlet Protection  | Y11   | 10/5/2021                        | Active                       | No                       |  |
| IP 14                       |   |   |                                  |                              |                          |  |
|                             |   |   | tection prior to the inspection  | on on 10/05/21. Rich End     | dahl removed the inle    |  |
| IP 14<br>Current Condition: | Active - Rich Engdahl inst  | alled the inlet and inlet pro                       | n is complete and the area       |                              | ,                        |  |

| PB 01                               | Portable toilet   | On Site  |  | Removed  |   |
|-------------------------------------|---|--|--|--|---|
| Current Condition:                  |   | removed the portable toilet  | prior to the 5/17/22 inspe   |  |   |
| SF 01 - SF 06                       | Silt Fence  | G3 to B15  |  | Removed  |   |
| Current Condition:                  |   | ector pre-approved removal   | of SE 3.6 on 0/22/21 SE  |  | prior to the increation on  |
| Current Condition.                  |   | ector pre-approved removal   |  |  |   |
|                                     |   | al in this area for sprinkler  |  |  |   |
|                                     | 12/14/21.   |  |  | removed an sin tence p   |   |
| SF 07 - SF 12                       | Silt Fence  | B16 to P12   |  | Removed  |   |
| Current Condition:                  |   | 1, the City has approved silf  | fence removal in this are  |  | d a majority of SF 7 - 12   |
|                                     |   | 12/7/21. Rich Engdahl remo   |  | •  |   |
| SF 13 - SF 17                       | Silt Fence  | S12 to Z5  |  | Removed  |   |
| Current Condition:                  |   | 1, the City has approved silt  | fence removal in this are  |  | od SE 13 and SE 14 prior  |
| ourrent oonution.                   |   | Rich Engdahl removed SF  |  | 0  |   |
| SF 18 - SF 22                       | Silt Fence  | Z3 to K3   |  | Removed  |   |
| Current Condition:                  |   |  | e from CE 10, 22 prior to  |  | /21 Dish Engdahl ramay  |
| Current Condition:                  | Removed - Rich Engdahl removed the silt fence posts from SF 18 - 22 prior to the inspection on 12/14/21. Rich Engdahl removed the trenched silt fence fabric prior to the inspection on 3/1/22.   |  |  |  |   |
| STR                                 |   | · · ·  |  | A /:   | N   |
| -                                   | Streets   | On Site  | 6/29/2021  | Active   | No  |
| Current Condition:                  | Good Condition - Rich En  | gdahl cleaned up the track   | out on 21st Ave. phor to tr  | le inspection on 9/7/21.   | Rich Englani cleaned up   |
|                                     |   |  |  |  |   |
|                                     |   | r to the inspection on 10/12   |  |  |   |
|                                     | on 11/2/21. Minor sedime  | ntation was observed arour   | nd CE 1 during the 12/14/2   | 21 inspection. Rich Enge   | dahl cleaned up the   |
|                                     | on 11/2/21. Minor sedime  |  | nd CE 1 during the 12/14/2   | 21 inspection. Rich Enge   | dahl cleaned up the   |
|                                     | on 11/2/21. Minor sedime<br>sediment around CE 1 pri  | ntation was observed arour<br>or to the 12/28/21 inspectio   | nd CE 1 during the 12/14/2   | 21 inspection. Rich Enge<br>21st Avenue prior to the   | dahl cleaned up the   |
| SWPPP Sign 01                       | on 11/2/21. Minor sedime<br>sediment around CE 1 pri  | ntation was observed arour<br>or to the 12/28/21 inspection<br>Adjacent to CE 1  | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned  | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed  | dahl cleaned up the<br>3/22/22 inspection.  |
| SWPPP Sign 01<br>Current Condition: | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah  | ntation was observed arour<br>or to the 12/28/21 inspection<br>Adjacent to CE 1  | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned  | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed  | dahl cleaned up the<br>3/22/22 inspection.  |
|                                     | on 11/2/21. Minor sedime<br>sediment around CE 1 pri  | ntation was observed arour<br>or to the 12/28/21 inspection<br>Adjacent to CE 1  | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned  | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed  | dahl cleaned up the<br>3/22/22 inspection.  |
| Current Condition:                  | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah<br>reinstallation will not be  | ntation was observed arour<br>or to the 12/28/21 inspection<br>Adjacent to CE 1  | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned :<br>gn prior to the 8/9/22 ins  | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed<br>pection. Due to immin   | dahl cleaned up the<br>3/22/22 inspection.<br>ent closure of the proje  |
| Current Condition:                  | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah<br>reinstallation will not be<br>"I certify, under penalty of  | ntation was observed arour<br>or to the 12/28/21 inspection<br>Adjacent to CE 1<br>I removed the SWPPP sign<br>recommended.  | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned<br>gn prior to the 8/9/22 ins<br>d all attachments were pre  | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed<br>pection. Due to immin<br>spared under my direction  | dahl cleaned up the<br>3/22/22 inspection.<br>ent closure of the proje  |
| Current Condition:                  | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah<br>reinstallation will not be<br>"I certify, under penalty of<br>accordance with a system  | ntation was observed arour<br>or to the 12/28/21 inspection<br>Adjacent to CE 1<br>I removed the SWPPP sign<br>recommended.<br>law, that this document and   | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned<br>gn prior to the 8/9/22 ins<br>d all attachments were pre<br>ualified personnel properly   | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed<br>pection. Due to immin<br>epared under my direction<br>gathered and evaluated  | dahl cleaned up the<br>3/22/22 inspection.<br>ent closure of the proje<br>on or supervision in<br>d the information submitt   |
| Current Condition:                  | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah<br>reinstallation will not be<br>"I certify, under penalty of<br>accordance with a system<br>Based on my inquiry of the  | ntation was observed arour<br>or to the 12/28/21 inspection<br>Adjacent to CE 1<br>I removed the SWPPP sign<br>recommended.<br>Iaw, that this document and<br>designed to assure that que<br>e person or persons who m | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned<br>gn prior to the 8/9/22 ins<br>d all attachments were pre<br>aalified personnel properly<br>anage the system or thos                             | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed<br>pection. Due to immin<br>spared under my direction<br>gathered and evaluated<br>e persons directly respo  | dahl cleaned up the<br>3/22/22 inspection.<br>ent closure of the proje<br>on or supervision in<br>d the information submitt<br>nsible for gathering the   |
| Current Condition:                  | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah<br>reinstallation will not be<br>"I certify, under penalty of<br>accordance with a system<br>Based on my inquiry of the<br>information, the informatic                               | Adjacent to CE 1<br>Adjacent to CE 1<br>I removed the SWPPP signed<br>recommended.<br>Iaw, that this document and<br>designed to assure that que<br>e person or persons who mon<br>submitted is, to the best           | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned<br>gn prior to the 8/9/22 ins<br>d all attachments were pre<br>ualified personnel properly<br>anage the system or thos<br>of my knowledge and beli | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed<br>pection. Due to immin<br>spared under my direction<br>gathered and evaluated<br>e persons directly respo<br>ef, true, accurate, and c   | dahl cleaned up the<br>3/22/22 inspection.<br>ent closure of the proje<br>on or supervision in<br>d the information submitted<br>nsible for gathering the<br>omplete. I am aware that                         |
| Current Condition:                  | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah<br>reinstallation will not be<br>"I certify, under penalty of<br>accordance with a system<br>Based on my inquiry of th<br>information, the informatio<br>there are significant penal | ntation was observed arour<br>or to the 12/28/21 inspection<br>Adjacent to CE 1<br>I removed the SWPPP sign<br>recommended.<br>Iaw, that this document and<br>designed to assure that que<br>e person or persons who m | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned<br>gn prior to the 8/9/22 ins<br>d all attachments were pre<br>ualified personnel properly<br>anage the system or thos<br>of my knowledge and beli | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed<br>pection. Due to immin<br>spared under my direction<br>gathered and evaluated<br>e persons directly respo<br>ef, true, accurate, and c   | dahl cleaned up the<br>3/22/22 inspection.<br>ent closure of the proje<br>on or supervision in<br>d the information submitt<br>nsible for gathering the<br>omplete. I am aware that                           |
| V                                   | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah<br>reinstallation will not be<br>"I certify, under penalty of<br>accordance with a system<br>Based on my inquiry of the<br>information, the informatic                               | Adjacent to CE 1<br>Adjacent to CE 1<br>I removed the SWPPP signed<br>recommended.<br>Iaw, that this document and<br>designed to assure that que<br>e person or persons who mon<br>submitted is, to the best           | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned<br>gn prior to the 8/9/22 ins<br>d all attachments were pre<br>ualified personnel properly<br>anage the system or thos<br>of my knowledge and beli | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>Removed<br>pection. Due to immin<br>spared under my direction<br>gathered and evaluated<br>e persons directly respo<br>ef, true, accurate, and c   | dahl cleaned up the<br>3/22/22 inspection.<br>ent closure of the proje<br>on or supervision in<br>d the information submitte<br>nsible for gathering the<br>omplete. I am aware that                          |
| Current Condition:                  | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah<br>reinstallation will not be<br>"I certify, under penalty of<br>accordance with a system<br>Based on my inquiry of th<br>information, the informatio<br>there are significant penal | Adjacent to CE 1<br>Adjacent to CE 1<br>I removed the SWPPP signed<br>recommended.<br>Iaw, that this document and<br>designed to assure that que<br>e person or persons who mon<br>submitted is, to the best           | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned<br>gn prior to the 8/9/22 ins<br>d all attachments were pre<br>ualified personnel properly<br>anage the system or thos<br>of my knowledge and beli | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>21st Avenue prior to the<br>pection. Due to immin<br>pared under my direction<br>gathered and evaluated<br>e persons directly respo<br>ef, true, accurate, and c<br>sibility of fines and impr | dahl cleaned up the<br>3/22/22 inspection.<br>ent closure of the proje<br>on or supervision in<br>d the information submitted<br>nsible for gathering the<br>omplete. I am aware that<br>isonment for knowing |
| Current Condition:                  | on 11/2/21. Minor sedime<br>sediment around CE 1 pri<br>SWPPP Signs<br>Removed - Rich Engdah<br>reinstallation will not be<br>"I certify, under penalty of<br>accordance with a system<br>Based on my inquiry of th<br>information, the informatio<br>there are significant penal | Adjacent to CE 1<br>Adjacent to CE 1<br>I removed the SWPPP signed<br>recommended.<br>Iaw, that this document and<br>designed to assure that que<br>e person or persons who mon<br>submitted is, to the best           | nd CE 1 during the 12/14/2<br>n. Rich Engdahl cleaned<br>gn prior to the 8/9/22 ins<br>d all attachments were pre<br>ualified personnel properly<br>anage the system or thos<br>of my knowledge and beli | 21 inspection. Rich Engr<br>21st Avenue prior to the<br>21st Avenue prior to the<br>pection. Due to immin<br>pared under my direction<br>gathered and evaluated<br>e persons directly respo<br>ef, true, accurate, and c<br>sibility of fines and impr | dahl cleaned up the<br>3/22/22 inspection.<br>ent closure of the projection<br>on or supervision in<br>d the information submitt<br>nsible for gathering the<br>omplete. I am aware that                      |