E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A- P2017.2	58.000		Stage		
Inspector: Ethan Anderson							
Project Name:	CSW-2	Ashbury Hills CSW-201802941 / PAP-20180830-4699-GP1					
For Week Ending:		11/11/2023					
Project Location:	120th Str	eet and Schram Road,	Papillion, NE (Sarpy Coun	ty)			
Grading:	99%						
Sanitary Sewer:	97%						
Storm Sewer:	97%						
Paving:	99%						
Seeding:	90%						
Utilities:	90%						
Overall Development:	50%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration		
						Week	
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.00"						
Thursday:	0.00"	11/9/2023	Sunny 63/31	3:45 PM			
Friday:	0.00"						
Saturday:	0.00"						
Complaints:	None						

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site: Grading commenced (11/8/2018) Grading has begun in Drainage Areas Dev. 2, Dev. 3, and Dev. 4 (11/15/2018). Grading has temporarily ceased due to winter conditions. Minor grading/regrading W of SB 3 to redirect water flowing off site to east (4/13/2019). Stockpiling in the western portion of Dev 2 (4/24/2019). Grading has begun in the western portion of Dev 2 (5/9/2019). Stripping/Grading in southern portion of Dev A and throughout Dev 5 (6/13/2019). Stripping/Grading in northeastern portion of Dev 2 (6/27/2019) Minor regrading/excavation in DEV 3 -School (7/31/2019). Excavation in Dev 3 and Dev 4 for sanitary installation (8/08/2019). Trenching in Dev 4 for utility installation (9/04/2019). Grading has temporarily ceased throughout the site (10/11/2019). Grading has resumed for basin installation (10/16/2019) Grading has resumed throughout the site (10/22/2019). Excavation near SB 4 for basin installation (10/22/2019). Excavation along the northern perimeter of the site near 120th St for sanitary tie-in (10/31/2019). Stripping/grading in DEV A (10/31/2019). Disking occurring in Dev 4 (11/7/2019). Sanitary installation in Dev 2/3 (11/7/2019). Grading in Dev 5 and Dev A for basin excavation (11/14/2019). Fine grading in Dev 4 and Dev 3 in preparation for paving (11/14/2019). Grading in Dev A (12/12/2019). Grading has temporarily ceased due to winter conditions (1/23/2020). Grading has resumed (4/27/2020); Backfilling of curbs for paving underway (10/21/2020). Excavation on Lot 110 (12/22/2020). Grading on eastern side of Dev 2 (1/12/2021). Grading in Dev A, and northern portion of Dev 2 (2/23/2021). Excavation by 124th st and Gold Coast Rd (3/4/2021). Excavation by 125th and Edward St, and sidewalk pavement near east end of Gold Coast Rd (3/10/2021). Utilities were put in the southwest corner of the site (4/21/2021). Grading in SW corner of site by Calabretto Building Group (9/8/2021). Ground disturbance west of SB 4 for sewer installation (10/19/2022). Storm sewer work in phase II (4/27/2023). Gradi

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire Site: Grading commenced (11/8/2018) Grading has begun in Drainage Areas Dev. 2, Dev. 3, and Dev. 4 (11/15/2018). Grading has temporarily ceased due to winter conditions. Minor grading/regrading W of SB 3 to redirect water flowing off site to east (4/13/219). Stockpiling in the western portion of Dev 2 (4/24/2019). Grading has begun in the western portion of Dev 2 (5/9/2019). Stripping/Grading in southern portion of Dev A and throughout Dev 5 (6/13/2019). Stripping/Grading in northeastern portion of Dev 2 (6/27/2019) Minor regrading/excavation in DEV 3 -School (7/31/2019). Excavation in Dev 3 and Dev 4 for sanitary installation (8/08/2019). Trenching in Dev 4 for utility installation (9/04/2019). Grading has temporarily ceased throughout the site (10/11/2019). Grading has resumed for basin installation (10/16/2019) Grading has resumed throughout the site (10/22/2019). Excavation near SB 4 for basin installation (10/22/2019). Excavation along the northern perimeter of the site near 120th St for sanitary tie-in (10/31/2019), Stripping/grading in DEV A (10/31/2019), Disking occurring in Dev 4 (11/7/2019), Sanitary installation in Dev 2/3 (11/7/2019), Grading in Dev 5 and Dev A for basin excavation (11/14/2019). Fine grading in Dev 4 and Dev 3 in preparation for paving (11/14/2019). Grading in Dev A (12/12/2019). Grading has temporarily ceased due to winter conditions (1/23/2020). Grading has resumed (4/27/2020); Backfilling of curbs for paving underway (10/21/2020). Excavation on Lot 110 (12/22/2020). Grading on eastern side of Dev 2 (1/12/2021), Grading in Dev A, and northern portion of Dev 2 (2/23/2021), Excavation by 124th st and Gold Coast Rd (3/4/2021), Excavation by 125th and Edward St, and sidewalk pavement near east end of Gold Coast Rd (3/10/2021). Utilities were put in the southwest corner of the site (4/21/2021). Grading in SW corner of site by Calabretto Building Group (9/8/2021). Ground disturbance for sewer installation around Outlot L (7/27/2022.) Ground disturbance west of SB 4 for sewer installation (10/19/2022). Storm sewer work in phase II (4/27/2023). Grading north of SB 5 to S 125th st., along Lake Vista and Windsor dr. (5/11/23). Grading of S 125th st (06/01/23). Grading along S 125th st, S 124th st and Horizon st (6/15/23). Grading along S 125th st, Lake Tahoe Drive and Lake Vista Drive (6/22/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/8/2018). EM 1 partially installed (9/30/2019). DEJ seeded the central drainage around the future S. 124th St., the slope in the northeastern guadrant of the site (6/16/2020); school site was sodded (12/9/2020). ROW seeding began (6/2/2021). Matting of the slope west of S 120th entrance (8/25/2021). Seeding/matting Outlots F, G, H, and ROW overseeding (4/1/2022). Commercial Seeding seeded and matted the northwest and southwest areas of the site (6/1/23). Erosion matting installed on outlot E (7/6/23). Erosion matting installed south of silt basin 1 (8/31/23). Matting installed at the end of the stub road on Lake Vista Dr (10/12/23). Seeding along Edgewater Dr, S 125th st, Windsor Dr, Windsor Dr, Lake Vista Dr, S 124th ave (10/12/23).

Checklist Questions:

1. Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

2. Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective Action?

No - See Findings Section.

3. Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

No - See BMP Section.

4. Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

No - See BMP Section.

5. Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

Comments:

- 1.) Site was active for home construction and paving during last inspection.
- 2.) Ashbury Hills Self Storage (CSW-202105789) is active on Lot 166 of the Ashbury Hills development as of 9/13/21.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
A 1	Area Inlet Protection	R 16	•	Removed			
Current Condition:	Removed - Silt fence around	Removed - Silt fence around the inlet will not be recommended as of 4/16/21 due to inlet leading to a sediment basin.					
Al 2	Area Inlet Protection	N of SB 5	3/9/2023	Active	No		
Current Condition:	Active - Graham Construction	n installed an area inlet prior	to the inspection on 3/09/23	3. The area inlet wa	as above grade, thus inlet		
	protection is not required at the	nis time. E&A inspector will r	nonitor.				
B 1		North side of site (west of					
ВΙ	Temporary Berm	SB 2)		Removed			
Current Condition:	Removed - DEJ Grading rem	Removed - DEJ Grading removed the temporary berm during the excavation of SB 5 prior to inspection on 11/14/19.					
B 2		Southwest side of site (NE					
D Z	Temporary Berm	of SB 5)		Removed			

Current Condition:	Removed - DEJ Grading rem	oved the berms prior to insp	ection on 12/18/19. The be	rms are not needed	l at this time. E&A will monitor.
В 3	Temporary Berm	Northwest side of site (Along SF 9)	5/18/2023	Active	No
Current Condition:	Good Condition - The Farmer	to the west installed the be	m prior to inspection on 5/	18/23. The E&A insp	pector will monitor.
CE 1	Stabilized Construction Entrance	Schram Road (W27)		Removed	
Current Condition:	Removed - The construction Improvements project grading			o longer in use due	to the Schram Road
CE 2	Stabilized Construction Entrance	Schram Road (AA27)		Removed	
Current Condition:	Removed - Prairie Constructi is associated with the school				construction. Since this BMP ection.
CE 3	Stabilized Construction Entrance	Schram Road (O27)		Removed	
Current Condition:	not necessary due to grading the inspection on 9/24/20.				on on 9/24/20. Reinstallation is g the entrance location prior to
CE 4	Stabilized Construction Entrance	Schram Road (W27)	0/40/00	Removed	
Current Condition:	Removed - MBC paved the e		on on 8/10/23.	1	
CW 1 Current Condition:	Concrete Washout Removed- Tab Construction	North of SB 4 removed the washout pit prid	or to 11/18/20	Removed	
CW 2	Concrete Washout	Outlot A-South 124th Street & Horizon Street	5/19/2021	Active	No
Current Condition:	Good Condition- GPCS insta cleaned up concrete waste at of the washout prior to the ins on 11/9/23.	lled the washout pit prior to t	to the inspection on 3/7/22.	Sudbeck Homes in	stalled a berm along the front
CW 3	Concrete Washout	Lot 65 to 267		Removed	
Current Condition:	Removed - MBC removed the		ut prior to the inspection or		
D 1	Temporary Diversion Ditch	(BB8-BB15)		Removed	
Current Condition:		e diversion was graded out			n does not appear necessary at
D 2	Temporary Diversion Ditch	(Q1-V2)		Removed	
Current Condition:	Removed - The diversion is r water via curb inlets to the ba	o longer necessary as of the	e inspection on 8/27/20 due		rd Avenue, which will divert
D 3 Current Condition:	Temporary Diversion Ditch Good Condition - DEJ installe inspection on 11/11/21. Com				No defined the diversion prior to the 6/1/23 .
D 4	Temporary Diversion Ditch	(BB21-BB25)		Removed	
Current Condition:	Removed- Due to pavement	operations and school work,	diversion ditch was remov	ed as of 10/21/2020	
D 5	Temporary Diversion Ditch	(X2-BB6)		Removed	
Current Condition:	Removed - Due to stabilization	on and lot building the divers	ion is no longer necessary	as of 10/5/23.	
D 6	Temporary Diversion Ditch	(V27-AA27)		Removed	
Current Condition:	<mark></mark>	•	•	•	getation in part of the intended nder of the intended location.
D 7	Temporary Diversion Ditch	(E28-P28)		Active	
Current Condition:	Removed - DEJ installed the	diversion prior to the inspec	tion on 8/27/20. DEJ redefi	ned the diversion pr	ior to the inspection on 6/15/21.
D 8	Temporary Diversion Ditch	(B8-B13)		Active	
Current Condition:	Removed - DEJ installed the 5/19/21.	diversion prior to the inspec	tion on 8/27/20. GPCS red	efined the diversion	prior to the inspection on
D 9	Temporary Diversion Ditch	(C3-E2)		Removed	
Current Condition:	Removed- Due to pavement	operations and school work,	diversion ditch was remov	ed as of 10/21/2020	
EM 1	Erosion Control Matting	(CC20-CC27)		Active	
Current Condition:	Removed - Erosion control m installation during future insp				
EM 2	Erosion Control Matting	B5	6/1/2023	Active	No
Current Condition:	<u> </u>		control matting from south o	of SB1 to north of lal	ke vista drive and from south of
EM 3	Erosion Control Matting	End of Lake Vista Dr stub road	10/12/2023	Active	No
Current Condition:	Good Condition - Commercia	l Seeding installed erosion of	control matting prior to insp	ection on 10/12/23.	
ET 1	Erosion Control Terrace	C 12-21		Removed	
Current Condition:	Removed - The erosion contr	ol terrace has been remove	d and replaced with D-3 an	d D-8 as of the insp	ection on 8/27/20.

FT 1	Fuel Tanks	O23		Removed		
Current Condition:	Removed - Roth Enterprises	removed the fuel tank prior	to the inspection on 5/26/20	O.		
FT X	Fuel Tank	Onsite	· ·	Removed		
Current Condition:	Removed - MBC removed th		otion on 10/5/22	Ttomovou		
			1	D	1	
Lot 1	Individual Lot	Lot 1	<u> </u>	Removed		
Current Condition:	Removed - Ideal Designs soc	ided the lot prior to the 5/18	/22 inspection.			
Lot 7	Individual Lot	Lot 7		Removed		
Current Condition:	Removed - Al Belt sodded the	e lot prior to the inspection o	on 7/20/23	!		
			T	Domoved		
Lot 8	Individual Lot	Lot 8		Removed		
Current Condition:	Removed - Baranko Homes s	sodded the lot prior to the in	spection on 8/10/23.			
Lot 10	Individual Lot	Lot 10		Removed		
Current Condition:	Removed - JC Custom sodde	ed the lot prior to the inspect	ion on 10/26/23.	•		
Lot 11	Individual Lot	Lot 11	4/27/2022	Active	Yes	
Current Condition:	Fair Condition - The homeow					
					owner installed silt fence along	
	the rear of the lot prior to the	inspection on 6/29/22. The I	nomeowner graded the fron	nt of the lot and rem	oved the rear silt fence prior to	
	the inspection on 8/3/23. The					
	homeowner cleaned the sig					
	nomeowner cleaned the sic	iewaik at the real and mist	alled a slit leffice prior to	the mopection on	11/3/23.	
	Wattles should be installed or	n front of the lot.				
	Heather and Kevin Welsh we	re informed to complete by	10/26/23. Not done as of la	st inspection.		
		,,				
Lot 14	Individual Lot	Lot 14	6/8/2023	Active	No	
Current Condition:					observed in the ROW on 6/8/23.	
Current Condition:					baserved in the NOW on 0/6/23.	
	The homeowner secured a po	ortable tollet and cleaned the	e streets prior to the 7/20/22	2 inspection.		
	Silt fence or wattles should be	e installed along the street.				
	The homeowner was informe	d to complete by 8/31/23 N	ot done as of last inspection	n The homeowner	was reminded on 9/29/23	
	10/26/23	a to complete by 0/3 1/23. IV	of dolle as of last inspection	ii. The nomeowici	was reminded on 5/25/25,	
1.47		1 1 1 7	1			
Lot 17	Individual Lot	Lot 17		Removed		
Current Condition:	Removed - Timeless Homes	sodded the lot and moved a	and secured the portable toi	let across the stree	t prior to the inspection on	
	6/22/23.					
Lot 19	Individual Lot	Lot 19		Removed		
Current Condition:	Removed - Belt Construction		1/19/22 increation			
Lot 20	Individual Lot	Lot 20	5/18/2023	Pending	Yes	
Current Canalitian.	D 11 T1 1 11 1					
Current Condition:	Current Condition: Pending - Timeless Homes began excavating the lot prior to the 5/18/23 inspection. Dirt piles were observed in the ROW					
Current Condition:						
Current Condition:	Timeless Homes cleaned the	streets prior to the inspection	on on 7/27/23. Timeless Ho			
Current Condition:		streets prior to the inspection	on on 7/27/23. Timeless Ho			
Current Condition:	Timeless Homes cleaned the secured a portable toilet prior	streets prior to the inspection to the inspection on 8/17/23	on on 7/27/23. Timeless Ho			
Current Condition:	Timeless Homes cleaned the	streets prior to the inspection to the inspection on 8/17/23	on on 7/27/23. Timeless Ho			
Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be	streets prior to the inspection to the inspection on 8/17/23 e installed along the street.	on on 7/27/23. Timeless Ho 3.	mes removed the d	lirt piles in the ROW and	
Current Condition:	Timeless Homes cleaned the secured a portable toilet prior	streets prior to the inspection to the inspection on 8/17/23 e installed along the street.	on on 7/27/23. Timeless Ho 3.	mes removed the d	lirt piles in the ROW and	
Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be	streets prior to the inspection to the inspection on 8/17/23 e installed along the street. ed to complete by 6/15/23.	on on 7/27/23. Timeless Ho 3. Not done as of last inspection	mes removed the d	lirt piles in the ROW and	
	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23	streets prior to the inspection to the inspection on 8/17/23 e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2	on on 7/27/23. Timeless Ho 3. Not done as of last inspection	omes removed the d	lirt piles in the ROW and	
Lot 26	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26	on on 7/27/23. Timeless Ho 3. Not done as of last inspection 9/23, 10/26/23	mes removed the d	lirt piles in the ROW and	
Lot 26 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the inspection	on on 7/27/23. Timeless Ho 3. Not done as of last inspection 9/23, 10/26/23	on. Timeless Homes Removed	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot	e installed along the street. det to complete by 6/15/23. N., 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in	Jon on 7/27/23. Timeless Ho 3. Jot done as of last inspection 9/23, 10/26/23 aspection on 6/21/22.	on. Timeless Homes Removed Removed	lirt piles in the ROW and	
Lot 26 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes	e installed along the street. det to complete by 6/15/23. N., 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in	Jon on 7/27/23. Timeless Ho 3. Jot done as of last inspection 9/23, 10/26/23 aspection on 6/21/22.	on. Timeless Homes Removed Removed	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Performance of the secure of the	e installed along the street. de to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior.	Jon on 7/27/23. Timeless Ho 3. Jot done as of last inspection 9/23, 10/26/23 aspection on 6/21/22.	on. Timeless Homes Removed Removed 14/23.	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Performent Individual Lot	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot place of the lot 27	Jot done as of last inspection on 6/21/22. Inspection on 6/21/22. Inspection on 9/21/22.	on. Timeless Homes Removed Removed	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perfor Individual Lot Removed - Timeless Homes	e installed along the street. e d to complete by 6/15/23. N., 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the ir Lot 25 mance Corp sodded the lot prior to the ir Lot 27 sodded the lot prior to the ir	Jot done as of last inspection on 6/21/22. Inspection on 6/21/22. Inspection on 9/21/22.	n. Timeless Homes Removed Removed 14/23. Removed	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Performent Individual Lot	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot place of the lot 27	Jot done as of last inspection on 6/21/22. Inspection on 6/21/22. Inspection on 9/21/22.	on. Timeless Homes Removed Removed 14/23.	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perfor Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot	e installed along the street. ed to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 27	Jot done as of last inspection of 1/27/23. Timeless Hotal. Jot done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 9/21/23. Inspection on 5/11/23.	on. Timeless Homes Removed Removed 14/23. Removed Removed	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perfor Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom H	e installed along the street. ed to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot Lot 27 sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 29	Jot done as of last inspection of 1/27/23. Timeless Hotal. Jot done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 9/21/23. Inspection on 5/11/23.	on. Timeless Homes Removed Removed 14/23. Removed Removed	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 39	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holividual Lot	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the lot 29	Jot done as of last inspection of 10/20/23, 10/26/23 spection on 6/21/22. prior to the inspection on 9/20/20, 10/26/	on. Timeless Homes Removed Removed 14/23. Removed Removed	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perfor Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom H	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the lot 29	Jot done as of last inspection of 10/20/23, 10/26/23 spection on 6/21/22. prior to the inspection on 9/20/20, 10/26/	on. Timeless Homes Removed Removed 14/23. Removed Removed	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 39	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holividual Lot	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the lot 29	Jot done as of last inspection of 10/20/23, 10/26/23 spection on 6/21/22. prior to the inspection on 9/20/20, 10/26/	on. Timeless Homes Removed Removed 14/23. Removed Removed	lirt piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 32 Current Condition: Lot 35	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot	e installed along the street. e installed along the street. e installed along the street. e to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the interpretable by 18/25 (CIR #19866), 9/2 Lot 25 mance Corp sodded the lot prior to the interpretable by 18/25 (CIR #19866), 9/2 Lot 27 sodded the lot prior to the interpretable by 18/25 (CIR #19866), 9/2 Lot 29 lomes sodded the lot prior to the interpretable by 18/25 (CIR #19866), 9/2 Lot 32 sodded the lot prior to the interpretable by 18/25 (CIR #19866), 9/2 Lot 35	lot done as of last inspection 9/23, 10/26/23 spection on 6/21/22. prior to the inspection on 9/1 spection on 5/11/23. be the inspection on 9/08/22. spection on 9/08/22.	n. Timeless Homes Removed Removed 14/23. Removed Removed Removed Removed	irit piles in the ROW and	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 35 (Ms. Ravichandar) sodded the lot prior to the in Lot 35	Jot done as of last inspection 9/23, 10/26/23 spection on 6/21/22. prior to the inspection on 9/2 spection on 5/11/23. be the inspection on 9/08/22. spection on 9/08/22. spection on 9/08/22. spection on 9/08/22. spection on 9/08/22.	n. Timeless Homes Removed Removed 14/23. Removed Removed Removed Removed	was reminded on 6/16/23,	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 35 Current Condition: Lot 38	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Individual Lot Indivi	e installed along the street. E installed along the inspection on along the street. E installed along the inspection on along the street. E installed along the inspection on along the street. E installed along the inspection on along the street. E installed along the inspection on along the street. E installed along the inspection on along the street. E installed along the inspection on along the street. E installed along	lot done as of last inspection 9/23, 10/26/23 spection on 6/21/22. prior to the inspection on 9/1 spection on 5/11/23. the inspection on 6/29/22. spection on 9/08/22.	n. Timeless Homes Removed Removed Removed Removed Removed Removed Removed Permoved Removed	s was reminded on 6/16/23, was reminded on 6/16/23, bition on 9/12/22.	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Development (Individual Lot Individual Lot Pending - Advantage Development (Individual Lot Individual Lot	e installed along the street. e d to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the installed along the lot prior to the installed alo	lot done as of last inspection on 7/27/23. Timeless Holds. lot done as of last inspection 9/23, 10/26/23	n. Timeless Homes Removed Removed Removed Removed Removed Removed Removed Pending On on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 35 Current Condition: Lot 38	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Individual Lot Indivi	e installed along the street. e d to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the installed along the lot prior to the installed alo	lot done as of last inspection on 7/27/23. Timeless Holds. lot done as of last inspection 9/23, 10/26/23	n. Timeless Homes Removed Removed Removed Removed Removed Removed Removed Pending On on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 35 Current Condition: Lot 38	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Development (Individual Lot Individual Lot Pending - Advantage Development (Individual Lot Individual Lot	e installed along the street. e d to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the installed along the lot prior to the installed alo	lot done as of last inspection on 7/27/23. Timeless Holds. lot done as of last inspection 9/23, 10/26/23	n. Timeless Homes Removed Removed Removed Removed Removed Removed Removed Pending On on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 35 Current Condition: Lot 38	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informed 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/2)	e installed along the street. de to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the interpretation of the interpr	lot done as of last inspection on 7/27/23. Timeless Holds. lot done as of last inspection 9/23, 10/26/23	n. Timeless Homes Removed Removed Removed Removed Removed Removed Removed Pending On on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 35 Current Condition: Lot 38	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/2011) Wattles should be installed	e installed along the street. de to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 35 [Ms. Ravichandar) sodded the lot prior to the in Lot 38 pment began excavation on 16/23. Advantage Development defends a street of the lot.	lot done as of last inspection on 7/27/23. Timeless Holds. lot done as of last inspection 9/23, 10/26/23	n. Timeless Homes Removed Removed Removed Removed Removed Removed Removed Pending On on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 35 Current Condition: Lot 38	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informed 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/2)	e installed along the street. de to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 35 [Ms. Ravichandar) sodded the lot prior to the in Lot 38 pment began excavation on 16/23. Advantage Development defends a street of the lot.	lot done as of last inspection on 7/27/23. Timeless Holds. lot done as of last inspection 9/23, 10/26/23	n. Timeless Homes Removed Removed Removed Removed Removed Removed Removed Pending On on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 35 Current Condition: Lot 38	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/21.) Wattles should be installe 2.) Concrete waste should be	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 35 Ms. Ravichandar) sodded the Lot 38 priment began excavation on 6/23. Advantage Development determined the lot.	on on 7/27/23. Timeless Holas. Jot done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 5/11/23. Inspection on 6/29/22. Inspection on 9/08/22.	n. Timeless Homes Removed Removed 14/23. Removed Removed Removed Removed Pemoved Pending On on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 35 Current Condition: Lot 38	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/2) 1.) Wattles should be installed 1.) Advantage Development of 1.	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 35 [Ms. Ravichandar) sodded the Lot 38 priment began excavation on 6/23. Advantage Development of the lot. I complete by 6/15/23. No. 8/15/23. No. 8/15/	on on 7/27/23. Timeless Holds. Jot done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 5/11/23. Inspection on 9/08/22.	Removed richterior to the inspection on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 35 Current Condition: Lot 38	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/21.) Wattles should be installe 2.) Concrete waste should be	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 35 [Ms. Ravichandar) sodded the Lot 38 priment began excavation on 6/23. Advantage Development of the lot. I complete by 6/15/23. No. 8/15/23. No. 8/15/	on on 7/27/23. Timeless Holds. Jot done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 5/11/23. Inspection on 9/08/22.	Removed richterior to the inspection on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 38 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/2) 1.) Wattles should be installed 1.) Advantage Development (2.) Advantage Development (3.) Advantage Development (4.)	e installed along the street. de to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the in Lot 25 mance Corp sodded the lot prior to the in Lot 27 sodded the lot prior to the in Lot 29 lomes sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 32 sodded the lot prior to the in Lot 35 [Ms. Ravichandar) sodded the Lot 38 priment began excavation on 6/23. Advantage Development of the lot. I complete by a sinformed to complete by was informed to complete by was informed to complete by the street.	on on 7/27/23. Timeless Holds. Jot done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 5/11/23. Inspection on 9/08/22.	n. Timeless Homes Removed Removed 14/23. Removed Removed Removed Removed Pending Pending on on 10/26/23. Dirt rior to the inspection st inspection.	irit piles in the ROW and s was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 38 Current Condition: Lot 38 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/21.) Wattles should be installed 2.) Concrete waste should be 1.) Advantage Development value individual Lot	e installed along the street. de to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the installed along the street. Lot 25 mance Corp sodded the lot prior to the installed along the lot prior to the installed th	on on 7/27/23. Timeless Holds. Not done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 5/11/23. Inspection on 9/08/22.	Removed richterior to the inspection on 10/26/23. Dirt	irit piles in the ROW and s was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 38 Current Condition: Lot 44 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/2 (1.) Wattles should be installed 2.) Concrete waste should be 1.) Advantage Development (2.) Advantage Development (3.) Advantage Development (3.) Removed - KRT Construction Removed - KRT Construction (4.)	e installed along the street. ed to complete by 6/15/23. No. 8/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the insurance Corp sodded the lot	on on 7/27/23. Timeless Holds. Not done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 5/11/23. Inspection on 9/08/22.	n. Timeless Homes Removed Removed 14/23. Removed Removed Removed Pending Pending on on 10/26/23. Dirt rior to the inspection st inspection. Removed	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 38 Current Condition: Lot 38 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/21.) Wattles should be installed 2.) Concrete waste should be 1.) Advantage Development value individual Lot	e installed along the street. de to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the installed along the street. Lot 25 mance Corp sodded the lot prior to the installed along the lot prior to the installed th	on on 7/27/23. Timeless Holds. Not done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 5/11/23. Inspection on 9/08/22.	n. Timeless Homes Removed Removed 14/23. Removed Removed Removed Removed Pending Pending on on 10/26/23. Dirt rior to the inspection st inspection.	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 38 Current Condition: Lot 44 Current Condition: Lot 44	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/2 (1.) Wattles should be installed 2.) Concrete waste should be Individual Lot Removed - KRT Construction Individual Lot Removed - KRT Construction Individual Lot	e installed along the street. de to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the insurance Corp sodded the lot prior sodded the lot prior to the insurance Corp sodded the lot prior sodded the lot prio	on on 7/27/23. Timeless Holds. Bot done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 9/08/22. Inspection on 9/08/23. Inspection on 9/08/23. Inspection on 9/08/23. Inspection on 9/14/23. Inspection on 9/14/23.	n. Timeless Homes Removed Removed 14/23. Removed Removed Removed Pending Pending on on 10/26/23. Dirt rior to the inspection st inspection. Removed	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 38 Current Condition: Lot 44 Current Condition: Lot 44 Current Condition: Lot 45 Current Condition:	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Homes Individual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/2 (Individual Lot Individual Lot Indiv	e installed along the street. de to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the insumance Corp sodded the lot. Was informed to complete by was informed to complete by was informed to complete by Lot 44 in sodded the lot prior to the insumance Corp sodded the lot prior sodded the lot prior to the insumance Corp sodded the lot prior sodded the lot prior to the insumance Corp sodded the lot prior sodded the lo	on on 7/27/23. Timeless Holds. Jot done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 5/11/23. Inspection on 9/08/22. Inspection on 9/08/23. Inspection on 9/08/23. Inspection on 9/14/23. Inspection on 9/14/23. Inspection on 9/14/23. Inspection on 9/14/23. Inspection on 4/20/23.	n. Timeless Homes Removed	irit piles in the ROW and s was reminded on 6/16/23, s was reminded on 6/16/23, stion on 9/12/22. Yes piles were observed on the lot on 11/02/23.	
Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition: Lot 29 Current Condition: Lot 32 Current Condition: Lot 35 Current Condition: Lot 38 Current Condition: Lot 44 Current Condition: Lot 44	Timeless Homes cleaned the secured a portable toilet prior Silt fence or wattles should be Timeless Homes was informe 6/26/23 (CIR 19423), 7/20/23 Individual Lot Removed - Timeless Homes Individual Lot Removed - Landmark Perford Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Removed - Colony Custom Holdividual Lot Removed - Belt Construction Individual Lot Removed - The homeowner (Individual Lot Removed - The homeowner (Individual Lot Pending - Advantage Develop during the inspection on 10/2 (1.) Wattles should be installed 2.) Concrete waste should be Individual Lot Removed - KRT Construction Individual Lot Removed - KRT Construction Individual Lot	e installed along the street. de to complete by 6/15/23. No. 18/24/23 (CIR #19866), 9/2 Lot 26 sodded the lot prior to the insurance Corp sodded the lot prior sodded the lot prior to the insurance Corp sodded the lot prior sodded the lot prio	on on 7/27/23. Timeless Holds. Bot done as of last inspection 9/23, 10/26/23 Inspection on 6/21/22. Inspection on 5/11/23. Inspection on 9/08/22. Inspection on 9/08/23. Inspection on 9/08/23. Inspection on 9/08/23. Inspection on 9/14/23. Inspection on 9/14/23.	n. Timeless Homes Removed Removed 14/23. Removed Removed Removed Pending Pending on on 10/26/23. Dirt rior to the inspection st inspection. Removed	irit piles in the ROW and s was reminded on 6/16/23, was reminded on 6/16/23, btion on 9/12/22. Yes piles were observed on the lot	

Current Condition:	Pending - Lot is inactive for colots and was not stabilized pr			ss point for the rear	areas of adjacent completed
	Street should be cleaned.	·			
	AL Belt Construction was info		3. Not done as of last inspe	ection. AL Belt Cons	truction was reminded on
Lot 47	10/19/23, 10/30/23 (CIR #203 Individual Lot	Lot 47		Removed	
Current Condition:	Removed - Matthew and Son		to the inspection on 6/22/2		L
Lot 58	Individual Lot	Lot 58	8/3/2022	Active	No
Current Condition:	Active - This lot is inactive for				
current condition.		8/3/22 inspection. Graves De	evelopment repaired the sil	It fence prior to the i	nspection on 6/15/23. Graves
Lot 70	Individual Lot	Lot 70	8/3/2022	Active	No
Current Condition:	Good Condition - This lot is i	nactive for construction. Gre	at Plains Contractor Service	ces installed silt fend	ce along the southeast corner of
	the lot prior to the 8/3/22 insp	ection. Graves Developmen	t repaired the silt fence price	or to the inspection of	on 6/15/23.
Lot 90	Individual Lot	Lot 90	8/3/2022	Pending	No
Current Condition:	Pending - This lot is inactive prior to the 8/3/22 inspection. removed the silt fence prior to	Graves Development repair	ed the silt fence prior to the	e inspection on 6/15	•
Lot 112	Individual Lot	Lot 112	4/29/2021	Active	No
Current Condition:					or to the inspection on 6/15/21.
	Legacy Homes re-secured ar				
	northeast corner of the lot pri Homes removed the silt fence	•	9	ed prior to the inspe	ction on 9/08/22. Legacy
Lot 114	Individual Lot	Lot 114	7/27/2022	Active	No
Current Condition:	Active - This lot is inactive for	construction. Legacy Home	s installed silt fence along	the south side and i	ear of the lot prior to the
	7/27/22 inspection. Graves D recommend reinstallation as		fence prior to the inspection	on on 7/6/23. E&A ir	nspector will monitor and
Lot 115	Individual Lot	Lot 115	7/27/2022	Active	No
Current Condition:	Active - This lot is inactive for	construction. Legacy Home	s installed silt fence along	the rear of the lot pr	for to the 7/27/22 inspection.
					r and recommend reinstallation
Lot 116	Individual Lot	Lot 116	7/27/2022	Active	No
Current Condition:	Active - This lot is inactive for Graves Development remove as needed.		_	•	rior to the 7/27/22 inspection. r and recommend reinstallation
Lot 120	Individual Lot	Lot 120	8/3/2022	Active	No
Current Condition:	Good Condition - This lot is i the lot prior to the 8/3/22 insp		at Plains Contractor Service	ces installed silt fend	ce along the southeast corner of
Lot 126	Individual Lot	Lot 126	8/3/2022	Active	No
Current Condition:	Active - This lot is inactive for				
	prior to the 8/3/22 inspection. removed the silt fence prior to	Graves Development repair the inspection on 7/6/23. E	ed the silt fence prior to the &A inspector will monitor a	e inspection on 6/22 nd recommend rein	2/23. Graves Development stallation as needed.
Lot 130	Individual Lot	Lot 130	10/28/2021	Active	No
Current Condition:		Legacy Homes repaired the	silt fence prior to the inspe	ection on 6/22/23. G	y Homes cleaned the streets iraves Development removed or to the inspection on 9/14/23.
Lot 131	Individual Lot	Lot 131		Removed	
Current Condition:	Removed - Legacy Homes so		pection on 7/27/22.	•	
Lot 132	Individual Lot	Lot 132	10/28/2021	Active	No
Current Condition:	Good Condition - This lot is in				
	prior to the 10/28/21 inspection				
Lot 133	Individual Lot	Lot 133		Removed	
Current Condition:	Removed - Legacy Homes so		pection on 7/27/22.	•	
Lot 134	Individual Lot	Lot 134		Removed	
Current Condition:	Removed - Legacy Homes so	-	pection on 7/27/22.		•
Lot 135	Individual Lot	Lot 135	10/28/2021	Active	No
Current Condition:					ing activities on adjacent lots
Sarront Sonation.		on. Legacy Homes installed	silt fence along the front co	rner of the lot prior	to the 8/3/22 inspection. Legacy
Lot 136	Individual Lot	Lot 136		Removed	
Current Condition:	Removed - Legacy Homes so		ection on 10/26/23	1 tomoved	<u> </u>
Lot 137	Individual Lot	Lot 137		Removed	
	Removed - Legacy Homes so		pection on 0/20/22	removed	
Current Condition:	ncemoved - Legacy Homes so	Juded the lot prior to the inst	JEGUOH OH 9/28/22.		

Lot 139	Individual Lot	Lot 139	7/7/2021	Active	No
Current Condition:	Active - This lot is inactive for				
	prior to the 8/3/22 inspection.				
	the silt fence prior to inspection			ence prior to the insp	pection on 7/6/23. E&A
	inspector will monitor and rec	I			
Lot 140	Individual Lot	Lot 140	8/3/2022	Active	No
Current Condition:	Active - This lot is inactive for				
	prior to the 8/3/22 inspection.				
	the silt fence prior to the inspe	ection on 7/6/23. E&A inspe	ctor will monitor and recom	mend reinstallation	as needed.
Lot 147	Individual Lot	Lot 147	8/3/2022	Active	No
Current Condition:	Active - This lot is inactive for	construction. Great Plains	Contractor Services installe	d silt fence along th	ne northwest corner of the le
	prior to the 8/3/22 inspection.	Graves Development repai	red the silt fence prior to the	e inspection on 6/22	2/23. Graves Development
	removed the silt fence prior to	the inspection on 7/6/23. E	&A inspector will monitor a	nd recommend rein	stallation as needed.
Lot 153	Individual Lot	Lot 153	8/3/2022	Active	No
Current Condition:	Active - This lot is inactive for	construction. Great Plains	Contractor Services installe	d silt fence along th	ne northwest corner of the le
	prior to the 8/3/22 inspection.				
	removed the silt fence prior to				
	I o i i o o i i o o i i o o o o o o o o				
Lot 154	Individual Lot	Lot 154		Removed	
			naction on 10/26/22	Removed	
Current Condition:	Removed - Legacy Homes so	· · · · · · · · · · · · · · · · · · ·	<u>'</u>	1	
Lot 159	Individual Lot	Lot 159	7/21/2021	Active	No
Current Condition:	Good Condition - Legacy Hor	mes began excavating the l	ot prior to the inspection on	7/21/21. Legacy Ho	omes installed silt fence alc
	the front corners of the lot price				
	Legacy Homes cleaned the s				
	wattles along the font of the		<mark>cured a portable toilet pric</mark>	1	<mark>n 11/9/23. </mark>
Lot 3, Replat 1	Individual Lot	Lot 3, Replat 1		Removed	
Current Condition:	Removed - THI Sodded the lo	ot prior to inspection on 4/27	7/23.		
Lot 5, Replat 1	Individual Lot	Lot 5, Replat 1		Removed	
Current Condition:	Removed - THI Builders sodo		2 inspection		
		· ·		Damassad	I
Lot 6, Replat 1	Individual Lot	Lot 6, Replat 1	1	Removed	
Current Condition:	Removed - THI Sodded the lo		0/23.	1	1
Lot 7, Replat 1	Individual Lot	Lot 7, Replat 1		Removed	
Current Condition:	Removed - THI sodded lot pr				
Lot 8, Replat 1	Individual Lot	Lot 8, Replat 1		Removed	
Current Condition:	Removed - THI Builders sodo	ded the lot prior to inspection	n on 4/27/23.	•	•
Lot 9, Replat 1	Individual Lot	Lot 9, Replat 1		Removed	
Current Condition:	Removed - THI Builders sodo		n on 4/27/23	110	
			T	D	I
Lot 10, Replat 1	Individual Lot	Lot 10, Replat 1	1/0=/00	Removed	
Current Condition:	Removed - Bridgewater sodd	ed the lot prior to inspection	n on 4/27/23.		
Lot 11, Replat 1	Individual Lot	Lot 11, Replat 1		Removed	
Current Condition:	Removed - Bridgewater Hom	es sodded the lot prior to the	e 5/18/22 inspection.		
Lot 12, Replat 1	Individual Lot	Lot 12, Replat 1		Removed	
Current Condition:	Removed - Bridgewater Hom		e 5/18/22 inspection.	1	1
	-		7/8/2022	Activo	No
Lot 13, Replat 1	Individual Lot	Lot 13, Replat 1		Active	
Current Condition:	Good Condition - Bridgewater			gewater Homes so	uded part of the lot and inst
	wattles in the rear of the lot pr	nor to the 7/8/22 inspection.		1	T
Lot 14, Replat 1	Individual Lot	Lot 14, Replat 1	7/18/2022	Active	No
Current Condition:	Good Condition - This lot is in	nactive for construction. Brid	lgewater Homes installed w	attles in the rear of	the lot prior to the 7/18/22
	inspection.				
Lot 15, Replat 1	Individual Lot	Lot 15, Replat 1	7/18/2022	Active	No
Current Condition:	Good Condition - This lot is in		lgewater Homes installed w	attles in the rear of	the lot prior to the 7/18/22
	inspection.		.9		р,
Lot 16, Replat 1	Individual Lot	Lot 16, Replat 1		Removed	
Current Condition:	Removed - Bridgewater Hom	· · ·	e 7/8/22 inspection	i (cilioveu	<u> </u>
			t morzz mopection.	I 5 ·	1
Lot 17, Replat 1	Individual Lot	Lot 17, Replat 1		Removed	
Current Condition:	Removed - Bridgewater Hom	es sodded the lot prior to the	e 7/8/22 inspection.		
Lot 44, Replat 1	Individual Lot	Lot 4, Replat 1	8/3/2022	Active	No
Lot ++, I topiat i	Good Condition - This lot is i	nactive for construction. Gre	eat Plains Contractor Service	es installed silt fend	ce along the east corner of
Current Condition:	10000 Condition Tills lot is i				
•		on. Graves Development re			
Current Condition:	lot prior to the 8/3/22 inspection		<u>. </u>	Removed	
Current Condition:	lot prior to the 8/3/22 inspection Portable Bathroom	Site		Removed	
Current Condition: PB 1 Current Condition:	lot prior to the 8/3/22 inspection Portable Bathroom Removed - Kersten Construct	Site tion removed the portable to		pection.	
PB 1 Current Condition: PB 2	lot prior to the 8/3/22 inspection Portable Bathroom Removed - Kersten Construct Portable Bathroom	Site tion removed the portable to Site	Dilet prior to the 4/21/21 insp	pection. Removed	
Current Condition: PB 1 Current Condition:	lot prior to the 8/3/22 inspection Portable Bathroom Removed - Kersten Construct	Site tion removed the portable to Site	Dilet prior to the 4/21/21 insp	pection. Removed	

Current Condition: SB 1	Removed - Tab Construction portable toilet on site prior to 6/22/23. MBC replaced the po 125th st prior to the inspectio MBC removed the portable to Sediment Basin	the inspection on 2/02/23. Mortable toilet and secured it non 8/10/23. MBC installed	MBC installed and secured a prior to the inspection on 7/ and secured a portable toil	a portable toilet on s 6/23. MBC removed	site prior to the inspection on d the portable toilet along S
Current Condition:	Good Condition - 10% Filled basin is still missing the outle not in place as of the 11/22/1	DEJ Grading began excavet structure, inlets, and the began inspection. DEJ Grading polipe prior to the inspection of 7/20. Roth Enterprises beganstalling the baffle prior to the	ation of the basin prior to in affle. The outlet pipe was in partially installed the riser pin 7/21/20. Great Plains Coin cleaning out the basin pries inspection on 9/8/21. Roth	ispection on 11/14/1/installed prior to inspection on intractor Services insort to the inspection on the the inspection in Enterprises cleaned.	19. As of the last inspection, the ection on 11/22/19. The riser is 12/12/19. DEJ closed the gaps stalled rip rap below the outfall on 8/17/21. Roth finished ed out the basin prior to the
SB 2	Sediment Basin	V5	8/19/2019	Active	No
Current Condition:	the basin during inspection or prior to the inspection on 12/2 DEJ closed the gaps between the inspection on 8/13/20. Ro	n 10/16/19. E&A will monitor 27/19. There are gaps betwen the riser and outlet pipe pr th cleaned out the eastern h completed cleanout and insta	r through completion of inst een the riser and outlet pipe ior to the inspection on 7/2 half of the basin, installed d alled dirt baffles and dewate	allation. DEJ Gradir that need closed a 1/20. DEJ installed i ewatering holes and ering holes prior to t	rip rap below the outfall prior to If the eastern baffle prior to the the inspection on 6/9/21. E&A
SB 3	Sediment Basin	AA17	11/15/2018	Active	No
Current Condition:	Good Condition - 20% Filled 11/28/18, however, excavatio 9/11/19 inspection. DEJ Grac inspection on 12/12/19. DEJ in	Basin will be installed when In/shaping of the basin was Iling rebuilt the berm of the b Installed a riser in the basin Roth began cleanout prior to	n grading begins in that are not complete. E&A will more asin prior to inspection on prior to the inspection on 7.0 the inspection on 6/9/21.	a. Basin excavation hitor. Excavation of 1 10/16/19. The outle /21/20. DEJ installe	h had begun as of inspection on the basin is complete as of the t pipe was installed prior to d rip rap below the outfall prior baffle prior to the inspection on
SB 4	Sediment Basin	AA26	11/15/2018	Active	No
	installed as of the 11/14/19 in	spection. The outlet pipe wa			of the basin was partially J installed a permanent riser in
	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A insp Sediment at the outfall was w	ne basin outfall prior to the in ore a silt fence wrap is no loo pector will continue to monit rashed away by natural proc	as installed prior to inspection respection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21	on on 11/27/19. DE outfall is connected f prises began clean ed the baffle prior to inspection. Roth Er	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection.
SB 5	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. E&A inspection in EAA inspection.	ne basin outfall prior to the increasilt fence wrap is no loopector will continue to monit washed away by natural procor to the 11/16/21 inspection	as installed prior to inspection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter 11/14/2019	on on 11/27/19. DE putfall is connected trivises began clean ed the baffle prior to inspection. Roth Erd the cleanout mark	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the during the 4/1/22 inspection.
SB 5 Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. 10/29/21, 10/10/10/20, 10/10/20	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit washed away by natural procor to the 11/16/21 inspection C28 DEJ Grading began excavat 9. DEJ installed a riser in the ecessary. Great Plains Contraned out the basin and instanced on 8/20/20 DEJ, Peter Ka 3/5/21. Roth Enterprises we Development was reminded.	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painted in 11/14/2019 tion of the basin prior to the inspection and the baffle prior to the inspection. SID repaired erosion and creat should be plugged.	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there is a pection on 10/25/round outfall north of the cleanout mark and the cleanout mark are pection on 10/25/round outfall north of the cleanout mark and the cleanout mark are pection on 10/25/round outfall north of the cleanout mark and the clea	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the during the 4/1/22 inspection. Yes The outlet pipe was installed before a silt fence wrap around all prior to the inspection on (21. An unidentified contractor of SB 5 prior to inspection on (25. Not done as of the last Services were reminded on (21. 9/10/21. DEJ was reminded)
Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. Inspection on 11/22/1 the outlet pipe is no longer no 8/07/20. Roth Enterprises clebegan installing the inlet pipe 5/11/23. The dewatering holes lower the DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 9/25/20, 10/30/20, 01/15/21, on 10/29/21, 2/23/22. Graves Enterprises was informed to a	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit washed away by natural procor to the 11/16/21 inspection C28 DEJ Grading began excavat 9. DEJ installed a riser in the prior to the 4/20/22 inspection and out the basin and instanced out the basin and instanced out the prior to the 4/20/22 inspection and Carlo	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painted in 11/14/2019 tion of the basin prior to the inspection and the baffle prior to the inspection. SID repaired erosion and creat should be plugged.	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there are pelow the outfar aspection on 10/25/round outfall north of the cleanout mark and the cleanout mark are pelow the outfar aspection on 10/25/round outfall north of the period outfall north of the period of the period outfall north outfall north of the period outfall north of the period outfall north	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the during the 4/1/22 inspection. Yes The outlet pipe was installed efore a silt fence wrap around all prior to the inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. Are unidentified contractor of SB 5 prior to inspection on 1/21. Are unidentified contractor of SB 5 prior to inspection on 1/21. Are unidentified contractor of SB 5 prior to inspection on 1/21. Are unidentified contractor of SB 5 prior to inspection on 1/21. Not done as of the last Services were reminded on 1/21, 9/10/21. DEJ was reminded 23 (CIR #18909). Roth
Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. 10/29/21, 10/10/10/20, 10/10/20	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit rashed away by natural procor to the 11/16/21 inspection C28 DEJ Grading began excavat 9. DEJ installed a riser in the ecessary. Great Plains Contraned out the basin and instanced on 8/20/20. DEJ, Peter Karaned out the triangle on 8/20/20. DEJ, Peter Karaned out the triangle on 8/20/20. DEJ, Peter Karaned on 8/20/20. D	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter it in 11/14/2019 tion of the basin prior to the inspection and the baffle prior to the inspection. SID repaired erosion and crest should be plugged. Stor Services were informed att, Gene Graves, and Greats reminded on 3/14/21, 5/1d on 12/6/21, 9/09/22, 12/00 and as of last inspection. Rother the control of the plugged.	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there is rap below the outfall north of the cleanout mark of the cleanout mark are pection on 10/25/19 on the cleanout mark of the cle	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the during the 4/1/22 inspection. Yes J. The outlet pipe was installed efore a silt fence wrap around all prior to the inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentifi
Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. Inspectio	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit rashed away by natural procor to the 11/16/21 inspection C28 DEJ Grading began excavat 9. DEJ installed a riser in the ecessary. Great Plains Contraned out the basin and instanced on 8/20/20. DEJ, Peter Karaned out the triangle on 8/20/20. DEJ, Peter Karaned out the triangle on 8/20/20. DEJ, Peter Karaned on 8/20/20. D	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter it in 11/14/2019 tion of the basin prior to the inspection and the baffle prior to the inspection. SID repaired erosion and crest should be plugged. Stor Services were informed att, Gene Graves, and Greats reminded on 3/14/21, 5/1d on 12/6/21, 9/09/22, 12/00 and as of last inspection. Rother the control of the plugged.	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there is rap below the outfall north of the cleanout mark of the cleanout mark are pection on 10/25/19 on the cleanout mark of the cle	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the during the 4/1/22 inspection. Yes J. The outlet pipe was installed efore a silt fence wrap around all prior to the inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentifi
SC 1 Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. Inspe	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit washed away by natural procor to the 11/16/21 inspection C28 DEJ Grading began excavat 9. DEJ installed a riser in the ecessary. Great Plains Contraned out the basin and instanced on 8/20/20. DEJ, Peter Ka 3/5/21. Roth Enterprises was Development was reminded complete by 7/27/23. Not do Lake Tahoe Drive lent removed the silt fence of Lake Tahoe Drive	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter in 11/14/2019 tion of the basin prior to the inspection of the basin prior to the inspection. SID repaired erosion and creat should be plugged. Stor Services were informed att, Gene Graves, and Great as reminded on 3/14/21, 5/14 on 12/6/21, 9/09/22, 12/00 one as of last inspection. Rother the grading in the area purposed to the grading in the area purposed to the grading in the area purposed in the grading	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there are pelow the outfall north of the cleanout mark and the cleanout mark are pelow the outfall north of the cleanout mark and the cleanout mark are pelow the outfall north of the cleanout mark and the	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the aduring the 4/1/22 inspection. Yes The outlet pipe was installed efore a silt fence wrap around all prior to the inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified on (21. An unidentifie
SC 1 Current Condition: SC 2	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. Inspection on 11/22/11 the outlet pipe is no longer not 8/07/20. Roth Enterprises clebegan installing the inlet pipe 5/11/23. The dewatering holes lower the DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 9/25/20, 10/30/20, 01/15/21, on 10/29/21, 2/23/22. Graves Enterprises was informed to contact the second second inspection. Silt Fence Removed - Graves developments.	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit washed away by natural procor to the 11/16/21 inspection C28 DEJ Grading began excavat 9. DEJ installed a riser in the ecessary. Great Plains Contraned out the basin and instanced on 8/20/20. DEJ, Peter Ka 3/5/21. Roth Enterprises was Development was reminded complete by 7/27/23. Not do Lake Tahoe Drive lent removed the silt fence of Lake Tahoe Drive	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter in 11/14/2019 tion of the basin prior to the inspection of the basin prior to the inspection. SID repaired erosion and creat should be plugged. Stor Services were informed att, Gene Graves, and Great as reminded on 3/14/21, 5/14 on 12/6/21, 9/09/22, 12/00 one as of last inspection. Rother the grading in the area purposed to the grading in the area purposed to the grading in the area purposed in the grading	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there are pelow the outfall north of the cleanout mark and the cleanout mark are pelow the outfall north of the cleanout mark and the cleanout mark are pelow the outfall north of the cleanout mark and the	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the aduring the 4/1/22 inspection. Yes The outlet pipe was installed efore a silt fence wrap around all prior to the inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified on (21. An unidentifie
SC 1 Current Condition: SC 2 Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection on 11/22/1 the outlet pipe is no longer no 8/07/20. Roth Enterprises clebegan installing the inlet pipe 5/11/23. The dewatering holes lower the DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 9/25/20, 10/30/20, 01/15/21, on 10/29/21, 2/23/22. Graves Enterprises was informed to control of the property of the property in the property of the property in the property of	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit washed away by natural procor to the 11/16/21 inspection or to	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter in 11/14/2019 tion of the basin prior to the inspection of the basin prior to the inspection. SID repaired erosion and creat should be plugged. Stor Services were informed att, Gene Graves, and Great as reminded on 3/14/21, 5/14 on 12/6/21, 9/09/22, 12/00 and as of last inspection. Rother the grading in the area prior to paving in the area prior to the inspection of the prior to the inspection. Rother the prior to the inspection are the prior to the inspection of	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there are pelow the outfar aspection on 10/25/round outfall north of the cleanout mark I to complete by 8/0 at Plains Contractor 14/21, 7/9/21, 8/10/2 8/22, 1/20/23, 4/14/20 at Enterprises was Removed Removed ior to the inspection Removed	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the aduring the 4/1/22 inspection. Yes The outlet pipe was installed afore a silt fence wrap around all prior to the inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. 9/10/21. DEJ was reminded (23 (CIR #18909). Roth reminded on 8/18/23, 10/3/23 and 6/29/23.
SC 1 Current Condition: SC 2 Current Condition: SC 3	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. Inspection on 11/22/11 the outlet pipe is no longer not 8/07/20. Roth Enterprises clebegan installing the inlet pipe 5/11/23. The dewatering holes lower the DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 9/25/20, 10/30/20, 01/15/21, on 10/29/21, 2/23/22. Graves Enterprises was informed to contain the second seco	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit washed away by natural procor to the 11/16/21 inspection or to	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter in 11/14/2019 tion of the basin prior to the inspection of the basin prior to the inspection. SID repaired erosion and creat should be plugged. Stor Services were informed att, Gene Graves, and Great as reminded on 3/14/21, 5/14 on 12/6/21, 9/09/22, 12/00 and as of last inspection. Rother the grading in the area prior to paving in the area prior to the inspection of the prior to the inspection. Rother the prior to the inspection are the prior to the inspection of	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there are pelow the outfar aspection on 10/25/round outfall north of the cleanout mark I to complete by 8/0 at Plains Contractor 14/21, 7/9/21, 8/10/2 8/22, 1/20/23, 4/14/20 at Enterprises was Removed Removed ior to the inspection Removed	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the aduring the 4/1/22 inspection. Yes The outlet pipe was installed afore a silt fence wrap around all prior to the inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. 9/10/21. DEJ was reminded (23 (CIR #18909). Roth reminded on 8/18/23, 10/3/23 and 6/29/23.
SC 1 Current Condition: SC 2 Current Condition: SC 3 Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. Fair Condition - 10% Filled - I prior to inspection on 11/22/1 the outlet pipe is no longer ne 8/07/20. Roth Enterprises clebegan installing the inlet pipe 5/11/23. The dewatering holes lower the DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 9/25/20, 10/30/20, 01/15/21, on 10/29/21, 2/23/22. Graves Enterprises was informed to continuous expection. Silt Fence Removed - Graves developm. Silt Fence Removed - Graves developm. Silt Fence Removed - Graves developm.	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit rashed away by natural processor to the 11/16/21 inspection. C28 DEJ Grading began excavat 9. DEJ installed a riser in the cessary. Great Plains Contraned out the basin and instanced out the basin and instanced out the basin and instanced out the sessary. Great Plains Contract of the 4/20/22 inspection of the 4/	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter it in 11/14/2019 the same prior to the inspection of the basin prior to the inspection are considered in the same prior to the inspection. SID repaired erosion are crest should be plugged. Stor Services were informed att, Gene Graves, and Great is reminded on 3/14/21, 5/14 on 12/6/21, 9/09/22, 12/00 in as of last inspection. Rother the prior in the area prior	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there are pelow the outfar aspection on 10/25/round outfall north of the cleanout mark I to complete by 8/0 at Plains Contractor 14/21, 7/9/21, 8/10/2 8/22, 1/20/23, 4/14/20 at Enterprises was Removed ior to the inspection Removed rior to the inspection Removed Removed Removed Removed	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the during the 4/1/22 inspection. Yes The outlet pipe was installed efore a silt fence wrap around all prior to the inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (21. An unidentified contractor of SB 5 prior to inspection on (22. An uni
SC 1 Current Condition: SC 2 Current Condition: SC 3 Current Condition: SC 4 Current Condition: SC 4 Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. Inspection on 11/22/1 the outlet pipe is no longer not 8/07/20. Roth Enterprises cle began installing the inlet pipe 5/11/23. The dewatering holes lower the DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 9/25/20, 10/30/20, 01/15/21, on 10/29/21, 2/23/22. Graves Enterprises was informed to contain the property of the property in the p	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit rashed away by natural procor to the 11/16/21 inspection or to	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter it in the prior to the season prior to the inspection of the basin prior to the inspection. SID repaired erosion and crest should be plugged. Stor Services were informed att, Gene Graves, and Greats reminded on 3/14/21, 5/14 do n 12/6/21, 9/09/22, 12/09 are as of last inspection. Rother the prior to painter the prior to the inspection of the basin prior to the inspection of the basin prior to the inspection. SID repaired erosion and crest should be plugged. Stor Services were informed att, Gene Graves, and Greats reminded on 3/14/21, 5/14 do n 12/6/21, 9/09/22, 12/09 are as of last inspection. Rother the prior to grading in the area prior to grad	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there are pelow the outfanspection on 10/25/round outfall north of the cleanout mark. It to complete by 8/0 at Plains Contractor 14/21, 7/9/21, 8/10/2 8/22, 1/20/23, 4/14/20 bth Enterprises was removed irror to the inspection Removed rior to the inspection Removed	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the aduring the 4/1/22 inspection. Yes J. The outlet pipe was installed efore a silt fence wrap around all prior to the inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 pr
SC 1 Current Condition: SC 2 Current Condition: SC 3 Current Condition: SC 4 Current Condition: SC 5 Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection on 11/22/1 the outlet pipe is no longer inspection. Inspection on 11/22/1 the outlet pipe is no longer inspection. E&A inspection. EAA ins	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit washed away by natural processor to the 11/16/21 inspection or	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter it in the prior to the season prior to the inspection of the basin prior to the inspection. SID repaired erosion and crest should be plugged. Stor Services were informed att, Gene Graves, and Greats reminded on 3/14/21, 5/14 do n 12/6/21, 9/09/22, 12/09 are as of last inspection. Rother the prior to painter the prior to the inspection of the basin prior to the inspection of the basin prior to the inspection. SID repaired erosion and crest should be plugged. Stor Services were informed att, Gene Graves, and Greats reminded on 3/14/21, 5/14 do n 12/6/21, 9/09/22, 12/09 are as of last inspection. Rother the prior to grading in the area prior to grad	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there are pelow the outfanspection on 10/25/round outfall north of the cleanout mark. It to complete by 8/0 at Plains Contractor 14/21, 7/9/21, 8/10/2 8/22, 1/20/23, 4/14/20 bth Enterprises was removed irror to the inspection Removed rior to the inspection Removed	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the aduring the 4/1/22 inspection. Yes J. The outlet pipe was installed efore a silt fence wrap around all prior to the inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 pr
SC 1 Current Condition: SC 2 Current Condition: SC 3 Current Condition: SC 4 Current Condition: SC 4 Current Condition:	the basin and rip rap below the inspection on 8/13/20, therefor 10/19/21 inspection. E&A inspection. Inspection on 11/22/1 the outlet pipe is no longer not allowed. In the outlet pipe is no longer not allowed. Expection inspection on 11/22/1 the outlet pipe is no longer not allowed. Expection inspection inspection. DEJ was reminde 9/25/20, 10/30/20, 01/15/21, on 10/29/21, 2/23/22. Graves Enterprises was informed to a silt Fence. Removed - Graves developm.	ne basin outfall prior to the incre a silt fence wrap is no loopector will continue to monit rashed away by natural processor to the 11/16/21 inspection or	as installed prior to inspection spection on 8/13/20. The conger necessary. Roth Enter or. Roth enterprises installe esses prior to the 10/28/21. The E&A inspector painter it is a spector painter of the basin prior to the inspection of the basin prior to the inspection. SID repaired erosion and crest should be plugged. Stor Services were informed att, Gene Graves, and Greats reminded on 3/14/21, 5/14 on 12/6/21, 9/09/22, 12/00 and as of last inspection. Rother as of last inspection. Rother as of last inspection. Rother as of last inspection and the area product to grading in the area product to paving in the area product t	on on 11/27/19. DE putfall is connected in prises began clean and the baffle prior to inspection. Roth Er d the cleanout mark Active pection on 11/14/19 on on 7/21/20, there are a below the outfanspection on 10/25/20 and outfall north of the cleanout mark I to complete by 8/0 at Plains Contractor and outfall north of the cleanout mark of the complete by 8/0 at Plains Contractor and a contract	J installed a permanent riser in to the riser pipe as of the ing out the basin prior to the the 10/25/21 inspection. Interprises completed the aduring the 4/1/22 inspection. Yes J. The outlet pipe was installed efore a silt fence wrap around all prior to the inspection on 1/21. An unidentified contractor of SB 5 prior to inspection on 1/21. An unidentified contractor of SB 5 pr

Current Condition:	Removed - Graves developm	ent removed the silt fence d	lue to grading in the area pr	ior to the inspection	n on 6/22/23.
SC 8	Silt Fence	S125th and Windsor drive	8/3/2023	Active	No
Current Condition:	Good Condition - Graves Dev line install prior to the inspect				
SC 9	Silt Fence	S124th ave and Horizon st	8/3/2023	Active	No
Current Condition:	Good Condition - Graves Dev line install prior to the inspect	•			· ·
SC 10	Silt Fence	S120th St and Lake Tahoe Dr.	10/19/2023	Pending	Yes
Current Condition:	Pending - Silt fence or wattles should be	· ·			
SC 11	Graves development was info	i '			Vac
SC 11 Current Condition:	Silt Fence Pending -	N of silt basin 5	11/2/2023	Pending	Yes
	Remaining section of silt fend	ormed to complete by 10/24/		ection.	
SF 1	Silt Fence	BB 20-BB14		Removed	
Current Condition:	corner of the site, including the inspection on 4/22/20. As of t	ne undermined portion by the he inspection on 7/29/20, ve e site that reinstallation of the	e outfall of the basin and the egetation has become suffic e removed silt fence is no lo	e multiple full spots, iently established o onger necessary. Th	ast of the slope in the southeast was removed prior to the in the slope located along the ne E&A inspector will continue
SF 2	Silt Fence	BB 14 - Gold Coast Rd		Removed	
Current Condition:	Removed - Graves Developn		orior to the inspection on 7/6		
SF 3	Silt Fence	Gold Coast Rd - BB 1	uion to the increation on E/A	Removed	
Current Condition: SF 4	Removed - Commercial Seed Silt Fence	BB 1 - 120th St	orior to the inspection on 5/4	Removed	
Current Condition:	Removed - Commercial Seed	·	L prior to the inspection on 10		
SF 5	Silt Fence	120th St - S 123rd Ave		Removed	
Current Condition:	Removed - Graves developn		prior to the inspection on 9/2	21/23.	
SF 6	Silt Fence	S 123rd Ave - S 125th St		Removed	
Current Condition:	Removed- (SF 1.1) Great Pla South 123rd Avenue; and east damaged by snow removal prinspection. E&A inspector re	st side of South 120th Street rior to inspection on 12/30/20	t prior to 11/10/2020. Silt fer 0. Great Plains Contractor S	nce going north/sou Services removed t	
SF 7	Silt Fence	S 125th St - A 5	11/7/2019	Active	Yes
Current Condition:	South 123rd Avenue; and east damaged by snow removal prinspection on 6/15/21. Comm 11/11/21 inspection. Great Pl removed part of the silt fence Silt fence should be repaired. Roth Enterprises was informably 10/5/23.	est side of South 120th Street rior to inspection on 12/30/20 percial seeding repaired and ains Contractor Services rep prior to the inspection on 10 and to complete by 8/24/23. N	t prior to 11/10/2020. Silt fer 0. GPCS removed a portion reinstalled the silt fence are paired the silt fence prior to 0/19/23.	nce going north/sou of the silt fence no bund S 125th street the 8/3/22 inspection	rth of SB 1 prior to the and north of SB 1 prior to the
SF 8	Silt Fence	B 24 - K 28		Removed	
Current Condition:	Removed - Graves Developn of silt basin 5 will be under Si			10/23. Remaining s	ection of silt fence 8 to the north
SF 9	Silt Fence	A 9 - A 12	11/7/2019	Active	No
Current Condition:	Services repaired/cleaned ou	the full portion, and backfille ctor Services cleaned out an ed in several areas (some sti the silt fence prior to the 4/ inspection. Commercial See	ed/trenched-in the portion so id repaired the silt fence wh ill need trenched-in) prior to /21/21 inspection. Great Pla eding cleaned out and repai	outh of the full porti ere full and trenche the inspection on s ins Contractor Serv	on prior to the inspection on
SF 10	Silt Fence	N of SB 4		Removed	
Current Condition:	Removed - Graves Developn			ior to the inspection	on 7/6/23.
SF 11	Silt Fence	Edgewater Dr and S 120th St		Removed	
Current Condition:	Removed - All recommendati	on will be under Silt Check,	SC 9 as of 10/12/23.		

STR	Streets	Site	11/8/2018	Active	Yes		
Current Condition:		·	•		spection. THI Builders cleaned		
	the streets prior to the 7/14/2						
					velopment scraped the streets		
					on on 9/7/23. SID was informed		
	and will clean when work is c 9/21/23.	ompleted in the area. Roth E	interprises cleaned the stre	et near silt basin A	prior to the inspection on		
	1.) Streets throughout project should be cleaned.						
	2.) Sidewalks and streets sho	ould be cleaned along S 120t	h st.				
	9/29/23, 10/19/23, 10/30/23 (CIR #20390)			Development was reminded on Development was reminded on		
SWPPP Sign	Misc./Other	Schram Road (W27) and S 120th Street (P1)	11/19/2018	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign at S 124th Street and Schram Road during inspection on 11/19/18. E&A inspector installed the SWPPP sign at S 120th Street at the north end of the site during the inspection on 6/9/21. The SWPPP sign on S 120th was blown over prior to the 3/23/22 inspection. The E&A inspector reinstalled the SWPPP sign on S 120th Street during the 4/1/22 inspection.						
Certification Statement	I certify, under penalty of law, with a system designed to as inquiry of the person or perso information submitted is, to the penalties for submitting false	sure that qualified personnel ons who manage the system ne best of my knowledge and	properly gathered and eva or those persons directly re belief, true, accurate, and	luated the informat esponsible for gathe complete. I am awa	ering the information, the are that there are significant		
Inspector Signature:	En Carlo			Reviewed By:	Posts Sol		