	E&A-	P2008.207.000		
Inspector: Phillip Dechant			Stage	
Project Name:			3	
For Week Ending:				
Grading:	100%	6		
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities: Overall Development:	100%			
Overali Development:	60%	0		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		
Sunday:	0.06"			Week 1
Monday	0.01"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			ļ
Saturday	0.28"			Wools 2
Sunday:	0.00"			Week 2
Monday	0.00"		1	
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.05"			Wook 2
Sunday:	1.39"			Week 3
Monday	0.02"	4/27/2009		
Tuesday	0.00"	1,21,2000		
Wednesday	0.02"			
Thursday	0.00"			
Friday	0.03"			
Saturday	0.00"			
Complexe	0.00"			Week 4/5
Sunday: Monday	0.00" 0.02"			
Tuesday	0.00"			
Wednesday	0.01"			
Thursday	0.04"	5/7/2009		
Friday	0.00"			
Saturday	0.00"			
Complaints:	None			
			1	
Construction Sequencing: Which portion(s) (i.e. drainage basins) of th days?	e site have had a temporary or	permanent cessation of gra	ading, earthwork, or groun	d disturbance in the last 14
Entire Site; grading completed and sit	e seeded prior to 4/2008.			
Which portion(s) (i.e. drainage basins) of th	e site do not have grading, eart	hwork, or ground disturba	nce scheduled in the next	14 days? :
Entire Site; grading completed and sit	e seeded prior to 4/2008.			
What temporary or permanent stabilization	measures listed in this section	are being implemented?		<u> </u>
Existing Vegetation (4/2008), Harriso Seeding and Matting on the hill south	n St. ROW between 201st	and 197th St seed and		
Comments:				
Comments: Home construction is the only activity by Nevurth prior to inspection on 4-27	-09.	all good condition. The	box culvert at 196th an	d Harrison was completed
Findings / Corrective Actions (Date	):			

## Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) Some minor erosion was noted by a curb inlet near lot 407, and needs to be repaired. Commercial Seeding was requested to perform repairs by 4-15-09. Maintenance completed prior to inspection on 4-27-09.
- 3) Some erosion was noted behind a curb inlet on 201st and Emiline, and needs to be repaired. Commecial Seeding was requested to perform repairs by 4-15-09. Maintenance completed prior to inspection on 4-27-09.
- 4) Lot 198-19732 Chandler St.- Good life Homes was called and was left a message for lot level silt fence installation, or stockpile removal by 5-14-09.
- 5) Lot 283- 7421 S. 198th Cir.- City Website was not updated with the owner's name, So Chad with Synergy was e-mailed and asked to inform Inspector of the owner of the lot for stockpile removal, or silt fence installation. Heavican Homes was requested to install silt fen e or remove stockpile by 5-14-09.
  6) Lot 142- 19654 Chandler St- Jeff Shaw Builders- Bally Castle Homes was called and was left a voicemail for stockpile removal, or silt
- 6) Lot 142- 19654 Chandler St- Jeff Shaw Builders- Bally Castle Homes was called and was left a voicemail for stockpile removal, or sil fence installation on lot by 5-14-09

			Projected Install						
Unique Name	Туре	Location	Date	Status	Maintance				
		N41d00m00s							
SB 1	Sediment Basin	W96d00m00s		Removed					
Current Condition:	Removed								
		N41d00m00s							
SB 2	Sediment Basin	W96d00m00s		Removed					
Current Condition:	Removed		1						
00.0	On discount Desire	N41d00m00s	In Diago	A -45	N-				
SB 3 Current Condition:	Sediment Basin	W96d00m00s	In Place	Active	No				
Current Condition.		Good Condition- 19% Filled Outlet pipe was repaired and Rip rap added prior to inspection on 8-19-08 by Commercial Seeding.							
	Odilet pipe was repaire								
00.4	0 " (D )	N41d00m00s		A					
SB 4 Current Condition:	Sediment Basin	W96d00m00s	In Place	Active	No				
Current Condition:	Good Condition- 24% F	Good Condition- 24% Filled							
00.5	On discount Desire	N41d00m00s		Damanad					
SB 5 Current Condition:	Sediment Basin Removed	W96d00m00s		Removed					
Current Condition:	Removed								
SB 6	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No				
Current Condition:			In Place	Active	INO				
Current Condition.	Good Condition- 17 % F	Good Condition- 17% Filled							
		N41d00m00s							
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No				
Current Condition:	Good Condition- 18% F	Good Condition- 18% Filled							
		N41d00m00s							
SB 8	Sediment Basin	W96d00m00s		Removed					
Current Condition:	Removed				•				
	Basin needs to be close	Basin needs to be closed							
	OID: O II								
	O'Brien Grading was ad	O'Brien Grading was actively closing basin during inspection on 5-7-09.							
		N41d00m00s							
SB 9	Sediment Basin	W96d00m00s		Removed					
Current Condition:	Removed								
		N41d00m00s							
SF 1	Silt Fence	W96d00m00s		Removed					
Current Condition:	Removed due to dense	Removed due to dense vegetation							
c=-		N41d00m00s		A					
STR	Streets	W96d00m00s	In Place	Active	No				
Current Condition:	Good Condition- No ma	Good Condition- No major signs of track off.							
SWPPP Sign	Signs	5 signs	8-19-08	Active	Yes				
Current Condition:	Fair Condition: RD sign	Fair Condition: RD signs installed							
	E&A Consulting signs r	E&A Consulting signs need to be installed at the entrances.							
	Now signs were and	New signs were ordered, and will be installed as each so they grive							
	ivew signs were ordere	New signs were ordered, and will be installed as soon as they arive.							
( ) DOL			7	schary L. Jilek					
nspector Signature:	1		Reviewed By:	a yun					