E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

Erosion Control Specialist- Manag	ger			LINGINELKING • FLANNIN	- CONTROL OF THE CONT	
		E&A- P2008	8.207.000		Stage	
Inspector: Patrick Pierce	r: Patrick Pierce					
Project Name:		Bell Brook				
For Week Ending:			5/8/2010			
Project Location:	Southwes	68135				
		Southwest corner of 192nd and Harrison Street- Omaha, NE (Douglas County)				
Grading:	100					
Sanitary Sewer:	100					
Storm Sewer:	100					
Paving:	100					
Seeding:	100					
Utilities:	100				_	
Overall Development:	00	0%				
DAIN FALL AMOUNTS		L			1	
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			Wook	
Sunday:	0.00"				Week 1	
Monday	0.00"				+	
Tuesday	0.00"				+	
Wednesday	0.02"				+	
Thursday	0.13"				+	
Friday	0.00"				†	
Saturday	0.00"				1	
,					Week 2	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.01"					
Wednesday	0.32"					
Thursday	0.00"					
Friday	2.71"	04/23/10				
Saturday	Trace					
	0.00"	0.4/0.7/4.0			Week 3	
Sunday:	0.00"	04/25/10				
Monday	0.24"				_	
Tuesday	0.00"					
Wednesday	0.00"					
Thursday Friday	0.24" 0.04"					
Saturday	0.04				+	
Oatul day	0.00				Week 4/5	
Sunday:	0.00"				Week 4/6	
Monday	0.00"					
Tuesday	0.00"				†	
Wednesday	0.00"				†	
Thursday	0.18"					
Friday	0.18"					
Saturday	0.00"					
	None					
Complaints:						
		ı			_	
Construction Sequencing:	the cite have bed a territory		on of grading and	ork or ground disturbance in the last 44	doug	
Which portion(s) (i.e. drainage basins) of	the site have had a tempor	ary or permanent cessati	on or grading, earthw	ork, or ground disturbance in the last 14	uays?	
Entire Site; grading completed and s	site seeded prior to 4/20	U8.				
Which portion(s) (i.e. drainage basins) of	the site do not have gradin	a parthwork or ground	disturbance schoduler	in the next 14 days?		
Timon portion(a) (i.e. dramage basins) or	and one do not have grauli	y, caraiwork, or ground	alotarbance scriedule	ani and heat 14 days! .		
Entire Site; grading completed and s	site seeded prior to 4/20	08.				

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (4/2008), Harrison St. ROW between 201st and 197th St seed and matting by Sarpy County (8/19/08)
Seeding and Matting on the hill south of the ROW between 197th and 199th St. (9/08), seeding and matting on outlot 'O' (3/09), removed basin 8 seeded (05/09)

Comments:

Comments:

Home construction is active in many areas of the development.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) Todd Menard Construction is developing lots 127 and 129 and have some pieces of silt fence that are down. Inspector called this builder while on site and requested that this be fixed by 8/22/09. This was not complete as of inspection on 8/21/09, but due to consecutive rain days the new completion date will be 8/28/09. This was not complete prior to inspection on 8/27/09, but contractor still has one day to complete. Todd Menard Construction was called on 03/30/10 and reminded of this overdue maintnenace, they stated that this lot is going to be sodded in the near future and the silt fence will be removed in the next few days. If this lot is not sodded within 14 day Todd Menard is to repair or re-install this silt fence. Silt fence has been removed prior to inspection on 04/07/10, but the lot has not been sodded yet. These lots were sodded prior to inspection on 04/23/10.

Unique Name	Туре	Location	Projected Install Date	Status	Maintan		
Lot 32	Silt Fence	Lot 32	5/1/2010	Pending	Yes		
Current Condition:	No BMP installed on this lot- active home construction						
	Crown Limited was	called on 03/30/10 a	d Homes and there is no lot and requested to get some ty 04/25/10, inspector called C	/pe of lot level BMP insta			
Lot 67	Silt Fence	Lot 67	E/1/2010	Donding	Voc		
Current Condition:	Fair Condition	Lot 67	5/1/2010	Pending	Yes		
	inspection on 9/28/0 cleaned up complet Tom contacted BHI	09. As of inspection ely. Inspector called who said they would	silt has been cleaned up and on 10/30/09 the sod has not Tom Wells with Lamp Ryne d get the silt cleaned up and his was not complete as of I	been repaired and the si arson to get an update o most likely mat or mulch	ilt has not beer on this mainten of the area until		
	inspection on 9/28/6 cleaned up complet Tom contacted BHI spring when the soc active and this area	09. As of inspection ely. Inspector called who said they would can be replaced. To could be damaged	on 10/30/09 the sod has not Tom Wells with Lamp Ryne d get the silt cleaned up and	been repaired and the signs arson to get an update of most likely mat or mulch ast inspection due to the is to be cleaned up and s	ilt has not beer on this mainten of the area until fact that gradi ostabilized ASAI		
Lot 96	inspection on 9/28/0 cleaned up complet Tom contacted BHI spring when the soc active and this area was not complete p	09. As of inspection ely. Inspector called who said they would can be replaced. To could be damaged rior to inspection on	on 10/30/09 the sod has not Tom Wells with Lamp Ryned get the silt cleaned up and his was not complete as of I again by silt. This is to area 04/25/10. Vince Vincent with	been repaired and the si- earson to get an update of most likely mat or mulch- ast inspection due to the is to be cleaned up and s n Lamp Rynearson & Ass	ilt has not beer on this mainten of the area until fact that gradin stabilized ASAI sociates was c		
Lot 96 Current Condition:	inspection on 9/28/6 cleaned up complet Tom contacted BHI spring when the soc active and this area	09. As of inspection ely. Inspector called who said they would can be replaced. To could be damaged	on 10/30/09 the sod has not Tom Wells with Lamp Ryne d get the silt cleaned up and his was not complete as of I again by silt. This is to area	been repaired and the signs arson to get an update of most likely mat or mulch ast inspection due to the is to be cleaned up and s	ilt has not beer on this mainten of the area until fact that gradii stabilized ASAI		
	inspection on 9/28/0 cleaned up complet Tom contacted BHI spring when the soc active and this area was not complete p Silt Fence Poor Condition The silt fence install properly.	09. As of inspection ely. Inspector called who said they would dean be replaced. To could be damaged rior to inspection on Lot 96	on 10/30/09 the sod has not Tom Wells with Lamp Ryned get the silt cleaned up and his was not complete as of I again by silt. This is to area 04/25/10. Vince Vincent with 4/25/2010	been repaired and the siverson to get an update of most likely mat or mulch east inspection due to the is to be cleaned up and sin Lamp Rynearson & Assin Lamp Rynearson & Active	ilt has not beer on this mainten of the area until fact that gradii stabilized ASAI sociates was c Yes the was not tren		
	inspection on 9/28/0 cleaned up complet Tom contacted BHI spring when the soc active and this area was not complete p Silt Fence Poor Condition The silt fence install properly.	09. As of inspection ely. Inspector called who said they would dean be replaced. To could be damaged rior to inspection on Lot 96	on 10/30/09 the sod has not Tom Wells with Lamp Ryned get the silt cleaned up and his was not complete as of lagain by silt. This is to area 04/25/10. Vince Vincent with	been repaired and the siverson to get an update of most likely mat or mulch east inspection due to the is to be cleaned up and sin Lamp Rynearson & Assin Lamp Rynearson & Active	ilt has not beer on this mainten of the area until fact that gradii stabilized ASAI sociates was c Yes the was not tren		
Current Condition:	inspection on 9/28/0 cleaned up complet Tom contacted BHI spring when the soc active and this area was not complete p Silt Fence Poor Condition The silt fence instal properly. Chris with Barr Hom	one. As of inspection ely. Inspector called who said they would can be replaced. To could be damaged rior to inspection on the Lot 96.	on 10/30/09 the sod has not Tom Wells with Lamp Ryned get the silt cleaned up and his was not complete as of I again by silt. This is to area 04/25/10. Vince Vincent with 4/25/2010	been repaired and the siterson to get an update of most likely mat or mulch ast inspection due to the is to be cleaned up and son Lamp Rynearson & Associated Active	ilt has not beer on this mainten in the area until fact that gradii stabilized ASAI sociates was commended in the commended in by 0 menched in		
	inspection on 9/28/0 cleaned up complet Tom contacted BHI spring when the soc active and this area was not complete p Silt Fence Poor Condition The silt fence install properly.	09. As of inspection ely. Inspector called who said they would dean be replaced. To could be damaged rior to inspection on Lot 96	on 10/30/09 the sod has not Tom Wells with Lamp Ryned get the silt cleaned up and his was not complete as of I again by silt. This is to area 04/25/10. Vince Vincent with 4/25/2010	been repaired and the siverson to get an update of most likely mat or mulch east inspection due to the is to be cleaned up and sin Lamp Rynearson & Assin Lamp Rynearson & Active	ilt has not beer on this mainten of the area until fact that gradin stabilized ASAI sociates was c Yes the was not tren		
Current Condition: Lot 168	inspection on 9/28/0 cleaned up complet Tom contacted BHI spring when the soc active and this area was not complete p Silt Fence Poor Condition The silt fence install properly. Chris with Barr Hom Silt Fence Not Installed	29. As of inspection ely. Inspector called who said they would can be replaced. To could be damaged rior to inspection on Lot 96. Lot 96. Lot 168.	on 10/30/09 the sod has not Tom Wells with Lamp Ryned get the silt cleaned up and his was not complete as of I again by silt. This is to area 04/25/10. Vince Vincent with 4/25/2010	been repaired and the siterson to get an update of most likely mat or mulch ast inspection due to the is to be cleaned up and sin Lamp Rynearson & Ast Active Active 1.4/25/10, but the silt fence requested to have this tree	ilt has not beer on this mainten in the area until fact that gradii stabilized ASAI sociates was contained in the area until fact that gradii stabilized ASAI sociates was contained in the conta		

L at 242	Cill Force	Lot 242	2/2/2040	Donding	Vac	
Lot 242 Current Condition:	Silt Fence No BMP installed	Lot 242 on this lot- active home	3/3/2010 construction	Pending	Yes	
Current Condition: Lot 255 Current Condition:	Lot 242 is being b Chris with Pro-Lin Line and Barr Hor	nes was called on 04/07	es and there is no lot le 03/30/10 and requeste 7/10 and reminded to go	evel silt fence installed. ed to have this installed by 0- et this maintenance taken ca aris on 04/25/10 and reminden Active	are of ASAP. This was	
	 Lot 255 is being built on by Pro-Line Homes and there is no lot level silt fence installed. Lot 255 has a stockpile in the ROW that needs to be removed or have some type of protection installed around it to prevent runoff. The silt fence installed on this lot needs to be extended to the West in order to protect the next lot to the North. Chris with Pro-Line was called on 03/30/10 and requested to get some type of lot level BMP installed by 04/06/10. Chris with Pro-Line and Barr Homes was called on 04/07/10 and reminded to get this maintenance taken care of ASAP. This was complete prior to inspection on 04/25/10, but the silt fence needs to be extended further to the West to protect the adjacent lot see finding 3 in this BMP for new maintenance. Chris with Pro-Line Homes was called on 03/30/10 and requested to have this taken care of by 04/06/10. This was not complete prior to inspection on 04/07/10, Chris with Pro-Line and Barr Homes was called on 04/07/10 and reminded to get this maintenance taken care of ASAP. This was removed prior to inspection on 04/25/10. Chris with Pro-Line Homes was called during inspection on 4/25/10 and requested to have this silt fence extended. 					
Lot 349 Current Condition:	Silt Fence Silt Fence- good o	Lot 349	5/1/2010	Active	Yes	
	Lot 349 has a stockpile in the ROW on the West side of the lot. R&A Builders was called on 03/30/10 and requested to remove this stockpile or add some silt fence to protect any runoff coming from it by 04/06/10. This was not complete prior to inspection on 04/25/10, R&A was called during inspection on 04/25/10 and reminded to get this removed or protected ASAP.					
Lot 446	Silt Fence	Lot 446	5/1/2010	Active	Yes	
Current Condition:	Fair Condition	1 201 440	3/1/2010	7101170	1 63	
SD 4	Frontier Construction is building on lot 446 and has some silt fence that is down and damaged as of inspection on 04/24/10. Frontier was called during inspection on 04/25/10 and requested to have this repaired by 05/01/10. N41d00m00s N41d00m00s					
SB 4 Current Condition:	Sediment Basin Good Condition- 2	W96d00m00s 24% Filled	In Place	Active	No	
	-Devegetation was completed by Commercial Seeding prior to inspection on 8/16/09.					
SB 5 Current Condition:	Sediment Basin Removed	N41d00m00s W96d00m00s		Removed		
SB 6	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition- 17% Filled -Devegetation was completed by Commercial Seeding prior to inspection on 8/16/09.					
SB 7	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition- 18% Filled -Devegetation was completed by Commercial Seeding prior to inspection on 8/16/09.					
SB 8	Sediment Basin	N41d00m00s W96d00m00s		Removed		
Current Condition:	Basin removed by O'Brien grading prior to inspection on 5-13-09. Silt fence has been installed on the toe of the slope, and the area seeded.					

		N41d00m00s				
SB 9	Sediment Basin	W96d00m00s		Removed		
Current Condition:	Removed					
		N41d00m00s				
SF 1	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed due to dense vegetation					
		N41d00m00s				
STR	Streets	W96d00m00s	In Place	Active	Yes	
Current Condition:	Fair Condition					
	-Track off was cleaned up by Pro-Line Homes and Sudbeck Builders prior to inspection on 04/25/10					
	Due to recent rains there is some new runoff coming from lot 59 during inspection on 04/25/10.					
	Sudbeck Builders was called and left a message on 04/25/10 requesting to get this cleaned up by 04/26/10.					
			-		· ·	
	•				No	
SWPPP Sign		5 signs	8-19-08	Active		
Current Condition:	Good condition					
	-195th and Harriso	• • •				
	-197th and Harrison					
	-198th and Harrison					
	-201st and Harrison					
	-192nd and Bellebrook Blvd.					
	<u> </u>					
				Toda / 11/c		
5	-e-e			Zachany k. Jiluk		
Inspector Signature:			Reviewed By:			