E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager E&A CONSULTING GROUP, INC. ENGINEERING • PLANNING • FIELD SERVICES

		E&A- P2008.2	201.000		01.0.0	
nspector: Mike Jacobson, CISEC					Stage 3	
Project Name:		Bell Brook				
For Week Ending:			12/10/2011			
Project Location:	Southwest	Southwest corner of 192nd and Harrison Street- Omaha, NE (Sarpy County)				
	oouintest	68135				
Brading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Jtilities:	100%					
Overall Development:	60%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected				
					Wee	
unday:	0.00"					
Nonday	0.00"					
uesday	0.00"					
Vednesday	0.00"					
hursday	0.00"					
Friday	0.00"					
Saturday	Trace					
	0.00				We	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Vednesday	0.00"					
Thursday	0.00"					
Friday	Trace					
Saturday	0.00"				Wee	
Sunday:	0.00"				Wet	
Monday	0.00"	11/28/11				
Tuesday	0.00"					
Vednesday	0.00"					
Thursday	Trace					
Friday	Trace					
Saturday	1.04"					
•					We	
Sunday:	0.00"					
Monday	Trace					
luesday	0.00"	12/06/11				
Vednesday	0.00"					
Thursday	0.16"					
Friday	0.01"					
Saturday	Trace					
					Wee	
Sunday:	N/A	N/A				
Monday	N/A	N/A				
Гuesday	N/A	N/A				
Vednesday	N/A	N/A				
Thursday	N/A	N/A				
Friday	N/A	N/A				
Saturday	N/A	N/A				
	None					
Complaints:						
			-			
Construction Sequencing:	to have had a f		median contract	ad distanting a first of the state of the		
Which portion(s) (i.e. drainage basins) of the sit	te have had a temporary or	permanent cessation of	grading, earthwork, or grou	nd disturbance in the last 14 days?		
intire Site; grading completed and site s	seeded prior to 4/2008.					
		1		1		

Which portion(s) (i.e. drainage basins) of the site	e do not have grading, ear	thwork, or ground disturba	nce scheduled in the next	14 days? :			
Entire Site; grading completed and site se	eeded prior to 4/2008.						
What temporary or permanent stabilization measurement	sures listed in this section	are being implemented?					
Existing Vegetation (4/2008), Harrison S Seeding and Matting on the hill south of the (05/09), Silt Basin 3 seeded and matted (he ROW between 197	7th and 199th St. (9/08)	, seeding and matting o	on outlot 'O' (3/09), removed	basin 8 seeded		
_							
Comments:							
Comments: Home construction is active in many area An inspection was not conducted on Sund			ection will be conducted	d as conditions allow. This ir	spection took place on		
12/6/11. Findings / Corrective Actions (Date):							
Findings / Corrective Actions (Date): 1) Some maintenance is required in the B	MP section						
			Projected Install				
Unique Name	Туре	Location	Date	Status	Maintenance		
CW 1	Concrete Washout	Lot 393	11/4/2010	Active	No		
Current Condition:	Good Condition						
	Washout was clea	aned out prior to inspec	tion on 6/18/11 by Cha	d with Synergy.			
Lot 42	Silt Fence	Lot 42	7/6/2011	Active	Yes		
Current Condition:	Fair Condition- Vacant lot.						
	Proline Homes wa		e maintenance by 7/13/	11. On 8/23/11, 10/3/11, and appleted ASAP. Maintenance			
Lot 87 Current Condition:	Silt Fence	Lot 87	7/6/2011	Active	No		
ourrent oblightion.	Good Condition- Active home construction on lot. A berm was installed on the back of the lot prior to inspection on 7/6/11 by Proline Homes.						
Let 02	Cilt Fanas	Lat 02	E/14/2011	Activo	No		
Lot 93 Current Condition:	Silt Fence Lot 93 5/14/2011 Active No Good Condition- Vacant Lot (There is a few rows of silt fence on this lot.) Image: Condition of the second						
	Maintenance was completed prior to inspection on 10/3/11 by Chris w/ Proline Homes.						
Lot 111	Misc/Other	Lot 111	11/3/2011	Active	Yes		
Current Condition:	Fair Condition Active Home construction on the lot.						
	On 11/28/11 KRT construction was informed to complete overdue maintenance ASAP.						
Lot 208	Silt Fence	Lot 208	8/5/2011	Active	No		
Current Condition:		Active Home construction	on on the lot.	•			
	Dirt was removed	prior to inspection on 8	/7/11 by Proline Home	S			
Lot 233	Misc/Other	Lot 235	8/14/2011	Active	No		
Current Condition:		Active Home constructi was removed prior to i		v Proline Homos			
	Dirt in the K.U.W.	was removed prior to r					
Lot 236	Misc/Other	Lot 236	8/5/2011	Active	Yes		

	Pending Active Home construction on the lot.						
	Dirt in the R.O.W. was removed prior to inspection on 8/30/11 by Proline Homes.						
	Silt fence needs to be installed on the Northeast corner of the lot. Proline Homes was informed to complete maintenance by 8/14/11. Maintenance not completed as of last inspection due to wet and muddy conditions, therefore another seven days is given to complete maintenance until 8/19/11. Maintenance not completed due to wet and muddy conditions therefore another seven days is given to complete maintenance until 8/26/11. Maintenance not completed due to wet and muddy conditions therefore another seven days is given to complete maintenance until 8/29/11. On 10/3/11 Proline Homes was reminded tha maintenance needs to be completed overdue maintenance ASAP. Maintenance not completed as of last inspection.						
					1		
Lot 245	Silt Fence	Lot 245	8/8/2011	Active	No		
Current Condition:	Good Condition- Vacant lot.						
	Maintenance was completed prior to inspection on 8/30/11 by Proline Homes.						
Lot 304	Misc/Other	Lot 304	8/5/2011	Active	Yes		
Current Condition:		ior to inspection on 11					
	Due to active hom	e construction on this I	ot the Outlot needs to b	e re-seeded.			
	On 11/28/11 HBC	was informed to comp	lete maintenance by 12	/5/11.			
Lot 339	Silt Fence	Lot 339	11/21/2011	Active	No		
Current Condition:		Active Home constructi ed along the back of th	on on the lot. e lot prior to inspection	on 11/28/11			
Lot 346	Silt Fence	Lot 346	5/20/2011	Active	No		
Current Condition:	Good Condition- V Silt fence installed		prior to inspection on 5/	/220/2011 by Bob Roth.			
Lot 347 Current Condition:	Silt Fence	Lot 347	5/20/2011	Active	No		
ourrent oonanion.	Good Condition- Vacant Lot. Silt fence installed on the back of the lot prior to inspection on 5/220/2011 by Bob Roth.						
Lot 356	Silt Fence	Lot 356		Removed			
Lot 356 Current Condition:		ior to inspection on 11.	/3/11 by Butch Michael				
Current Condition: SB 3	Lot was sodded pr	ior to inspection on 11. N41d00m00s W96d00m00s		Homes. Removed			
Current Condition:	Lot was sodded pr	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar		Homes.	Excavation.		
Current Condition: SB 3	Lot was sodded pr	ior to inspection on 11. N41d00m00s W96d00m00s		Homes. Removed	Excavation.		
Current Condition: SB 3 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled	d matted prior to inspec	Homes. Removed ction on 4/17/11 by Beaver f Active	No		
Current Condition: SB 3 Current Condition: SB 4	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi	d matted prior to inspec	Homes. Removed ction on 4/17/11 by Beaver F	No		
Current Condition: SB 3 Current Condition: SB 4	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled	d matted prior to inspec	Homes. Removed ction on 4/17/11 by Beaver f Active	No		
Current Condition: SB 3 Current Condition: SB 4 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s	d matted prior to inspec	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o	No		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v Sediment Basin	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s	d matted prior to inspec	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o	No		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition- 1	ior to inspection on 11. N41d00m00s W96d00m00s moved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s W96d00m00s W96d00m00s 7% Filled	d matted prior to inspect In Place n area by Commercial S In Place	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active	No on 8/16/09.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition- 1	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s W96d00m00s 7% Filled vas removed from basi	d matted prior to inspect In Place n area by Commercial S In Place	Homes. <u>Removed</u> ction on 4/17/11 by Beaver I <u>Active</u> Seeding prior to inspection o <u>Removed</u>	No on 8/16/09.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition- 1 Trees/vegetation v	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s W96d00m00s	d matted prior to inspect In Place n area by Commercial S In Place	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active	No on 8/16/09.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v Sediment Basin Good Condition- 1 Trees/vegetation v Sediment Basin Good Condition- 2	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s % Filled V41d00m00s % Filled	d matted prior to inspect In Place n area by Commercial S In Place	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active Seeding prior to inspection o Active	No on 8/16/09. No on 8/16/09.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition- 1 Trees/vegetation v Sediment Basin Good Condition- 2 Basin was cleaned	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s % Filled vas removed from basi N41d00m00s % Filled vas removed from basi N41d00m00s % Filled vas removed from basi N41d00m00s % Filled to ut prior to inspectior s buried and extended	In Place In area by Commercial 3 In Place In Place In Place In Place In On 6/18/11 by Bob Rot	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active Seeding prior to inspection o Active	No on 8/16/09. No on 8/16/09.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition- 1 Trees/vegetation v Sediment Basin Good Condition- 2 Basin was cleaned	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s W96d00m00s % Filled d out prior to inspectior	In Place In area by Commercial 3 In Place In Place In Place In Place In On 6/18/11 by Bob Rot	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active Seeding prior to inspection o Active th.	No on 8/16/09. No on 8/16/09.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition-2 Trees/vegetation v Sediment Basin Good Condition-1 Trees/vegetation v Sediment Basin Good Condition-2 Basin was cleaned The outlet pipe wa Sediment Basin Basin removed by	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s W96d00m00s % Filled to prior to inspectior s buried and extended N41d00m00s W96d00m00s % Filled to uprior to inspectior s buried and extended N41d00m00s W96d00m00s O'Brien grading prior to	In Place In Of Marce In Place In Pla	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active Seeding prior to inspection o Active th. to inspection on 10/3/11 by	No on 8/16/09. No no No no No Tim Geis.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition- 1 Trees/vegetation v Sediment Basin Good Condition- 2 Basin was cleaned The outlet pipe wa	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s W96d00m00s % Filled to prior to inspectior s buried and extended N41d00m00s W96d00m00s % Filled to uprior to inspectior s buried and extended N41d00m00s W96d00m00s O'Brien grading prior to	In Place In Of Marce In Place In Pla	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active Seeding prior to inspection o Active th. to inspection on 10/3/11 by Removed	No on 8/16/09. No no No no No Tim Geis.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 7 Current Condition: SB 8 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition- 2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition- 1 Trees/vegetation v Sediment Basin Good Condition- 2 Basin was cleaned The outlet pipe wa Sediment Basin Basin removed by slope, and the are Sediment Basin	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s W96d00m00s % Filled vas removed from basi N41d00m00s W96d00m00s % Filled out prior to inspectior is buried and extended N41d00m00s W96d00m00s 0'Brien grading prior to a seeded.	In Place In Of Marce In Place In Pla	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active Seeding prior to inspection o Active th. to inspection on 10/3/11 by Removed	No on 8/16/09. No no No no No Tim Geis.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: SB 8 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition-2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition-1 Trees/vegetation v Sediment Basin Good Condition-2 Basin was cleaned The outlet pipe wa Sediment Basin Basin removed by slope, and the are Sediment Basin Removed	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s W96d00m00s % Filled to ut prior to inspectior s buried and extended N41d00m00s W96d00m00s O'Brien grading prior to a seeded. N41d00m00s W96d00m00s W96d00m00s	In Place In Of Marce In Place In Pla	Homes. Removed tion on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active Seeding prior to inspection o Active th. to inspection on 10/3/11 by Removed Seeding Prior has been install Removed	No on 8/16/09. No no No no No Tim Geis.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 7 Current Condition: SB 8 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition-2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition-1 Trees/vegetation v Sediment Basin Good Condition-2 Basin was cleaned The outlet pipe wa Sediment Basin Basin removed by slope, and the area Sediment Basin Removed Silt Fence	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s W96d00m00s % Filled to uprior to inspection s buried and extended N41d00m00s W96d00m00s O'Brien grading prior to a seeded. N41d00m00s W96d00m00s W96d00m00s W96d00m00s N41d00m00s W96d00m00s N41d00m00s W96d00m00s N41d00m00s W96d00m00s	In Place In Of Marce In Place In Pla	Homes. Removed ction on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active Seeding prior to inspection o Active th. to inspection on 10/3/11 by Removed Seeding has been install	No on 8/16/09. No no No no No Tim Geis.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 7 Current Condition: SB 8 Current Condition: SB 8 Current Condition: SB 9 Current Condition: SB 9 Current Condition:	Lot was sodded pr Sediment Basin Basin has been re Sediment Basin Good Condition-2 Trees/vegetation v Sediment Basin Removed Sediment Basin Good Condition-1 Trees/vegetation v Sediment Basin Good Condition-2 Basin was cleaned The outlet pipe wa Sediment Basin Basin removed by slope, and the are Sediment Basin Removed	ior to inspection on 11. N41d00m00s W96d00m00s emoved and seeded ar N41d00m00s W96d00m00s 4% Filled vas removed from basi N41d00m00s W96d00m00s 7% Filled vas removed from basi N41d00m00s W96d00m00s % Filled to uprior to inspection s buried and extended N41d00m00s W96d00m00s O'Brien grading prior to a seeded. N41d00m00s W96d00m00s W96d00m00s W96d00m00s N41d00m00s W96d00m00s N41d00m00s W96d00m00s N41d00m00s W96d00m00s	In Place In Of Marce In Place In Pla	Homes. Removed tion on 4/17/11 by Beaver I Active Seeding prior to inspection o Removed Active Seeding prior to inspection o Active th. to inspection on 10/3/11 by Removed Seeding Prior has been install Removed	No on 8/16/09. No no No no No Tim Geis.		

Current Condition:	Good Condition- No major signs of track off.						
SWPPP Sign	SWPPP Sign	5 signs	8-19-08	Active	No		
Current Condition:	Good condition -195th and Harrison -197th and Harrison -198th and Harrison -201st and Harrison -192nd and Bellbrool	Good condition -195th and Harrison -197th and Harrison -198th and Harrison					
Inspector's Signature:	1 Jawlan		F	Reviewed By:	Zachany K. Julik		