	E&A- 2002.1	53.000		
Inspector: Phillip Dechant	LUV2.1			Stage
Project Name:	Cir	marron Woods		3
For Week Ending:		12/13/2008		
Tor Wook Ending.		,		
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving: Seeding:	100%			
Utilities:	100%			
Overall Development:	62%			
RAIN FALL AMOUNTS	Amount in inches			
	Amount in inches	Date inspected		Week 1
Sunday:	0.00"			
Monday	0.39"			
Tuesday	0.89"	11/10/00		
Wednesday Thursday	0.00" 0.10"	11/12/08 11/13/08		
Friday	0.04"	11/13/06		
Saturday	0.00"			
				Week 2
Sunday:	0.00"			
Monday	0.00"			
Tuesday Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 3
Sunday:	0.00"			
Monday	0.00"			
Tuesday Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.09"			
				Week 4 / 5
Sunday:	<b>0.02</b> "; 0.00"			
Monday	0.00"; 0.00"	10/0/00		
Tuesday	0.00"; 0.00"	none; 12/9/08		
Wednesday Thursday	0.00"; 0.00" 0.00"; 0.00"			
Friday	0.00"; 0.00"			
Saturday	0.00"; 0.00"			
				•
Complaints:	_			
Construction Sequencing:				
Nhich portion(s) (i.e. drainage basins) of the si lays?	te have had a temporary or permane	nt cessation of grading, ea	rthwork, or ground distur	bance in the last 14
Entire site, grading completed and stabil	lized prior to Spring 2005.			
			[	1
Which portion(s) (i.e. drainage basins) of the si	ite do not have grading, earthwork, c	or ground disturbance sche	duled in the next 14 days	?:
Entire site, grading completed and stabil	lized prior to Spring 2005.			
				1
Vhat temporary or permanent stabilization mea	asures listed in this section are being	g implemented?	1	1
Dense Vegetation, (Some re-seeding in a			andscaping. (Some re-	seeding in Sept.
2007)		0.1 0.		0 1
Comments: Comments:				
Lomments'	the site			
	แกะ อแษ.			
Home construction is active through out				
Home construction is active through out Findings / Corrective Actions (Date):				
Home construction is active through out	MP section. Int lot, South of silt basin 3, and	BHI was requested to	clean up by 9-25-08. E	3HI was reminded
Home construction is active through out Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1) Some required maintenance in the BM 2) Concrete was washed out into a vaca	MP section. Int lot, South of silt basin 3, and	BHI was requested to (	clean up by 9-25-08. E	BHI was reminded
Home construction is active through out Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1) Some required maintenance in the BM 2) Concrete was washed out into a vacai	MP section. Int lot, South of silt basin 3, and	BHI was requested to	Clean up by 9-25-08. E	BHI was reminded

CE 1	Construction Entrance	N41d00m00s W96d00m00s		Removed		Repairs Needed/P		
Current Condition:	Entrance Paved.	1						
IF 1	Inlat Eiters	N41d00m00s W96d00m00s		Demoved				
Current Condition:	Inlet Filters Removed, due to problems		n and continual slope	Removed erosion.				
		N41d00m00s						
IF 2	Inlet Filters	W96d00m00s		Removed				
Current Condition:	Removed, due to problems	N41d00m00s	n and continual slope	erosion.				
SB 1	Sediment Basin	W96d00m00s		Removed	No			
Current Condition:	Sediment Basin has been	approved to be closed. A	s of inspection on 5/9	0/08 berm has been	removed and			
	basin is in the process of b			1				
SB 2	Sediment Basin	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed due to lot develo			Heineved				
		N41d00m00s						
SB 3 Current Condition:	Sediment Basin Basin is closed as of 12-9	W96d00m00s		Removed				
Current Condition.	Dasiinis closed as of 12-9							
SB 4	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	Yes			
Current Condition:	Good Condition - 30% Fille	d						
	Cleaned on 5/05 by BHI	Cleaned on 5/05 by BHIMaintenance- Outlet Pipe on 5/30/07.						
	Concrete collar connecting	Concrete collar connecting riser to outlet pipe is broken and needs to be repaired. As of inspection on 10-						
	23-08, the broken collar is	23-08, the broken collar is creating an erosion problem around the outlet pipe and riser, and soil is falling						
	into the hole	into the hole						
	BHI was directed to compl	BHI was directed to complete maintenance by 5/16/08, and reminded on 9/19/08. BHI reminded again on						
		10/27/2008. This has not been completed as of last inspection.						
		N41d00m00s						
SF 1	Silt Fence	W96d00m00s	In Place	Active	No			
Current Condition:	Good Condition - Partially Maintanced 7/05 by BHI	removed.						
		N41d00m00s						
SF 2	Silt Fence	W96d00m00s		Removed				
Current Condition:	Removed; due to lot devel	1						
SF 3	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed; due to lot devel			Removed				
	,	N41d00m00s						
SF 4	Silt Fence	W96d00m00s		Removed				
Current Condition:	Removed; due to lot devel							
SF 5	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed; due to lot devel			Removed				
		N41d00m00s						
SF 6	Silt Fence	W96d00m00s	In Place	Active	No			
Current Condition:	Fair Condition - Silt fence i							
	Maintenance completed prior to inspection 8-8-08 and with the removal of the silt fence in the areas were the lots were sodded.							
		N41d00m00s						
SF 7	Silt Fence	W96d00m00s	In Place	Removed	No			
Current Condition:	Removed; due to lot devel	opment						
	Removed; due to lot devel							
Current Condition: ST 1	Sediment Trap	N41d00m00s W96d00m00s		Removed				
Current Condition:		N41d00m00s W96d00m00s pment.		Removed				
Current Condition: ST 1 Current Condition:	Sediment Trap Removed due to lot develo	N41d00m00s W96d00m00s pment. N41d00m00s						
Current Condition: ST 1	Sediment Trap	N41d00m00s W96d00m00s pment. N41d00m00s W96d00m00s		Removed				
Current Condition: ST 1 Current Condition: ST 2 Current Condition:	Sediment Trap Removed due to lot develo Sediment Trap Removed due to lot develo	N41d00m00s W96d00m00s pment. N41d00m00s W96d00m00s pment. N41d00m00s		Removed				
Current Condition: ST 1 Current Condition: ST 2 Current Condition: STR	Sediment Trap Removed due to lot develo Sediment Trap Removed due to lot develo Streets	N41d00m00s W96d00m00s pment. N41d00m00s W96d00m00s pment.	In Place		Yes			
Current Condition: ST 1 Current Condition: ST 2 Current Condition:	Sediment Trap Removed due to lot develo Sediment Trap Removed due to lot develo	N41d00m00s W96d00m00s pment. N41d00m00s W96d00m00s pment. N41d00m00s	In Place	Removed	Yes			
Current Condition: ST 1 Current Condition: ST 2 Current Condition: STR	Sediment Trap Removed due to lot develo Sediment Trap Removed due to lot develo Streets	N41d00m00s W96d00m00s pment. N41d00m00s W96d00m00s pment. N41d00m00s W96d00m00s		Removed	Yes			
Current Condition: ST 1 Current Condition: ST 2 Current Condition: STR	Sediment Trap           Removed due to lot develop           Sediment Trap           Removed due to lot develop           Streets           Good Condition           There were signs of track of	N41d00m00s W96d00m00s pment. N41d00m00s pment. N41d00m00s pment. N41d00m00s W96d00m00s		Removed	Yes			
Current Condition: ST 1 Current Condition: ST 2 Current Condition: STR	Sediment Trap Removed due to lot develo Sediment Trap Removed due to lot develo Streets Good Condition	N41d00m00s W96d00m00s pment. N41d00m00s pment. N41d00m00s pment. N41d00m00s W96d00m00s		Removed	Yes			
Current Condition: ST 1 Current Condition: ST 2 Current Condition: STR Current Condition:	Sediment Trap Removed due to lot develo Sediment Trap Removed due to lot develo Streets Good Condition There were signs of track of Streets cleaned by Jerry T	N41d00m00s W96d00m00s pment. N41d00m00s pment. N41d00m00s pment. N41d00m00s W96d00m00s	nt.	Removed Active				
Current Condition: ST 1 Current Condition: ST 2 Current Condition: STR	Sediment Trap           Removed due to lot develop           Sediment Trap           Removed due to lot develop           Streets           Good Condition           There were signs of track of	N41d00m00s W96d00m00s pment. N41d00m00s pment. N41d00m00s pment. N41d00m00s W96d00m00s		Removed	Yes			
Current Condition: ST 1 Current Condition: ST 2 Current Condition: STR Current Condition:	Sediment Trap           Removed due to lot developed           Sediment Trap           Removed due to lot developed           Streets           Good Condition           There were signs of track of Streets cleaned by Jerry T           Streets signs	N41d00m00s W96d00m00s pment. N41d00m00s W96d00m00s pment. N41d00m00s W96d00m00s Off / run off after rain eve prozon on 11-12-08 2 signs	nt.	Removed Active				