	E&A- 2	002.153.000		Store		
Inspector: Mike Jacobson		marron Woods		Stage 3		
Project Name:	CII			5		
For Week Ending:	4/12/2008					
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding: Utilities:	100%					
Overall Development:	100% 61%					
overall bevelopment.	0170					
RAIN FALL AMOUNTS	Amount in inches	Date inspected				
				Week 1		
Sunday:	0.00"					
Monday	0.00"					
Tuesday Wednesday	0.00"					
Wednesday Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"	İ				
				Week 2		
Sunday:	0.01"					
Monday	0.07"					
Tuesday	0.00"					
Wednesday	0.01"					
Thursday Friday	0.00"					
Saturday	0.00"					
Saturday	0.00			Week 3		
Sunday:	0.00"			HOOR O		
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.02"	03/27/08				
Friday	0.00"					
Saturday	0.00"			Week 4 / 5		
Sunday:	0.00"; 0.01 "			Week 475		
Monday	1.28"; 0.01"	3/31/2008; None				
Tuesday	0.00"; 0.00"					
Wednesday	0.00"; 0.01 "	4/2/2008; None				
Thursday	0.52"; 1.00"					
Friday	0.00"; 0.07"	4/4/2008; 4/11/08				
Saturday	0.00"; 0.00"	4/5/2008; 4/12/08				
Complaints:	None					
Construction Sequencing:	1		1			
Which portion(s) (i.e. drainage bas	ins) of the site have had a tempora	ary or permanent cessation	of grading, earthwork. or o	round disturbance in		
the last 14 days?			g			
Entire site, grading completed	and stabilized prior to Sprir	iy 2005.	1			
Which portion(s) (i.e. drainage bas	ins) of the site do not have grading	g, earthwork, or ground dis	turbance scheduled in the	next 14 days? :		
en al la la la						
Entire site, grading completed	d and stabilized prior to Sprir	ng 2005.	-			
What there are	Martin and the second					
What temporary or permanent stab Dense Vegetation, (Some re- seeding in Sept. 2007) Comments:				ing. (Some re-		
Comments:						
Home construction is active t St.,102nd & Harrison St., and			a SWPPP sign at 104tl	n & Harrison		
Findings / Corrective Action						
Findings / Corrective Action 1) Varies lot corners are dow directed to complete mainten needs to be completed by 4/ ⁷ 2) Some required maintenance	n, damaged or full and needs ance by 4/3/08. Due to rains 10/08. Maintenance not com	BHI will be allowed an	other seven days and			

			ſ		Т	Description of	
			Projected Install			Description of Maintenance/Activity:	
Unique Name	Туре	Location	Date	Status	Maintenance		
CE 1	Construction Entrance	N41d00m00s W96d00m00s		Removed		Repairs Needed/Planned:	
Current Condition:	Entrance Paved.						
		N41d00m00s					
IF 1 Current Condition:	Inlet Filters Removed, due to problems	W96d00m00s with flooded intersecti	on and continual class	Removed		{	
Current Condition:	Removed, due to problems	N41d00m00s	on and continual slope			1	
IF 2	Inlet Filters	W96d00m00s		Removed]	
Current Condition:	Removed, due to problems		on and continual slope	erosion.			
SB 1	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- 40% Filled		Intrace				
	Sediment Basin to be close						
	to drainage area meeting st since basins meets require			erm is a little low in	one spot but		
		N41d00m00s	il be left as for flow.		1	-	
SB 2	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Removed due to lot develop		·]	
	Codiment Desire	N41d00m00s		Demonst			
SB 3 Current Condition:	Sediment Basin During inspection on 3/27/0	W96d00m00s 8 basin is in the proce	ss of being closed by F	Removed BHI. As of insepction	on on 4/2/08		
Surrent Sonation.	riser was removed and bas				5 011 1, Z/00		
		N41d00m00s				1	
SB 4	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 10% Filler Cleaned on 5/05 by BHIN		ine on 5/30/07				
		N41d00m00s				1	
SF 1	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - Partially r	emoved.					
	Maintanced 7/05 by BHI	N41d00m00s				4	
SF 2	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed; due to lot develo	pment]	
05.0	014 5	N41d00m00s		Demail			
SF 3 Current Condition:	Silt Fence Removed; due to lot develo	W96d00m00s		Removed	1	1	
our on onution.		N41d00m00s					
SF 4	Silt Fence	W96d00m00s	In Place	Active	Yes		
Current Condition:	Fair Condition - Portions of	silt fence have been re	emoved for trail constru	uction.			
	A few areas are down/dama	aged. These areas car	be removed as area h	nas good vegetatio	on and is not		
	needed any longer.						
	BHI was directed to comple	te maintenance by 4/3	/08. Due to rains BHI	will be allowed an	other seven		
	days and maintenance nee						
	inspection.	N141 d00 00					
SF 5	Silt Fence	N41d00m00s W96d00m00s	In Place	Active	Yes		
Current Condition:	Fair Condition - Portions of					1	
	A fow groop are down (down	and Those erece er	be removed as area		on and is not		
	A few areas are down/dama needed any longer.	aged. These areas car	The removed as area f	las good vegetatio	on and is not		
	, č						
	BHI was directed to comple						
	days and maintenance nee inspection.	us to be completed by		not completed as	011851		
		N41d00m00s					
SF 6	Silt Fence	W96d00m00s	In Place	Active	Yes		
Current Condition:	Fair Condition - Portions of	sil lence have been re	emoved for trail constru				
	One area is full and down/d				eds to be		
	reinstalled up and around the riser and reconnected to the existing silt fence.						
	BHI was directed to complete maintenance by 4/9/08. Due to rains BHI will be allowed another seven days and maintenance needs to be completed by 4/16/08. Maintenance not completed as of last						
	inspection.	N141 d00 00					
SF 7	Silt Fence		In Place	Active	Yes		
SF 7	Silt Fence	N41d00m00s W96d00m00s	In Place	Active	Yes]	

Current Condition:	Fair Condition - Portions of silt fence have been removed for trail construction.							
	A few areas are down/damaged. This section that is damaged can be be removed as the area has good vegetation and is not needed any longer.							
	BHI was directed to complete maintenance by 4/3/08. Due to rains BHI will be allowed another seven days and maintenance needs to be completed by 4/10/08. Maintenance not completed as of last							
ST 1	Sediment Trap	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed due to lot development.							
ST 2	Sediment Trap	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed due to lot development.							
STR	Streets	N41d00m00s W96d00m00s	In Place	Active	Yes			
Current Condition:	Good Condition							
	Some streets have some minor trackoff and needs to be cleaned up. BHI cleaned streets on 3/28/08.							
Inspector Signature:	Archael Jawlorn		Reviewed By:	Zadnary K. Jil	de			