

E&A Consulting Group, Inc.
 330 North 117th Street
 Omaha, NE 68154-2509
 tel 402.895.4700
 fax 402.895.3599
 www.eacg.com



E&A CONSULTING GROUP, INC.
 ENGINEERING • PLANNING • FIELD SERVICES

Zachary A. Jilek, CPESC, CISEC
 Erosion Control Specialist- Manager

E&A- P2005.198.000

Inspector: Mike Jacobson, CISEC		Stage 2
Project Name:	Clearwater Falls NER110573	
For Week Ending:	11/24/2012	
Project Location:	48th and Fairview Road- Bellevue, NE (Sarpy County)	68123

Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	85%			
Paving:	80%			
Seeding:	70%			
Utilities:	75%			
Overall Development:	45%			

RAIN FALL AMOUNTS	Amount in tenths	Date inspected		
				Week 1
Sunday:	0.01"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 2
Sunday:	0.00"			
Monday	0.00"	11/19/12		
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 3
Sunday:	N/A	N/A		
Monday	N/A	N/A		
Tuesday	N/A	N/A		
Wednesday	N/A	N/A		
Thursday	N/A	N/A		
Friday	N/A	N/A		
Saturday	N/A	N/A		

Complaints:	None
-------------	------

Construction Sequencing:
 Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?
 Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :
 Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009)

What temporary or permanent stabilization measures listed in this section are being implemented?
 Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011)

Comments:
 Comments:
 Celebrity Homes is actively building in the South part of the development. Home Construction is active in the Northeast part of the development by a few builders.


Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP Section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	N41d00m00s W96d00m00s	5/5/2010	Active	Yes
Current Condition:	Poor Condition- 60% Effectiveness - Installed by Anchor Construction prior to inspection on 5/5/10 Construction entrance is in poor condition and due to the streets being installed it is no longer needed and it needs to be removed. Boyer Young was given a plan requesting to have the entrance removed by 8/5/11. On 9/21/11 and again on 11/21/11 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.				
CW 3	Concrete Washout	Lot 348	11/21/2011	Active	No
Current Condition:	Good Condition Concrete washout was cleaned out prior to inspection on 7/9/12 by Tim Moore/Celebrity Homes.				
Lot 17	Misc/other	Lot 17		Removed	
Current Condition:	There concrete debris was cleaned up prior to inspection on 9/28/12 by the Home owner's association.				
Outlot D	Misc/other	Outlot D	9/20/2012	Pending	Yes
Current Condition:	Pending Due to a section of the trail being replaced in the outlot there is an area around the area inlet that needs to be stabilized. Home owner association was informed to complete maintenance by 9/20/12. On 10/15/12 E&A Consulting Group Inc. SID manager Bob Czerwinski emailed the HOA and reminded them that seeding needs to be completed ASAP. On 10/31/12 the HOA sent an email to SID manager Bob Czerwinski informing him that they was going to inform the builder HBC to re-seed the area. Seeding was not completed as of last inspection.				
Pod A	Silt Fence	Lots 225-254		Removed	
Current Condition:	Lot 244 was sodded prior to inspection on 9/4/12 by Dave Hausman/Celebrity Homes. Silt fence on Lot 243 was removed due to the lot being fine graded prior to inspection on 9/4/12 by Dave Hausman/Celebrity Homes. Full Dumpster was removed from lot 242 prior to inspection on 9/4/12 by Dave Hausman/Celebrity Homes.				
Pod B	Silt Fence	Lots 212-224		Removed	
Current Condition:	All lots in this Pod have been sodded as of inspection on 6/25/11.				
Pod C	Silt Fence	Lots 175-183; 474-480		Removed	
Current Condition:	Silt fence on lots 474-480 have been removed due to the lots being sodded prior to inspection on 10/14/12 by Dave Hausman/Celebrity Homes. All other remaining lots in this pod has been sodded.				
Pod D	Silt Fence	Lots 199-210		Removed	
Current Condition:	All remaining lots in this pod have been sodded prior to inspection on 9/28/12 by Dave Hausman/Celebrity Homes.				
Pod E	Silt Fence	Lots 184-198	12/6/2011	Active	Yes
Current Condition:	Fair Condition 1) Silt fence at the toe of the slope on 188 is down/damaged and it needs to be replaced. 2) Silt fence that is at the top of the slope on the back of lot 194 is full and it needs to be cleaned out. Silt fence needs to be added at the back of the lots 194, 195, 196 and 197. 3) There are full dumpsters on lots 195 and 196 and they need to be emptied or covered. 1) Dave Hausman/Celebrity Homes was informed to complete maintenance by 5/14/12. On 5/5/12, 5/8/12, 5/22/12, 6/6/12, 6/13/12, 6/18/12, 6/23/12, 7/9/12, 7/24/12, 8/6/12, 8/23/12, 9/29/12, 10/15/12, 10/26/12 and again on 11/19/12 Dave Hausman/Celebrity Homes was reminded that maintenance needs to be completed ASAP. 2) Dave Hausman/Celebrity Homes was informed to complete maintenance by 7/31/12. On 8/23/12, 9/29/12, 10/15/12, 10/26/12 and again on 11/19/12 Dave Hausman/Celebrity Homes was reminded that maintenance needs to be completed ASAP. 3) Dave Hausman/Celebrity Homes was informed to complete maintenance by 11/26/12.				
Pod F	Silt Fence	Lots 426-454	11/8/2012	Active	Yes

Current Condition:	<p>Good Condition</p> <p>Silt fence checks were installed on the front of lots 447 and 448 prior to inspection on 11/8/12 by Dave Hausman/Celebrity Homes.</p> <p>1) Silt fence checks need to be installed on the front of lots 444, 445 and 446 to help prevent run off. 2) There are full dumpsters on lots 463 and 464 and they need to be emptied or covered.</p> <p>1) Dave Hausman/Celebrity Homes was informed to complete maintenance by 10/5/12. On 10/15/12, 10/26/12 and again on 11/19/12 Dave Hausman/Celebrity Homes was reminded that maintenance needs to be completed ASAP. 2) Dave Hausman/Celebrity Homes was informed to complete maintenance by 11/26/12.</p>				
Pod G	Silt Fence	Lots 404-425	11/8/2012	Active	No
Current Condition:	<p>Good Condition</p> <p>A silt fence check was installed on the South side of the dirt stockpile prior to inspection on 11/8/12 by Dave Hausman/Celebrity Homes.</p>				
SB 1	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	<p>Good Condition-11% Filled</p> <p>Basin cleaned out was completed prior to inspection on 6/10/11 by Bob Roth.</p>				
SB 2	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>Basin was removed and the outlet B area was seeded prior to inspection on 7/12/11 by Jochim.</p>				
SB 3	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	<p>Good Condition-17% Filled</p>				
SB 4	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>Removed per Hill-Farrell construction.</p>				
SB 5	Sediment Basin	N41d00m00s W96d00m00s	11/17/2009	Active	No
Current Condition:	<p>Good Condition- 5% Filled</p> <p>- JC Excavating installed prior to inspection on 11/18/09.</p>				
SF 1	Silt Fence	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this area.</p>				
SF 2	Silt Fence	N41d00m00s W96d00m00s		Removed	No
Current Condition:	<p>Removed for grading on 8/4/08</p>				
SF 3	Silt Fence	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>Removed due to home construction.</p>				
SF 4	Silt Fence	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>Removed due to home construction.</p>				
SF 5	Silt Fence	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>Removed due to home construction.</p>				
SF 6	Silt Fence	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>Removed due to road construction</p>				
SF 7	Silt Fence	N41d00m00s W96d00m00s	In Place	Active	Yes
Current Condition:	<p>Fair Condition</p> <p>A few areas of silt fence are down/damaged and need to be repaired or removed.</p> <p>Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11 and again on 11/21/11 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.</p>				
SF 8	Silt Fence	N41d00m00s W96d00m00s	In Place	Active	Yes
Current Condition:	<p>Fair Condition</p> <p>A few areas of silt fence are down/damaged and need to be repaired or removed.</p> <p>Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11 and again on 11/21/11 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.</p>				
SF 9	Silt Fence	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is located, therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.</p>				

SF 10	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this area.					
SF 11	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this area.					
SF 12	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Removed due to landscaping.					
SF A	Silt Fence	Lots 474-480		Removed		
Current Condition:	All this maintenance has been moved to Pod C in the BMP section.					
SF B	Silt Fence	N41d00m00s W96d00m00s	10/30/2009	Active	Yes	
Current Condition:	<p>Fair Condition</p> <p>There are a few areas of this silt fence that are full and need to be cleaned out. One area of silt fence is down/damaged and it needs to be repaired or removed.</p> <p>Boyer Young was sent a plan requesting to clean this out by 8/31/10. On 9/23/10, 2/23/11, 9/21/11 and again 11/21/11 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.</p>					
STR	Street Cleaning	N41d00m00s W96d00m00s	5/1/2007	Active	No	
Current Condition:	Good Condition- Tim Moore cleaned the streets prior to inspection on 11/8/12.					
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition: 48th and Birchwood Drive					
Inspector Signature: 					Reviewed By: 