E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager		ENGINEERI	NG • PLANNING • ENVIRONMENTAI	L & FIELD SERVICES
	E&A- F	2005.198.000		_
Inspector: Mike Jacobson, CISEC		Stage		
		Clearwater	r Falls	2
Project Name:		NER110	573	
For Week Ending:		5/25/20	13	
Project Location:	48th an		vue, NE (Sarpy County)	68123
1 Toject Location.	70tii aii	u i ali view itoau- belle	vue, NE (Oarpy County)	00123
Grading:	1	00%		
Sanitary Sewer:	1	00%		
Storm Sewer:		85%		
Paving:		80%		
Seeding: Utilities:		70% 75%		
Overall Development:		45%		
Overall Development.		4370	L	
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		
MAINT ALL AMOUNTS	, and an terrain	Date inspected		Week '
Sunday:	0.00"			Week
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			Week
Sunday:	0.59"			Week A
Monday	0.00"			
Tuesday	0.00"	05/21/13		
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.34"			Week
Sunday:	N/A	N/A		WCCK .
Monday	N/A	N/A		
Tuesday	N/A	N/A		
Wednesday	N/A	N/A		
Thursday	N/A	N/A		
Friday	N/A	N/A		
Saturday	N/A	N/A		
	None			
Complaints:	1 2 2 2			
•				
Construction Sequencing:				
Which portion(s) (i.e. drainage basins) of the site I	have had a temporary or permaner	nt cessation of grading, earth	work, or ground disturbance in the last	14 days?
Grading completed and entire site seeded	prior to 2005.			
Entire Site; JC Excavating completed gradi	ing Lots 346 through 480 Sect	tion II, drainage area 1 ar	nd 2 (11/2009).	
Which portion(s) (i.e. drainage basins) of the site of	do not have grading, earthwork, or	ground disturbance schedul	ed in the next 14 days? :	•
Grading completed and entire site seeded	prior to 2005.			
Form O'to 10 Form in the control of	1 - 1 - 1 - 0 40 th	Para III dan Para		
Entire Site; JC Excavating completed gradi	ing Lots 346 through 480 Sect	tion II, drainage area 1 ar	na 2 (11/2009)	
		T.		

## What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011)

### Comments

## Comments:

Celebrity Homes is actively building in the South part of the development. Home Construction is active in the North part of the development by various builders.

## Findings / Corrective Actions (Date):

# Findings / Corrective Actions (Date):

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	N41d00m00s W96d00m00s	5/5/2010	Active	Yes		
Current Condition:	Poor Condition- 60% Effectiveness  Construction entrance is in poor condition and due to the streets being installed it is no longer needed and it needs to be removed.  Boyer Young was given a plan requesting to have the entrance removed by 8/5/11. On 9/21/11, 11/21/11 and again on 3/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.						
CW 3	Concrete Washout	Lot 348	11/21/2011	Active	Yes		
	·	Fair Condition  Concrete spoils are in the R.O.W. of the concrete washout and it needs to be cleaned up.  Dave Hausman/Celebrity Homes was informed to complete maintenance by 5/28/13.					
Lot 26	Silt Fence	Lot 26	5/3/2013	Active	Yes		
	Silt fence needs to be install Horizon Homes was informe Homes was reminded that s	ed to install silt fence by	4/8/13. On 5/3/13 a	and again on 5/2	1/13 Horizon		
Lot 27	Silt Fence	Lot 27	4/1/2013	Active	Yes		
Current Condition:	Fair Condition  A few areas of the silt fence in front of the silt fence run is undermined and it needs to be backfilled at compacted.  Horizon Homes was informed to complete maintenance by 5/28/13.						
Lot 30	Silt Fence	Lot 30	5/3/2013	Active	Yes		
Current Condition:	Fair Condition  A few areas of the silt fence have dirt piled on it and it needs to be cleaned out.  Horizon Homes was informed to complete maintenance by 5/28/13.						

Current Condition:	Good Condition					
	<ol> <li>Silt fence needs to be installed on the front of the lot above the curb inlet.</li> <li>Additional silt fence needs to be installed on the North end of the silt fence run due to silt going around the silt fence.</li> </ol>					
	1) Gabe w/ The Home Company was informed to install silt fence by 4/18/13. On 4/24/13, 5/3/13 and again on 5/21/13 Thomas w/ The Home Company was reminded that silt fence needs to be installed ASAP.					
	2) Thomas w/ The Home Co	ompany was informed to o	complete mainter	nance by 5/28/13.		
Lot 268	Misc/other	Lot 268	4/8/2013	Pending	Yes	
Current Condition:	Pending					
	Dirt is piled in the R.O.W. and it needs to be removed or add silt fence around it.  Sherwood Homes was informed to complete maintenance by 4/8/13. On 5/21/13 Sherwood Homes was reminded that maintenance needs to be completed ASAP.					
		The same to be seemple to a re-				
Lot 277	Silt Fence	Lot 277	5/3/2013	Active	No	
Current Condition:	Good Condition Silt fence was installed on the back of the lot prior to inspection on 5/3/13 by Gabe w/ The Home Company.					
Lot 287	Misc/other	Lot 287		Removed		
Current Condition:	The portable toilet was removed the company.  Maintenance was completed	oved from the lot prior to it	•	0/13 by Gabe w/ 1		
Lot 305	Silt Fence	Lot 305	4/8/2013	Pending	Yes	
Current Condition:	Pending			, comming		
	<ol> <li>Silt fence needs to be installed on the Southeast section of the lot.</li> <li>There is a full dumpster on the lot and it needs to be emptied or covered.</li> <li>Legacy Homes was informed to install silt fence by 4/8/13. On 4/24/13, 5/3/13 and again on 5/21/13 Legacy Home was reminded that silt fence needs to be installed ASAP.</li> <li>Legacy Homes was informed to complete maintenance by 5/28/13.</li> </ol>					
Lot 311	Silt Fence	Lot 311	4/8/2013	Pending	Yes	
Current Condition:	Pending Dirt was removed from the R.O.W. prior to inspection on 5/3/13 by Havican Homes.  Silt fence needs to be installed on the back of the lot.  Havican Homes was informed to install silt fence by 4/8/13. On 4/24/13 Havican Homes was reminded that silt fence needs to be installed ASAP. Silt fence has not been installed as of last inspection.					
Lot 312	Silt Fence	Lot 312	4/8/2013	Pending	Yes	
Current Condition:	Pending Silt fence was installed on the back of the lot prior to inspection on 5/10/13 by Banyan Homes.					
	<ol> <li>Dirt piled in the R.O.W. and it needs to be removed or add silt fence around it. As of inspection on 5/10/13 silt fence was installed on the front of the lot but in was not trenched in and it needs to be trenched in. As of inspection on 5/21/13 the dirt piled behind the silt fence run has been removed, therefore the damaged silt fence can be removed.</li> <li>There is dirt piled in the R.O.W. at the South end of the lot and it needs to be removed or add silt fence around it.</li> <li>Banyan Homes was informed to complete maintenance by 5/10/13. On 5/10/13 and again on 5/21, Banyan Homes was informed to complete maintenance ASAP.</li> <li>Banyan Homes was informed to complete maintenance by 5/28/13.</li> </ol>					
Lot 313	Silt Fence	Lot 313	4/10/2013	Active	No	

Current Condition:	Good Condition Silt fence was installed on the back of the lot prior to inspection on 4/10/13 by Showcase Homes.					
Lot 333	Silt Fence	Lot 333	5/1/2013	Active	No	
Current Condition:	Good Condition	the beat of the let unique.		0/42 h., D.,		
	Silt fence was installed on t	the back of the lot prior to	Inspection on 5/1	0/13 by Regency	Homes.	
Lot 339	Silt Fence	Lot 339	3/6/2013	Pending	Yes	
Current Condition:	Pending					
	Silt fence needs to be installed on the back of the lot.					
	Gabe w/ The Home Compa and again on 5/21/13 Gabe ASAP.					
Lot 341	Silt Fence	Lot 341	4/1/2013	Active	Yes	
Current Condition:	Good Condition	- to increation 5/04/40 have	Caatlah sidaa 11a.			
	Dumpster was emptied prior	or to inspection 5/21/13 by	Castlebridge Hor	nes.		
	As of inspection on 5/21/13	the dumpster is full again	and it needs to b	e emptied or cove	ered.	
	Castlebridge Homes was in	formed to complete maint	enance by 5/28/1	3.		
Outlot D	Misc/other	Outlot D	9/20/2012	Pending	Yes	
Current Condition:	Pending	Outlot D	9/20/2012	rending	162	
	Due to a section of the trail being replaced in the outlot there is an area around the area inlet that needs to be stabilized.  Home owner association was informed to complete maintenance by 9/20/12. On 10/15/12 E&A Consulting Group Inc. SID manager Bob Czerwinski emailed the HOA and reminded them that seeding needs to be completed ASAP. On 10/31/12 the HOA sent an email to SID manager Bob Czerwinski informing him that they was going to inform the builder HBC to re-seed the area. Seeding was not completed as of last inspection. On 4/1/13 the HBC was reminded that the disturbed area needs to be seeded ASAP. Seeding was not completed as of last inspection.					
Pod A	Silt Fonco	Lots 225-254		Pomovod		
Current Condition:	Silt Fence Lots 225-254 Removed  Lot 244 was sodded prior to inspection on 9/4/12 by Dave Hausman/Celebrity Homes. Silt fence on Lot 243 was removed due to the lot being fine graded prior to inspection on 9/4/12 by Dave Hausman/Celebrity Homes. Full Dumpster was removed from lot 242 prior to inspection on 9/4/12 by Dave Hausman/Celebrity Homes.					
Pod B	Silt Fence	Lots 212-224		Removed		
Current Condition:	All lots in this Pod have bee	en sodded as of inspection	on 6/25/11.			
Pod C Current Condition:	Silt Fence Silt fence on lots 474-480 h	Lots 175-183; 474-480	the lots being so	Removed	ection on	
	Silt fence on lots 474-480 have been removed due to the lots being sodded prior to inspection on 10/14/12 by Dave Hausman/Celebrity Homes.  All other remaining lots in this pod has been sodded.					
Pod D	Silt Fence	Lots 199-210		Removed		
Current Condition:	All remaining lots in this pool Hausman/Celebrity Homes.	d have been sodded prior	to inspection on 9			
	au -			_		
Pod E  Current Condition:	Silt Fence Lot 194 was sodded prior to	Lots 184-198 o inspection on 5/21/13 by	Dave Hausman/	Removed Celebrity Homes.		
	All lots in this Pod have bee			, , , , , , , , , , , , , , , , , , , ,		
Pod F	Silt Fence	Lots 426-454	11/8/2012	Active	Yes	

Current Condition:	Fair Condition- Lots 447, 448, 449, 450 were sodded prior to inspection on 5/10/13 by Dave Hausman/Celebrity Homes.  1) Lots 435, 436, 437, 438 and 439 needs lot level silt fence installed on the front of the lots. 2) Silt fence check on lot 444 needs to be extended due to silt going around the existing silt fence check. 3) Silt fence on the back of lots 431- 436 is down/damaged and has dirt piled on it in varies areas and ineeds to be repaired and cleaned out.  1) Dave Hausman/Celebrity Homes was informed to install silt fence by 4/8/13. On 4/11/13, 4/24/13, 5/3/13, 5/10/13 and again on 5/21/13 Dave Hausman/Celebrity Homes was reminded that silt fence needs to be completed ASAP. 2) Dave Hausman/Celebrity Homes was informed to complete maintenance by 5/1/13. On 5/3/13, 5/10/13 and again on 5/21/13 Dave Hausman/Celebrity Homes was reminded that maintenance needs to be completed ASAP. 3) Dave Hausman/Celebrity Homes was informed to complete maintenance by 5/28/13.					
D. LO	Silt Fence Lots 404-425 11/8/2012 Active Yes					
Pod G Current Condition:	Fair Condition- Silt fence ch			Active	Yes	
	<ol> <li>There is dirt piled in the R.O.W. on lot 415 and it needs to be removed or add silt fence around it.</li> <li>Silt fence check on lot 414 is down/damaged and some of the t-posts have been removed/stolen and need to be repaired and reinstall the t-posts.</li> <li>Dave Hausman/Celebrity Homes was informed to complete maintenance by 4/8/13. On 4/11/13, 4/24/13, 5/3/13 and again on 5/10/13 Dave Hausman/Celebrity Homes was reminded that maintenance needs to be completed ASAP.</li> <li>Dave Hausman/Celebrity Homes was informed to complete maintenance by 5/16/13. On 5/21/13 Dave Hausman/Celebrity Homes was reminded that maintenance needs to be completed ASAP.</li> </ol>					
Pod H	Silt Fence	Lots 455-473	12/4/2012	Active	Yes	
Current Condition:	Fair Condition- Lot 468 was sodded prior to inspection on 5/21/13 by Dave Hausman/Celebrity Homes.  Silt fence on front of lot 467 is down/damaged and it needs to be replaced.  Dave Hausman/Celebrity Homes was informed to complete maintenance by 5/28/13.					
Pod I	Silt Fence	Lots 346-355	5/10/2013	Active	Yes	
Current Condition:	Good Condition- Silt fence was installed on back of lots 349-355 prior to inspection on 5/10/13 by Dave Hausman/Celebrity Homes.  1) There is a portable toilet on lot 354 and it needs to be staked down. 2) There is dirt piled in the R.O.W. of lots 349, 350, 351 and 352 and they need to be removed or add silt fence around them. 3) Silt fence was removed on lot 346 and it needs to be reinstalled or sod the lot. Silt fence needs to be installed in the Southwest section of lot 347. Silt fence on the East side of lot 348 is full and down/damaged and it needs to be cleaned out and repaired. Additional T-posts need to be added on the back of lot 255 in a few areas.  1) Dave Hausman was informed to complete maintenance by 5/16/13. On 5/21/13 Dave Hausman/Celebrity Homes was reminded that maintenance needs to be completed ASAP. 2) Dave Hausman was informed to complete maintenance needs to be completed ASAP. 3) Dave Hausman was informed to complete maintenance needs to be completed ASAP. 3) Dave Hausman was informed to complete maintenance by 5/16/13.					
SB 1	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition-18% Filled			•	140	
	Basin cleaned out was completed prior to inspection on 6/10/11 by Bob Roth.  N41d00m00s					
SB 2	Sediment Basin	W96d00m00s		Removed		
Current Condition:	Basin was removed and the	outlot B area was seeded	d prior to inspect	ion on 7/12/11 by	Jochim.	

SB 3 Sediment Basin W96d00m00s In Place Active  Current Condition: Good Condition-17% Filled  N41d00m00s N41d00m00s SB 4 Sediment Basin W96d00m00s Removed  Current Condition: Removed per Hill-Farrell construction.	No
SB 4 Sediment Basin W96d00m00s Removed	INO
SB 4 Sediment Basin W96d00m00s Removed	
N41d00m00s	-
SB 5 Sediment Basin W96d00m00s 11/17/2009 Active	No
Current Condition: Good Condition- 6% Filled	
- JC Excavating installed prior to inspection on 11/18/09.  N41d00m00s	
SF 1 Silt Fence W96d00m00s Removed	
Current Condition: silt fence was removed by Boyer Young due to dense vegetation and lack of construction in thi	is area.
N44 100 :: 00 :	
SF 2 Silt Fence W96d00m00s Removed	No
Current Condition: Removed for grading on 8/4/08	140
N41d00m00s	
SF 3 Silt Fence W96d00m00s Removed	
Current Condition: Removed due to home construction.  N41d00m00s	
SF 4 Silt Fence W96d00m00s Removed	
Current Condition: Removed due to home construction.	
N41d00m00s	
SF 5 Silt Fence W96d00m00s Removed	
Current Condition: Removed due to home construction.  N41d00m00s	
SF 6 Silt Fence W96d00m00s Removed	
Current Condition: Removed due to road construction	
	V
N41d00m00s	
SF 7 Silt Fence W96d00m00s In Place Active	Yes
SF 7 Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.	
SF 7 Silt Fence W96d00m00s In Place Active  Current Condition: Fair Condition	ain on
SF 7 Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten	ain on
SF 7 Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  N41d00m00s  SF 8  Silt Fence  W96d00m00s  In Place  Active	ain on
SF 7 Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  N41d00m00s	ain on nance not
SF 7 Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  N41d00m00s  SF 8  Silt Fence  W96d00m00s  In Place  Active	ain on nance not
SF 7 Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of inspection.	ain on nance not Yes spection o.
SF 7 Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8 Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.	ain on nance not Yes spection o.
SF 7 Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten	ain on nance not Yes spection o.
SF 7  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence  N41d00m00s  W96d00m00s  In Place  Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of inson 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also be governed as a section of the t-posts were removed and the silt fence needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence  N41d00m00s  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence  N41d00m00s  Removed  Current Condition:  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is lot current condition:	ain on nance not Yes spection o. ain on nance not
SF 7  Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also and 4/2/2013 Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence W96d00m00s Removed  N41d00m00s Removed  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is let therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the	ain on nance not Yes spection o. ain on nance not
SF 7  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also be sometimed. Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and aga 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence W96d00m00s Removed  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is lot therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.	ain on nance not Yes spection o. ain on nance not
SF 7  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also be provided as of last inspection.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence N41d00m00s W96d00m00s Removed  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is to therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.  N41d00m00s	ain on nance not Yes spection o. ain on nance not
SF 7  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence  N41d00m00s  W96d00m00s  In Place  Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of inspection of the t-posts were removed and the silt fence needs to be completed ASAP. Mainten completed as of last inspection.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence  W96d00m00s  Removed  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is let therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.  SF 10  Silt Fence  W96d00m00s  Removed	ain on nance not Yes spection o. ain on nance not ocated,
SF 7  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also be provided as of last inspection.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence N41d00m00s W96d00m00s Removed  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is to therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.  N41d00m00s	ain on nance not Yes spection o. ain on nance not ocated,
SF 7  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also be gover Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence W96d00m00s Removed  Current Condition:  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is let therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.  SF 10  Silt Fence W96d00m00s Removed  Current Condition:  silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this	ain on nance not Yes spection o. ain on nance not ocated,
SF 7  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and agg 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence  N41d00m00s  SF 8  Silt Fence  W96d00m00s  In Place  Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the 1-posts were removed and the silt fence needs to be removed also Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and agg 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence  N41d00m00s  Removed  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is the therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.  SF 10  Silt Fence  W96d00m00s  Removed  Current Condition:  silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this N41d00m00s	ain on nance not Yes spection o. ain on nance not ocated,
SF 7 Current Condition: Fair Condition A few areas of the silt fence are down/damaged and need to be repaired or removed. Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8 Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also and 4/1/2013 Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and age 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9 Silt Fence W96d00m00s Removed  Current Condition:  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is to therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.  SF 10 Silt Fence W96d00m00s Removed  Current Condition: silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this SILT fence w96d00m00s Removed Removed  Removed  N41d00m00s Removed Removed Removed Removed Removed	ain on nance not yes spection o. ain on nance not ocated,
SF 7  Silt Fence W96d00m00s In Place Active Terror Condition:  Fair Condition:  Fair Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and agg 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active Terror Condition:  Fair Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of inso on 4/1/13 one section of the 1-posts were removed and the silt fence needs to be removed also so year Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and agg 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 9  Silt Fence N41d00m00s W96d00m00s Removed Terror Completed as of last inspection.  SF 9  Current Condition:  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is left therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.  SF 10  Silt Fence W96d00m00s Removed Current Condition:  SI Silt Fence W96d00m00s Removed Silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this silt fence was removed by Boyer Young due to dense vegetation and lack of construction in this silt fence was removed by Boyer Young due to dense vegetation and lack	ain on nance not yes spection o. ain on nance not ocated,
SF 7  Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and agg 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintent completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of inspection of the t-posts were removed and the silt fence needs to be removed also and 4/1/3 one section of the t-posts were removed and the silt fence needs to be removed also and 4/2/2013 Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and agg 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintent completed as of last inspection.  SF 9  Silt Fence W96d00m00s Removed  Current Condition:  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is let therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.  SF 10  Silt Fence W96d00m00s Removed  Current Condition:  silt fence was removed by Boyer Young due to dense vegetation and lack of construction in thi SF 11  Silt Fence W96d00m00s Removed  Current Condition:  silt fence was removed by Boyer Young due to dense vegetation and lack of construction in thi N41d00m00s  SF 11  Silt Fence W96d00m00s Removed  Current Condition:  silt fence was removed by Boyer Young due to dense vegetation and lack of construction in thi N41d00m00s	ain on nance not yes spection o. ain on nance not ocated,
SF 7  Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11, On 9/21/11, 11/21/11 and agg 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Mainten completed as of last inspection.  SF 8  Silt Fence N41d00m00s N96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of ins on 4/1/13 one section of the t-posts were removed and the silt fence needs to be removed also be removed and the silt fence needs to be removed also removed be removed to be removed to be removed also removed	ain on nance not yes spection o. ain on nance not ocated,
SF 7  Silt Fence W96d00m00s In Place Active  Current Condition:  A few areas of the silt fence are down/damaged and need to be repaired or removed.  Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and agg 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintent completed as of last inspection.  SF 8  Silt Fence W96d00m00s In Place Active  Current Condition:  Fair Condition  A few areas of the silt fence are down/damaged and need to be repaired or removed. As of inspection of the t-posts were removed and the silt fence needs to be removed also and 4/1/3 one section of the t-posts were removed and the silt fence needs to be removed also and 4/2/2013 Boyer Young was sent a plan requesting to repair this by 3/3/11. On 9/21/11, 11/21/11 and agg 4/2/2013 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintent completed as of last inspection.  SF 9  Silt Fence W96d00m00s Removed  Current Condition:  As of inspection on 8/6/12 there is active home construction on the lots were this silt fence is let therefore the maintenance on this silt fence is being moved to BMP Pod E and it will be the responsibility of the builder.  SF 10  Silt Fence W96d00m00s Removed  Current Condition:  silt fence was removed by Boyer Young due to dense vegetation and lack of construction in thi SF 11  Silt Fence W96d00m00s Removed  Current Condition:  silt fence was removed by Boyer Young due to dense vegetation and lack of construction in thi N41d00m00s  SF 11  Silt Fence W96d00m00s Removed  Current Condition:  silt fence was removed by Boyer Young due to dense vegetation and lack of construction in thi N41d00m00s	ain on nance not yes spection o. ain on nance not ocated,

Current Condition:	All this maintenance has been moved to Pod C in the BMP section.				
SF B	Silt Fence	N41d00m00s W96d00m00s		Removed	
Current Condition:	Silt fence was removed prior to inspection on 5/10/13 by Dave Hausman/Celebrity Homes.				
		N41d00m00s			
STR	Street Cleaning	W96d00m00s	5/1/2007	Active	No
Current Condition:	Good Condition-				
	Street was cleaned up prior	to inspection on 5/21/13 b	by Commercial S	eeding for Celebri	ity Homes.
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No
Current Condition:	Good Condition: 48th and Birchwood Drive	-			
Inspector Signature:	Jawlan		Reviewed By:	Zadrany k. J	lidelC