E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

E & A CONSULTING GROUP, INC.
ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept. Manager	E&A-	P2005.198.000				
Inspector: Patrick Sechser				Stage		
Project Name:		Clearwater Falls NER110573				
For Week Ending:	9/28/2013					
Project Location:	48th a	nd Fairview Road- Belle	evue, NE (Sarpy County)	68123		
Grading:		100%				
Sanitary Sewer:		100%				
Storm Sewer:		85%				
Paving:		80%				
Seeding: Utilities:		70% 75%				
Overall Development:		45%				
•						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected				
Sunday	0.44"			Week 1		
Sunday: Monday	0.44 " 0.00"					
Tuesday	0.00 0.28"					
Wednesday	0.00"					
Thursday	0.21"	09/19/13				
Friday	0.00"					
Saturday	0.00"			10/		
Sunday:	0.00"			Week 2		
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.21"			Mark 0		
Sunday:	N/A			Week 3		
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
Complaints:	None					
		1				
Construction Sequencing:						
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site	have had a temporary or permane	ent cessation of grading, eart	thwork, or ground disturbance in the	last 14 days?		
	, , , , , , , , , , , , , , , , , , ,		, <u></u>			
Grading completed and entire site seeded	prior to 2005.					
Entire Site; JC Excavating completed grad	•		, ,	oving io atill panding		
Paving operations will begin on 9/3/2013 o	11 4210 AVEILUE & 4310 STEET	by Luxa Construction. A	is or mspection on 9/11/2013, pa	aving is suii peridirig.		
Which portion(s) (i.e. drainage basins) of the site	do not have grading, parthwork	or ground disturbance school	uled in the next 14 days?			
Grading completed and entire site seeded		or ground disturbance schedi	uica iii iiie iieat 14 udys r .			
Entire Site; JC Excavating completed grad	•	ction II, drainage area 1 ar	nd 2 (11/2009)			
Paving operations will begin on 9/3/2013 o	n 42nd Avenue & 43rd Street	by Luxa Construction. As	s of inspection on 9/11/2013, pa	ving is still pending.		
What temporary or permanent stabilization meas	ures listed in this section are beir	ng implemented?	<u> </u>			
Paving, dense vegetation and landscaping phase, lots 346-480, seeded (4/10); Outlot				ıs lots (Fall '08), New		
Comments:						

Celebrity Homes is actively building in the South part of the development. Home Construction is active in the North part of the development by various builders. Grading operations continuing on 42nd Avenue & 43rd Street by Luxa Construction for future roads.

- Findings / Corrective Actions (Date):

 1.) Some maintenance is required in the BMP Section.
- 2.) Fuel container for Luxa was bermed prior to inspection on 9/19/2013 on future 42nd Avenue.

			Projected		
Unique Name	Туре	Location	Install Date	Status	Maintenance
CE 1	Construction Entrance	N41d00m00s W96d00m00s	5/5/2013	Active	Yes
Current Condition:	Poor Condition- 60% Effectiv		0,0/2010	7101170	100
	Construction entrance is in pure and it needs to be removed. Boyer Young was given a pla 11/21/11 and again on 3/2/20 ASAP. Maintenance not com	an requesting to have th	e entrance remove	ed by 8/5/11. On	9/21/11,
CW 3	Concrete Washout	Lot 348		Removed	
Current Condition:	Removed- Bob w/ Celebrity Homes rem		o inspection on 8/2		
CW 4	Concrete Washout	Lot 414	8/27/2013	Active	No
Current Condition:	Good Condition-	Lot 414	0/21/2010	7101170	140
	Bob w/ Celebrity Homes insta	alled a washout pit on lo	ot 414 prior to inspe	ection on 8/27/20)13.
Lot 26 Current Condition:	Silt Fence	Lot 26	5/3/2013	Active	Yes
	Silt fence needs to be re-insta Horizon Homes was informed inspection. Horizon Homes w 8/28/2013. Not completed as 9/3/2013 to complete mainter was reminded again on 9/20/	d to re-install silt fence l yas informed to complet of last inspection on 9/ nance. Maintenance no	oy 8/7/2013. Mainte e maintenance AS 1/2013. Horizon He	enance not cond AP again on 8/1 omes was inform	ucted on last 4/2013 and on ned again on
Lot 27 Current Condition:	Silt Fence Fair Condition-	Lot 27	6/6/2013	Active	
	Fair Condition-				Yes
	1.) One area of the front silt figoing into the neighbor's yard going into the neighbor's yard yard. 2.) Silt fence needs to be inst 1.) Horizon Homes was informerminder was sent on 7/18/13 9/3/2013 to complete mainter was reminded again on 9/20/2.) Horizon Homes was informer was sent 7/18/13, 8/14/2013 Horizon Homes was informed was sent 7/18/13, 8/14/2013	ence is down/damaged d and a few hay bales n d or use an alternative E talled on the front of the med to complete mainte 3, 8/14/2013 and on 8/2 nance. Maintenance no (2013. med to complete mainte and on 8/28/2013. Mai d again on 9/3/2013 to	nay need to be inst MP to prevent silt lot. enance by 6/6/13. (8/2013. Horizon H at completed as of I enance by 6/6/13. (Intenance not component of the complete maintenance)	alled to help pre- from running int (See prior commomes was informast inspection. However, the commoder of the	is some silt vent the silt from o the neighbors ents). A ned again on lorizon Homes ents) A reminder nspection.
	1.) One area of the front silt figoing into the neighbor's yard going into the neighbor's yard yard. 2.) Silt fence needs to be inst 1.) Horizon Homes was infort reminder was sent on 7/18/13 9/3/2013 to complete mainter was reminded again on 9/20/2.) Horizon Homes was infort was sent 7/18/13, 8/14/2013	ence is down/damaged d and a few hay bales n d or use an alternative E talled on the front of the med to complete mainte 3, 8/14/2013 and on 8/2 nance. Maintenance no (2013. med to complete mainte and on 8/28/2013. Mai d again on 9/3/2013 to	nay need to be inst MP to prevent silt lot. enance by 6/6/13. (8/2013. Horizon H at completed as of I enance by 6/6/13. (Intenance not component of the complete maintenance)	alled to help pre- from running int (See prior commomes was informast inspection. However, the commoder of the	is some silt vent the silt from o the neighbors ents). A ned again on lorizon Homes ents) A reminder nspection.

Current Condition:	Fair Condition- Maintenance was completed prior to inspection on 6/23/13 by Horizon Homes.						
	 Silt fence needs to be installed on the front of the lot. Silt fence has dirt piled on it and needs cleaned out. Horizon Homes was informed to complete maintenance by 6/6/13. Maintenance not completed as of inspection on 6/5/13 due to wet and muddy conditions another seven days is given to complete maintenance until 6/12/13. Maintenance not completed as of inspection on 6/9/13 due to wet and muddy conditions another seven days is given to complete maintenance until 6/16/13. Maintenance not completed as of inspection on 6/15/13 due to wet and muddy conditions another seven days is given to complete maintenance until 6/22/13. A reminder was sent on 7/18/13, 8/14/2013 and on 8/28/2013. Horizon Homes was informed again on 9/3/2013 to complete maintenance. Maintenance not completed as of last inspection. Horizon Homes was reminded again on 9/20/2013. Horizon Homes was notified to complete maintenance by 7/23/13. Maintenance was not completed prior to last inspection. A reminder was sent on 8/14/2013 and on 8/28/2013. Maintenance not completed 						
Lot FF	Silt Fonce	Lot 55		Removed	No		
Lot 55 Current Condition:	Silt Fence Removed Lot was sodded prior to insp	Lot 55 bection on 7/16/13 by The	Home Company	Removed	No		
Lot 56	Silt Fence	Lot 56	7/16/2013	Active	No		
Current Condition:	Good Condition- Silt fence was installed prior Dirt in R.O.W was removed Gator Guard was installed o	to inspection on 7/16/13 prior to inspection on 7/1	by Childers Cust 6/13 by Childers	om Homes. Custom Homes.			
Lot 268	Misc/other	Lot 268	4/8/2013	Active	No		
Current Condition:	Good Condition- Sherwood Homes cleaned of	out the dumpster prior to i	nspection on 9/19	9/2013.			
Lot 271	Silt Fence	Lot 271	8/20/2013	Pending	Yes		
	SF needed along the east a Gabe and Thomas with the Maintenance not completed complete ASAP. Maintenan was informed on 9/13/2013	Home Company were con as of last inspection. Tho ce not completed as of las	omas was informe st inspection on 9	ed again on 8/28/2 9/1/2013. The Hom	013 to		
Lot 277	Silt Fence	Lot 277		Removed			
Current Condition:	Dumpster and PP were reminstallation.	oved on site prior to 7/30/	/2013 by the Hon	ne Company due t	o sod		
Lot 283	Silt fence	Lot 283	9/19/2013	Active	Yes		
Current Condition:	Fair Condition- Sherwood Homes installed Dirt needs to be removed free Sherwood Homes was infor	om the ROW.		on 9/19/2013.			
Lot 286	Silt fence	Lot 286		Removed			
Current Condition:	Sherwood Homes installed		on 7/30/2013.	Nomoved			
Lot 287	Silt fence	Lot 287		Removed			
Current Condition:	Tom w/ The Home Compan		inspection on 7/				
Lot 305 Current Condition:	Silt Fence Removed Silt fence was installed on the				- sidewell		
	Silt fence was removed fron construction being active in		1011 7/6/13 by Le	gacy nomes due t	o sidewaik		

Current Condition:	Removed- Heavican Homes sodded th	e lot prior to the inspection	Heavican Homes sodded the lot prior to the inspection on 8/13/2013.					
Lot 312	Silt Fence	Lot 312	4/8/2013	Active	Yes			
Lot 312 Current Condition: Lot 313 Current Condition:	Fair Condition- The dumpster was emptied 1.) Silt fence is down/damag 2.) Construction debris on lo 1.) Banyan Homes was notir 7/30/2013 & on 8/14/2013 to Banyan Homes was informe last inspection. Banyan Hom 2.) Banyan Homes was onlo 7/30/2013 & on 8/14/2013 to Banyan Homes was informe last inspection. Banyan Hom Silt Fence Removed-	prior to inspection on 9/1/ ged and need repaired or of the needs placed in dumpst of the needs again on 9/3/2013 to complete was informed again of the needs of t	2013. replaced on SE atter. 3. Banyan home mpleted prior to lamplete ASAP. Non 9/20/2013. 3. Banyan home mpleted prior to lamplete ASAP. Non 9/20/2013.	s was informed agast inspections on laintenance not consistency of the second sections on Maintenance not consistency of the sections on Maintenance not consistency of the second sections of the second sections of the sec	gain on 8/27 & 9/1. mpleted as of gain on 8/27 & 9/1. ompleted as of			
			pection on 6/27/2	2013. SF Was lelli	oved prior to			
Lot 322 Current Condition:	Silt Fence	Lot 322	9/19/2013	Active	No			
Current Condition:	Heavican Homes sodded the lot prior to the inspection on 8/13/2013. Silt Fence Lot 312 4/8/2013 Active Yes Fair Condition- The dumpster was emptied prior to inspection on 9/1/2013. 1.) Silt fence is down/damaged and need repaired or replaced on SE and NE corners. 2.) Construction debris on lot needs placed in dumpster. 1.) Banyan Homes was notified to complete by 7/23/13. Banyan homes was informed again on 7/30/2013 & on 8/14/2013 to complete ASAP. Not completed prior to last inspections on 8/27 & 9/1. Banyan Homes was informed again on 9/3/2013 to complete ASAP. Maintenance not completed as of last inspection. Banyan Homes was informed again on 9/20/2013. 2.) Banyan Homes was notified to complete by 7/23/13. Banyan homes was informed again on 7/30/2013 & on 8/14/2013 to complete by 7/23/13. Banyan homes was informed again on 9/3/2013 to complete ASAP. Maintenance not completed as of last inspection. Banyan Homes was informed again on 9/3/2013 to complete ASAP. Maintenance not completed as of last inspection. Banyan Homes was informed again on 9/20/2013. Silt Fence Lot 313 Removed Removed- Lot 313 was sodded by Showcase Homes prior to inspection on 8/27/2013. SF was removed prior to inspection on 9-11-2013 by Showcase Homes.							
Lot 323 Current Condition:		Lot 323	8/13/2013	Active	Yes			
Lot 327 Current Condition:		Lot 327	9/19/2013	Active	Yes			
	Sherwood Homes installed a Dirt needs to be removed from	om the ROW.		on 9/19/2013.				
Lot 331 Current Condition:		Lot 331	7/16/2013	Active	No			
Caron Condition	Silt fence was installed in ba							
Lot 333	Silt Fence	Lot 333		Removed				
Current Condition:	Removed- All of the torn and down silt fence was removed along the perimeter of the lot prior to inspection on 8/27/2013 by Regency Homes. Gator guards were removed along the perimeter and the house was							
Lot 339	Misc/other	Lot 339	7/30/2013	Active	Yes			
Current Condition:	Tom with The Home Compa 1.) Concrete rubble needs to 2.) The sides of the lot need	by sodded the lot prior to be removed from next to to be overseeded. The Home Company were as of last inspection. The aintenance. Maintenance minded again on 9/13/20 the Home Company were Home Company was infornot completed as of last it.	the inspection of the lot. contacted to conomas with the Ho enot completed a 3 & on 9/20/201 contacted to co	n 7/30/2013. nplete maintenancy me Company was as of last inspectio 3. nplete maintenancy (28/2013 to comple	e by 8/20/2013. s informed again n on 9/1/2013. se by			

					1			
Lot 341	Silt Fence	Lot 341		Removed				
Current Condition:	As of inspection on 6/15/13	As of inspection on 6/15/13 the silt fence was removed to fine grade the lot by Castlebridge Hol lot was sodded prior to inspection on 6/23/13 by Castlebridge Homes.						
	au =							
Lot 343	Silt Fence	Lot 343	9/19/2013	Active	No			
Current Condition:	Good Condition- Charles Thomas Builders ir Charles Thomas Builders ir Charles Thomas Builders s	nstalled wattles on the fron	t of the lot prior t	o inspection on 9				
Outlot D	Misc/other	Outlot D		Removed				
Current Condition:	The disturbed area around		inspection on 7/8					
Pod A	Silt Fence	Lots 225-254	9/4/2012	Active	No			
Current Condition:	Good Condition- SF still protecting drain betoneeded on lot 236 as of ins SF removed on lot 237 by B	ween lots 237 & 241, and pection on 9/1/2013. SF re	on the SE corner	of lot 242. SF is pection on 9/1/201	no longer			
Pod B	Silt Fence	Lots 212-224		Removed				
Current Condition:	All lots in this Pod have bee	·	on 6/25/11.					
Pod C	Silt Fence	Lots 175-183; 474-480	L	Removed	L _			
Current Condition:	Silt fence on lots 474-480 h 10/14/12 by Dave Hausmar All other remaining lots in the	n/Celebrity Homes.	the lots being so	idded prior to insp	pection on			
Pod D	Silt Fence	Lots 199-210		Removed				
Current Condition:	All remaining lots in this por Hausman/Celebrity Homes		to inspection on	9/28/12 by Dave				
Pod E	Silt Fence	Lots 184-198		Removed				
Current Condition:	Lot 194 was sodded prior to All lots in this Pod have bee		Dave Hausman/	Celebrity Homes				
Pod F	Silt Fence	Lots 426-454	11/8/2012	Active	Yes			
Current Condition:	Fair condition- SF check in place in front o on lot 451 prior to inspectio SF is down behind lot 435 a Bob with Celebrity Homes v completed as of inspection. 9/20/2013.	n on 9/19/2013. and needs to be reinstalled was informed to complete	d.	9/3/2013. Mainter	nance not			
Pod G	Misc/other	Lots 404-425	11/8/2012	Active	Yes			
Current Condition:	Fair Condition- SF removed and stockpile I Concrete debris needs to b Bob with Celebrity Homes v inspection on 9/1/2013.Cele	e removed from in front of	washout pit on loby 9/3/2013. Mai	ntenance not con	npleted as of			
Pod H	Silt Fence	Lots 455-473	12/4/2012	Active	Yes			
		-	-	•				

	Fair Condition-				
	Lot 468 was sodded prior to				
	rear of lot 471 by Bob with C 456 prior to inspection on 9/				
	repaired by lot 456, on side of				
	inspection on 9/11/2013.				
	1.) Silt fence needed along for	ront of lots 461-464 and	456.		
	2.) SF needed along the real				
	 SF removal needed along SF needed along the from 				
	5.) SF cleanout needed alon				
	6.) Dirt needs to be removed		170.		
	7.) SF needed along front of	10t 457.			
	1.) Bob w/ Celebrity Homes	was informed to install si	It fence by 8/7/20	13. Maintenance	was not
	completed as of last inspecti				ce needs to be
	completed ASAP on 8/14/20 2.) Bob w/ Celebrity Homes				e was not comple
	3.) Bob w/ Celebrity Homes	was informed to complet	e maintenance by	/ 9/03/13. Mainte	nance was not co
	4.) Bob w/ Celebrity Homes				
	5.) Bob w/ Celebrity Homes6.) Bob w/ Celebrity Homes				
	7.) Bob w/ Celebrity Homes				
Pod I	Silt Fence	Lots 346-355	5/10/2013	Active	Yes
Current Condition:	Fair Condition-	L013 340-333	3/10/2013	Active	103
	SF was removed behind lots				
	Homes. Lots 350-353 were s 347 & 348 were sodded by E				
	our a one were souded by E	Sob war Gelebrity Floride	o prior to mopeout	511 611 67 16726 16.	
	1.) SF removal needed behin		\ - 4		
	2.) Concrete debris needs to	be cleaned up from lot 3	354.		
	1.) Bob with Celebrity Home	s was informed to comple	ete by 9/18/2013.	Not done as of I	ast inspection.
	Bob with Celebrity Homes w				
	 Bob with Celebrity Homes not completed as of last insp 				
	be completed ASAP on 9/12				
		N41d00m00s			
SB 1	Sediment Basin	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition-25% Filled Basin cleaned out was comp	oleted prior to inspection	on 6/10/11 by Bo	h Roth	
	Baoin oleaned out was comp		T		1
SB 2	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Basin was removed and the		d prior to inspecti		Jochim.
22.0	0 11 15 1	N41d00m00s			
SB 3	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
SB 3 Current Condition:	Sediment Basin Good Condition-17% Filled -Cleaned out 02/06		In Place	Active	No
	Good Condition-17% Filled		In Place	Active	No
	Good Condition-17% Filled	W96d00m00s	In Place	Active	No
	Good Condition-17% Filled		In Place	Active Removed	No
Current Condition:	Good Condition-17% Filled -Cleaned out 02/06	W96d00m00s N41d00m00s W96d00m00s	In Place		No
Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin	W96d00m00s N41d00m00s W96d00m00s nstruction.	In Place		No
Current Condition: SB 4 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor	N41d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s		Removed	
Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin	W96d00m00s N41d00m00s W96d00m00s nstruction.	In Place		No No
Current Condition: SB 4 Current Condition: SB 5	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor	W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s	11/17/2009	Removed	
Current Condition: SB 4 Current Condition: SB 5	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled	W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s	11/17/2009	Removed	
SB 4 Current Condition: SB 5 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed pric	W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18, N41d00m00s W96d00m00s	11/17/2009	Removed Active	No
SB 4 Current Condition: SB 5 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed price	W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18, N41d00m00s W96d00m00s	11/17/2009	Removed Active	No
SB 4 Current Condition: SB 5 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed pric	N41d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18. N41d00m00s W96d00m00s ioyer Young due to dense	11/17/2009	Removed Active	No
SB 4 Current Condition: SB 5 Current Condition: SF 1 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed privices in the condition of the co	N41d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18, N41d00m00s W96d00m00s Over Young due to dense	11/17/2009	Removed Active Removed ack of constructi	No no in this area.
SB 4 Current Condition: SB 5 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed pric	N41d00m00s W96d00m00s w96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18, N41d00m00s W96d00m00s sover Young due to dense	11/17/2009	Removed Active	No
SB 4 Current Condition: SB 5 Current Condition: SF 1 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed price Silt Fence silt fence was removed by B	W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18, N41d00m00s W96d00m00s ioyer Young due to dense N41d00m00s W96d00m00s	11/17/2009	Removed Active Removed ack of constructi	No no in this area.
SB 4 Current Condition: SB 5 Current Condition: SF 1 Current Condition: SF 2 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed prid Silt Fence silt fence was removed by B Silt Fence Removed for grading on 8/4,	N41d00m00s N41d00m00s M96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18, N41d00m00s W96d00m00s oyer Young due to dense N41d00m00s W96d00m00s N41d00m00s N41d00m00s	11/17/2009	Removed Active Removed ack of construction	No no in this area.
SB 4 Current Condition: SB 5 Current Condition: SF 1 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed price Silt Fence silt fence was removed by B	W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18, N41d00m00s W96d00m00s sover Young due to dense N41d00m00s W96d00m00s N41d00m00s W96d00m00s	11/17/2009	Removed Active Removed ack of constructi	No no in this area.
SB 4 Current Condition: SB 5 Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed pric Silt Fence silt fence was removed by B Silt Fence Removed for grading on 8/4 Silt Fence	W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18. N41d00m00s W96d00m00s Sover Young due to dense N41d00m00s W96d00m00s W96d00m00s struction.	11/17/2009	Removed Active Removed ack of construction	No no in this area.
SB 4 Current Condition: SB 5 Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed pric Silt Fence silt fence was removed by B Silt Fence Removed for grading on 8/4 Silt Fence	W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18, N41d00m00s W96d00m00s sover Young due to dense N41d00m00s W96d00m00s N41d00m00s W96d00m00s	11/17/2009	Removed Active Removed ack of construction	No no in this area.
SB 4 Current Condition: SB 5 Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition:	Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed prid Silt Fence silt fence was removed by B Silt Fence Removed for grading on 8/4 Silt Fence Removed due to home cons	W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18, N41d00m00s W96d00m00s sover Young due to dense N41d00m00s W96d00m00s N41d00m00s W96d00m00s struction. N41d00m00s W96d00m00s	11/17/2009	Removed Active Removed ack of constructi Removed Removed	No no in this area.

		N41d00m00s						
SF 5 Current Condition:	Silt Fence Removed due to home con:	W96d00m00s		Removed				
Current Condition.	Removed due to nome cons	Struction.						
SE 6	Cilk Fance	N41d00m00s W96d00m00s		Damayad				
SF 6 Current Condition:	Silt Fence Removed due to road cons			Removed				
		N41d00m00s		ı	<u> </u>			
SF 7	Silt Fence	W96d00m00s		Removed				
Current Condition:	Silt fence was removed price	or to inspection on 6/23/13	by Boyer Young					
		N41d00m00s						
SF 8 Current Condition:	Silt Fence Fair Condition	W96d00m00s	In Place	Active	Yes			
Current Condition.	Fail Collulion							
	A few areas of the silt fence on 4/1/13 one section of the							
	on 4/1/13 one section of the	e t-posts were removed an	u trie siit lerice ri	leeds to be remov	eu aiso.			
	Boyer Young was sent a pla 4/2/2013 Boyer Young was							
	completed as of last inspec		e fieeds to be co	ompleted ASAF . It	namenance not			
		N41d00m00s		I				
SF 9	Silt Fence	W96d00m00s		Removed				
Current Condition:	As of inspection on 8/6/12 therefore the maintenance of							
	responsibility of the builder.							
		N41d00m00s						
SF 10 Current Condition:	Silt Fence silt fence was removed by E	W96d00m00s	vegetation and	Removed	n in this area			
Current Condition.	Silt ferice was feriloved by E	boyer roung due to dense	vegetation and	lack of construction	iii iii iiis arca.			
		N41d00m00s		1				
SF 11	Silt Fence	W96d00m00s		Removed				
Current Condition:	silt fence was removed by E	Boyer Young due to dense	vegetation and	lack of constructio	n in this area.			
					ı			
SF 12	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed due to landscapir	ng.		•				
SF A	Silt Fence	Lots 474-480		Removed				
Current Condition:	All this maintenance has be	een moved to Pod C in the	BMP section.					
		N41d00m00s						
SF B Current Condition:	Silt Fence Silt fence was removed price	W96d00m00s	hy Dave Hausm	Removed	20			
Current Condition.	Oilt ferice was removed pric	or to inspection on 5/10/13	by Dave Hausin	ian/Celebrity Florii	63.			
OTD	0: 10!	N41d00m00s	5/4/0007		V			
STR Current Condition:	Street Cleaning Fair Condition-	W96d00m00s	5/1/2007	Active	Yes			
	Streets were cleaned up in front of lot 268 by Sherwood Homes prior to inspection on 9/19/2013; lot 27							
	by Horizon Homes prior to inspection on 9/19/2013; and on Clearwater Drive and in front of lots 348-35 prior to inspection on 9/19/2013 by Celebrity Homes.							
	1.) Street cleaning needed for in front of lots 432-436, 461-464, 455-458. 2.) Street cleaning needed on 44th Street.							
	3.) Street cleaning needed in front of lot 455 on Birchwood.							
	4.) Street cleaning needed in front of lot 271. 5.) Street cleaning needed in front of lot 331.							
	1.) Celebrity Homes was notified to clean up the streets on 7/30/2013 & on 8/14/2013 ASAP. Maintenance was not completed as of last inspection. Bob w/ Celebrity Homes was reminded that maintenance needs to be completed ASAP on 8/28/2013, 9/3/2013, 9/12/2013, and on 9/20/2013. 2.) Celebrity Homes was notified to clean up the streets on 8/14/2013 ASAP. Maintenance was not completed as of last inspection. Bob w/ Celebrity Homes was reminded that maintenance needs to be							
	completed ASAP on 8/28/20	013, 9/3/2013, 9/12/2013,	and on 9/20/201	3.				
	3.) Celebrity Homes was not4.) The Home Company was	the state of the s						
	5.) Sherwood Homes was in							
SWPPP Sign	Signs Good Condition:	1 sign on site	8-19-08	Active	No			
Current Condition:	48th and Birchwood Drive							
				Zadrany k. L	11 le			