E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



## Engineering Answers

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager E & A CONSULTING GROUP, INC. ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES F84- P2005 198 000

	E&A- P2	005.198.000		
Inspector: Patrick Sechser				Stage
Clearwater Falls				2
Project Name:				
For Week Ending:				
Project Location:	68123			
-	•			· ·
Grading:	100	0%		
Sanitary Sewer:	100	0%		
Storm Sewer:	8!	5%		
Paving:	80	0%		
Seeding:	70	0%		
Utilities:		5%		
Overall Development:	45	5%		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		
				Week 1
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"	10/02/13		
Thursday	1.99"	10/03/13		
Friday	1.46"	10/04/13		
Saturday	0.00"			
				Week 2
Sunday:	0.06"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
Gaturday	0.00			Week 3
Sunday:	N/A			
Monday	N/A			
Tuesday	N/A			
Wednesday	N/A			
Thursday	N/A			
Friday	N/A			
Saturday	N/A			
	None			
Complaints:				
Construction Sequencing:				1
Which portion(s) (i.e. drainage basins) of the	site have had a temporary or permanent	cessation of grading, eartr	nwork, or ground disturbance in the	last 14 days?
Grading completed and entire site seed	led prior to 2005.			
Entire Site; JC Excavating completed g	rading Lots 346 through 480 Section	n II, drainage area 1 an	d 2 (11/2009).	
	0 are 40 al Augusta 8, 40 al Otra at hu			ally a second and 40 and
Paving operations will begin on 9/3/201			ading operations have tempora	irily ceased on 42nd
Avenue & 43rd Street by Luxa Constru	clion for future roads as of inspectio	n on 10/2/2013.		
Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthwork, or g	round disturbance schedu	led in the next 14 days? :	· ·
Grading completed and entire site seed	led prior to 2005.			
Entire Site; JC Excavating completed g	rading Lots 346 through 480 Section	n II, drainage area 1 an	d 2 (11/2009)	
Paving operations will begin on 9/3/201			ading operations have tempora	arily ceased on 42nd
Avenue & 43rd Street by Luxa Constru	ction for future roads as of inspectio	n on 10/2/2013.		
What temporary or permanent stabilization m	leasures listed in this section are being ir	mplemented?	• •	
Paving, dense vegetation and landscap				is lots (Fall '08), New
phase, lots 346-480, seeded (4/10); Ou	itlot B was seeded (6/2011); Lots 16	5-19 was seeded (8/201	11)	

Comments:						
Comments:						
Celebrity Homes is actively building in the South	nart of the development. Hor	me Construction is active	in the North part	of the developme	nt by various	
builders. Grading operations have temporarily ce						
Fuel container from Luxa Construction remains b						
Findings / Corrective Actions (Date):						
Findings / Corrective Actions (Date):						
1.) Some maintenance is required in the BMP Se		(0040 II / II / I			(1	
2.) Due to temporary work by Janke for utility wo 471, 457, & 450-452 by 10/09/2013. Janke remo			e removed from t	he ROW in front o	of lots 467, 470,	
471, 457, & 450-452 by 10/09/2015. Janke remo		rispection on 10/3/2013.				
			Projected			
Unique Name	Туре	Location	Install Date	Status	Maintenance	
•		N41d00m00s				
CE 1	Construction Entrance	W96d00m00s	5/5/2013	Active	Yes	
Current Condition:	Poor Condition- 60% Effecti	veness				
	Construction entrance is in and it needs to be removed.		the streets being	installed it is no l	onger needed	
	and it needs to be removed.	•				
	Boyer Young was given a pl	lan requesting to have the	entrance remov	ed by 8/5/11. On 9	9/21/11.	
	11/21/11 and again on 3/2/2					
	ASAP. Maintenance not cor	npleted as of last inspecti	on.			
CW 3	Concrete Washout	Lot 348		Removed		
Current Condition:	Removed-					
	Bob w/ Celebrity Homes ren	noved washout pit prior to	inspection on 8/	27/2013.		
CW 4	Concrete Washout	Lot 414	8/27/2013	Active	No	
Current Condition:	Good Condition-				10	
	Bob w/ Celebrity Homes ins	talled a washout pit on lot	414 prior to insp	ection on 8/27/20	13.	
Lot 26	Silt Fence	Lot 26	5/3/2013	Active	Yes	
Current Condition:	Fair Condition-					
	Dumpster was emptied prio	r to inspection on 7/30/20	13 by Horizon Ho	mes.		
	0111	and the second second				
	Silt fence needs to be re-ins	stalled in the Northeast se	ction of the lot wr	ere it was remove	ed/downed.	
	Horizon Homes was informe	ed to re-install silt fence b	8/7/2013 Maint	enance not condu	icted on last	
	inspection. Horizon Homes					
	8/28/2013. Not completed a					
	9/3/2013, 9/20/2013 and on	10/4/2013 to complete m	aintenance. Main	tenance not comp	pleted as of last	
	inspection.					
	<b>a</b> 11 E					
Lot 27	Silt Fence	Lot 27	6/6/2013	Active	Yes	
Current Condition:						
	Fair Condition-					
	1.) One area of the front silt					
	going into the neighbor's ya					
	going into the neighbor's yard or use an alternative BMP to prevent silt from running into the neighbors yard. 2.) Silt fence needs to be installed on the front of the lot.					
	z.) Sin ichce needs to be ins		0			
	1.) Horizon Homes was info	rmed to complete mainter	nance by 6/6/13.	(See prior comme	ents). A	
	1.) Horizon Homes was informed to complete maintenance by 6/6/13. (See prior comments). A reminder was sent on 7/18/13, 8/14/2013 and on 8/28/2013. Horizon Homes was informed again on					
	9/3/2013 to complete maintenance. Maintenance not completed as of last inspection. Horizon Homes					
	was reminded again on 9/20					
	2.) Horizon Homes was info					
	was sent 7/18/13, 8/14/2013 and on 8/28/2013. Maintenance not completed as of last inspection.					
	Horizon Homes was informed again on 9/3/2013 to complete maintenance. Maintenance not completed as of last inspection. Horizon Homes was reminded again on 9/20/2013 and on 10/4/2013. Maintenance					
	as or last inspection, nonzon nontes was reminited again on 9/20/2013 and on 10/4/2013. Maintenance					
Lot 30	Silt Fence	Lot 30	5/3/2013	Active	Yes	
_31.00	2		0.0.2010			

Current Condition:	Fair Condition- Maintenance was completed prior to inspection on 6/23/13 by Horizon Homes.					
	<ol> <li>Silt fence needs to be installed on the front of the lot.</li> <li>Silt fence has dirt piled on it and needs cleaned out.</li> <li>Silt fence needs to be cleaned out in several areas along the East SF as of inspection on 10/4/2013.</li> <li>SF needs to be repaired where it blew out as of inspection on 10/4/2013.</li> <li>SF needs to be raked out of the adjoining yard and re-seeded to the East as of inspection on 10/4/2013.</li> </ol>					
	<ol> <li>Horizon Homes was informed to complete maintenance by 6/6/13. Maintenance not completed as of inspection on 6/5/13 due to wet and muddy conditions another seven days is given to complete maintenance until 6/12/13. Maintenance not completed as of inspection on 6/9/13 due to wet and muddy conditions another seven days is given to complete maintenance until 6/16/13. Maintenance not completed as of inspection on 6/5/13 due to wet and muddy conditions another seven days is given to complete maintenance until 6/16/13. Maintenance not completed as of inspection on 6/15/13 due to wet and muddy conditions another seven days is given to complete maintenance until 6/12/13. A reminder was sent on 7/18/13, 8/14/2013 and on 8/28/2013. Horizon Homes was informed again on 9/3/2013, 9/20/2013 and on 10/5/2013 to complete maintenance.</li> <li>Horizon Homes was contacted to complete maintenance by 10/11/2013.</li> <li>Horizon Homes was contacted to complete maintenance by 10/11/2013.</li> <li>Horizon Homes was contacted to complete maintenance by 10/11/2013.</li> </ol>					
Lot 55	Silt Fence Lot 55 Removed No					
Current Condition:	Removed Lot was sodded prior to inspection on 7/16/13 by The Home Company.					
Lot 56 Current Condition:	Silt Fence Lot 56 7/16/2013 Active Yes					
	Fair Condition- Silt fence was installed prior to inspection on 7/16/13 by Childers Custom Homes. Dirt in R.O.W was removed prior to inspection on 7/16/13 by Childers Custom Homes. Gator Guard was installed on front of lot prior to inspection on 7/16/13 by Childers Custom Homes. SF needs to be repaired in 2 areas along the rear of the lot as of inspection on 10/4/2013. Childers Custom Homes was informed to complete maintenance by 10/11/2013.					
Lot 268	Misc/other Lot 268 4/8/2013 Active No					
Current Condition:	Good Condition- Sherwood Homes cleaned out the dumpster prior to inspection on 9/19/2013.					
Lot 271	Silt Fence Lot 271 10/2/2013 Active No					
Current Condition:	Good Condition- Thomas with the Home Company installed SF around the lot to the east and Northeast prior to inspection on 10/2/2013.					
Lot 277	Silt Fence Lot 277 Removed					
Current Condition:	Removed- Dumpster and PP were removed on site prior to 7/30/2013 by the Home Company due to sod installation.					
Lot 283	Silt fence Lot 283 9/19/2013 Active Yes					
Current Condition:	Fair Condition- Sherwood Homes installed SF on the rear of the lot prior to inspection on 9/19/2013. Dirt needs to be removed from the ROW. Sherwood Homes was informed to complete by 9/26/2013. Maintenance not completed as of last inspection. Sherwood Homes was reminded again on 10/4/2013.					
Lot 286	Silt fence Lot 286 Removed					
Current Condition:	Sherwood Homes installed sod prior to the inspection on 7/30/2013.					
Lot 287	Silt fence Lot 287 Removed					
Current Condition:	Tom w/ The Home Company installed sod prior to the inspection on 7/30/2013.					
Lot 305	Silt Fence Lot 305 Removed					
Current Condition:	Removed Silt fence was installed on the lot prior to inspection on 6/23/13 by Legacy Homes. Silt fence was removed from the lot prior to inspection on 7/8/13 by Legacy Homes due to sidewalk construction being active in the area.					

Lot 311 Current Condition:	Silt Fence Removed-	Lot 311		Removed			
	Heavican Homes sodded the lot prior to the inspection on 8/13/2013.						
Lot 312	Silt Fence	Lot 312	4/8/2013	Active	Yes		
Current Condition:	Fair Condition-	prior to inspection on 9/1	1/2013				
	The dumpster was emptied prior to inspection on 9/1/2013.						
	<ol> <li>Silt fence is down/damaged and need repaired or replaced on SE and NE corners.</li> <li>Construction debris on lot needs placed in dumpster.</li> </ol>						
	<ol> <li>2.) Construction debits on lot needs praced in dumpster.</li> <li>1.) Banyan Homes was notified to complete by 7/23/13. Banyan homes was informed again on</li> </ol>						
	7/30/2013 & on 8/14/2013 to						
	Banyan Homes was informe last inspection. Banyan Hom						
	completed as of last inspect	Ŭ	011 9/20/2013 and	011 10/4/2013. Wa			
	2.) Banyan Homes was noti 7/30/2013 & on 8/14/2013 to						
	Banyan Homes was informe	ed again on 9/3/2013 to o	complete ASAP. N	Maintenance not c	ompleted as of		
	last inspection. Banyan Hon completed as of last inspect		on 9/20/2013 and	on 10/4/2013. Ma	intenance not		
Lot 313	Silt Fence	Lot 313		Removed			
Current Condition:	Removed-		4				
	Lot 313 was sodded by Sho inspection on 9-11-2013 by		spection on 8/27/2	2013. SF was rem	oved prior to		
Lot 322	Silt Fence	Lot 322	9/19/2013	Active	No		
Current Condition:	Good Condition- Regency Homes installed S	F Check in front of curb	line prior to inspec	ction on 9/19/2013			
Lot 323	Misc/other	Lot 323	8/13/2013	Active	No		
Current Condition:	Active-		·				
	SF check was removed prio and sidewalk installation.	r to the 10/2/2013 inspec	ction. No BMPs ar	e currently in use	due to flat lot		
Lot 327	Silt fence	Lot 327	9/19/2013	Active	Yes		
Current Condition:	Fair Condition-		·	•			
	Sherwood Homes installed SF on the front of the lot prior to inspection on 9/19/2013.						
	Dirt needs to be removed from the ROW.						
	Sherwood Homes was informed to complete by 9/26/2013. Maintenance not completed as of last						
	inspection. Sherwood Home	es was reminded again o	n 10/4/2013.				
Lot 331	Silt Fence	Lot 331	7/16/2013	Active	No		
Current Condition:	Good Condition		•				
	Silt fence was installed in ba	ack of the lot prior to insp	ection on 7/16/13	by Sherwood Hor	nes.		
	Cill [	Lat 200		Domessed			
Lot 333 Current Condition:	Silt Fence Removed-	Lot 333		Removed			
	All of the torn and down silt fence was removed along the perimeter of the lot prior to inspection on 8/27/2013 by Regency Homes. Gator guards were removed along the perimeter and the house was sodded prior to inspection on 9/1/2013.						
Lot 339	Misc/other	Lot 339	7/30/2013	Active	Yes		

Current Condition:	Tom with The Home Company sodded the lot prior to the inspection on 7/30/2013.					
	<ol> <li>Concrete rubble needs to be removed from next to the lot.</li> <li>The sides of the lot need to be overseeded.</li> </ol>					
	<ol> <li>The sides of the lot need to be overseeded.</li> <li>(1.) Gabe and Thomas with the Home Company were contacted to complete maintenance by 8/20/2013 Maintenance not completed as of last inspection. Thomas with the Home Company was informed again on 8/28/2013 to complete maintenance. Maintenance not completed as of last inspection on 9/1/2013. The Home Company was reminded again on 9/13/2013 &amp; on 9/20/2013. Maintenance not completed as of last inspection.</li> <li>(2.) Gabe and Thomas with the Home Company were contacted to complete maintenance by 8/20/2013. Thomas with the Home Company was informed again on 8/28/2013 to complete maintenance. Maintenance not completed as of last inspection on 9/1/2013. The Home Company was</li> </ol>					
	reminded again on 9/13/2013 and on 9/20/2013. Maintenance not completed as of last inspection.					
Lot 341	Silt Fence Lot 341 Removed					
Current Condition:	As of inspection on 6/15/13 the silt fence was removed to fine grade the lot by Castlebridge Homes. The lot was sodded prior to inspection on 6/23/13 by Castlebridge Homes.					
Lot 343	Silt Fence Lot 343 9/19/2013 Active Yes					
	Charles Thomas Builders installed SF on the rear of the lot prior to inspection on 9/19/2013. Charles Thomas Builders installed wattles on the front of the lot prior to inspection on 9/19/2013. Charles Thomas Builders staked in the PP prior to inspection on 9/19/2013. SF needs to be repaired and cleaned out in the rear of the lot as of inspection on 10/4/2013. Charles Thomas Builders was informed to complete maintenance by 10/11/2013.					
Outlot D	Misc/other Outlot D Removed					
Current Condition:	The disturbed area around the inlet has filled in as of inspection on 7/8/13.					
Pod A	Silt Fence Lots 225-254 9/4/2012 Active No					
Current Condition:	Good Condition- Bob with Celebrity Homes sodded lot 237 and removed SF check to the SW of lot 237 for sod installation prior to inspection on 10/02/2013.					
Pod B	Silt Fence Lots 212-224 Removed					
Current Condition:	All lots in this Pod have been sodded as of inspection on 6/25/11.					
Pod C Current Condition:	Silt Fence         Lots 175-183; 474-480         Removed           Silt fence on lots 474-480 have been removed due to the lots being sodded prior to inspection on 10/14/12 by Dave Hausman/Celebrity Homes.         All other remaining lots in this pod has been sodded.					
Pod D	Silt Fence Lots 199-210 Removed					
Current Condition:	All remaining lots in this pod have been sodded prior to inspection on 9/28/12 by Dave Hausman/Celebrity Homes.					
Pod E	Silt Fence Lots 184-198 Removed					
Current Condition:	Lot 194 was sodded prior to inspection on 5/21/13 by Dave Hausman/Celebrity Homes. All lots in this Pod have been built out.					
Pod F	Silt Fence Lots 426-454 11/8/2012 Active Yes					
Current Condition:	Fair condition- SF was removed behind lots 435 and 434 due to sod installation by Bob with Celebrity Homes prior to the 10/2/2013 inspection. SF needs repair on lot 450 as of inspection on 10/2/2013. Bob with Celebrity Homes was informed to complete maintenance by 10/09/2013. Due to rain event, contractor was given rain extension till 10/11/2013.					
Pod G	Misc/other Lots 404-425 11/8/2012 Active Yes					
Current Condition:	Fair Condition- SF removed and stockpile reduced prior to inspection on 9/11/2013. Concrete debris needs to be removed from in front of washout pit on lot 414 and on lot. Bob with Celebrity Homes was informed to complete by 9/3/2013. Maintenance not completed as of inspection on 9/1/2013.Celebrity Homes was informed again on 9/3/2013, 9/12/2013, 9/20/2013 and o					
Pod H	10/5/2013. Maintenance not completed as of last inspection.           Silt Fence         Lots 455-473         12/4/2012         Active         Yes					
FUU F	Gill Felice Luis 455-475 12/4/2012 Active Tes					

Current Condition:						
	<ul> <li>Fair Condition- Bob with Celebrity Homes installed new SF checks in the front of lots 456, 457, 461, 462, and 471; SF check was installed in front of 469; SF was installed on sides of lot 469 prior to the 10/2/2013 inspection. Sidewalk installation occurring on lots 463 to 464 prior to inspection on 10/2/2013 by Bob with Celebrity Homes.</li> <li>1.) SF cleanout needed along the NW side of lot 455.</li> <li>2.) SF cleanout needed behind lot 471 and repair in front of lot 471 as of inspection on 10/2/2013.</li> <li>3.) SF checks need to be removed on lot 461 and 462 as of inspection on 10/2/2013.</li> <li>4.) SF needs to be repaired on lot 457 in the front of the lot as of inspection on 10/2/2013.</li> <li>5.) SF needs to be cleaned out and entrenched behind lot 456 as of inspection on 10/2/2013.</li> <li>6.) SF needs to be cleaned out behind lot 470 as of inspection on 10/4/2013.</li> <li>7.) SF needs to be cleaned out behind lot 470 as of inspection on 10/4/2013.</li> <li>8.) SF needs to be cleaned out on the side of lot 469 as of inspection on 10/4/2013.</li> <li>9.) SF needs to be cleaned out behind lot 470 as of inspection on 10/4/2013.</li> <li>8.) SF needs to be cleaned out on the side of lot 469 as of inspection on 10/4/2013.</li> <li>9.) SF needs to be cleaned out on the side of lot 469 as of inspection on 10/4/2013.</li> </ul>					
	<ol> <li>Bob w/ Celebrity Homes was informed to complete maintenance by 9/8/2013. Bob w/ Celebrity Homes</li> <li>Bob w/ Celebrity Homes was informed to complete maintenance by 10/09/2013. Due to rain event, c</li> <li>Bob w/ Celebrity Homes was informed to complete maintenance by 10/09/2013. Due to rain event, c</li> <li>Bob w/ Celebrity Homes was informed to complete maintenance by 10/09/2013. Due to rain event, c</li> <li>Bob w/ Celebrity Homes was informed to complete maintenance by 10/09/2013. Due to rain event, c</li> <li>Bob w/ Celebrity Homes was informed to complete maintenance by 10/09/2013. Due to rain event, c</li> </ol>					
	6.) Bob w/ Celebrity Homes 7.) Bob w/ Celebrity Homes 8.) Bob w/ Celebrity Homes 9.) Bob w/ Celebrity Homes	was informed to comple was informed to comple	te maintenance by te maintenance by	/ 10/11/2013. / 10/11/2013.		
Pod I	Silt Fence	Lots 346-355	5/10/2013	Active	Yes	
Current Condition:	Fair Condition- SF was removed behind lots Homes. Lots 350-353 were s 347 & 348 were sodded by E 1.) SF removal needed behin 2.) Concrete debris needs to	sodded by Bob with Cele Bob with Celebrity Home nd lot 350-353.	brity Homes prior s prior to inspection	to inspection on 9		
	1.) Bob with Celebrity Homes Bob with Celebrity Homes w 2.) Bob with Celebrity Homes not completed as of last insp be completed ASAP on 9/12	as reminded again on 9/ s was informed by 9/03/: pection. Bob w/ Celebrity	20/2013 and on 1 2013 to complete Homes was remi	0/05/2013. maintenance. Ma	intenance was	
SB 1	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active		
Current Condition:	Good Condition-25% Filled				No	
	Basin cleaned out was comp		on 6/10/11 by Bo		NO	
5P.0	Basin cleaned out was comp	N41d00m00s	on 6/10/11 by Bo	b Roth.	NO	
SB 2 Current Condition:		N41d00m00s W96d00m00s outlot B area was seede		b Roth. Removed		
Current Condition:	Basin cleaned out was comp Sediment Basin Basin was removed and the	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s	ed prior to inspecti	b Roth. Removed on on 7/12/11 by .	Jochim.	
	Basin cleaned out was comp	N41d00m00s W96d00m00s outlot B area was seede		b Roth. Removed		
Current Condition: SB 3	Basin cleaned out was comp Sediment Basin Basin was removed and the Sediment Basin Good Condition-17% Filled -Cleaned out 02/06	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s	ed prior to inspecti	b Roth. Removed on on 7/12/11 by J	Jochim.	
Current Condition: SB 3	Basin cleaned out was comp Sediment Basin Basin was removed and the Sediment Basin Good Condition-17% Filled	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s N41d00m00s W96d00m00s	ed prior to inspecti	b Roth. Removed on on 7/12/11 by .	Jochim.	
Current Condition: SB 3 Current Condition: SB 4	Basin cleaned out was comp Sediment Basin Basin was removed and the Sediment Basin Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s N41d00m00s W96d00m00s	ed prior to inspecti	b Roth. Removed on on 7/12/11 by J	Jochim.	
Current Condition: SB 3 Current Condition: SB 4 Current Condition:	Basin cleaned out was comp Sediment Basin Basin was removed and the Sediment Basin Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s	In Place	b Roth. Removed on on 7/12/11 by Active Removed	Jochim. No	
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SF 1	Basin cleaned out was comp Sediment Basin Basin was removed and the Sediment Basin Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed price Silt Fence	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18 N41d00m00s W96d00m00s	In Place	b Roth.  Removed  Active  Active  Removed  Active	Jochim. No No	
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition:	Basin cleaned out was comp Sediment Basin Basin was removed and the Sediment Basin Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed prio	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18 N41d00m00s W96d00m00s oyer Young due to dens	In Place	b Roth.  Removed  Active  Active  Removed  Active	Jochim. No No	
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SF 1	Basin cleaned out was comp Sediment Basin Basin was removed and the Sediment Basin Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed price Silt Fence	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18 N41d00m00s W96d00m00s	In Place	b Roth.  Removed  Active  Active  Removed  Active	Jochim. No No	
Current Condition:         SB 3         Current Condition:         SB 4         Current Condition:         SB 5         Current Condition:         SF 1         Current Condition:	Basin cleaned out was comp Sediment Basin Basin was removed and the Sediment Basin Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed price Silt Fence silt fence was removed by B	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s N41d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18 N41d00m00s W96d00m00s over Young due to dens N41d00m00s W96d00m00s V96d00m00s	In Place	b Roth.  Removed  Active  Removed  Active  Removed  ack of construction	Jochim. No No	
Current Condition:         SB 3         Current Condition:         SB 4         Current Condition:         SB 5         Current Condition:         SF 1         Current Condition:         SF 2         Current Condition:         SF 2         Current Condition:         SF 3	Basin cleaned out was comp         Sediment Basin         Basin was removed and the         Sediment Basin         Good Condition-17% Filled         -Cleaned out 02/06         Sediment Basin         Removed per Hill-Farrell cor         Sediment Basin         Good Condition- 6% Filled         - JC Excavating installed prior         Silt Fence         silt fence was removed by B         Silt Fence         Removed for grading on 8/4/         Silt Fence	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18 N41d00m00s W96d00m00s over Young due to dens N41d00m00s W96d00m00s W96d00m00s	In Place	b Roth.  Removed  Active  Removed  Active  Removed  ack of construction	Jochim. No No	
Current Condition:         SB 3         Current Condition:         SB 4         Current Condition:         SB 5         Current Condition:         SF 1         Current Condition:         SF 2         Current Condition:	Basin cleaned out was comp Sediment Basin Basin was removed and the Sediment Basin Good Condition-17% Filled -Cleaned out 02/06 Sediment Basin Removed per Hill-Farrell cor Sediment Basin Good Condition- 6% Filled - JC Excavating installed price Silt Fence silt fence was removed by B Silt Fence Removed for grading on 8/4/	N41d00m00s W96d00m00s outlot B area was seede N41d00m00s W96d00m00s W96d00m00s nstruction. N41d00m00s W96d00m00s or to inspection on 11/18 N41d00m00s W96d00m00s over Young due to dens N41d00m00s W96d00m00s W96d00m00s	In Place	b Roth.  Removed  Active  Removed  Active  Removed  Removed  Removed  Removed  Removed  Removed  Removed  Removed	Jochim. No No	

Current Condition:	Removed due to home cons	struction.				
SF 5	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Removed due to home construction.					
		N41d00m00s				
SF 6 Current Condition:	Silt Fence Removed due to road const	W96d00m00s		Removed		
		N41d00m00s	1			
SF 7	Silt Fence	W96d00m00s		Removed		
Current Condition:	Silt fence was removed prior to inspection on 6/23/13 by Boyer Young.					
	Oith France	N41d00m00s	la Diaca	A	Maa	
SF 8 Current Condition:	Silt Fence Fair Condition	W96d00m00s	In Place	Active	Yes	
	A few areas of the silt fence on 4/1/13 one section of the Boyer Young was sent a pla 4/2/2013 Boyer Young was completed as of last inspect	t-posts were removed an in requesting to repair this reminded that maintenan	nd the silt fence n s by 3/3/11. On 9	eeds to be remov /21/11, 11/21/11 a	ed also. Ind again on	
		N41d00m00s		1		
SF 9	Silt Fence	W96d00m00s		Removed		
Current Condition:	As of inspection on 8/6/12 therefore the maintenance of responsibility of the builder.	on this silt fence is being r				
SF 10	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	silt fence was removed by E	Boyer Young due to dense	e vegetation and	lack of constructio	n in this area.	
SF 11	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	silt fence was removed by E		e vegetation and		n in this area.	
		N41d00m00s				
SF 12	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed due to landscapir	ng.				
SF A Current Condition:	Silt Fence All this maintenance has be	Lots 474-480	PMD costion	Removed		
Current Condition:	All this maintenance has be		BMP section.			
SF B	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Silt fence was removed pric	r to inspection on 5/10/13	by Dave Hausm	an/Celebrity Hom	es.	
		N41d00m00s				
STR Current Condition:	Street Cleaning Fair Condition-	W96d00m00s	5/1/2007	Active	Yes	
	Celebrity Homes cleaned st Homes cleaned streets in fr cleaned 43rd Avenue, 44th,	ont of lot 331 prior to the Clearwater Drive and Bir	10/2/2013 inspec chwood Drive pri	tion. Commercial for to the 10/3/201	Seeding street	
	<ol> <li>Street cleaning needed for in front of lots 432-436, 464, 415, 455-456, 470-468.</li> <li>Street cleaning needed in front of lot 271.</li> <li>Street cleaning needed in front of lot 27, and at the end of 43rd and Sheridan Road.</li> <li>Street cleaning needed in front of lot 268.</li> </ol>					
	<ol> <li>Celebrity Homes was not</li> <li>The Home Company was completed as of last inspect 9/20/2013. Maintenance was</li> <li>Horizon Homes was noti</li> <li>Sherwood Homes was n</li> </ol>	s notified to clean up the tion. The Home Company as not completed as of las fied to clean up the street	streets on 9/1/20 was reminded a st inspection. ts on 10/05/2013.	13 ASAP. Mainter gain on 9/13/2013		
	Signa	1 sign on site	8-10.09	Activo	No	
SWPPP Sign Current Condition:	Signs Good Condition: 48th and Birchwood Drive	1 sign on site	8-19-08	Active	No	
Inspector Signature:	to Sel		Reviewed By:	Zadrany k. L	filde	