E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

E & A CONSULTING GROUP, INC. ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

Inspector: Patrick Sechser Project Name: For Week Ending: Project Location: Grading: Sapitary Sever:		Clearwa		Stage Winter		
For Week Ending: Project Location: Grading:						
For Week Ending: Project Location: Grading:	_	NER110573				
Project Location: Grading:			/2015			
Grading:	48th and	68123				
	-					
Sanitary Sowor:	100%	1				
Sanitary Sewer:	100%					
Storm Sewer: Paving:	100%					
Seeding:	100%		- -			
Utilities:	100%		- - - - - - - - - - 			
Overall Development:	66%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
	0.00			Week		
Sunday:	0.00"	 				
Monday Tuesday	0.00"	02/17/15	24/12 Partly cloudy			
Wednesday	0.00"	V=/1/10	Z-7 12 1 artiy Gloudy			
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"			Manh		
Sunday:	0.00"			Week		
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.07"					
Thursday	0.00"					
Friday Saturday	0.00"					
Saturday	0.00			Week		
Sunday:	N/A	N/A				
Monday	N/A	N/A				
Tuesday	N/A	N/A				
Wednesday Thursday	N/A N/A	N/A N/A				
Friday	N/A	N/A				
Saturday	N/A	N/A				
				Week		
Sunday:	N/A	N/A				
Monday	N/A	N/A				
Tuesday Wednesday	N/A N/A	N/A N/A				
wednesday Thursday	N/A N/A	N/A				
Friday	N/A	N/A				
Saturday	N/A	N/A				
				Week		
Sunday:	N/A	N/A				
Monday	N/A	N/A				
Tuesday Wednesday	N/A N/A	N/A N/A				
wednesday Thursday	N/A N/A	N/A N/A	+			
Friday	N/A	N/A				
Saturday	N/A	N/A				
Complaints:	None					
oompiants.	_					
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site hav	re had a temporary or permanent cos	ssation of grading oar	thwork or ground disturbance in the last 14 c	lavs?		
remon portion(s) (i.e. drainage basins) of the site hav	o nad a temporary or permanent ces	saction of grading, ear	and a ground distribution in the last 14 0	uyo.		
Grading completed and entire site seeded price	or to 2005.					
Entire Site; JC Excavating completed grading		, drainage area 1 a	nd 2 (11/2009).			
			, ,			
Entire site is now inactive for major grading ac	minuos as or une maperion on t					

Grading completed and entire site seeded prior to 2005 Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009). Entire site is now inactive for major grading activities as of the inspection on 11/20/2013. Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014); SUMMARY QUESTIONS CHECKLIST QUESTIONS Yes Comments: Celebrity Homes is actively building in the South part of the development. Home Construction is active in the North part of the development by various builders. Site was covered with light snow as of the inspection on 2/17/2015. Findings / Corrective Actions (Date): Some maintenance is required in the BMP Section. Projected Install Date **Unique Name** Type Location Status Maintenance CW 5 Concrete Washout Lot 387 5/12/2014 Active No **Current Condition:** Good Condition- Celebrity Homes cleaned out the washout pit prior to the inspection on 12/2/2014. Lot 54 Lot 54 6/18/2014 **Current Condition:** Due to the removal of the perimeter SF, sod is needed. Homeowner Nick Peterson was informed to complete sod install by 12/2/2014 permitting weather conditions. Not completed as of the last inspection. Lot 57 Silt Fence Lot 57 8/11/2014 Active **Current Condition:** 1.) SF is needed in the rear of the lot due to the new excavation. 2.) SF needs to be entrenched on the North side of the lot. 3.) SF is ripped on the side of the lot as of inspection on 9/24/14. 4.) Additional SF is torn on the north side and needs repair as of 2/17/2015. 1.) Horizon Homes was requested to install silt fence by 8/11/14. Not done as of last inspection. Horizon Homes was reminded again on 9/11/2014, 11/6/2014, 2/18/2015. 2.) Horizon Homes was requested to complete silt fence maintenance by 9/17/2014. Not done as of last inspection. Horizon Homes was reminded again on 11/6/2014, 2/18/2015. 3.) Horizon Homes was requested to repair the ripped SF by 10/1/14. Not done as of last inspection. Horizon Homes was reminded again on 11/6/2014, 2/18/2015. 4.) Horizon Homes was informed to repair by 2/24/2015. Lot 76 6/27/2014 Lot 76 Silt Fence Active Nο **Current Condition:** Good Condition-Proline Homes installed SF in the rear and side of the lot prior to the inspection on 6/27/2014. Silt Fence Lot 80 8/23/2014 Lot 80 Active **Current Condition:** air Condition-Silt fence was installed on the North side of the lot by Horizon Homes prior to inspection on 8/23/14 1.) SF is needed in the rear of the lot. 2.) SF is damaged in the NW corner and needs repair as of 2/17/2015. 3.) SF is torn in multiple areas on the north side and needs repair as of 2/17/2015. 1.) Horizon Homes was requested to install silt fence by 9/17/2014. Not done as of last inspection. Horizon Homes was reminded again on 11/6/2014, 2/18/2015. 2.) Horizon Homes was informed to repair by 2/24/2015. 3.) Horizon Homes was informed to repair by 2/24/2015. Lot 132 Silt Fence Lot 132 8/11/2014 No Active **Current Condition:** Good Condition- Regency Homes installed erosion eels in the front corner of the lot prior to the inspection on

12/2/2014.

Silt Fence

Lot 155

8/11/2014

Active

Lot 155

	Fair Condition-						
	SF needs to be retied to the posts on the East side of the lot as of 2/17/2015. Regency Homes was informed to complete by 2/24/2015.						
Lot 255	Silt Fence Active- Due to the vegetate	Lot 255	8/4/2014	Active	No No		
Current Condition:	by Legacy Homes.	a buller benina the lot, Sr	is no longer needed as	or the inspection	101111/5/2		
Lot 258	Individual Lot	Lot 258	10/14/2014	Pending	Yes		
Current Condition:	Pending-Charleston Homes	<u> </u>					
	SF or wattles are needed in the front of the lot.						
	Charleston Homes was requested CH was reminded again on		11/12/2014. Not compl	eted as of the las	st inspectio		
Lot 259	Individual Lot	Lot 259	10/14/2014	Pending	Yes		
Current Condition:	Pending-Charleston Homes	removed the stockpile pr	or to the inspection on	11/5/2014.			
	SF or wattles are needed in	Pending-Charleston Homes removed the stockpile prior to the inspection on 11/5/2014. SF or wattles are needed in the front of the lot.					
	Charleston Homes was requested CH was reminded again on		11/12/2014. Not compl	eted as of the las	st inspectio		
Lot 279	Silt Fence	Lot 279	7/15/2014	Active	Yes		
Current Condition:	Fair Condition						
	SF is full in the SE corner as	SF is full in the SE corner as of inspection on 10/23/14.					
	Charleston Homes was requested to clean out the SF by 10/30/14. Not completed as of the last inspection CH was reminded again on 12/29/2014.						
	err was reminada again on						
Lot 282	Silt Fence	Lot 282	1/21/2015	Pending	Yes		
Current Condition:	Pending- Dirt was removed	d from the ROW prior to	the inspection on 2/17	72015.			
	SF is needed in the rear of the lot.						
	of is needed in the real of the lot.						
	Oakwood Homes was inform	med to complete by 1/21/2	2015. Not completed a	s of the last ins	pection.		
Lot 286	Silt Fence	Lot 286	12/2/2014	Active	Yes		
Current Condition:	Fair Condition- Sherwood H	ionnes installed St. In the i					
	Dirt needs to be removed fr						
	Dirt needs to be removed for Sherwood Homes was infor inspection.						
Lot 300	Sherwood Homes was infor						
Lot 300 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate	med to remove the dirt fro	m the ROW by 12/9/20	14. Not complete	ed as of the		
Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor.	Lot 300 d buffer behind the lot, SF	m the ROW by 12/9/20 12/23/2014 is not needed at this tir	14. Not complete Active ne by Pinecrest H	ed as of the		
Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence	Lot 300 d buffer behind the lot, SF	12/23/2014 12/33/2014	14. Not complete Active ne by Pinecrest H	ed as of the		
Current Condition: Lot 324 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I	Lot 324 Homes retied the SF prior	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/	14. Not complete Active ne by Pinecrest I Active 14.	No No		
Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015	Active Active Active Active Active Active	No No		
Current Condition: Lot 324 Current Condition: Lot 326	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015	Active Active Active Active Active Active	No No		
Current Condition: Lot 324 Current Condition: Lot 326	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was ins	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015	Active Active Active Active Active Active	No No en inspection		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was ins	Lot 324 Homes retied the SF prior Lot 326 Lot 326 Lot 328 Lot 328	12/23/2014 Is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 Ith side by Sherwood H	Active Active Active Active Active Active	No No sinspection		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was ins 1/14/2015. Silt Fence Fair Condition- SF was insta	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and so	m the ROW by 12/9/20 12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 uth side by Sherwood H 12/15/2014 by Oakwood Homes pr	Active Active Active Active Active Active	No No sinspection		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetater inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was install/14/2015. Silt Fence Fair Condition- SF was install/15/2014. SF on the side of the lot ne	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and so Lot 328 alled on the front and side	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr	Active Active Active Active Active Active Active Active Active omes prior to the Active ior to the inspect	No No Prinspection on		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was install 1/4/2015. Silt Fence Fair Condition- SF was install 1/15/2014.	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and so Lot 328 alled on the front and side	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr	Active Active Active Active Active Active Active Active Active omes prior to the Active ior to the inspect	No No No Procession on No		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was install 1/4/2015. Silt Fence Fair Condition- SF was install 1/15/2014. SF on the side of the lot ne Cakwood Homes was information. Silt Fence Fair Condition- Sherwood Homes	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and so Lot 328 alled on the front and side eds to be retied to the pos med to complete by 1/21/2 Lot 337 lomes removed the stocky	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr ts as of 1/14/2015. 2015. Not completed a: 8/30/2014 iille from the ROW prior	Active Active Active Active Active Active Active Active Active ior to the inspect Active ior to the inspect Active ior to inspect on on	No No No President No		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was install 1/4/2015. Silt Fence Fair Condition- SF was install 1/2/15/2014. SF on the side of the lot ne Oakwood Homes was inform	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and so Lot 328 alled on the front and side eds to be retied to the pos med to complete by 1/21/2 Lot 337 lomes removed the stocky	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr ts as of 1/14/2015. 2015. Not completed a: 8/30/2014 iille from the ROW prior	Active Active Active Active Active Active Active Active Active ior to the inspect Active ior to the inspect Active ior to inspect on on	No N		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition-SF was install 1/4/2015. Silt Fence Fair Condition- SF was install 1/2/15/2014. SF on the side of the lot ne Oakwood Homes was inform Silt Fence Fair Condition- Sherwood H SF needs repaired on the N Sherwood Homes was required.	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and sol Lot 328 alled on the front and side eds to be retied to the pos med to complete by 1/21/2 Lot 337 lomes removed the stocky lorth end due to power ins lested to repair SF by 10/3	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr ts as of 1/14/2015. 1015. Not completed a: 8/30/2014 iile from the ROW prior tallation as of inspection	Active comes prior to the inspect Active to inspection on a on 10/23/14.	No No Pection.		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was install 1/14/2015. Silt Fence Fair Condition- SF was install 1/15/2014. SF on the side of the lot ne Oakwood Homes was inform Silt Fence Fair Condition- Sherwood H SF needs repaired on the N	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and sol Lot 328 alled on the front and side eds to be retied to the pos med to complete by 1/21/2 Lot 337 lomes removed the stocky lorth end due to power ins lested to repair SF by 10/3	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr ts as of 1/14/2015. 1015. Not completed a: 8/30/2014 iile from the ROW prior tallation as of inspection	Active comes prior to the inspect Active to inspection on a on 10/23/14.	No No Pection.		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition: Lot 337 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active-Due to the vegetate-inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition-SF was install/14/2015. Silt Fence Fair Condition-SF was install/15/2014. SF on the side of the lot ne Oakwood Homes was inform Silt Fence Fair Condition- Sherwood H SF needs repaired on the N Sherwood Homes was requeled the service of the lot	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and so Lot 328 alled on the front and side eds to be retied to the pos med to complete by 1/21/2 Lot 337 lomes removed the stocky orth end due to power ins rested to repair SF by 10/3 n on 12/2/2014.	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr ts as of 1/14/2015. 1015. Not completed as 8/30/2014 tallation as of inspection 10/14. Not completed as	Active ior to the inspect active Active Active Active Active Active Active Active To inspection on To n 10/23/14. Active Active	No No Pection. Yes 10/23/14.		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition: Lot 337 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was install/14/2015. Silt Fence Fair Condition- SF was install/12/15/2014. SF on the side of the lot ne Oakwood Homes was inform Silt Fence Fair Condition- Sherwood H SF needs repaired on the N Sherwood Homes was requested the service of the lot of t	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and so Lot 328 alled on the front and side eds to be retied to the pos med to complete by 1/21/2 Lot 337 lomes removed the stocky orth end due to power ins lested to repair SF by 10/3 on 12/2/2014. Lots 426-454 Homes retied the SF to t	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr ts as of 1/14/2015. 1015. Not completed as 8/30/2014 tallation as of inspection 10/14. Not completed as	Active ior to the inspect active Active Active Active Active Active Active Active To inspection on To n 10/23/14. Active Active	No No Pection. Yes 10/23/14.		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition: Lot 337 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active-Due to the vegetate-inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition-SF was install/14/2015. Silt Fence Fair Condition-SF was install/15/2014. SF on the side of the lot ne Oakwood Homes was inform Silt Fence Fair Condition- Sherwood H SF needs repaired on the N Sherwood Homes was requeled the service of the lot	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and so Lot 328 alled on the front and side eds to be retied to the pos med to complete by 1/21/2 Lot 337 lomes removed the stocky orth end due to power ins lested to repair SF by 10/3 on 12/2/2014. Lots 426-454 Homes retied the SF to t	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr ts as of 1/14/2015. 1015. Not completed as 8/30/2014 tallation as of inspection 10/14. Not completed as	Active ior to the inspect active Active Active Active Active Active Active Active To inspection on To n 10/23/14. Active Active	No No No Pection. Yes 10/23/14.		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition: Lot 337 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition- SF was install/14/2015. Silt Fence Fair Condition- SF was install/12/15/2014. SF on the side of the lot ne Oakwood Homes was inform Silt Fence Fair Condition- Sherwood H SF needs repaired on the N Sherwood Homes was requested the service of the lot of t	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and sole alled on the front and side eds to be retied to the pose med to complete by 1/21/2 Lot 337 lomes removed the stocky forth end due to power ins lested to repair SF by 10/3 n on 12/2/2014. Lots 426-454 Homes retied the SF to to 2/17/2015. the posts on the front, si	12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr 12/15/2014 by Oakwood Homes pr 13/14/2015 tt as of 1/14/2015. 1015. Not completed as 8/30/2014 sille from the ROW prior italiation as of inspection 10/14. Not completed as 11/8/2012 the posts on the south de and rear of lots 42.	Active Active Active Active 14. Active Active Active in Active Active Active ior to the inspect Active Active ior to the last inspect to inspection on a on 10/23/14. Active	No N		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition: Lot 337 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active-Due to the vegetater inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition-SF was install/2015. Silt Fence Fair Condition-SF was install/14/2014. SF on the side of the lot ne Oakwood Homes was inform Silt Fence Fair Condition-Sherwood H SF needs repaired on the N Sherwood Homes was requelled to silt Fence Fair Condition-Celebrity I prior to the inspection on 1.) SF needs to be tied to silt Fence	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and sol Lot 328 alled on the front and side eds to be retied to the pose med to complete by 1/21/2 Lot 337 lomes removed the stocky forth end due to power ins lested to repair SF by 10/3 for on 12/2/2014. Lots 426-454 Homes retied the SF to to 2/17/2015. the posts on the front, si to the posts on the north informed to complete by	m the ROW by 12/9/20 12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr ts as of 1/14/2015. 2015. Not completed as 8/30/2014 sile from the ROW prior tallation as of inspection as 11/8/2012 the posts on the south of and west sides of lot 2/24/2015.	Active Active Active Active 14. Active Active Active in Active Active Active ior to the inspect Active Active ior to the last inspect to inspection on a on 10/23/14. Active	No No Pection. Yes 10/23/14.		
Current Condition: Lot 324 Current Condition: Lot 326 Current Condition: Lot 328 Current Condition: Lot 337 Current Condition:	Sherwood Homes was infor inspection. Silt Fence Active- Due to the vegetate inspector will monitor. Silt Fence Good Condition-Sherwood I Silt Fence Good Condition-SF was install 1/14/2015. Silt Fence Fair Condition- SF was install 1/15/2014. SF on the side of the lot ne Oakwood Homes was inform Silt Fence Fair Condition- Sherwood H SF needs repaired on the N Sherwood Homes was requested again Silt Fence Fair Condition- Celebrity I prior to the inspection on 1.) SF needs to be tied to 1/2.) SF needs to be re-tied 1/1.) Celebrity Homes was information on 1.) Celebrity Homes was information on 1.	Lot 300 d buffer behind the lot, SF Lot 324 Homes retied the SF prior Lot 326 stalled on the front and sol Lot 328 alled on the front and side eds to be retied to the pose med to complete by 1/21/2 Lot 337 lomes removed the stocky forth end due to power ins lested to repair SF by 10/3 for on 12/2/2014. Lots 426-454 Homes retied the SF to to 2/17/2015. the posts on the front, si to the posts on the north informed to complete by	m the ROW by 12/9/20 12/23/2014 is not needed at this tir 8/30/2014 to inspection on 10/14/ 1/14/2015 th side by Sherwood H 12/15/2014 by Oakwood Homes pr ts as of 1/14/2015. 2015. Not completed as 8/30/2014 sile from the ROW prior tallation as of inspection as 11/8/2012 the posts on the south of and west sides of lot 2/24/2015.	Active Active Active Active 14. Active Active Active in Active Active Active ior to the inspect Active Active ior to the last inspect to inspection on a on 10/23/14. Active	No No Pection. Yes 10/23/14.		

Current Condition:	Fair Condition- Celebrity Homes reinstalled the SF on the side of lot 422 prior to the inspection on 2/17/2015. Excavation has begun on lot 406, but BMPs are not currently needed to the lot being flat as of 2/17/2015. SF needs to be repaired on the north, front side of lot 422.						
	Celebrity Homes was info	rmed to complete by 2/2	24/2015.				
Pod H	Silt Fence	Lots 455-473	12/4/2012	Active	No		
Current Condition:	Good Condition-Erosion eels were reinstalled on the front of lot 460 prior to the inspection on 2/17/2015 by Celebrity Homes.						
Pod I	Silt Fence	Lots 346-355	11/18/2014	Active	No		
Current Condition:	Good Condition-Silt Fence was cleaned out on lot 355 prior to the inspection on 2/17/2015 by Cele Homes.						
Pod J	Silt Fence	Lots 381-394	11/18/2014	Active	Yes		
	 SF needs to be reinstalled and extended to the east on the south side of lot 388. SF needs to be cleaned out at the end of 43rd Street. Celebrity Homes was informed to complete by 12/9/2014. Not completed as of the last inspection. Celebrity Homes was reminded again on 1/14/2015, 2/18/2015. Celebrity Homes was informed to complete by 1/21/2015. Not completed as of the last inspection. Celebrity Homes was reminded again on 2/18/2015. 						
SB 1	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition-30% Filled. Vegetation was removed from the basin and the slopes were seeded and matte by the SID prior to inspection on 10/23/14.						
		N41d00m00s					
SB 3	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition-20% Filled -Cleaned out 02/06						
		N41d00m00s					
SB 5	Sediment Basin	W96d00m00s	11/17/2009	Active	No		
Current Condition:	Good Condition- 15% Filled - JC Excavating installed prior to inspection on 11/18/09.						
STR	Street Cleaning	N41d00m00s W96d00m00s	5/1/2007	Active	No		
Current Condition:	Good Condition- 43rd Str	eet was cleaned up by C	elebrity Homes prior t	o the inpsection	on 2/17/201		
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No		
Current Condition:	Good Condition: 48th and Birchwood Drive						
pector Signature:	Set Se		Reviewed By:	Tadhany L. Jile	k		