E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

# E&A- P2005.198.000 (Clearwater Falls) E&A-P2005.198.009 (Clearwater Falls Trail)

	E&A-P2005.198.009	(Clearwater Falls Ti	rail)		
Inspector: Matthew Russell		•	,		Stage
	Clearw	ater Falls/Clearw	ater Falls Trail		
Project Name:		NER11057	<b>'</b> 3		3
-		9/9/2017			
For Week Ending: Project Location:	48th and	Fairview Road- Bellevu			68123
Project Location.	40tii anu	rall view Road- Bellevu	e, NE (Sarpy County)		00123
Grading:	100%	0%			
Sanitary Sewer:	100%	0%			
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	87%	0%			
	I			l	
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		Maria 4
Sunday:	0.02"				Week 1
Monday	0.02				
Tuesday	0.00"				
Wednesday	0.01"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
	la con				Week 2
Sunday:	0.62"				
Monday Tuesday	<b>2.13"</b> 0.00"	9/22/2047	D.Claudy 77/FF		
Wednesday	0.00"	8/22/2017	P Cloudy 77/55		
Thursday	0.00"				
Friday	0.30"				
Saturday	0.00"				
					Week 3
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
- attai atty	0.00				Week 4
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday					Week 5
Sunday:	N/A				- Week 3
Monday	N/A				
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				
	INI				
Complaints	None				
Complaints:					

# Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

#### What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014);

#### SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

No- see BMP section

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

#### CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No- see BMP section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

#### Comments:

### Comments:

Home Construction is active in the North part of the development by various builders.

#### Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP Section.

· ·	1				T	
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CW 5	Concrete Washout	Lot 387		Removed		
Current Condition:	Removed-Celebrity Homes re		ashout prior to inspection	on 11/12/2015.		
CW 6	Concrete Washout	Lot 359		Removed		
Current Condition:	Removed- Washout pit was removed by Celebrity Homes prior to 3/30/2016.					
CW 7	Concrete Washout	Lot 361		Removed		
Current Condition:	Removed- due to the progression of the site, individual lots will be responsible for their concrete waste Builders will washout on their own lots, if a washout becomes needed the inspector will inform the appl					
	install a washout.					
Lot 16	Individual Lot	Lot 16		Removed		
Current Condition:	Removed- Outlot B was seed	led and matted by Horiz	on Homes prior to 5/27/2	016.		
Lot 17	Individual Lot	Lot 17		Removed		
Current Condition:	Removed- Newport Homes s	odded the lot prior to 11	/12/2015.			
Lot 54	Silt Fence	Lot 54		Removed		
Current Condition:	Removed-Nick Peterson sod		ection on 5/28/15.			
Lot 57	Silt Fence	Lot 57		Removed		
Current Condition:	Removed-Horizon Homes so		pection on 5/28/15.			
Lot 59	Individual Lot	Lot 59		Removed		
Current Condition:	Removed- Horizon Homes so		/12/2015.			
Lot 60	Silt Fence	Lot 60		Removed		
Current Condition:	Removed- Horizon Homes sodded the lot prior to 11/1/16.					
Lot 68	Silt Fence	Lot 68	2/3/2017	Active	No	
Current Condition:	Good Condition- Pacesetter Homes installed silt fence in the rear of the lot prior to 6/28/17. Construction is set to begin on the lot.					
Lot 69	Silt Fence	Lot 69		Removed		
Current Condition:	Removed- Sherwood Homes	Removed- Sherwood Homes sodded the lot prior to 7/13/17.				
Lot 76	Silt Fence	Lot 76		Removed		
Current Condition:	Removed- Lot was sodded by	y Proline Homes prior to	7/31/2015.			

Lot 80	Silt Fence	Lot 80	1	Removed	
Current Condition:	Removed- Horizon Homes	1	1/2015	Removed	
Lot 82	Silt Fence	Lot 82	1/2013.	Removed	
Current Condition:	Removed- Lot was sodded		0/18/2015	Removed	
Lot 88	Silt Fence	Lot 88	T 10/2010.	Removed	
Current Condition:	Removed- Legacy Homes		<u> </u> 	Removed	
	ŭ ,	·	12/10.	· -	
Lot 89	Individual Lot	Lot 89		Removed	
Current Condition:	Removed- the Home Comp	oany sodded the lot prior to	o 11/1/16.		
Lot 132	Silt Fence	Lot 132		Removed	
Current Condition:	Removed- Regency Homes	s sodded the lot prior to 4/	19/2015.	•	'
Lot 155	Silt Fence	Lot 155		Removed	
Current Condition:	Removed- Regency Homes	s sodded the lot prior to 4/	19/2015.		
Lot 209-210	Silt Fence	Lots 209-210		Removed	
Current Condition:	Removed- Celebrity Homes prior to 3/27/17.	·	/1/16. Celebrity Homes		naining silt fence
Lot 255	Individual Lot	Lot 255		Removed	
Current Condition:	Removed - Legacy Homes	sodded the lot prior to the	6/24/15 inspection.		
Lot 256	Silt Fence	Lot 256		Removed	
Current Condition:	Removed- Regency Homes	s sodded the lot prior to 11	/22/16.		
Lot 258	Silt Fence	Lot 258		Removed	
Current Condition:	Removed-Charleston Home		nspection on 5/14/15.		
Lot 259	Silt Fence	Lot 259		Removed	
Current Condition:	Removed-Charleston Home	es sodded the lot prior to i	nspection on 5/14/15.		
Lot 260	Individual Lot	Lot 260		Removed	
Current Condition:	Removed- Sherwood Home	es sodded the lot prior to 5	5/27/2016.		
Lot 261	Individual Lot	Lot 261		Removed	
Current Condition:	Removed- Sherwood Home	es sodded the lot prior to 5	5/27/2016.		
Lot 272	Silt Fence	Lot 272		Removed	
Current Condition:	Removed- Dean Vogel sod	ded the lot prior to 8/12/20	)16.		
Lot 273	Silt Fence	Lot 273		Removed	
Current Condition:	Removed- Sherwood Home		<u> </u> 5/11/17	rtemoved	
Current Condition.	Temoved- one wood Home	T	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,	
Lot 274	Silt Fence	Lot 274		Removed	
Current Condition:	Removed- Regency Homes	s sodded the lot prior to 12	2/14/16.	•	
Lot 275	Temporary Seeding	Lot 275	4/20/2017	Pending	No
Current Condition:	Pending- Dean Vogel distu				
Gunon estimation.	buffer in the rear of the lot t monitor the lot.				
Lot 276	Silt Fence	Lot 276		Removed	
Current Condition:	Removed- Dean Vogel sod		)17.		
	-		1	1	
Lot 277	Silt Fence	Lot 277		Removed	
Current Condition:	Removed- the lot was mista	aken as lot 276 This was a	aiready sodded.		
Lot 280	Silt Fence	Lot 280		Removed	
Current Condition:	Removed - Sherwood Hom	es sodded the lot prior to	inspection on 7/27/17.		
Lot 281	Silt Fence	Lot 281		Removed	
Current Condition:	Removed- Dean Vogel sod	ded the lot prior to 8/12/20	016 and removed the silt	t fence prior to 8/	20/2016.
Lot 284	Silt Fence	Lot 284	1	Removed	
Current Condition:	Removed- Sherwood Home			rtemoved	l
		•			
Lot 282	Silt Fence	Lot 282		Removed	
Current Condition:	Removed- Oakwood Home		n tne rear prior to 7/26/2		
Lot 285	Silt Fence	Lot 285	[/11/17	Removed	
Current Condition:	Removed- Sherwood Home	es soaaea the lot prior to t	0/11/1/.		
Lot 286	Silt Fence	Lot 286		Removed	
Current Condition:	Removed-Sherwood Home	s sodded the lot prior to in	spection on 7/8/15.		
Lot 292	Silt Fence	Lot 292	7/13/2017	Active	No
Current Condition:	Good Condition- Pacesette		<u> </u>	,	
Lot 294	Silt Fence	Lot 294	3/31/2017	Active	Yes

Current Condition:	Fair Condition- Sherwood F 3/31/17. Construction starte		n the rear and along the	south side of the	lot prior to	
	The silt fence in the rear of the lot needs to be cleaned out and retied.					
	Sherwood Homes was info	rmed to complete by 6/21/	17. Not done as of last i	nspection.		
Lot 296	Silt Fence	Lot 296	6/28/2017	Active	No	
Current Condition:	Good Condition- Pine Cres	t Homes removed the stoo	kpile from the ROW pric	or to 7/13/17.		
Lot 297	Silt Fence	Lot 297	7/13/2017	Active	No	
Current Condition:	Good Condition- Pacesette	r Homes installed silt fenc	e in the rear of the lot pri	ior to 7/13/17		
Lot 300	Silt Fence	Lot 300		Removed		
Current Condition:	Removed- Pinecrest Home	s sodded the lot prior to 7/	31/2015.			
Lot 302	Silt Fence	Lot 302	6/28/2017	Active	Yes	
Current Condition:	Fair Condition- Sherwood For the lot prior to 6/28/17.  Silt fence needs to be reti			ilt fence along the	front and rear	
1 -+ 207	Sherwood Homes was inf		<del>29/17.</del>	I Damestad I		
Lot 307  Current Condition:	Silt Fence Removed-Sherwood Home	Lot 307 s sodded the lot prior to 8	<u> </u> /20/2016.	Removed		
Lot 310	Silt Fence	Lot 310		Removed		
Current Condition:	Removed- Sherwood Home		<u> </u> 14/17	Removed		
				Domested		
Lot 314 Current Condition:	Silt Fence Removed - The Home Cor	Lot 314	l or to inspection on 8/2	Removed 22/17.		
Lot 315	Silt Fence	Lot 315		Removed		
Current Condition:	Removed- Legacy Homes		22/16.			
Lot 316	Silt Fence	Lot 316	4/21/2017	Pending	Yes	
Current Condition:	Pending- THC removed the	dirt stockpile from the RC	W prior to 5/1/17.	,		
	THC was informed to comp	lled along the rear of the lolete by 4/21/2017. Not don		THC was reminde	ed on 5/20/17,	
Lot 319	THC was informed to comp 7/14/17. Silt Fence	lete by 4/21/2017. Not dor	ne as of last inspection.	THC was reminded	ed on 5/20/17,	
Lot 319  Current Condition:	THC was informed to comp 7/14/17.	lete by 4/21/2017. Not dor	ne as of last inspection.		ed on 5/20/17,	
Current Condition: Lot 324	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence	lete by 4/21/2017. Not dor  Lot 319 s sodded the lot prior to 9,	ne as of last inspection.  13/2016.		ed on 5/20/17,	
Current Condition:	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home	lete by 4/21/2017. Not dor  Lot 319 s sodded the lot prior to 9,	ne as of last inspection.  13/2016.	Removed	ed on 5/20/17,	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio	ne as of last inspection.  13/2016.  spection on 7/8/15.	Removed     Removed	ed on 5/20/17,	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed- Lot was sodded Silt Fence	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326	ne as of last inspection.  1/3/2016.    spection on 7/8/15.   r to 11/17/2015.	Removed	ed on 5/20/17,	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326	ne as of last inspection.  1/3/2016.    spection on 7/8/15.   r to 11/17/2015.	Removed     Removed	ed on 5/20/17,	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence Removed-Oakwood Homes Removed-Oakwood Homes	Lot 319 s sodded the lot prior to 9 Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s	ne as of last inspection.  (13/2016.  spection on 7/8/15.  r to 11/17/2015.  spection on 7/16/15.  odded the lot prior to ins	Removed Removed Removed Removed Removed Removed	5.	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed- Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto	ne as of last inspection.  (13/2016.  spection on 7/8/15.  r to 11/17/2015.  spection on 7/16/15.  odded the lot prior to ins 3/6/2017  ckpile from the ROW pri	Removed Removed Removed Removed Removed Removed Active For to 5/11/17 and	5.  Yes I installed a	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:  Lot 329	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence Removed-Oakwood Homes Silt Fence Fair Condition- Regency Hogator guard along the front prior to 6/23/17.  Silt fence needs to be instinct the front of the lot.	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto of the lot. Regency Homes talled in the front of the lot	ne as of last inspection.  (13/2016.    spection on 7/8/15.   r to 11/17/2015.   spection on 7/16/15.   odded the lot prior to ins 3/6/2017   ckpile from the ROW prior is reinstalled the gator gator of or the erosion eels in the specific prior to the erosion eels in the specific prior to the erosion eels in the specific prior the erosion else pr	Removed  Removed  Removed  Removed  Removed  Spection on 5/4/15  Active  For to 5/11/17 and aurds along the free	5.  Yes I installed a ont of the lot	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:  Lot 329  Current Condition:	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence Removed-Oakwood Homes Silt Fence Fair Condition- Regency Hogator guard along the front prior to 6/23/17.  Silt fence needs to be instinct the front of the lot.  Regency Homes was info	Lot 319 s sodded the lot prior to 9 Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto of the lot. Regency Homes talled in the front of the later to complete by 8/2	ne as of last inspection.  (13/2016.    spection on 7/8/15.   r to 11/17/2015.   spection on 7/16/15.   odded the lot prior to ins 3/6/2017   ckpile from the ROW prior is reinstalled the gator gator of or the erosion eels in the specific prior to the erosion eels in the specific prior to the erosion eels in the specific prior the erosion else prio	Removed Removed Removed Removed Removed Removed Removed Removed spection on 5/4/15 Active for to 5/11/17 and aurds along the free	5.  Yes I installed a ont of the lot	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:  Lot 329	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence Removed-Oakwood Homes Silt Fence Fair Condition- Regency Hogator guard along the front prior to 6/23/17.  Silt fence needs to be instinct the front of the lot.	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto of the lot. Regency Homes talled in the front of the lot rmed to complete by 8/2.	ne as of last inspection.  1/13/2016.    spection on 7/8/15.   r to 11/17/2015.   spection on 7/16/15.   odded the lot prior to ins 3/6/2017   ckpile from the ROW prior is reinstalled the gator gator of or the erosion eels in 2/2/17.	Removed  Removed  Removed  Removed  Removed  Spection on 5/4/15  Active  For to 5/11/17 and aurds along the free	5.  Yes I installed a ont of the lot	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:  Lot 329  Current Condition:  Lot 339  Current Condition:	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence Removed-Oakwood Homes Silt Fence Removed-Oakwood Homes Silt Fence Fair Condition- Regency Hogator guard along the front prior to 6/23/17.  Silt fence needs to be instin the front of the lot.  Regency Homes was info Temp. Seeding Removed- As of 8/18/2015. Silt Fence	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto of the lot. Regency Homes talled in the front of the lot.  rmed to complete by 8/2 Lot 336 lot has filled in and temp Lot 336	ne as of last inspection.  1/13/2016.    1/13/2016.   1/13/2016.   1/15/2015.   1/16/15/15.   1/16/15/15.   1/16/15/15/15/15/15/15/15/15/15/15/15/15/15/	Removed Removed Removed Removed Removed Removed Removed Removed spection on 5/4/15 Active for to 5/11/17 and aurds along the free	5.  Yes I installed a ont of the lot	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:  Lot 329  Current Condition:  Lot 339  Current Condition:	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence Removed-Oakwood Homes Silt Fence Fair Condition- Regency Hogator guard along the front prior to 6/23/17.  Silt fence needs to be instinct the front of the lot.  Regency Homes was info Temp. Seeding Removed- As of 8/18/2015.	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto of the lot. Regency Homes talled in the front of the lot.  rmed to complete by 8/2 Lot 336 lot has filled in and temp Lot 336	ne as of last inspection.  1/13/2016.    1/13/2016.   1/13/2016.   1/15/2015.   1/16/15/15.   1/16/15/15.   1/16/15/15/15/15/15/15/15/15/15/15/15/15/15/	Removed	5.  Yes I installed a ont of the lot	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:  Lot 329  Current Condition:  Lot 339  Current Condition:  Lot 336  Current Condition:  Lot 336  Current Condition:  Lot 337	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence Removed-Oakwood Homes Silt Fence Removed-Oakwood Homes Silt Fence Fair Condition- Regency Hogator guard along the front prior to 6/23/17.  Silt fence needs to be instin the front of the lot.  Regency Homes was info Temp. Seeding Removed- As of 8/18/2015. Silt Fence Removed- Sherwood Home Silt Fence	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto of the lot. Regency Homes talled in the front of the lot rmed to complete by 8/2 Lot 336 lot has filled in and temp Lot 336 es sodded the lot prior to 1 Lot 336 es sodded the lot prior to 1 Lot 337	ne as of last inspection.  (13/2016.    spection on 7/8/15.   r to 11/17/2015.   spection on 7/16/15.   spection on 7/16/15.   codded the lot prior to ins 3/6/2017   ckpile from the ROW prior or control of the gator gas of or the erosion eels of the code of the lot prior to ins seeding is not needed.	Removed  Removed  Removed  Removed  Removed  Removed  Removed  Spection on 5/4/15  Active  ior to 5/11/17 and aurds along the from the second aurds along the second aurds alon	7es I installed a ont of the lot red/replaced	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:  Lot 329  Current Condition:  Lot 339  Current Condition:  Lot 336  Current Condition:  Lot 336  Current Condition:	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence Removed-Oakwood Homes Silt Fence Removed-Oakwood Homes Silt Fence Fair Condition- Regency Hogator guard along the front prior to 6/23/17.  Silt fence needs to be instinithe front of the lot.  Regency Homes was info Temp. Seeding Removed- As of 8/18/2015. Silt Fence Removed- Sherwood Homes Removed- Sherwood Homes	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto of the lot. Regency Homes talled in the front of the lot rmed to complete by 8/2 Lot 336 lot has filled in and temp Lot 336 es sodded the lot prior to 1 Lot 336 es sodded the lot prior to 1 Lot 337	ne as of last inspection.  (13/2016.    spection on 7/8/15.   r to 11/17/2015.   spection on 7/16/15.   spection on 7/16/15.   codded the lot prior to ins 3/6/2017   ckpile from the ROW prior or control of the gator gas of or the erosion eels of the code of the lot prior to ins seeding is not needed.	Removed  Removed  Removed  Removed  Removed  Removed  Removed  Spection on 5/4/15  Active  ior to 5/11/17 and aurds along the from the second aurds along the second aurds alon	7es I installed a ont of the lot red/replaced	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:  Lot 329  Current Condition:  Lot 339  Current Condition:  Lot 336  Current Condition:  Lot 336  Current Condition:  Lot 337	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt fence Removed-Lot was sodded Silt Fence Removed-Sherwood Home Silt Fence Removed-Oakwood Homes Silt Fence Removed-Oakwood Homes Silt Fence Fair Condition- Regency Hogator guard along the front prior to 6/23/17.  Silt fence needs to be instin the front of the lot.  Regency Homes was info Temp. Seeding Removed- As of 8/18/2015. Silt Fence Removed- Sherwood Home Silt Fence	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto of the lot. Regency Homes talled in the front of the lot rmed to complete by 8/2 Lot 336 lot has filled in and temp Lot 336 es sodded the lot prior to 1 Lot 336 es sodded the lot prior to 1 Lot 337	ne as of last inspection.  (13/2016.    spection on 7/8/15.   r to 11/17/2015.   spection on 7/16/15.   spection on 7/16/15.   codded the lot prior to ins 3/6/2017   ckpile from the ROW prior or control of the gator gas of or the erosion eels of the code of the lot prior to ins seeding is not needed.	Removed  Removed  Removed  Removed  Removed  Removed  Removed  Spection on 5/4/15  Active  ior to 5/11/17 and aurds along the from the second aurds along the second aurds alon	7es I installed a ont of the lot red/replaced	
Current Condition:  Lot 324  Current Condition:  Lot 325  Current Condition:  Lot 326  Current Condition:  Lot 328  Current Condition:  Lot 329  Current Condition:  Lot 336  Current Condition:  Lot 336  Current Condition:  Lot 336  Current Condition:  Lot 337  Current Condition:	THC was informed to comp 7/14/17.  Silt Fence Removed-Sherwood Home Silt Fence Removed-Sherwood Home Silt Fence Removed-Lot was sodded Silt Fence Removed-Lot was sodded Silt Fence Removed-Oakwood Home Silt Fence Removed-Oakwood Homes Silt Fence Fair Condition- Regency He gator guard along the front prior to 6/23/17.  Silt fence needs to be insi in the front of the lot.  Regency Homes was info Temp. Seeding Removed- As of 8/18/2015. Silt Fence Removed- Sherwood Home Silt Fence Removed-Sherwood Home	Lot 319 s sodded the lot prior to 9, Lot 324 s sodded the lot prior to in Lot 325 by Sherwood Homes prio Lot 326 s sodded the lot prior to in Lot 328 s removed silt fence and s Lot 329 comes removed the dirt sto of the lot. Regency Homes talled in the front of the lot Lot 336 lot has filled in and temp Lot 336 es sodded the lot prior to 1 Lot 337 s removed the silt fence and	ne as of last inspection.  1/13/2016.  spection on 7/8/15.  r to 11/17/2015.  spection on 7/16/15.  spection on 7/16/15.  codded the lot prior to ins 3/6/2017  ckpile from the ROW prior serious talled the gator garden of or the erosion eels of the company of the erosion eels of the company of the erosion eels of the erosion	Removed  Removed  Removed  Removed  Removed  Removed  Removed  Spection on 5/4/18  Active  ior to 5/11/17 and aurds along the from the spection on the spection of the spection of the spection on the specific or the specifi	7es I installed a ont of the lot red/replaced	

Current Condition:	Removed-Lots 427 and 428	3 were sodded prior to 12/	1/2015 by Celebrity Hor	nes.	
Pod G	Silt Fence	Lots 404-425		Removed	
Current Condition:	Removed-Lot 404 was sode	ded prior to 6/29/2016. Po	d has been built out.	•	,
Pod H	Silt Fence	Lots 455-473		Removed	
Current Condition:	Removed- Lot 460 was soo		L rior to the inspection on		
Pod I	Silt Fence	Lots 346-355	nor to the inepocion of	Removed	
Current Condition:	Removed-Lot 355 was sode	ded prior to 8/18/2015 by 0	Celebrity Homes.	•	
Pod J	Silt Fence	Lots 381-394		Removed	
Current Condition:	Removed- Lot 385 was soo				
	5/27/2016. Lot 383 was soo was sodded prior to 8/12/20			of 386 prior to 6/2	29/2016. Lot 386
Dod I/	·			Removed	
Pod K  Current Condition:	Silt Fence Removed-Celebrity Homes	Lots 372-403	Lot 370 prior to 9/13/20		silt fence on the
ourient condition.	front of lots 380, 378-376 p		•		
	sodded by Celebrity Homes			•	
	completion of the sidewalk	as of 11/1/16. Celebrity Ho	omes sodded lot 379 pri	or to 11/22/16 co	mpleting the
	pod.				
Pod L	Silt Fence	Lots 371-356		Removed	
Current Condition:	Removed- Silt fence was re	paired in the rear of lot 36	0 prior to 9/13/2016 by	Celebrity Homes	. Lot 365 was
	sodded prior to inspection of				
	repaired on the front of lot 3				
	sodded by Celebrity Homes				
	inspector will monitor for so		, , ,	J	,
	pod.	aag c. a		.,	empreung ure
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No
Current Condition:	Good Condition-45% Filled	Vegetation was removed	from the basin and the	slopes were see	ded and matted
	by the SID prior to inspection	n on 10/23/14.			
SB 3	Sediment Basin	School Lot 165	In Place	Active	No
Current Condition:	Good Condition-20% Filled			•	•
	-Cleaned out 02/06				
SB 5	Sediment Basin	Outlot "L"	11/17/2009	Active	No
Current Condition:	Good Condition- 15% Filled				
	- JC Excavating installed pr	ior to inspection on 11/18/	09.		
	Clearwa	ter Falls Trail			
CD 1	Check Dam	Northern side of site	10/2/2017	Pending	No
Current Condition:	Check Dam Pending - BMP will be ins	Northern side of site talled once grading has	begun on site.		
Current Condition: EM 1	Check Dam Pending - BMP will be ins Sediment Basin	Northern side of site talled once grading has East side of site	begun on site. 10/2/2017	Pending Pending	No No
Current Condition: EM 1 Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has	begun on site. 10/2/2017 begun on site.	Pending	No
Current Condition: EM 1 Current Condition: EM 2	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin	Northern side of site talled once grading has East side of site talled once grading has West side of site	begun on site. 10/2/2017 begun on site. 10/2/2017		
Current Condition: EM 1 Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has West side of site	begun on site. 10/2/2017 begun on site. 10/2/2017	Pending	No
Current Condition: EM 1 Current Condition: EM 2 Current Condition: SF 1 Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has	pegun on site. 10/2/2017 pegun on site. 10/2/2017 pegun on site. 10/2/2017 pegun on site.	Pending Pending Pending	No No
Current Condition: EM 1 Current Condition: EM 2 Current Condition: SF 1 Current Condition: SF 2	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site	pegun on site. 10/2/2017 pegun on site. 10/2/2017 pegun on site. 10/2/2017 pegun on site. 10/2/2017	Pending   Pending	No No
Current Condition: EM 1 Current Condition: EM 2 Current Condition: SF 1 Current Condition: SF 2 Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has	Degun on site. 10/2/2017 Degun on site.	Pending Pending Pending Pending	No No No
Current Condition: EM 1 Current Condition: EM 2 Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has	Degun on site. 10/2/2017	Pending Pending Pending	No No
Current Condition: EM 1 Current Condition: EM 2 Current Condition: SF 1 Current Condition: SF 2 Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has	Degun on site. 10/2/2017	Pending Pending Pending Pending	No No No
Current Condition: EM 1 Current Condition: EM 2 Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site	Degun on site.  10/2/2017 Degun on site.	Pending Pending Pending Pending Pending Pending	No No No No No No
Current Condition: EM 1 Current Condition: EM 2 Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: IP 1	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Souther side of site	Degun on site.  10/2/2017 Degun on site.	Pending Pending Pending Pending Pending	No No No No
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  SF 4  Current Condition:  SF 4  Current Condition:  SF 4  Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has	Degun on site.  10/2/2017	Pending Pending Pending Pending Pending Pending Pending Pending	No No No No No No No
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has souther side of site talled once grading has streets	Degun on site.  10/2/2017 Degun on site.  5/1/2007	Pending Pending Pending Pending Pending Pending Active	No No No No No No No Yes
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  SF 4  Current Condition:  SF 4  Current Condition:  SF 4  Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has streets	Degun on site.  10/2/2017 Degun on site.  5/1/2007 The street in front of logun on site.	Pending Pending Pending Pending Pending Pending Active	No No No No No No No Yes
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has streets	Degun on site.  10/2/2017 Degun on site.  5/1/2007 The street in front of logun on site.	Pending Pending Pending Pending Pending Pending Active	No No No No No No No Yes
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has streets Homes scraped up dirt frout from along lot 292 prior	Degun on site.  10/2/2017 Degun on site.  5/1/2007 The street in front of logun on site.	Pending Pending Pending Pending Pending Pending Active	No No No No No No No Yes
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Street Cleaning Fair Condition- Pacesetter I Homes cleaned the track of	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has streets  Homes scraped up dirt from the formal ong lot 292 prior oved from along lot 329.	begun on site.  10/2/2017 begun on site.  5/1/2007 m the street in front of lot to 7/13/17.	Pending Pending Pending Pending Pending Pending Pending Active pt 297 prior to 6/1	No No No No No Yes 9/17. Pacetter
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Street Cleaning Fair Condition- Pacesetter I Homes cleaned the track of Sediment needs to be remo	Northern side of site talled once grading has been side of site talled once grading has west side of site talled once grading has southern side of site talled once grading has souther side of site talled once grading has souther side of site talled once grading has souther side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets	begun on site.  10/2/2017 begun on site.  5/1/2007 m the street in front of lot to 7/13/17.	Pending Pending Pending Pending Pending Pending Pending Active pt 297 prior to 6/1	No No No No No Yes 9/17. Pacetter
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Street Cleaning Fair Condition- Pacesetter I Homes cleaned the track of	Northern side of site talled once grading has been side of site talled once grading has west side of site talled once grading has southern side of site talled once grading has souther side of site talled once grading has souther side of site talled once grading has souther side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets	begun on site.  10/2/2017 begun on site.  5/1/2007 m the street in front of lot to 7/13/17.	Pending Pending Pending Pending Pending Pending Pending Active pt 297 prior to 6/1	No No No No No Yes 9/17. Pacetter
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Street Cleaning Fair Condition- Pacesetter I Homes cleaned the track of Sediment needs to be remo	Northern side of site talled once grading has been side of site talled once grading has west side of site talled once grading has southern side of site talled once grading has souther side of site talled once grading has souther side of site talled once grading has souther side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets  Homes scraped up dirt from the side of site talled once grading has streets	begun on site.  10/2/2017 begun on site.  5/1/2007 m the street in front of lot to 7/13/17.	Pending Pending Pending Pending Pending Pending Pending Active pt 297 prior to 6/1	No No No No No Yes 9/17. Pacetter
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR  Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Street Cleaning Fair Condition- Pacesetter Homes cleaned the track of Sediment needs to be remo	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has streets  Homes scraped up dirt from along lot 292 prior oved from along lot 329.  The detection of side to complete by 5/24/17.	pegun on site.  10/2/2017 pegun on site.  5/1/2007 m the street in front of lot to 7/13/17.	Pending Pending Pending Pending Pending Pending Pending Active to 297 prior to 6/1	No No No No No No Yes 9/17. Pacetter
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Street Cleaning Fair Condition- Pacesetter I Homes cleaned the track of Sediment needs to be remo	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has streets Homes scraped up dirt from the streets of site talled once grading has streets Homes scraped up dirt from the street of the street	begun on site.  10/2/2017 begun on site.  5/1/2007 m the street in front of lot to 7/13/17.	Pending Pending Pending Pending Pending Pending Pending Active pt 297 prior to 6/1	No No No No No Yes 9/17. Pacetter
Current Condition:  EM 1  Current Condition:  EM 2  Current Condition:  SF 1  Current Condition:  SF 2  Current Condition:  SF 3  Current Condition:  SF 4  Current Condition:  IP 1  Current Condition:  STR  Current Condition:  STR  Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has streets Homes scraped up dirt from the streets of site talled once grading has streets Homes scraped up dirt from the street of the street	pegun on site.  10/2/2017 pegun on site.  5/1/2007 m the street in front of lot to 7/13/17.	Pending Pending Pending Pending Pending Pending Pending Active to 297 prior to 6/1	No No No No No No Yes 9/17. Pacetter
Current Condition: EM 1 Current Condition: EM 2 Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: IP 1 Current Condition: STR Current Condition: STR Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has streets Homes scraped up dirt from the streets of site talled once grading has streets Homes scraped up dirt from the street of the street	pegun on site.  10/2/2017 pegun on site.  5/1/2007 m the street in front of lot to 7/13/17.	Pending Pending Pending Pending Pending Pending Pending Pending Active Active Active	No No No No No No Yes 9/17. Pacetter
Current Condition: EM 1 Current Condition: EM 2 Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition: IP 1 Current Condition: STR Current Condition: STR Current Condition:	Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Check Dam Pending - BMP will be ins Check Dam Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Sediment Basin Pending - BMP will be ins Street Cleaning Fair Condition- Pacesetter Homes cleaned the track of Sediment needs to be remo	Northern side of site talled once grading has East side of site talled once grading has West side of site talled once grading has Southern side of site talled once grading has Souther side of site talled once grading has Souther side of site talled once grading has Northern side of site talled once grading has Northern side of site talled once grading has Souther side of site talled once grading has streets Homes scraped up dirt from the streets of site talled once grading has streets Homes scraped up dirt from the street of the street	pegun on site.  10/2/2017 pegun on site.  5/1/2007 m the street in front of lot to 7/13/17.	Pending Pending Pending Pending Pending Pending Pending Active to 297 prior to 6/1	No No No No No No Yes 9/17. Pacetter