E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

		.000 (Clearwater Falls 9 (Clearwater Falls Ti			
Inspector: Matthew Russell					Stage
	Clear	water Falls/Clearw	ater Falls Trail		
Project Name:	CSW-201701144				3 and 2
· · ·					
For Week Ending:	404h an	10/14/2017 - 9/			
Project Location:	48th an	d Fairview Road- Bellevu	e, NE (Sarpy County)		68123
Grading:	100%	6 10%			
Sanitary Sewer:	100%				
Storm Sewer:	100%	6 0%			
Paving:	100%				
Seeding:	1009				
Utilities:	1009				
Overall Development:	87%	6 0%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
					Week '
Sunday:	0.00"				
Monday	0.00"	40/04/47	01		
Tuesday Wednesday	0.00"	10/24/17	Clear 54/39		
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				Mook
Sunday:	0.00"				Week 3
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
outuruuy	0.00				Week 4
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week {
Sunday:	N/A				
Monday	N/A			_	
Tuesday	N/A				
Wednesday	N/A			4	
Thursday	N/A			-	
Friday	N/A			_	
Saturday	N/A				

	None				
Complaints:					
Construction Sequencing:		•			
Which portion(s) (i.e. drainage basins) of the site have h	ad a temporary or permanent ces	sation of grading, earthwork,	or ground disturbance in th	e last 14 days?	
Grading completed and entire site seeded prior to	o 2005.				
Entire Site; JC Excavating completed grading Lo	s 346 through 480 Section II	, drainage area 1 and 2 (1	1/2009).		
Entire site is now inactive for major grading activity	ties as of the inspection on 1	1/20/2013.			
Which portion(s) (i.e. drainage basins) of the site do not		nd disturbance scheduled in	the next 14 days? :		
Grading completed and entire site seeded prior to					
Entire Site; JC Excavating completed grading Lo	0		1/2009).		
Entire site is now inactive for major grading activity	ties as of the inspection on 1	1/20/2013.	· · · · · · · · · · · · · · · · · · ·		
What temporary or permanent stabilization measures lis					
Paving, dense vegetation and landscaping, Seed		•	· · ·	· · · ·	
lots 346-480, seeded (4/10); Outlot B was seeded					
and 43rd Avenue was temp seeded (5/22/2014);	-	lied on the South side of C	Jutiot L (8/4/2014); Matti	ng nas been inst	alled on the
side slopes surrounding outlot M Basin (12/15/20	14);				
SUMMARY QUESTIONS:					
Are approved entrances and adjacent streets being main	tained adequately?				
No- see BMP section					
Are receiving waters adjacent to the project free of any	significant signs of erosion or se	diment that would be associa	ted with the construction ac	tivity?	
Yes	1				
CHECKLIST QUESTIONS: Are waste materials (concrete, construction material, ha	zardous, etc.) being managed pro	anerly2			
No- see BMP section.	zaruous, etc.) being manageu pro	openy:			
Is dust associated with the construction activity adequa	tely controlled on the site?	•			
Yes	1	1	1		
Common control					
Comments:					
Comments:	h				
	he development by various b	ouilders.			
Comments: Home Construction is active in the North part of t		ouilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe		puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date):		puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):	ction on 10/24/17.	puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date):	ction on 10/24/17.	puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):	ction on 10/24/17.	puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):	ction on 10/24/17.	puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):	ction on 10/24/17.	Location	Projected Install Date	Status	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se	ction on 10/24/17. ction. Type Concrete Washout	Location Lot 387	-	Removed	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes	Location Lot 387 removed the concrete wa	-	Removed on 11/12/2015.	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout	Location Lot 387 removed the concrete wa Lot 359	shout prior to inspection	Removed	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes	Location Lot 387 removed the concrete wa Lot 359	shout prior to inspection	Removed on 11/12/2015.	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho	shout prior to inspection	Removed on 11/12/2015. Removed	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361	shout prior to inspection mes prior to 3/30/2016.	Removed on 11/12/2015. Removed Removed	
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible	Removed on 11/12/2015. Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible	Removed on 11/12/2015. Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the install a washout.	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 sssion of the site, individua ir own lots, if a washout b	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible	Removed on 11/12/2015. Removed Removed of for their concre bector will inform	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the Builders will washout on the install a washout. Individual Lot	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp	Removed on 11/12/2015. Removed Removed of their concre vector will inform Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout on the puilders will washout on the install a washout. Individual Lot Removed- Outlot B was see	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp	Removed on 11/12/2015. Removed for their concre vector will inform Removed 016.	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 16	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout on the pinstall a washout. Individual Lot Removed- Outlot B was see Individual Lot	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2	Removed on 11/12/2015. Removed Removed of their concre vector will inform Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition:	ction on 10/24/17. Ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2	Removed on 11/12/2015. Removed e for their concre sector will inform Removed 016. Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 7 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54	ction on 10/24/17. Ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Pit Washout Removed- Washout pit Washout Removed- due to the progres Builders will Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015.	Removed on 11/12/2015. Removed for their concre vector will inform Removed 016.	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition:	ction on 10/24/17. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Nick Peterson so	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015.	Removed on 11/12/2015. Removed e for their concre pector will inform Removed 016. Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout on the progre Builders will washout on the progre Builders will washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Nick Peterson so Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 esded and matted by Horizo Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 ded the lot prior to inspe- Lot 57	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015.	Removed on 11/12/2015. Removed e for their concre sector will inform Removed 016. Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Nick Peterson so Silt Fence Removed-Horizon Homes s	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 esded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe- Lot 57 odded the lot prior to inspe-	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015.	Removed on 11/12/2015. Removed e for their concre bector will inform Removed 016. Removed Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57 Current Condition: Lot 57 Current Condition: Lot 59	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to inspe Lot 59	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ection on 5/28/15.	Removed on 11/12/2015. Removed e for their concre pector will inform Removed 016. Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57 Current Condition: Lot 59 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Concenter S Conc	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizc Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to insp Lot 59 sodded the lot prior to insp Lot 59	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ection on 5/28/15.	Removed on 11/12/2015. Removed for their concre vector will inform Removed 016. Removed Removed Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 7 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 54 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 60	ction on 10/24/17. Ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Nick Peterson so Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to inspe Lot 59 sodded the lot prior to inspe Lot 59 sodded the lot prior to 11/ Lot 59	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ection on 5/28/15.	Removed on 11/12/2015. Removed e for their concre bector will inform Removed 016. Removed Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua is solved the lot prior to inspe Lot 59 sodded the lot prior to 11/ Lot 60 sodded the lot prior to 11/	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ection on 5/28/15. 12/2015.	Removed on 11/12/2015. Removed for their concre bector will inform Removed 016. Removed Removed Removed Removed	te waste. the applicant to
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 68	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the install a washout. Individual Lot Removed-Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to inspe Lot 59 sodded the lot prior to 11/ Lot 60 sodded the lot prior to 11/ Lot 68	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ction on 5/28/15. 12/2015. 12/2015. 12/2015.	Removed on 11/12/2015. Removed for their concre bector will inform Removed 016. Removed Removed Removed Removed Removed	te waste. the applicant to
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to inspe Lot 59 sodded the lot prior to 11/ Lot 60 sodded the lot prior to 11/ Lot 68	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ction on 5/28/15. 12/2015. 12/2015. 12/2015.	Removed on 11/12/2015. Removed for their concre bector will inform Removed 016. Removed Removed Removed Removed Removed	te waste. the applicant to
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 68	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the install a washout. Individual Lot Removed-Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to inspe Lot 59 sodded the lot prior to 11/ Lot 60 sodded the lot prior to 11/ Lot 68	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ction on 5/28/15. 12/2015. 12/2015. 12/2015.	Removed on 11/12/2015. Removed for their concre bector will inform Removed 016. Removed Removed Removed Removed Removed	te waste. the applicant to

1.100	0.11 E	1 1 00			
Lot 69 Current Condition:	Silt Fence Removed- Sherwood Home	Lot 69	7/12/17	Removed	
Current Condition:	Removed- Sherwood Home		/13/17.		
Lot 76	Silt Fence	Lot 76		Removed	
Current Condition:	Removed- Lot was sodded		7/31/2015.		
Lot 80 Current Condition:	Silt Fence Removed- Horizon Homes	Lot 80	1/2015	Removed	
Lot 82	Silt Fence	Lot 82	1/2015.	Removed	
Current Condition:	Removed- Lot was sodded		9/18/2015.		
Lot 88	Silt Fence	Lot 88		Removed	
Current Condition:	Removed- Legacy Homes s	odded the lot prior to 11/2	22/16.		
Lot 89	Individual Lot	Lot 89		Removed	
Current Condition:	Removed- the Home Comp	any sodded the lot prior to	o 11/1/16.		
Lot 132	Silt Fence	Lot 132		Removed	
Current Condition:	Removed- Regency Homes		19/2015.		
Lot 155	Silt Fence	Lot 155	10/00/15	Removed	
Current Condition: Lot 209-210	Removed- Regency Homes Silt Fence	Lots 209-210	19/2015. I	Removed	
Current Condition:	Removed- Celebrity Homes		/1/16. Celebrity Homes		aining silt fence
	prior to 3/27/17.				
Lot 255	Individual Lot	Lot 255		Removed	
Current Condition:	Removed - Legacy Homes	sodded the lot prior to the	6/24/15 inspection.	1 1	
Lot 256	Silt Fence	Lot 256		Removed	
Current Condition:	Removed- Regency Homes	sodded the lot prior to 11	/22/16.		
Lot 258	Silt Fence	Lot 258		Removed	
Current Condition:	Removed-Charleston Home		nspection on 5/14/15.		
Lot 259	Silt Fence	Lot 259		Removed	
Current Condition:	Removed-Charleston Home	es sodded the lot prior to i	nspection on 5/14/15.		
Lot 260	Individual Lot	Lot 260		Removed	
Current Condition:	Removed- Sherwood Home		5/27/2016.		
Lot 261	Individual Lot	Lot 261		Removed	
Current Condition:	Removed- Sherwood Home		5/27/2016.		
Lot 272 Current Condition:	Silt Fence Removed- Dean Vogel sode	Lot 272	1	Removed	
			T		
Lot 273	Silt Fence	Lot 273		Removed	
Current Condition:	Removed- Sherwood Home	es sodded the lot prior to a	5/11/17. T	1	
Lot 274	Silt Fence	Lot 274		Removed	
Current Condition:	Removed- Regency Homes	sodded the lot prior to 12	2/14/16.		
Lot 275	Temporary Seeding	Lot 275	4/20/2017	Pending	No
Current Condition:	Pending- Dean Vogel distur buffer in the rear of the lot the monitor the lot.				
Lot 276	Silt Fence	Lot 276		Removed	
Current Condition:	Removed- Dean Vogel sod	ded the lot prior to 4/14/20)17.		
Lot 277	Silt Fence	Lot 277		Removed	
Current Condition:	Removed- the lot was mista	ken as lot 276 This was a	Iready sodded.		
Lot 280	Silt Fence	Lot 280		Removed	
Current Condition:	Removed - Sherwood Hom	es sodded the lot prior to	inspection on 7/27/17.		
Lot 281	Silt Fence	Lot 281		Removed	
Current Condition:	Removed- Dean Vogel sode	ded the lot prior to 8/12/20)16 and removed the silt	fence prior to 8/2	20/2016.
Lot 284	Silt Fence	Lot 284	1	Removed	
Current Condition:	Removed- Sherwood Home		5/27/2016.	Removed	
Lot 282	Silt Fence	Lot 282		Removed	
Current Condition:	Removed- Oakwood Home		the rear prior to 7/26/20		
Lot 285	Silt Fence	Lot 285		Removed	
Current Condition:	Removed- Sherwood Home		5/11/17.		
Lot 286	Silt Fence	Lot 286		Removed	
Current Condition:	Removed-Sherwood Home		spection on 7/8/15.		
Lot 292	Silt Fence	Lot 292		Removed	
Current Condition:	Removed - Pacesetter Hom Silt Fence	les sodded the lot prior to Lot 294	inspection on 10/9/17.	Removed	

Current Condition:	Removed - Sherwood Homes s	odded the lot prior to i	inspection on 10/9/17.		
Lot 296	Silt Fence	Lot 296	6/28/2017	Active	Yes
Current Condition:	Fair Condition- Pine Crest Hom	es removed the stock	pile from the ROW prior	to 7/13/17.	
	Silt fence in the rear of the lot no	anda to be ratiad			
		eeus lo be relieu.			
	Pinecrest Homes was informed	to complete by 9/26/1	7. Not done as of last in	spection.	
Lot 297	Silt Fence	Lot 297	7/13/2017	Active	No
Current Condition:	Good Condition- Pacesetter Ho	mes installed silt fence	e in the rear of the lot pr	ior to 7/13/17	
Lot 300	Silt Fence	Lot 300		Removed	
Current Condition:	Removed- Pinecrest Homes so		<u> </u> 31/2015.	Rellioved	
Lot 302	Silt Fence	Lot 302	6/28/2017	Active	No
Current Condition:	Good Condition- Sherwood Hor				
	rear of the lot prior to 6/28/17. S				
Lot 307	Silt Fence	Lot 307		Removed	
Current Condition:	Removed-Sherwood Homes so	dded the lot prior to 8/	20/2016.		
Lot 310	Silt Fence	Lot 310		Removed	
Current Condition:	Removed- Sherwood Home so	ded the lot prior to 6/	14/17.		
Lot 314	Silt Fence	Lot 314		Removed	
Current Condition:	Removed - The Home Compan		to inspection on 8/22/17		
Lot 315	Silt Fence	Lot 315		Removed	
Current Condition:	Removed- Legacy Homes sodd	ed the lot prior to 11/2	22/16.	•	
Lot 316	Silt Fence	Lot 316		Removed	
Current Condition:	Removed - THC sodded the lot		9/19/17.	Removed	
Lot 319	Silt Fence	Lot 319		Removed	
Current Condition:	Removed-Sherwood Homes so	dded the lot prior to 9/	13/2016.		
Lot 324	Silt Fence	Lot 324		Removed	
Current Condition:	Removed-Sherwood Homes so		spection on 7/8/15.		
Lot 325 Current Condition:	Silt fence Removed- Lot was sodded by S	Lot 325	r to 11/17/2015	Removed	
Lot 326	Silt Fence	Lot 326		Removed	
Current Condition:	Removed-Sherwood Homes so		spection on 7/16/15.		
Lot 328	Silt Fence Removed-Oakwood Homes ren	Lot 328	added the lateriar to inc	Removed	
Current Condition:		Lot 329		Active	
Lot 329	Slit Fence				Yes
Lot 329 Current Condition:	Silt Fence Fair Condition- Regency Homes				
	Fair Condition- Regency Homes gator guard along the front of th	e lot. Regency Homes	s reinstalled the gator ga	urds along the fro	installed a ont of the lot
	Fair Condition- Regency Homes	e lot. Regency Homes	s reinstalled the gator ga	urds along the fro	installed a ont of the lot
	Fair Condition- Regency Homes gator guard along the front of th	e lot. Regency Homes s replaced the erosio	s reinstalled the gator ga n eels around the lot pri	aurds along the fro or to inspection or	installed a ont of the lot
	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Home The erosion eels along the front	e lot. Regency Homes as replaced the erosio t of the lot are damage	s reinstalled the gator ga n eels around the lot pri ed and need to be replac	aurds along the fro or to inspection or	installed a ont of the lot
Current Condition: Lot 336	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Home The erosion eels along the front Regency Homes was informed Temp. Seeding	e lot. Regency Homes as replaced the erosio to the lot are damage to complete by 10/16/ Lot 336	s reinstalled the gator ga n eels around the lot pri ed and need to be replac 17.	aurds along the fro or to inspection or	installed a ont of the lot
Current Condition: Lot 336 Current Condition:	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Home The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I	e lot. Regency Homes is replaced the erosio to the lot are damage to complete by 10/16/ Lot 336 mas filled in and temp	s reinstalled the gator ga n eels around the lot pri ed and need to be replac 17.	urds along the fro or to inspection or ced.	installed a ont of the lot
Current Condition: Lot 336 Current Condition: Lot 336	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Home The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence	e lot. Regency Homes se replaced the erosio to the lot are damage to complete by 10/16/ Lot 336 has filled in and temp Lot 336	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. 17. Seeding is not needed.	aurds along the from the from the from the inspection of the section of the secti	installed a ont of the lot
Current Condition: Lot 336 Current Condition:	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Home The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I	e lot. Regency Homes is replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 odded the lot prior to 1	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. 17. Seeding is not needed.	urds along the fro or to inspection or ced.	installed a ont of the lot
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Silt Fence Silt Fence	e lot. Regency Homes s replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 odded the lot prior to 1 Lot 337	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. Seeding is not needed. 0/6/16.	aurds along the from from the inspection of the section of the sec	installed a ont of the lot n 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition:	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Removed- Sherwood Homes so	e lot. Regency Homes s replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 odded the lot prior to 1 Lot 337	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. Seeding is not needed. 0/6/16.	aurds along the from from the inspection of the section of the sec	installed a ont of the lot n 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition:	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Silt Fence Removed-Sherwood Homes represented	e lot. Regency Homes s replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 odded the lot prior to 1 Lot 337 moved the silt fence a	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. Seeding is not needed. 0/6/16.	along the from the inspection of the inspectin of the inspection of the inspection of the	installed a ont of the lot n 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Silt Fence Silt Fence	e lot. Regency Homes is replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 bdded the lot prior to 1 Lot 337 moved the silt fence a Lot 344	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. 17. 17. 17. 17. 17. 17. 17. 17. 17.	aurds along the from from the inspection of the section of the sec	installed a ont of the lot n 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Silt Fence Removed- Sherwood Homes ref Silt Fence	e lot. Regency Homes is replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 bdded the lot prior to 1 Lot 337 moved the silt fence a Lot 344	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. 17. 17. 17. 17. 17. 17. 17. 17. 17.	along the from the inspection of the inspectin of the inspection of the inspection of the	installed a ont of the lot n 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition:	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Removed- Sherwood Homes represent Silt Fence Removed-Sherwood Homes represent Silt Fence Removed-the Home Company	e lot. Regency Homes is replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 bdded the lot prior to 1 Lot 337 moved the silt fence a Lot 344 sodded the lot prior to	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. 17. 17. 17. 17. 17. 17. 17. 10. 10. 10. 10. 10. 10. 10. 10. 10. 11. 11	nurds along the from the inspection of the inspecting data and the inspecting data and the inspecting data	installed a ont of the lot n 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F Current Condition:	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Removed- Sherwood Homes so Silt Fence Silt Fence Removed- Sherwood Homes rel Silt Fence Removed- the Home Company Silt Fence Removed- Lots 427 and 428 we	e lot. Regency Homes as replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 bdded the lot prior to 1 Lot 337 moved the silt fence a Lot 344 sodded the lot prior to Lots 426-454 re sodded prior to 12/	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. 17. 17. 17. 17. 17. 17. 17. 10. 10. 10. 10. 10. 10. 10. 10. 10. 11. 11	nurds along the from the inspection of the inspection of the sed. Removed	installed a ont of the lot n 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Removed- Sherwood Homes ref Silt Fence Removed-Sherwood Homes ref Silt Fence Silt Fence	e lot. Regency Homes is replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 bdded the lot prior to 1 Lot 337 moved the silt fence a Lot 344 sodded the lot prior to Lots 426-454 re sodded prior to 12/ Lots 404-425	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. seeding is not needed. 0/6/16. nd sodded the lot prior t 0 11/1/16. 1/2015 by Celebrity Hon	nurds along the from the inspection of the inspecting data and the inspecting data and the inspecting data	installed a ont of the lot n 9/19/17.
Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F Current Condition: Pod G Current Condition:	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Removed- Sherwood Homes ref Silt Fence Removed- Sherwood Homes ref Silt Fence Removed- the Home Company Silt Fence Removed-Lots 427 and 428 we Silt Fence Removed-Lot 404 was sodded	e lot. Regency Homes is replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 bdded the lot prior to 1 Lot 337 moved the silt fence a Lot 344 sodded the lot prior to Lots 426-454 re sodded prior to 12/ Lots 404-425 prior to 6/29/2016. Po	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. seeding is not needed. 0/6/16. nd sodded the lot prior t 0 11/1/16. 1/2015 by Celebrity Hon	nurds along the from the inspection of the inspection of the inspection of the inspection of the inspection on 5/ Removed	installed a ont of the lot n 9/19/17.
Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F Current Condition: Pod G Current Condition: Pod H	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Removed- Sherwood Homes ref Silt Fence Removed- Sherwood Homes ref Silt Fence Removed- the Home Company Silt Fence Removed-Lots 427 and 428 we Silt Fence Removed-Lot 404 was sodded Silt Fence	e lot. Regency Homes is replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 bidded the lot prior to 1 Lot 337 moved the silt fence a Lot 344 sodded the lot prior to 12/ Lots 426-454 re sodded prior to 12/ Lots 404-425 prior to 6/29/2016. Po Lots 455-473	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. Seeding is not needed. 0/6/16. 0/6/16. 11/1/1/16. 1/2015 by Celebrity Hon 1/2015 by Celebrity Hon d has been built out.	nurds along the from the inspection of the inspection of the inspection of the inspection of the inspection on 5/ Removed	installed a ont of the lot n 9/19/17.
Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F Current Condition: Pod G Current Condition:	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Removed- Sherwood Homes ref Silt Fence Removed- Sherwood Homes ref Silt Fence Removed- the Home Company Silt Fence Removed-Lots 427 and 428 we Silt Fence Removed-Lot 404 was sodded	e lot. Regency Homes is replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 bidded the lot prior to 1 Lot 337 moved the silt fence a Lot 344 sodded the lot prior to 12/ Lots 426-454 re sodded prior to 12/ Lots 404-425 prior to 6/29/2016. Po Lots 455-473	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. Seeding is not needed. 0/6/16. 0/6/16. 11/1/1/16. 1/2015 by Celebrity Hon 1/2015 by Celebrity Hon d has been built out.	nurds along the from the inspection of the inspection of the inspection of the inspection of the inspection on 5/ Removed	installed a ont of the lot n 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F Current Condition: Pod G Current Condition: Pod H Current Condition:	Fair Condition- Regency Homes gator guard along the front of th prior to 6/23/17. Regency Homes The erosion eels along the front Regency Homes was informed Temp. Seeding Removed- As of 8/18/2015, lot I Silt Fence Removed- Sherwood Homes sc Silt Fence Removed- Sherwood Homes rei Silt Fence Removed- the Home Company Silt Fence Removed- Lots 427 and 428 we Silt Fence Removed-Lot 404 was sodded Silt Fence Removed-Lot 404 was sodded	e lot. Regency Homes se replaced the erosio to complete by 10/16/ Lot 336 has filled in and temp Lot 336 bdded the lot prior to 1 Lot 337 moved the silt fence a Lot 344 sodded the lot prior to 12/ Lots 426-454 re sodded prior to 12/ Lots 404-425 prior to 6/29/2016. Po Lots 455-473 by Celebrity Homes p Lots 346-355	s reinstalled the gator ga n eels around the lot prive ad and need to be replace 17. seeding is not needed. 0/6/16. 0/6/16. 1/2015 by Celebrity Hon 1/2015 by Celebrity Hon d has been built out.	nurds along the from the inspection of the inspection of the inspection of the inspection of the inspection on 5/ Removed	installed a ont of the lot n 9/19/17.

Current Condition:	Removed- Lot 385 was sod 5/27/2016. Lot 383 was sod was sodded prior to 8/12/20	ded and the silt fence wa	s repaired on the sides o		
Pod K	Silt Fence	Lots 372-403		Removed	
Current Condition:	Removed-Celebrity Homes front of lots 380, 378-376 pr sodded by Celebrity Homes completion of the sidewalk a pod.	installed new silt fence or ior to 9/13/2016. Lot 380, prior to 11/1/16. The silt	376, and 377 were sode fence on the front of lot 3	16 and removed ded prior to 9/26/ 379 isn't needed a	16. Lot 378 was anymore due to
Pod L	Silt Fence	Lots 371-356		Removed	
Current Condition:	Removed- Silt fence was re sodded prior to inspection of repaired on the front of lot 3 sodded by Celebrity Homes and on the front of the lots p inspector will monitor for so pod.	n 9/26/16. Silt fence was 60 prior to inspection on prior to 11/1/16. Celebrit prior to 11/1/16 presumab	reinstalled on the front of 9/26/16 by Celebrity Hor y Homes removed the si ly in preparation for sode	of lots 359, and 36 nes. Lot 262, and llt fence behind lo ding as the lots we	64, and 263 were ts 359-364 ere fine graded;
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No
Current Condition:	Good Condition-45% Filled. by the SID prior to inspectio inspection on 9/19/17.				
SB 3	Sediment Basin	School Lot 165	In Place	Active	No
Current Condition:	Good Condition-20% Filled -Cleaned out 02/06				
SB 5	Sediment Basin	Outlot "L"	11/17/2009	Active	No
Current Condition:	Good Condition- 15% Filled - JC Excavating installed pr		/09.		
		ter Falls Trail			
CD 1	Check Dam	Northern side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta				N
EM 1	Erosion Control Matting	East side of site	10/2/2017	Pending	No
Current Condition: EM 2	Pending - BMP will be insta Erosion Control Matting	West side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta			r chaing [110
SF 1	Silt Fence	Southern side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta				
SF 2	Silt Fence	Souther side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta		gun on site. 10/2/2017	Den dia a	NI-
SF 3 Current Condition:	Silt Fence Pending - BMP will be insta	Souther side of site		Pending	No
SF 4	Silt Fence	Northern side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta			l chang l	
IP 1	Inlet Protection	Souther side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta	lled once grading has beg	jun on site.	14) 	
STR	Street Cleaning	streets	5/1/2007	Active	No
Current Condition:	Good Condition- Pacesetter Homes cleaned the track of front of lot 329. Track out w	ut from along lot 292 prior	to 7/13/17. Regency Ho	mes cleaned the	
	0:	1 aigm!+-	0 10 00	A ather	NI -
SWPPP Sign Current Condition:	Signs Good Condition: 48th and B	1 sign on site	8-19-08	Active	No
			Reviewed By:	Costo de	ie.