E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

		000 (Clearwater Falls (Clearwater Falls Ti			
Inspector: Matthew Russell					
	Clearv	vater Falls/Clearw	ater Falls Trail		0
Project Name:	CSW-201701144				3 and 2
-	11/11/2017 - 11/11/17				
For Week Ending: Project Location:	48th and Fairview Road- Bellevue, NE (Sarpy County)				00400
	4011 410	Failview Roau- Bellevu	e, NE (Sarpy County)		68123
Grading:	100%	10%			
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding: Utilities:	100%				
Overall Development:	100%				
	0170	070			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
					Week 1
Sunday:	0.00"				
Monday	0.00"	40/04/47	Ole en 54/20		
Tuesday Wednesday	0.00"	10/24/17	Clear 54/39		
Thursday	0.00"				
Friday	0.00"				
Saturday	0.15"				
					Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
Quadau					Week 3
Sunday:	0.00"				
Monday	0.00"				
Tuesday	MM"				
Wednesday Thursday	0.00"				
	0.00"				
Friday	0.00"				
Saturday	10.00				Week 4
Sunday:	0.00"				
Monday	0.00"	11/06/17	Partly Cloudy 44/28		
Tuesday	0.00"		·		
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 5
Sunday:	N/A				
Monday	N/A				
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				

	None				
Complaints:					
Construction Sequencing:		•			
Which portion(s) (i.e. drainage basins) of the site have h	ad a temporary or permanent ces	sation of grading, earthwork,	or ground disturbance in th	e last 14 days?	
Grading completed and entire site seeded prior to	o 2005.				
Entire Site; JC Excavating completed grading Lo	s 346 through 480 Section II	, drainage area 1 and 2 (1	1/2009).		
Entire site is now inactive for major grading activity	ties as of the inspection on 1	1/20/2013.			
Which portion(s) (i.e. drainage basins) of the site do not		nd disturbance scheduled in	the next 14 days? :		
Grading completed and entire site seeded prior to					
Entire Site; JC Excavating completed grading Lo	0		1/2009).		
Entire site is now inactive for major grading activity	ties as of the inspection on 1	1/20/2013.	· · · · · · · · · · · · · · · · · · ·		
What temporary or permanent stabilization measures lis					
Paving, dense vegetation and landscaping, Seed		•	· · ·	· · · ·	
lots 346-480, seeded (4/10); Outlot B was seeded					
and 43rd Avenue was temp seeded (5/22/2014);	-	lied on the South side of C	Jutiot L (8/4/2014); Mattir	ng nas been inst	alled on the
side slopes surrounding outlot M Basin (12/15/20	14);				
SUMMARY QUESTIONS:					
Are approved entrances and adjacent streets being main	tained adequately?				
No- see BMP section					
Are receiving waters adjacent to the project free of any	significant signs of erosion or se	diment that would be associa	ted with the construction ac	tivity?	
Yes	1				
CHECKLIST QUESTIONS: Are waste materials (concrete, construction material, ha	zardous, etc.) being managed pro	anerly2			
No- see BMP section.	zaruous, etc.) being manageu pro	openy:			
Is dust associated with the construction activity adequa	tely controlled on the site?	•			
Yes	1	1	1		
Common control					
Comments:					
Comments:	h				
	he development by various b	ouilders.			
Comments: Home Construction is active in the North part of t		ouilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe		puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date):		puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):	ction on 10/24/17.	puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date):	ction on 10/24/17.	puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):	ction on 10/24/17.	puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):	ction on 10/24/17.	puilders.			
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):	ction on 10/24/17.	Location	Projected Install Date	Status	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se	ction on 10/24/17. ction. Type Concrete Washout	Location Lot 387	-	Removed	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes	Location Lot 387 removed the concrete wa	-	Removed on 11/12/2015.	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout	Location Lot 387 removed the concrete wa Lot 359	shout prior to inspection	Removed	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes	Location Lot 387 removed the concrete wa Lot 359	shout prior to inspection	Removed on 11/12/2015.	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho	shout prior to inspection	Removed on 11/12/2015. Removed	Maintenance
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361	shout prior to inspection mes prior to 3/30/2016.	Removed on 11/12/2015. Removed Removed	
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible	Removed on 11/12/2015. Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible	Removed on 11/12/2015. Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the install a washout.	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 sssion of the site, individua ir own lots, if a washout b	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible	Removed on 11/12/2015. Removed Removed of for their concre bector will inform	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the Builders will washout on the install a washout. Individual Lot	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp	Removed on 11/12/2015. Removed Removed of their concre vector will inform Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout on the puilders will washout on the install a washout. Individual Lot Removed- Outlot B was see	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp	Removed on 11/12/2015. Removed for their concre vector will inform Removed 016.	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 16	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout on the pinstall a washout. Individual Lot Removed- Outlot B was see Individual Lot	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2	Removed on 11/12/2015. Removed Removed of their concre vector will inform Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition:	ction on 10/24/17. Ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2	Removed on 11/12/2015. Removed e for their concre sector will inform Removed 016. Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 7 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54	ction on 10/24/17. Ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Pit Washout Removed- Washout pit Washout Removed- due to the progres Builders will Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015.	Removed on 11/12/2015. Removed for their concre vector will inform Removed 016.	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition:	ction on 10/24/17. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Nick Peterson so	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015.	Removed on 11/12/2015. Removed e for their concre pector will inform Removed 016. Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57	ction on 10/24/17. Ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Nick Peterson so Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 esded and matted by Horizo Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 ded the lot prior to inspe- Lot 57	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015.	Removed on 11/12/2015. Removed e for their concre sector will inform Removed 016. Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Nick Peterson so Silt Fence Removed-Horizon Homes s	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua Lot 37 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe- Lot 57 odded the lot prior to inspe-	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015.	Removed on 11/12/2015. Removed e for their concre bector will inform Removed 016. Removed Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57 Current Condition: Lot 57 Current Condition: Lot 59	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to inspe Lot 59	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ection on 5/28/15.	Removed on 11/12/2015. Removed e for their concre pector will inform Removed 016. Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57 Current Condition: Lot 59 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Concenter S Conc	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizc Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to insp Lot 59 sodded the lot prior to insp Lot 59	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ection on 5/28/15.	Removed on 11/12/2015. Removed for their concre vector will inform Removed 016. Removed Removed Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 7 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 54 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 60	ction on 10/24/17. Ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Nick Peterson so Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to inspe Lot 59 sodded the lot prior to inspe Lot 59 sodded the lot prior to 11/ Lot 59	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ection on 5/28/15.	Removed on 11/12/2015. Removed e for their concre bector will inform Removed 016. Removed Removed Removed	te waste.
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed- Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua ir own lots, if a washout b Lot 361 ession of the site, individua is solved the lot prior to inspe Lot 59 sodded the lot prior to 11/ Lot 60 sodded the lot prior to 11/	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ection on 5/28/15. 12/2015.	Removed on 11/12/2015. Removed for their concre bector will inform Removed 016. Removed Removed Removed Removed	te waste. the applicant to
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 68	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the install a washout. Individual Lot Removed-Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to insp Lot 59 sodded the lot prior to 11/ Lot 60 sodded the lot prior to 11/ Lot 68	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ction on 5/28/15. 12/2015. 12/2015. 12/2015.	Removed on 11/12/2015. Removed for their concre bector will inform Removed 016. Removed Removed Removed Removed Removed	te waste. the applicant to
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition:	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout pit was Concrete Washout pit was Concrete Washout on the install a washout. Individual Lot Removed- Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to insp Lot 59 sodded the lot prior to 11/ Lot 60 sodded the lot prior to 11/ Lot 68	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ction on 5/28/15. 12/2015. 12/2015. 12/2015.	Removed on 11/12/2015. Removed for their concre bector will inform Removed 016. Removed Removed Removed Removed Removed	te waste. the applicant to
Comments: Home Construction is active in the North part of t Work has not progressed on the Trail as of inspe Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se Unique Name CW 5 Current Condition: CW 6 Current Condition: CW 7 Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 54 Current Condition: Lot 57 Current Condition: Lot 59 Current Condition: Lot 59 Current Condition: Lot 68	ction on 10/24/17. ction. Type Concrete Washout Removed-Celebrity Homes Concrete Washout Removed- Washout pit was Concrete Washout Removed- due to the progre Builders will washout on the install a washout. Individual Lot Removed-Outlot B was see Individual Lot Removed-Newport Homes Silt Fence Removed-Horizon Homes s Individual Lot Removed-Horizon Homes s Silt Fence	Location Lot 387 removed the concrete wa Lot 359 removed by Celebrity Ho Lot 361 ession of the site, individua ir own lots, if a washout b Lot 16 eded and matted by Horizo Lot 17 sodded the lot prior to 11/ Lot 54 dded the lot prior to inspe Lot 57 odded the lot prior to insp Lot 59 sodded the lot prior to 11/ Lot 60 sodded the lot prior to 11/ Lot 68	shout prior to inspection mes prior to 3/30/2016. al lots will be responsible ecomes needed the insp on Homes prior to 5/27/2 12/2015. ction on 5/28/15. ction on 5/28/15. 12/2015. 12/2015. 12/2015.	Removed on 11/12/2015. Removed for their concre bector will inform Removed 016. Removed Removed Removed Removed Removed	te waste. the applicant to

1.100	0.11 E	1 1 00			
Lot 69 Current Condition:	Silt Fence Removed- Sherwood Home	Lot 69	7/12/17	Removed	
Current Condition:	Removed- Sherwood Home		/13/17.		
Lot 76	Silt Fence	Lot 76		Removed	
Current Condition:	Removed- Lot was sodded		7/31/2015.		
Lot 80 Current Condition:	Silt Fence Removed- Horizon Homes	Lot 80	1/2015	Removed	
Lot 82	Silt Fence	Lot 82	1/2015.	Removed	
Current Condition:	Removed- Lot was sodded		9/18/2015.		
Lot 88	Silt Fence	Lot 88		Removed	
Current Condition:	Removed- Legacy Homes s	odded the lot prior to 11/2	22/16.		
Lot 89	Individual Lot	Lot 89		Removed	
Current Condition:	Removed- the Home Comp	any sodded the lot prior to	o 11/1/16.		
Lot 132	Silt Fence	Lot 132		Removed	
Current Condition:	Removed- Regency Homes		19/2015.		
Lot 155	Silt Fence	Lot 155	10/00/15	Removed	
Current Condition: Lot 209-210	Removed- Regency Homes Silt Fence	Lots 209-210	19/2015. I	Removed	
Current Condition:	Removed- Celebrity Homes		/1/16. Celebrity Homes		aining silt fence
	prior to 3/27/17.				
Lot 255	Individual Lot	Lot 255		Removed	
Current Condition:	Removed - Legacy Homes	sodded the lot prior to the	6/24/15 inspection.	1 1	
Lot 256	Silt Fence	Lot 256		Removed	
Current Condition:	Removed- Regency Homes	sodded the lot prior to 11	/22/16.		
Lot 258	Silt Fence	Lot 258		Removed	
Current Condition:	Removed-Charleston Home		nspection on 5/14/15.		
Lot 259	Silt Fence	Lot 259		Removed	
Current Condition:	Removed-Charleston Home	es sodded the lot prior to i	nspection on 5/14/15.		
Lot 260	Individual Lot	Lot 260		Removed	
Current Condition:	Removed- Sherwood Home		5/27/2016.		
Lot 261	Individual Lot	Lot 261		Removed	
Current Condition:	Removed- Sherwood Home		5/27/2016.		
Lot 272 Current Condition:	Silt Fence Removed- Dean Vogel sode	Lot 272	1	Removed	
			T		
Lot 273	Silt Fence	Lot 273		Removed	
Current Condition:	Removed- Sherwood Home	es sodded the lot prior to a	5/11/17. T	1	
Lot 274	Silt Fence	Lot 274		Removed	
Current Condition:	Removed- Regency Homes	sodded the lot prior to 12	2/14/16.		
Lot 275	Temporary Seeding	Lot 275	4/20/2017	Pending	No
Current Condition:	Pending- Dean Vogel distur buffer in the rear of the lot the monitor the lot.				
Lot 276	Silt Fence	Lot 276		Removed	
Current Condition:	Removed- Dean Vogel sod	ded the lot prior to 4/14/20)17.		
Lot 277	Silt Fence	Lot 277		Removed	
Current Condition:	Removed- the lot was mista	ken as lot 276 This was a	Iready sodded.		
Lot 280	Silt Fence	Lot 280		Removed	
Current Condition:	Removed - Sherwood Hom	es sodded the lot prior to	inspection on 7/27/17.		
Lot 281	Silt Fence	Lot 281		Removed	
Current Condition:	Removed- Dean Vogel sode	ded the lot prior to 8/12/20)16 and removed the silt	fence prior to 8/2	20/2016.
Lot 284	Silt Fence	Lot 284	1	Removed	
Current Condition:	Removed- Sherwood Home		5/27/2016.	Removed	
Lot 282	Silt Fence	Lot 282		Removed	
Current Condition:	Removed- Oakwood Home		the rear prior to 7/26/20		
Lot 285	Silt Fence	Lot 285		Removed	
Current Condition:	Removed- Sherwood Home		5/11/17.		
Lot 286	Silt Fence	Lot 286		Removed	
Current Condition:	Removed-Sherwood Home		spection on 7/8/15.		
Lot 292	Silt Fence	Lot 292		Removed	
Current Condition:	Removed - Pacesetter Hom Silt Fence	les sodded the lot prior to Lot 294	inspection on 10/9/17.	Removed	

Current Condition:	Removed - Sherwood Homes sodded the lot prior to inspection on 10/9,	/17.	
Lot 296	Silt Fence Lot 296 6/28/2017	Active	Yes
Current Condition:	Fair Condition- Pine Crest Homes removed the stockpile from the ROW	prior to 7/13/17.	
	Silt fence in the rear of the lot needs to be retied.		
	Pinecrest Homes was informed to complete by 9/26/17. Not done as of	last inspection.	
Lot 297	Silt Fence Lot 297 7/13/2017	Active	No
Current Condition:	Good Condition- Pacesetter Homes installed silt fence in the rear of the	lot prior to 7/13/17	
Lot 300	Silt Fence Lot 300	Removed	
Current Condition:	Removed- Pinecrest Homes sodded the lot prior to 7/31/2015.		
Lot 302	Silt Fence Lot 302 6/28/2017	Active	No
Current Condition:	Good Condition- Sherwood Homes started construction on the lot and ir rear of the lot prior to 6/28/17. Silt fence has been repaired in the front o	0	
Lot 307	Silt Fence Lot 307	Removed	
Current Condition:	Removed-Sherwood Homes sodded the lot prior to 8/20/2016.		
Lot 310	Silt Fence Lot 310	Removed	
Current Condition:	Removed- Sherwood Home sodded the lot prior to 6/14/17.		
Lot 314	Silt Fence Lot 314	Removed	
Current Condition:	Removed - The Home Company sodded the lot prior to inspection on 8/	/22/17.	
Lot 315	Silt Fence Lot 315	Removed	
Current Condition:	Removed- Legacy Homes sodded the lot prior to 11/22/16.		
Lot 316	Silt Fence Lot 316	Removed	
Current Condition:	Removed - THC sodded the lot prior to inspection on 9/19/17.		
Lot 319	Silt Fence Lot 319	Removed	
Current Condition:	Removed-Sherwood Homes sodded the lot prior to 9/13/2016.		
Lot 324	Silt Fence Lot 324 Removed-Sherwood Homes sodded the lot prior to inspection on 7/8/15	Removed	
Current Condition: Lot 325	Silt fence Lot 325	Removed	
Current Condition: Lot 326	Removed- Lot was sodded by Sherwood Homes prior to 11/17/2015. Silt Fence Lot 326	Removed	
Current Condition:	Removed-Sherwood Homes sodded the lot prior to inspection on 7/16/1		
Lot 328	Silt Fence Lot 328 Removed-Oakwood Homes removed silt fence and sodded the lot prior	Removed	
Current Condition: Lot 329			
LUI 329	Silt Fence Lot 329 3/6/2017	to inspection on 5/4/15.	Yes
Lot 329 Current Condition:		Active W prior to 5/11/17 and in ator gaurds along the fror lot prior to inspection on replaced.	istalled a it of the lot
Current Condition: Lot 336	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as o Temp. Seeding	Active W prior to 5/11/17 and in ator gaurds along the from lot prior to inspection on replaced. of last inspection. Removed	istalled a it of the lot
Current Condition: Lot 336 Current Condition:	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as o Temp. Seeding Lot 329 3/6/2017 Removed- As of 8/18/2015, lot has filled in and temp seeding is not need	Active W prior to 5/11/17 and in ator gaurds along the from lot prior to inspection of replaced. of last inspection. Removed	istalled a it of the lot
Current Condition: Lot 336	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as o Temp. Seeding	Active W prior to 5/11/17 and in ator gaurds along the from lot prior to inspection on replaced. of last inspection. Removed	istalled a it of the lot
Current Condition: Lot 336 Current Condition: Lot 336	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as of Temp. Seeding Lot 329 3/6/2017 Regency Homes replaced the erosion eels around the IT the erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as of Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not nee Silt Fence	Active W prior to 5/11/17 and in ator gaurds along the from lot prior to inspection of replaced. of last inspection. Removed	istalled a it of the lot
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition:	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the IThe erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as on Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not nee Silt Fence Lot 336 Removed- Sherwood Homes sodded the lot prior to 10/6/16.	Active W prior to 5/11/17 and in to gaurds along the fror lot prior to inspection on replaced. flast inspection. Removed Removed Removed Removed	Istalled a It of the lot 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition:	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the I The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as o Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not nee Silt Fence Lot 336 Removed- Sherwood Homes sodded the lot prior to 10/6/16. Silt Fence Lot 337 Removed-Sherwood Homes removed the silt fence and sodded the lot prior	Active W prior to 5/11/17 and in to gaurds along the fror lot prior to inspection on replaced. I Removed Removed Removed Removed prior to inspection on 5/2	Istalled a It of the lot 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the I The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as on the Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not need Silt Fence Lot 336 Removed- Sherwood Homes sodded the lot prior to 10/6/16. Silt Fence Lot 337 Lot 337	Active W prior to 5/11/17 and in to gaurds along the fror lot prior to inspection on replaced. flast inspection. Removed Removed Removed Removed	Istalled a It of the lot 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the I The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as o Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not nee Silt Fence Lot 336 Removed- Sherwood Homes sodded the lot prior to 10/6/16. Silt Fence Lot 337 Silt Fence Lot 337 Removed-Sherwood Homes removed the silt fence and sodded the lot prior to 10/6/16. Silt Fence Lot 337 Silt Fence Silt Fence Lot 337 Silt Fence Silt Fence Lot 334 Silt Fence	Active W prior to 5/11/17 and in to gaurds along the fror lot prior to inspection on replaced. I Removed Removed Removed Removed prior to inspection on 5/2	Istalled a It of the lot 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition:	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the lot are damaged and need to be The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as on the seeding Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not need Silt Fence Lot 336 Removed- Sherwood Homes removed the silt fence and sodded the lot prior to 10/6/16. Silt Fence Lot 337 Removed-Sherwood Homes removed the silt fence and sodded the lot prior to 11/1/16.	Active W prior to 5/11/17 and in tor gaurds along the fror lot prior to inspection on replaced. I Removed Removed prior to inspection on 5/2 Removed Removed Removed Removed Removed	Istalled a It of the lot 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the I The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as o Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not nee Silt Fence Lot 336 Removed- Sherwood Homes removed the silt fence and sodded the lot silt Fence Lot 337 Removed-Sherwood Homes removed the silt fence and sodded the lot silt Fence Lot 344 Silt Fence Lot 344 Silt Fence Lot 344	Active W prior to 5/11/17 and in tor gaurds along the fror lot prior to inspection on replaced. I Removed Removed prior to inspection on 5/2 Removed Removed Removed Removed Removed	Istalled a It of the lot 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F Current Condition:	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the IThe erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as on Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not need Silt Fence Lot 337 Removed- Sherwood Homes removed the silt fence and sodded the lot prior to 10/6/16. Silt Fence Lot 337 Removed- Sherwood Homes removed the silt fence and sodded the lot prior to 11/1/16. Silt Fence Lot 344 Removed- the Home Company sodded the lot prior to 11/1/16. Silt Fence Lots 426-454 Removed-Lots 427 and 428 were sodded prior to 12/1/2015 by Celebrit	Active W prior to 5/11/17 and in the second	Istalled a It of the lot 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F Current Condition: Pod G Current Condition: Pod H	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the I The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as o Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not nee Silt Fence Lot 336 Removed- Sherwood Homes removed the silt fence and sodded the lot prior to 10/6/16. Silt Fence Lot 337 Removed- Sherwood Homes removed the silt fence and sodded the lot prior to 11/1/16. Silt Fence Lot 344 Removed- the Home Company sodded the lot prior to 12/1/2015 by Celebrit Silt Fence Lots 426-454 Removed-Lots 427 and 428 were sodded prior to 12/1/2015 by Celebrit Silt Fence Lots 404-425 Removed-Lot 404 was sodded prior to 6/29/2016. Pod has been built or Silt Fence Lots 404-425 Removed-Lot 404 was sodded prior to 6/29/2016. Pod has been built or Silt Fence	Active W prior to 5/11/17 and in tor gaurds along the fror lot prior to inspection on replaced. I Removed	Istalled a It of the lot 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F Current Condition: Pod G Current Condition: Pod H Current Condition:	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the I The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as o Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not nee Silt Fence Lot 336 Removed- Sherwood Homes removed the silt fence and sodded the lot prior to 10/6/16. Silt Fence Lot 337 Removed- Sherwood Homes removed the silt fence and sodded the lot prior to 11/1/16. Silt Fence Lot 344 Removed- the Home Company sodded the lot prior to 12/1/2015 by Celebrit Silt Fence Lots 426-454 Removed-Lots 427 and 428 were sodded prior to 12/1/2015 by Celebrit Silt Fence Lots 404-425 Removed-Lot 404 was sodded prior to 6/29/2016. Pod has been built or Silt Fence Lots 455-473 Removed- Lot 460 was sodded by Celebrity Homes prior to the inspecti	Active W prior to 5/11/17 and in tor gaurds along the from lot prior to inspection on the replaced. of last inspection. Removed ded. Removed prior to inspection on 5/2 Removed prior to inspection on 5/2 Removed replaced. Removed prior to inspection on 5/2 Removed ut. Removed ut. Removed ion on 4/25/2015.	Istalled a It of the lot 9/19/17.
Current Condition: Lot 336 Current Condition: Lot 336 Current Condition: Lot 337 Current Condition: Lot 344 Current Condition: Pod F Current Condition: Pod G Current Condition: Pod H	Silt Fence Lot 329 3/6/2017 Fair Condition- Regency Homes removed the dirt stockpile from the RO gator guard along the front of the lot. Regency Homes reinstalled the ga prior to 6/23/17. Regency Homes replaced the erosion eels around the I The erosion eels along the front of the lot are damaged and need to be Regency Homes was informed to complete by 10/16/17. Not done as o Temp. Seeding Lot 336 Removed- As of 8/18/2015, lot has filled in and temp seeding is not nee Silt Fence Lot 336 Removed- Sherwood Homes removed the silt fence and sodded the lot prior to 10/6/16. Silt Fence Lot 337 Removed- Sherwood Homes removed the silt fence and sodded the lot prior to 11/1/16. Silt Fence Lot 344 Removed- the Home Company sodded the lot prior to 12/1/2015 by Celebrit Silt Fence Lots 426-454 Removed-Lots 427 and 428 were sodded prior to 12/1/2015 by Celebrit Silt Fence Lots 404-425 Removed-Lot 404 was sodded prior to 6/29/2016. Pod has been built or Silt Fence Lots 404-425 Removed-Lot 404 was sodded prior to 6/29/2016. Pod has been built or Silt Fence	Active W prior to 5/11/17 and in tor gaurds along the fror lot prior to inspection on replaced. I Removed	Istalled a It of the lot 9/19/17.

Current Condition:	Removed- Lot 385 was soo				
	5/27/2016. Lot 383 was so was sodded prior to 8/12/2			01 300 0101 10 0/28	9/2016. LOI 30
Pod K	Silt Fence	Lots 372-403		Removed	
Current Condition:	Removed-Celebrity Homes				
	front of lots 380, 378-376 p sodded by Celebrity Homes completion of the sidewalk pod.	s prior to 11/1/16. The silt	fence on the front of lot	379 isn't needed a	nymore due
Pod L	Silt Fence	Lots 371-356		Removed	
Current Condition:	Removed- Silt fence was re sodded prior to inspection of repaired on the front of lot 3 sodded by Celebrity Homes and on the front of the lots inspector will monitor for so pod.	on 9/26/16. Silt fence was 360 prior to inspection on s s prior to 11/1/16. Celebrit prior to 11/1/16 presumab	reinstalled on the front 9/26/16 by Celebrity Ho y Homes removed the s ly in preparation for sod	of lots 359, and 36 mes. Lot 262, and ilt fence behind lot ding as the lots we	4, and 263 were s 359-364 ere fine grade
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No
Current Condition:	Good Condition-45% Filled by the SID prior to inspection inspection on 9/19/17.	on on 10/23/14. Vegetatior	n was removed from the	basin by the SID	orior to
SB 3	Sediment Basin	School Lot 165	In Place	Active	No
Current Condition:	Good Condition-20% Filled -Cleaned out 02/06				
SB 5	Sediment Basin	Outlot "L"	11/17/2009	Active	No
Current Condition:	Good Condition- 15% Filled - JC Excavating installed p	-	/09.		
CD 1	Check Dam	Northern side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta	-		rending	110
EM 1	Erosion Control Matting	East side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta	alled once grading has bec	un on site.	<u> </u>	
EM 2	Erosion Control Matting	West side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta	alled once grading has bec	gun on site.		
SF 1	Silt Fence	Southern side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta				
SF 2	Silt Fence	Souther side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta				
SF 3	Silt Fence	Souther side of site	10/2/2017	Pending	No
Current Condition:	Pending - BMP will be insta				N
SF 4	Silt Fence	Northern side of site	10/2/2017	Pending	No
Current Condition:		alled once grading has bec		Danding	Na
Current Condition: IP 1	Inlet Protection	Souther side of site	10/2/2017	Pending	No
Current Condition: IP 1 Current Condition:	Inlet Protection Pending - BMP will be insta	Souther side of site alled once grading has beg	10/2/2017 gun on site.	· · ·	
Current Condition: IP 1 Current Condition: STR	Inlet Protection Pending - BMP will be insta Street Cleaning	Souther side of site alled once grading has beg streets	10/2/2017 gun on site. 5/1/2007	Active	No
Current Condition: IP 1 Current Condition:	Inlet Protection Pending - BMP will be insta	Souther side of site alled once grading has beg streets or Homes scraped up dirt fi ut from along lot 292 prior	10/2/2017 gun on site. 5/1/2007 rom the street in front of to 7/13/17. Regency Ho	Active for the former of the f	No 19/17. Pacet
Current Condition: IP 1 Current Condition: STR Current Condition: SWPPP Sign	Inlet Protection Pending - BMP will be insta Street Cleaning Good Condition- Pacesette Homes cleaned the track o front of lot 329. Track out w Signs	Souther side of site alled once grading has beg streets or Homes scraped up dirt fi ut from along lot 292 prior vas cleaned in front of lot 3 1 sign on site	10/2/2017 gun on site. 5/1/2007 rom the street in front of to 7/13/17. Regency Ho	Active for the former of the f	No 19/17. Pacet
Current Condition: IP 1 Current Condition: STR Current Condition:	Inlet Protection Pending - BMP will be insta Street Cleaning Good Condition- Pacesette Homes cleaned the track o front of lot 329. Track out w	Souther side of site alled once grading has beg streets or Homes scraped up dirt fi ut from along lot 292 prior vas cleaned in front of lot 3 1 sign on site	10/2/2017 gun on site. 5/1/2007 rom the street in front of to 7/13/17. Regency Ho 302 prior to inspection o	Active f lot 297 prior to 6/ omes cleaned the n 10/9/17.	No 19/17. Pace track out in