E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Friday

Saturday

Sunday:

Monday Tuesday

Friday

Saturday

Sunday:

Monday Tuesday

Wednesday

Thursday

Friday Saturday

Wednesday Thursday **Engineering Answers** 

Week 4

## Inspector: Matthew Russell Stage **Clearwater Falls/Clearwater Falls Trail** 3 and 2 CSW-201701144 **Project Name:** 1/13/2018 - 1/13/2018 For Week Ending: 48th and Fairview Road- Bellevue, NE (Sarpy County) Project Location: Grading: Sanitary Sewer: 100% 95% 100% N/A Storm Sewer: 100% 10% 90% Paving: 100% Seeding: 100% 0% Utilities: 100% 0% Overall Development: 87% 40% RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Sunday: 0.00" 0.00" Monday Tuesday 0.00" Wednesday 0.00" 0.00" Thursday Friday 0.00" Saturday 0.00" Week 2 Sunday: 0.07" Monday 0.00" 12/18/17 Fog 52/19 0.00" Tuesday Wednesday 0.00" 0.07" Thursday 0.00" Friday Saturday 0.03" Week Sunday: 0.05" 0.00" Monday 0.00" Tuesday Wednesday 0.00" Thursday 0.00"

0.00"

0.00"

0.00"

0.00"

0.00"

0.00"

0.00"

0.00" 0.00"

0.00"

0.01" 0.01"

0.00"

0.00"

E&A- P2005.198.000 (Clearwater Falls) E&A-P2005.198.009 (Clearwater Falls Trail)

On well of the	None				
Complaints:					
		I	I	1	
Construction Sequencing:					
Which portion(s) (i.e. drainage basins) of the site have he	ad a temporary or permanent ces	ssation of grading, earthwork	or ground disturbance in th	e last 14 days?	
Grading completed and entire site seeded prior to			<b>3</b>		
Entire Site; JC Excavating completed grading Lot		drainage area 1 and 2 (1	1/2009)		
Entire site is now inactive for major grading activi	_	- '	.,2000).		
Grading for the Clearwater Falls Trail has ceased	•				
	·				
Which portion(s) (i.e. drainage basins) of the site do not	have grading, earthwork, or grou	ind disturbance scheduled in	the next 14 days? :		
Grading completed and entire site seeded prior to	2005.		•		
Entire Site; JC Excavating completed grading Lot	s 346 through 480 Section II	, drainage area 1 and 2 (1	1/2009).		
Entire site is now inactive for major grading activi	ties as of the inspection on 1	1/20/2013.			
Grading for the Clearwater Falls Trail has ceased	l as of inspection on 12/18/1	7.			
What temporary or permanent stabilization measures lis	ted in this section are being impl	emented?			
Paving, dense vegetation and landscaping, Seed					
lots 346-480, seeded (4/10); Outlot B was seeded					
and 43rd Avenue was temp seeded (5/22/2014);		lled on the South side of C	Outlot L (8/4/2014); Matti	ng has been inst	alled on the
side slopes surrounding outlot M Basin (12/15/20	14);				
SUMMARY QUESTIONS:					
Are approved entrances and adjacent streets being main	tained adequately?				
No- see BMP section  Are receiving waters adjacent to the project free of any	cianificant ciano of execton exec	diment that would be accord	tod with the construction of	etivitus	
Yes	significant signs of erosion of se	dilitett tilat would be associa	ted with the construction at	ctivity:	
CHECKLIST QUESTIONS:					
Are waste materials (concrete, construction material, ha	zardous, etc.) being managed pro	operly?			
No- see BMP section.	T	1		ı	
Is dust associated with the construction activity adequa	tely controlled on the site?				
Yes					
Comments:					
Comments:	ha davalanmant hvvariava h	wildoro			
Home Construction is active in the North part of t	ne development by various t	Juliders.			
Findings / Corrective Actions (Date):					
Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP Se	ction				
1.) Come maintenance is required in the bini Ce	T.	ı	ı	1	•
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CW 5	Concrete Washout	Lot 387	Frojecteu ilistali Date	Removed	Wallitellalice
Current Condition:	Removed-Celebrity Homes		shout prior to inspection		
CW 6	Concrete Washout	Lot 359		Removed	
Current Condition:	Removed- Washout pit was	removed by Celebrity Ho	mes prior to 3/30/2016.	•	
CW 7	Concrete Washout	Lot 361		Removed	<u>.                                    </u>
Current Condition:	Removed- due to the progre		•		
	Builders will washout on the install a washout.	eir own lots, it a washout b	ecomes needed the insp	pector will inform	tne applicant to
Lot 16		1 at 16	ı	Domoved	•
Lot 16	Individual Lot Removed- Outlot B was see	Lot 16	n Hamaa nriar ta E/27/2	Removed	
Current Condition:			i nomes prior to 5/2//2		
Lot 17	Individual Lot	Lot 17	140/0045	Removed	
Current Condition: Lot 54	Removed- Newport Homes Silt Fence	Lot 54	12/2013.	Removed	
Current Condition:	Removed-Nick Peterson so		ction on 5/28/15	rtemoved	
Lot 57	Silt Fence	Lot 57		Removed	
Current Condition:	Removed-Horizon Homes s		ection on 5/28/15.	•	
Lot 59	Individual Lot	Lot 59		Removed	
Current Condition:	Removed- Horizon Homes		12/2015.		
Lot 60	Silt Fence	Lot 60	1//0	Removed	
Current Condition:	Removed- Horizon Homes	sodded the lot prior to 11/	1/16.		
Lot 65					
Current Condition:	Silt Fence	Lot 65	12/18/2017	Active	No
Current Condition.	Silt Fence Good Condition- The Hom				
Current Condition.		ie Company began cons			
Lot 68	Good Condition- The Hom	ie Company began cons			

Current Condition:	Good Condition- Pacesette set to begin on the lot.	r Homes installed silt fenc	e in the rear of the lot pri	ior to 6/28/17. Co	onstruction is
Lot 69	Silt Fence	Lot 69		Removed	
Current Condition:	Removed- Sherwood Home	es sodded the lot prior to 7	//13/17.	•	•
Lot 76	Silt Fence	Lot 76		Removed	
Current Condition:	Removed- Lot was sodded		7/31/2015.		
Lot 80	Silt Fence Removed- Horizon Homes	Lot 80	1/2015	Removed	
Current Condition: Lot 82	Silt Fence	Lot 82	1/2013.	Removed	
Current Condition:	Removed- Lot was sodded	by Legacy Homes prior to	9/18/2015.		'
Lot 88	Silt Fence	Lot 88		Removed	
Current Condition:	Removed- Legacy Homes s	sodded the lot prior to 11/2	22/16.		
Lot 89	Individual Lot	Lot 89		Removed	
Current Condition:	Removed- the Home Comp	any sodded the lot prior to	o 11/1/16.		
Lot 132	Silt Fence	Lot 132		Removed	
Current Condition:	Removed- Regency Homes		19/2015.		
Lot 155	Silt Fence	Lot 155	10/00/15	Removed	
Current Condition: Lot 209-210	Removed- Regency Homes Silt Fence	Lots 209-210	19/2015. I	Removed	1
Current Condition:	Removed- Celebrity Homes		/1/16. Celebrity Homes		naining silt fence
	prior to 3/27/17.	•			
Lot 255	Individual Lot	Lot 255		Removed	
Current Condition:	Removed - Legacy Homes	· '	б/24/15 inspection.	1	
Lot 256	Silt Fence	Lot 256	100/40	Removed	
Current Condition:	Removed- Regency Homes	s sodded the lot prior to 11	/22/16.		
Lot 258	Silt Fence	Lot 258		Removed	
Current Condition: Lot 259	Removed-Charleston Home Silt Fence	es sodded the lot prior to i Lot 259	nspection on 5/14/15.	Removed	
Current Condition:	Removed-Charleston Home		nspection on 5/14/15.	removed	
Lot 260	Individual Lot	Lot 260		Removed	
Current Condition:	Removed- Sherwood Home		5/27/2016.		
Lot 261	Individual Lot	Lot 261		Removed	
Current Condition:	Removed- Sherwood Home		5/27/2016.		
Lot 272  Current Condition:	Silt Fence Removed- Dean Vogel sod	Lot 272	116	Removed	
Lot 273	Silt Fence	Lot 273	T	Removed	
Current Condition:	Removed- Sherwood Home		<u> </u> 5/11/17	Removed	
		· · · · · · · · · · · · · · · · · · ·	,	Ī	I
Lot 274	Silt Fence	Lot 274	2/4.4/4.0	Removed	
Current Condition:	Removed- Regency Homes	· ·		1	
Lot 275	Temporary Seeding	Lot 275	4/20/2017	Pending	No
Current Condition:	Pending- Dean Vogel disturbed soils on the lot from past construction on lot 276. Due to a dense vegetative buffer in the rear of the lot the inspector will not recommend seeding at this time, inspector will continue to monitor the lot.				
Lot 276	Silt Fence	Lot 276		Removed	
Current Condition:	Removed- Dean Vogel sod		) 17.	•	•
Lot 277	Silt Fence	Lot 277		Removed	
Current Condition:	Removed- the lot was mista		lready sodded.	•	
Lot 280	Silt Fence	Lot 280		Removed	
Current Condition:	Removed - Sherwood Hom	es sodded the lot prior to	inspection on 7/27/17.		
Lot 281	Silt Fence	Lot 281		Removed	100/00/
Current Condition:	Removed- Dean Vogel sod	ded the lot prior to 8/12/20	J16 and removed the silt	tence prior to 8/	20/2016.
Lot 284	Silt Fence	Lot 284		Removed	
Current Condition:	Removed- Sherwood Home	es sodded the lot prior to 5	5/27/2016.		
Lot 282	Silt Fence	Lot 282		Removed	
Current Condition:	Removed- Oakwood Home		the rear prior to 7/26/20		1
Lot 285  Current Condition:	Silt Fence Removed- Sherwood Home	Lot 285	<u> </u> 5/11/17	Removed	
		·	1	Dowr	
Lot 286 Current Condition:	Silt Fence Removed-Sherwood Home	Lot 286 s sodded the lot prior to in	L spection on 7/8/15.	Removed	1
Lot 292	Silt Fence	Lot 292	,	Removed	

Current Condition:	Removed - Pacesetter Homes sodded the lot prior to inspection on 10/9/17.						
Lot 293	Silt Fence	Lot 293	12/18/2017	Active	Yes		
Current Condition:	Fair Condition- The Home	Company began constr	uction on the lot prior	to inspection o	n 12/18/17.		
	Silt fence needs to be installed on the front of the lot.						
	The Home Company was i		12/25/17.				
Lot 294  Current Condition:	Silt Fence Removed - Sherwood Hom	Lot 294	inspection on 10/9/17	Removed			
		<u> </u>	T .		V		
Lot 296  Current Condition:	Silt Fence Fair Condition- Pine Crest F	Lot 296	6/28/2017	Active	Yes		
Current Condition:	Fair Condition- Fine Crest F	Torries removed the stock	pile from the ROW prior	10 7/13/17.			
	Silt fence in the rear of the I	ot needs to be repaired.					
	Pinecrest Homes was inform	med to complete by 9/26/	17 Not done as of last in	spection Pinecro	est Homes was		
	reminded on 11/28/17.						
Lot 297	Silt Fence	Lot 297	7/13/2017	Active	No		
Current Condition:	Good Condition- Pacesetter	ı r Homes installed silt fenc	e in the rear of the lot pr	ior to 7/13/17			
Lot 299	Silt Fence	Lot 299	12/18/2017	Active	Yes		
Current Condition:	Fair Condition- The Home			1 10 11 1			
		. , ,		·			
	The dirt pile needs to be r lot.	emoved from the ROW of	or silt fence needs to be	e installed on th	e front of the		
	iot.						
1.1000	The Home Company was i		12/25/17.		•		
Lot 300  Current Condition:	Silt Fence Removed- Pinecrest Home:	Lot 300 s sodded the lot prior to 7.	<u> </u> /31/2015	Removed			
Lot 302	Silt Fence	Lot 302	101/2010.	Removed			
Current Condition:	Removed - Sherwood Hor		to inspection on 12/18				
Lot 307	Silt Fence	Lot 307		Removed			
Current Condition:	Removed-Sherwood Home		/20/2016.	•			
Lot 310	Silt Fence	Lot 310		Removed			
Current Condition:	Removed- Sherwood Home	sodded the lot prior to 6/	14/17.	'			
Lot 314	Silt Fence	Lot 314		Removed			
Current Condition:	Removed - The Home Com	• •	to inspection on 8/22/17	-			
Lot 315 Current Condition:	Silt Fence	Lot 315	20/4.0	Removed			
Current Condition:	Removed- Legacy Homes s	1	22/10.				
Lot 316 Current Condition:	Silt Fence Removed - THC sodded the	Lot 316	0/40/47	Removed			
Lot 319	Silt Fence	Lot 319	9/19/17. T	Removed			
Current Condition:	Removed-Sherwood Home		/13/2016.	rtemoved			
Lot 324	Silt Fence	Lot 324		Removed			
Current Condition:	Removed-Sherwood Home		spection on 7/8/15.		-		
Lot 325	Silt fence	Lot 325	1 44/47/0045	Removed			
Current Condition: Lot 326	Removed- Lot was sodded Silt Fence	by Sherwood Homes prio	r to 11/1//2015.	Removed			
Current Condition:	Removed-Sherwood Home		spection on 7/16/15.	rtomovou			
Lot 328	Silt Fence	Lot 328		Removed			
Current Condition:	Removed-Oakwood Homes						
Lot 329  Current Condition:	Silt Fence Fair Condition- Regency Ho	Lot 329	3/6/2017	Active	Yes Linetalled a		
Current Condition.	gator guard along the front						
	prior to 6/23/17. Regency H	omes replaced the erosion	n eels around the lot pri	or to inspection o	n 9/19/17.		
	The erosion eels along the	front of the lot are damage	ad and need to be replace	red			
	The crosion cels along the	noncor the locare damage	sa ana need to be replac	oca.			
	Regency Homes was inform	ned to complete by 10/16/	17. Not done as of last i	nspection. Reger	ncy Homes was		
Lot 336	reminded on 11/28/17.  Temp. Seeding	Lot 336		Removed			
Current Condition:	Removed- As of 8/18/2015,		seeding is not needed.	1			
Lot 336	Silt Fence	Lot 336		Removed			
Current Condition:	Removed- Sherwood Home	es sodded the lot prior to 1	10/6/16.				
Lot 337	Silt Fence	Lot 337		Removed			
	<del></del>						

Current Condition:	Removed-Sherwood Home	s removed the silt fence a	nd sodded the lot prior t	o inspection on 5	5/28/15.		
Lot 344	Silt Fence	Lot 344		Removed			
Current Condition:	Removed- the Home Comp		11/1/16.	rtomovou			
Pod F	Silt Fence Lots 426-454 Removed						
Current Condition:	Removed-Lots 427 and 428 were sodded prior to 12/1/2015 by Celebrity Homes.						
Pod G	Silt Fence	Lots 404-425		Removed			
Current Condition:	Removed-Lot 404 was sodded prior to 6/29/2016. Pod has been built out.						
Pod H	Silt Fence	Lots 455-473		Removed			
Current Condition:	Removed- Lot 460 was soo		I rior to the inspection on				
Pod I	Silt Fence	Lots 346-355	•	Removed			
Current Condition:	Removed-Lot 355 was sod	· · · · · · · · · · · · · · · · · · ·	Celebrity Homes.				
Pod J	Silt Fence Removed - Pod J is built ou	Lots 381-394		Removed			
Current Condition: Pod K	Silt Fence	Lots 372-403		Removed			
Current Condition:	Removed - Celebrity Home		1/22/16 completing the				
Pod L	Silt Fence	Lots 371-356	,	Removed			
Current Condition:	Removed - Celebrity Home		1-359 completing the po				
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No		
Current Condition:	Good Condition-45% Filled						
	by the SID prior to inspection inspection on 9/19/17.	on on 10/23/14. Vegetation	was removed from the	basin by the SID	prior to		
00.0		0 1 11 1405	I DI	1 4 0			
SB 3 Current Condition:	Sediment Basin Good Condition-20% Filled	School Lot 165	In Place	Active	No		
Current Condition.	-Cleaned out 02/06						
SB 5	Sediment Basin	Outlot "L"	11/17/2009	Active	No		
Current Condition:	Good Condition- 15% Filled	1		1			
	- JC Excavating installed pr	ior to inspection on 11/18/	09.				
	Clearwater Falls Trail						
CD 1	Check Dam	Northern side of site	10/2/2017	Active	No		
Current Condition:	<b>Good Condition - BMP wil</b>	l be installed once grading	has begun on site. Joh	n Navarro insta	lled the check		
			3		neu the check		
	dam prior to inspection o	n 12/18/17.					
EM 1	Erosion Control Matting	n 12/18/17.  East side of site	10/2/2017	Pending	Yes		
EM 1 Current Condition:		n 12/18/17.  East side of site	10/2/2017				
	Erosion Control Matting	n 12/18/17.  East side of site  Illed once grading has beg	10/2/2017				
	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting	n 12/18/17.  East side of site liled once grading has beg g needs to be installed	10/2/2017 un on site.	Pending			
	Erosion Control Matting Pending - BMP will be insta	n 12/18/17.  East side of site liled once grading has beg g needs to be installed	10/2/2017 un on site.	Pending			
Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting	n 12/18/17.  East side of site Illed once grading has beg g needs to be installed to complete by 11/27/17.  West side of site	10/2/2017 un on site.  Not done as of last insp 10/2/2017	Pending			
Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed	n 12/18/17.  East side of site Illed once grading has beg g needs to be installed to complete by 11/27/17.  West side of site	10/2/2017 un on site.  Not done as of last insp 10/2/2017	Pending pection.	Yes		
Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta	n 12/18/17.  East side of site lilled once grading has beg g needs to be installed to complete by 11/27/17.  West side of site lilled once grading has beg	10/2/2017 un on site.  Not done as of last insp 10/2/2017	Pending pection.	Yes		
Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting	East side of site liled once grading has beg g needs to be installed to complete by 11/27/17. West side of site lilled once grading has beg g needs to be installed	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending Dection. Pending	Yes		
Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta	East side of site liled once grading has beg g needs to be installed to complete by 11/27/17. West side of site lilled once grading has beg g needs to be installed	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending Dection. Pending	Yes		
Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting	East side of site liled once grading has beg g needs to be installed to complete by 11/27/17. West side of site lilled once grading has beg g needs to be installed	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending Dection. Pending	Yes		
EM 2 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed	n 12/18/17.  East side of site alled once grading has beggg needs to be installed to complete by 11/27/17.  West side of site alled once grading has beggg needs to be installed to complete by 11/27/17.  Southern side of site	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017	Pending  Dection.  Pending	Yes Yes		
EM 2 Current Condition:  SF 1	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta	East side of site liled once grading has beg g needs to be installed to complete by 11/27/17.  West side of site lilled once grading has beg g needs to be installed to complete by 11/27/17. Southern side of site	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017	Pending  Dection.  Pending	Yes Yes		
EM 2 Current Condition:  SF 1	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence	East side of site liled once grading has beg g needs to be installed to complete by 11/27/17.  West side of site lilled once grading has beg g needs to be installed to complete by 11/27/17. Southern side of site	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017	Pending  Dection.  Pending	Yes Yes		
EM 2 Current Condition:  SF 1	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta	East side of site lead once grading has beggg needs to be installed to complete by 11/27/17.  West side of site lead once grading has beggg needs to be installed to complete by 11/27/17.  Southern side of site lead to complete by 11/27/17.  Southern side of site lead once grading has begggnstalled	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pending	Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i	East side of site liled once grading has beg g needs to be installed to complete by 11/27/17.  West side of site lilled once grading has beg g needs to be installed to complete by 11/27/17.  Southern side of site lilled once grading has beg mstalled to complete by 11/27/17.	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pending  Pending	Yes Yes		
EM 2 Current Condition:  SF 1	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be in	East side of site liled once grading has beg g needs to be installed d to complete by 11/27/17.  West side of site liled once grading has beg g needs to be installed d to complete by 11/27/17.  Southern side of site liled once grading has beg installed d to complete by 11/27/17.  Souther side of site liled once grading has beg installed d to complete by 11/27/17. Souther side of site	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pending	Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta	East side of site leads to be installed to complete by 11/27/17.  West side of site to complete by 11/27/17.  West side of site leads to be installed to complete by 11/27/17.  Southern side of site leads to complete by 11/27/17.  Southern side of site leads to complete by 11/27/17.  Souther side of site leads to complete by 11/27/17.  Souther side of site leads to complete by 11/27/17.  Souther side of site leads to complete by 11/27/17.	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pending  Pending	Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence	East side of site leads to be installed to complete by 11/27/17.  West side of site to complete by 11/27/17.  West side of site leads to be installed to complete by 11/27/17.  Southern side of site leads to complete by 11/27/17.  Southern side of site leads to complete by 11/27/17.  Souther side of site leads to complete by 11/27/17.  Souther side of site leads to complete by 11/27/17.  Souther side of site leads to complete by 11/27/17.	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pending  Pending	Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i	East side of site liled once grading has beg g needs to be installed d to complete by 11/27/17.  West side of site liled once grading has beg g needs to be installed d to complete by 11/27/17.  Southern side of site liled once grading has beg installed d to complete by 11/27/17.  Souther side of site liled once grading has beg installed Souther side of site liled once grading has beg installed souther side of site liled once grading has beg installed	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pection.  Pending  Pending	Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i	East side of site led once grading has begg needs to be installed to complete by 11/27/17.  West side of site led once grading has begg needs to be installed to complete by 11/27/17.  Southern side of site led once grading has begg needs to be installed to complete by 11/27/17.  Southern side of site led once grading has beggnestalled to complete by 11/27/17.  Souther side of site led once grading has beggnestalled to complete by 11/27/17.	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp	Pending  Pending  Pending  Pending  Pection.  Pending  Pending	Yes Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta	East side of site leaded once grading has beggg needs to be installed to complete by 11/27/17.  West side of site leaded once grading has beggg needs to be installed to complete by 11/27/17.  Southern side of site leaded once grading has begg needs to be installed to complete by 11/27/17.  Southern side of site leaded once grading has beggnstalled to complete by 11/27/17.  Souther side of site leaded once grading has beggnstalled to complete by 11/27/17.  Souther side of site leaded to complete by 11/27/17.  Souther side of site	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pection.  Pending  Pending	Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta	East side of site liled once grading has beg g needs to be installed d to complete by 11/27/17.  West side of site lilled once grading has beg g needs to be installed d to complete by 11/27/17.  Southern side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pection.  Pending  Pending	Yes Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta	East side of site liled once grading has beg g needs to be installed d to complete by 11/27/17.  West side of site lilled once grading has beg g needs to be installed d to complete by 11/27/17.  Southern side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pection.  Pending  Pending	Yes Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed	East side of site liled once grading has beg g needs to be installed d to complete by 11/27/17.  West side of site lilled once grading has beg g needs to be installed d to complete by 11/27/17.  Southern side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pending  Pending  Pending  Pending  Pending  Pending	Yes Yes Yes		
EM 2 Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:	Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Erosion Control Matting Pending - BMP will be insta The Erosion Control matting John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta The silt fence needs to be i John Navarro was informed Silt Fence Pending - BMP will be insta	East side of site liled once grading has beg g needs to be installed d to complete by 11/27/17.  West side of site lilled once grading has beg g needs to be installed d to complete by 11/27/17.  Southern side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed d to complete by 11/27/17.  Souther side of site lilled once grading has beg installed	10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.  Not done as of last insp 10/2/2017 un on site.	Pending  Pending  Pending  Pending  Pending  Pending  Pending  Pending  Pending  Pending	Yes Yes Yes		

Current Condition:	Pending - BMP will be installed once grading has begun on site.					
	The silt fence needs to be installed					
	John Navarro was informed to complete by 11/27/17. Not done as of last inspection.					
IP 1	Inlet Protection	Souther side of site	10/2/2017	Pending	Yes	
Current Condition:	Pending - BMP will be installed once grading has begun on site.  The inlet protection needs to be installed  John Navarro was informed to complete by 11/27/17. Not done as of last inspection.					
STR	Street Cleaning	streets	5/1/2007	Active	Yes	
Current Condition:	Fair Condition- Pacesetter Homes scraped up dirt from the street in front of lot 297 prior to 6/19/17. Pacetter Homes cleaned the track out from along lot 292 prior to 7/13/17. Regency Homes cleaned the track out in front of lot 329. Track out was cleaned in front of lot 302 prior to inspection on 10/9/17.  Street in between the trail entrance and the park needs to be cleaned.  John Navarro was informed to complete by 12/11/17. Not done as of last inspection.					
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition: 48th and Birchwood Drive					
Inspector Signature:			Reviewed By:	Cato to	he	