E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

## E&A-P2005.198.000 (Clearwater Falls) E&A-P2005.198.009 (Clearwater Falls Trail)

	E&A-P2005.19	98.009 (Clo	earwater Falls 1	rail)			
Inspector: Aaron Tulley		,		,		Stage	
Project Name:	C	Clearwater Falls/Clearwater Falls Trail CSW-201701144				3 and 2	
For Week Ending:							
Project Location:	48	8th and Fair	6/9/2018 view Road- Bellev	ue, NE (Sarpy County)		68123	
Grading:		100%	100%				
Sanitary Sewer: Storm Sewer:		100%	N/A 50%				
Paving:		100%	95%				
Seeding:		100%	50%				
Utilities:		100%	N/A				
Overall Development:		87%	75%				
RAIN FALL AMOUNTS	Amount in tenths	Date in	spected	Weather Conditions			
						Week 1	
Sunday:	0.00"						
Monday Tuesday	<b>0.13"</b> 0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"		05/18/18	Scattered Clouds 83/54			
Saturday	0.01"					W 1.0	
Sunday:	0.05"					Week 2	
Monday	0.00"						
Tuesday	0.63"		05/22/18	Scattered Clouds 84/56			
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
						Week 3	
Sunday:	0.00"						
Monday	0.00"			T			
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"					Week 4	
Sunday:	0.00"					Week 4	
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
						Week 5	
Sunday:	NA						
Monday	NA						
Tuesday	NA						
Wednesday	NA NA						
Thursday	NA NA						
Friday Saturday	NA NA						
Osturusy INA						l	
	None						
Complaints:							

### **Construction Sequencing:**

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail.

# Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail.

#### What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014); John Navarro installed the erosion control matting 1 & 2 for the trail project (1/17/18). Park Area has been seeded and matted (5/9/18). Storm Sewer Installed and disturbed area has been seeded and matted (5/9/18).

# SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

Voc

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

#### CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

#### Comments:

#### Comments:

Home Construction is active in the North part of the development by various builders.

Outlot J was disturbed when construction equipment used it to access lot 279.

### Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP Section.

		ı	T	ı	1	
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CW 5	Concrete Washout	Lot 387		Removed		
Current Condition:	Removed-Celebrity Homes	removed the concrete was	shout prior to inspection on	11/12/2015.		
CW 6	Concrete Washout	Lot 359		Removed		
Current Condition:	Removed- Washout pit was	Removed- Washout pit was removed by Celebrity Homes prior to 3/30/2016.				
CW 7	Concrete Washout	Lot 361		Removed		
Current Condition:	Removed- due to the progre	ession of the site, individua	al lots will be responsible fo	r their concrete	waste. Builders	
	will washout on their own lot washout.	ts, if a washout becomes i	needed the inspector will in	form the applica	nt to install a	
Lot 16	Individual Lot	Lot 16		Removed		
Current Condition:	Removed- Outlot B was see	eded and matted by Horizo	on Homes prior to 5/27/2016	3.		
Lot 17	Individual Lot	Lot 17		Removed		
Current Condition:	Removed- Newport Homes	sodded the lot prior to 11/	12/2015.			
Lot 54	Silt Fence	Lot 54		Removed		
Current Condition:	Removed-Nick Peterson so	dded the lot prior to inspe	ction on 5/28/15.			
Lot 57	Silt Fence	Lot 57		Removed		
Current Condition:	Removed-Horizon Homes sodded the lot prior to inspection on 5/28/15.					
Lot 59	Individual Lot	Lot 59		Removed		
Current Condition:	Removed- Horizon Homes	sodded the lot prior to 11/	12/2015.			
Lot 60	Silt Fence	Lot 60		Removed		
Current Condition:	Removed- Horizon Homes sodded the lot prior to 11/1/16.					
Lot 65	Silt Fence	Lot 65	12/18/2017	Active	Yes	

Current Condition:	Fair Condition - The Home Company began construction on the lot prior to inspection on 12/18/17. No BMPs are required at this time. Silt fence around lot was removed prior to inspection on 5/9/18.					
	Sediment in the streets needs to be cleaned daily.     Silt fence should be reinstalled in the NW corner OR the lot should be stabilized.					
	1. The Home Company was informed to complete by 3/20/18. Not done as of last inspection. The Home Company was reminded on 4/13/18, 5/10/18.					
	2. The Home Company was	informed to complete by	5/16/18.			
Lot 68	Silt Fence	Lot 68	2/3/2017	Active	Yes	
Current Condition:	Fair Condition - Pacesetter I begin on the lot. Pacesetter					
	already in place is sufficient the lot prior to inspection The silt fence needs to be re	as a lot level BMP. Paces on 5/22/18.	setter Homes added a pie			
	Pacesetter Homes was inf	ormed to complete by 5/	129/18			
Lot 69	Silt Fence	Lot 69		Removed		
Current Condition:	Removed- Sherwood Home	s sodded the lot prior to 7	/13/17.			
Lot 76	Silt Fence	Lot 76		Removed		
Current Condition:	Removed- Lot was sodded I		7/31/2015.		T	
Lot 80 Current Condition:	Silt Fence Removed- Horizon Homes s	Lot 80	  /2015	Removed		
Lot 82	Silt Fence	Lot 82		Removed		
Current Condition:	Removed- Lot was sodded I	, , , ,	9/18/2015.			
Lot 88	Silt Fence	Lot 88		Removed		
Current Condition:	Removed- Legacy Homes s		2/16.			
Lot 89  Current Condition:	Individual Lot Removed- the Home Comp	Lot 89	11/1/16	Removed		
Lot 132	Silt Fence	Lot 132		Removed		
Current Condition:	Removed- Regency Homes		19/2015.	1100104		
Lot 155	Silt Fence	Lot 155		Removed		
Current Condition: Lot 209-210	Removed- Regency Homes Silt Fence	sodded the lot prior to 4/1 Lots 209-210	19/2015. I	Removed	1	
Current Condition:	Removed- Celebrity Homes		I		ning silt fence	
	prior to 3/27/17.		,		3	
Lot 255	Individual Lot	Lot 255	0/04/45 :	Removed		
Current Condition:	Removed - Legacy Homes s	· ·	6/24/15 inspection.	Τ		
Lot 256  Current Condition:	Silt Fence Removed- Regency Homes	Lot 256	122/16	Removed		
Current Condition.	rtemoveu- rtegency riomes	souded the lot phor to 11.				
Lot 257	Individual Lot	Lot 257	3/19/2018	Active	Yes	
Current Condition:	Fair Condition - The Home (				. The Home	
	Company installed silt fence	around the perimeter of t	ne lot prior to inspection o	n 3/19/18.		
	1. The streets need to be cle	eaned in front of the lot.				
	2. The silt fence on the S sid	de of the lot is full and sho	uld be cleaned out.			
	1. The Home Company was	informed to complete by	1/3/18 Not done as of last	t inspection. The	Home Company	
	was reminded on 4/13/18, 5	/10/18	4/5/10. Not dolle as of last	inspection. The	Tionie Company	
	2. The Home Company was	informed to complete by	4/18/18. Not done as of la	<mark>st inspection. The</mark>	e Home	
	Company was reminded on	5/10/18.				
Lot 258	Silt Fence	Lot 258		Removed		
Current Condition:	Removed-Charleston Home		nspection on 5/14/15.	Damayad	1	
Lot 259 Current Condition:	Silt Fence Removed-Charleston Home	Lot 259	spection on 5/14/15	Removed		
		•				
Lot 260	Individual Lot	Lot 260	107/0040	Removed		
Current Condition: Lot 261	Removed- Sherwood Home Individual Lot	s sodded the lot prior to 5  Lot 261	/ <i>Z1/Z</i> U16.	Removed		
Current Condition:	Removed- Sherwood Home		l	1 Nonioved		
Lot 272	Silt Fence	Lot 272		Removed		
Current Condition:	Removed- Dean Vogel sodo	led the lot prior to 8/12/20	16.			
Lot 273	Silt Fence	Lot 273		Removed		
Current Condition:	Removed- Sherwood Home		/11/17.	1	1	
Lot 274	Silt Fence	Lot 274	/14/16	Removed	l	
Current Condition:	Removed- Regency Homes		T			
Lot 275	Individual Lot	Lot 275	1/24/2018	Active	No	

Current Condition:	Good Condition - Pacesetter Homes began construction on the lot prior to inspection on 1/24/18. Pacesetter Homes installed silt fence in the rear of the lot prior to inspection on 1/24/18. Streets were cleaned by Pacesetter Homes prior to inspection on 3/27/18.					
Lot 276	Silt Fence	Lot 276		Removed		
Current Condition:	Removed- Dean Vogel sod		)17.			
Lot 277	Silt Fence	Lot 277		Removed		
Current Condition:	Removed- the lot was mista		already sodded.	Removed		
Lot 279	Individual Lot	Lot 279	1/17/2018	Active	Yes	
Current Condition:	Fair Condition -	20(2)0	1/11/2010	7101170	100	
	1. Silt Fence along W side of lot should be repaired/retied & extended and possibly wrapped around corner on front of lot 2. Silt fence on rear of lot is undermined and needs to be backfilled/retrenched  1. The Home Company was informed to complete by 4/18/18. Not done as of last inspection. The Home Company was reminded on 5/10/18.  2. The Home Company was informed to complete by 4/18/18. Not done as of last inspection. The Home Company was reminded on 5/10/18.					
Lot 280	Silt Fence	Lot 280		Removed		
Current Condition:	Removed - Sherwood Hom	es sodded the lot prior to	inspection on 7/27/17.			
Lot 281	Silt Fence	Lot 281		Removed		
Current Condition:	Removed- Dean Vogel sod	ded the lot prior to 8/12/20	016 and removed the silt fe	ence prior to 8/20/2	2016.	
Lot 284	Silt Fence	Lot 284		Removed		
Current Condition:	Removed- Sherwood Home	es sodded the lot prior to 5	5/27/2016.			
Lot 282	Silt Fence	Lot 282		Removed		
Current Condition:	Removed- Oakwood Home		the rear prior to 7/26/201			
Lot 285  Current Condition:	Silt Fence Removed- Sherwood Home	Lot 285	<u> </u> 5/11/17	Removed		
		·	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
Lot 286  Current Condition:	Silt Fence Removed-Sherwood Home	Lot 286	enaction on 7/9/15	Removed		
Lot 291	Silt Fence	Lot 291	1/17/2018	Active	Yes	
Current Condition:	Fair Condition- Silt Fence in the back of the lot needs to be cleaned out and repaired.  Sherwood Homes was informed to complete by 4/3/18. Not done as of last inspection.					
Lot 292	Silt Fence	Lot 292		Removed		
Current Condition:	Removed - Pacesetter Hon	nes sodded the lot prior to	inspection on 10/9/17.			
Lot 293  Current Condition:	Silt Fence	Lot 293	12/25/2017	Active	Yes The Home	
Sansit Condition.	Fair Condition- The Home Company began construction on the lot prior to inspection on 12/18/17. The Home Company installed silt fence in the rear and side of the lot prior to inspection on 3/19/18.  Silt fence is down on the side and in back corner of the lot and needs to be repaired/reinstalled.  The Home Company was informed to complete by 5/16/18.					
Lot 294	Silt Fence	Lot 294		Removed		
Current Condition:	Removed - Sherwood Hom	es sodded the lot prior to	inspection on 10/9/17.			
Lot 296	Silt Fence	Lot 296		Removed		
Current Condition:	Removed - Pine Crest Hom	nes sodded the lot prior to	inspection on 5/9/18.			
Lot 297	Silt Fence	Lot 297	7/13/2017	Active	No	
Current Condition:	Good Condition- Pacesetter Homes installed silt fence in the rear of the lot prior to 7/13/17. Silt fence was removed from the lot prior to inspection on 5/9/18. Due to the lot being inactive, no BMPs will be recommended at this time.					
Lot 299	Silt Fence	Lot 299	1/25/2018	Active	Yes	
L		1	1	1		

Current Condition:	Active - The Home Company began construction on the lot prior to inspection on 12/18/17. The Home Company removed the dirt pile from the front of the lot prior to inspection on 1/17/18. Silt fence was repaired in the NW corner of the lot prior to inspection on 5/9/18.					
	Silt fence needs to be installed on the front of the lot.     Sediment needs to be removed from the curbline.					
	Sediment needs to be removed from the curbline.     Silt fence is down on the side of the lot and needs to be repaired/retied.					
	1. The Home Company was informed on 1/25/18 to complete when weather conditions allow. Not done as of last inspection. The Home company was reminded on 2/21/18, 3/28/18, 5/10/18.					
	2. The Home Company was informed to complete by 3/20/18. Not done as of last inspection. The Home					
	Company was reminded on 3/28/18, 5/10/18.  3. The Home Company was informed to complete by 5/29/18.					
Lot 300	Silt Fence Lot 300 Removed					
Current Condition:	Removed- Pinecrest Homes sodded the lot prior to 7/31/2015.					
Lot 302	Silt Fence Lot 302 Removed					
Current Condition:	Removed - Sherwood Homes sodded the lot prior to inspection on 12/18/17.					
Lot 307	Silt Fence Lot 307 Removed					
Current Condition:	Removed-Sherwood Homes sodded the lot prior to 8/20/2016.					
Lot 310	Silt Fence Lot 310 Removed					
Current Condition:	Removed- Sherwood Home sodded the lot prior to 6/14/17.					
Lot 314	Silt Fence Lot 314 Removed					
Current Condition:	Removed - The Home Company sodded the lot prior to inspection on 8/22/17.					
Lot 315 Current Condition:	Silt Fence Lot 315 Removed  Removed- Legacy Homes sodded the lot prior to 11/22/16.					
Lot 316  Current Condition:	Silt Fence Lot 316 Removed  Removed - THC sodded the lot prior to inspection on 9/19/17.					
Lot 319	Silt Fence Lot 319 Removed					
Current Condition:	Removed-Sherwood Homes sodded the lot prior to 9/13/2016.					
Lot 324	Silt Fence Lot 324 Removed					
Current Condition:	Removed-Sherwood Homes sodded the lot prior to inspection on 7/8/15.  Silt fence Lot 325 Removed					
Lot 325 Current Condition:	Silt fence Lot 325 Removed  Removed- Lot was sodded by Sherwood Homes prior to 11/17/2015.					
Lot 326	Silt Fence Lot 326 Removed					
Current Condition: Lot 328	Removed-Sherwood Homes sodded the lot prior to inspection on 7/16/15.  Silt Fence Lot 328 Removed					
Current Condition:	Removed-Oakwood Homes removed silt fence and sodded the lot prior to inspection on 5/4/15.					
Lot 329  Current Condition:	Silt Fence Lot 329 Removed  Removed - Regency Homes sodded the lot prior to inspection on 5/9/18.					
Lot 336  Current Condition:	Temp. Seeding Lot 336 Removed Removed- As of 8/18/2015, lot has filled in and temp seeding is not needed.					
Lot 336	Silt Fence Lot 336 Removed					
Current Condition:	Removed- Sherwood Homes sodded the lot prior to 10/6/16.					
Lot 337	Silt Fence Lot 337 Removed					
Current Condition:	Removed-Sherwood Homes removed the silt fence and sodded the lot prior to inspection on 5/28/15.					
Lot 344	Silt Fence Lot 344 Removed					
Current Condition:	Removed- the Home Company sodded the lot prior to 11/1/16.					
Pod F	Silt Fence Lots 426-454 Removed					
Current Condition:	Removed-Lots 427 and 428 were sodded prior to 12/1/2015 by Celebrity Homes.					
Pod G	Silt Fence Lots 404-425 Removed					
Current Condition:	Removed-Lot 404 was sodded prior to 6/29/2016. Pod has been built out.					
Pod H	Silt Fence Lots 455-473 Removed					
Current Condition:	Removed- Lot 460 was sodded by Celebrity Homes prior to the inspection on 4/25/2015.					
Pod I  Current Condition:	Silt Fence Lots 346-355 Removed  Removed-Lot 355 was sodded prior to 8/18/2015 by Celebrity Homes.					
Pod J	Silt Fence Lots 381-394 Removed					
Current Condition:	Removed - Pod J is built out as of 8/12/2016.					
Pod K  Current Condition:	Silt Fence Lots 372-403 Removed Removed Removed - Celebrity Homes sodded lot 379 prior to 11/22/16 completing the pod.					
Pod L	Silt Fence Lots 371-356 Removed					
Current Condition:	Removed - Celebrity Homes sodded lots 364, and 361-359 completing the pod.					
SB 1	Sediment Basin Outlot "M" In Place Active No					
Current Condition:	Good Condition-45% Filled. Vegetation was removed from the basin and the slopes were seeded and matted by the SID prior to inspection on 10/23/14. Vegetation was removed from the basin by the SID prior to inspection on 9/19/17.					
SB 2	Sediment Basin   Outlot "L"   11/17/2009   Active   No					
552	11/11/2000 / 10/10					

Current Condition:	Good Condition- 15% Filled - JC Excavating installed pr		/09.		
SB 3	Sediment Basin	School Lot 165	In Place	Active	No
Current Condition:	Good Condition-20% Filled -Cleaned out 02/06				
	Clearw	rater Falls Trail			
CD 1	Check Dam	Northern side of site	10/2/2017	Active	No
Current Condition:	Good Condition - John Nav	varro installed the check d	am prior to inspection on	12/18/17.	
EM 1	Erosion Control Matting	East side of site	10/2/2017	Active	No
Current Condition:	Good Condition -John Nava	arro installed the erosion o	control matting prior to insp	pection on 1/17/18.	
EM 2	Erosion Control Matting	West side of site	10/2/2017	Active	Yes
Current Condition:	Fair Condition - BMP will be matting prior to inspection of the erosion control matting John Navarro was informed	on 1/17/18.	t and needs to be repaired	i.	erosion control
SF 1	Silt Fence	Southern side of site		Removed	
Current Condition:	Removed - BMP no longer	being recommended beca	ause of stabilization of area	a.	
SF 2	Silt Fence	Southern side of site		Removed	
Current Condition:	Removed - BMP no longer	being recommended beca	ause of stabilization of area	a.	
SF 3	Silt Fence	Southern side of site		Removed	
Current Condition:	Removed - John Navarro s	tabilized the area prior to i	nspection on 3/6/18 and the	he silt fence is no l	onger required.
SF 4	Silt Fence	Northern side of site	11/27/2017	Pending	Yes
Current Condition:	Pending - BMP will be insta The silt fence needs to be i John Navarro was informed on 3/7/18.	nstalled		ction. John Navarro	o was reminded
IP 1	Inlet Protection	Southern side of site		Removed	
Current Condition:	Removed - BMP no longer	being recommended beca	ause of stabilization of area	a.	
STR	Street Cleaning	streets	5/1/2007	Active	No
Current Condition:	Good Condition- Pacesetter Homes scraped up dirt from the street in front of lot 297 prior to 6/19/17. Pacesetter Homes cleaned the track out from along lot 292 prior to 7/13/17. Regency Homes cleaned the track out in front of lot 329. Track out was cleaned in front of lot 302 prior to inspection on 10/9/17. Street in between trail entrance and park was cleaned prior to inspection on 5/9/18.				
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No
Current Condition:	Good Condition: 48th and E				
Inspector Signature:			Reviewed By:	et su	