E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599

www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Hannah Herzfeld		- P2005.198.000			Stage	
mapector. Haiman nerzielu	nspector: Hannan Herzfeld Clearwater Falls					
					3	
Project Name:		CSW-201701144				
For Week Ending:	4/10/2021					
Project Location:	48th	48th and Fairview Road- Bellevue, NE (Sarpy County)				
Grading:	10	00% 100%		I		
Sanitary Sewer:		00% N/A				
Storm Sewer:		00% 100%				
Paving:		00% 100%				
Seeding:		00% 99%				
Utilities: Overall Development:		00% N/A 99% 99%		+		
Overan Development.		9970				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
Over the control of t	E 0411				Week	
Sunday: Monday:	5.61" 0.00"					
мопаау: Tuesday:	0.00"	3/16/2021	Showers 49/38	8:30 AM		
Wednesday:	0.00"	3/10/2021	JIIUWEI 3 43/30	U.SU AIVI		
Thursday:	0.00"			†		
Friday:	0.00"			1		
Saturday:	0.00"					
					Week	
Sunday:	0.00"					
Monday:	0.28"					
Tuesday:	0.47"					
Wednesday:	0.00"					
Thursday:	0.00"	3/26/2021	Mostly Cloudy 56/44	8:15 AM		
Friday:	0.02"					
Saturday:	0.00"					
					Week	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					
,					Week	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.12"			1		
Wednesday:	0.54"					
Thursday:	0.10"					
Friday:	0.00"	4/9/2021	Cloudy 63/0	6:40 PM		
Saturday:	0.00"			1		
•					Week	
Sunday:	N/A					
Monday:	N/A					
Tuesday:	N/A					
Wednesday:	N/A					
Thursday:	N/A					
Friday:	N/A					
Saturday:	N/A					
Complaints:	None					
	1. 10110					

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014); John Navarro installed the erosion control matting 1 & 2 for the trail project (1/17/18). Park Area has been seeded and matted (5/9/18). Storm Sewer Installed and disturbed area has been seeded and matted (5/9/18). Area surrounding new sidewalk in NE portion of site has been seeded and matted (7/5/18).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

1 1// (

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?
N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

Inactive built out residential subdivision.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is required in the BMP Section.

				-		
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CW 5	Concrete Washout	Lot 387		Removed		
Current Condition:	Removed - Celebrity Homes removed the concrete washout prior to inspection on 11/12/2015.					
CW 6	Concrete Washout	Lot 359		Removed		
Current Condition:	Removed - Washout pit was removed by Celebrity Homes prior to 3/30/2016.					
CW 7	Concrete Washout	Lot 361		Removed		
Current Condition:	Removed - due to the progression of the site, individual lots will be responsible for their concrete waste.					
	Builders will washout on their own lots, if a washout becomes needed the inspector will inform the applicant					
	to install a washout.					
Lot 81	Individual Lot	Lot 81		Removed		
Current Condition:	Removed - Pacesetter Homes sodded the lot prior to inspection on 9/30/19.					
Lot 297	Individual Lot	Lot 297		Removed		
Current Condition:	Removed - Pacesetter Homes sodded the lot prior to inspection on 8/12/19.					
Pod F	Silt Fence	Lots 426-454		Removed		
Current Condition:	Removed - Lots 427 and 428 were sodded prior to 12/1/2015 by Celebrity Homes.					
Pod G	Silt Fence	Lots 404-425		Removed		
Current Condition:	Removed - Lot 404 was sodded prior to 6/29/2016. Pod has been built out.					
Pod H	Silt Fence	Lots 455-473		Removed		
Current Condition:	Removed - Lot 460 was sodded by Celebrity Homes prior to the inspection on 4/25/2015.					
Pod I	Silt Fence	Lots 346-355		Removed		
Current Condition:	Removed - Lot 355 was sodded prior to 8/18/2015 by Celebrity Homes.					

Pod J	Silt Fence	Lots 381-394		Removed		
Current Condition:	Removed - Pod J is built ou	ıt as of 8/12/2016.				
Pod K	Silt Fence Lots 372-403 Removed					
Current Condition:	Removed - Celebrity Home	s sodded lot 379 prior to	11/22/16 completing the p	od.		
Pod L	Silt Fence	Lots 371-356		Removed		
Current Condition:	Removed - Celebrity Home	s sodded lots 364, and 3	61-359 completing the poo	d.		
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No	
Current Condition:	Good Condition - 26% Fille	d. Vegetation was remove	ed from the basin and the	slopes were see	eded and	
	matted by the SID prior to inspection on 10/23/14. Vegetation was removed from the basin by the SID prior					
	inspection on 9/19/17.					
SB 2	Sediment Basin	Outlot "L"	11/17/2009	Active	No	
Current Condition:	Good Condition - 16% Fille	d				
	- JC Excavating installed prior to inspection on 11/18/09.					
SB 3	Sediment Basin	School Lot 165	In Place	Active	No	
Current Condition:	Good Condition - 21% Filler		1111100	7101170	110	
Current Condition.	- Cleaned out 02/06	u .				
	Clearwa	ater Falls Trail				
CD 1	Check Dam	Northern side of site		Removed		
Current Condition:	Removed - The check dam	will remain in place as a	permanent erosion contro	ol feature in the c	Irainageway	
	running through the Clearw	ater Falls Trail project are	ea, however it will no longe	er be inspected a	as a temporary	
	erosion control BMP.		_	-		
EM 1	Erosion Control Matting	East side of site		Removed		
Current Condition:	Removed - Due to establish		ion control matting will no		cted as a BMP.	
EM 2	Erosion Control Matting	West side of site	J	Removed		
Current Condition:	Removed - Due to establish		ion control matting will no		cted as a BMP.	
SF 1	Silt Fence	Southern side of site	J	Removed		
Current Condition:	Removed - BMP no longer	being recommended bec	ause of stabilization of are	a.		
SF 2	Silt Fence	Southern side of site		Removed		
Current Condition:	Removed - BMP no longer	being recommended bec	ause of stabilization of are	a.		
SF 3	Silt Fence	Southern side of site		Removed		
Current Condition:	Removed - John Navarro s	tabilized the area prior to	inspection on 3/6/18 and	the silt fence is r	no longer	
	required.	·	•		Ü	
SF 4	Silt Fence	Northern side of site		Removed		
Current Condition:	Removed - BMP no longer		ause of stabilization of are			
IP 1	Inlet Protection	Southern side of site	dado or otabilization or are	Removed		
Current Condition:	Removed - BMP no longer		ause of stabilization of are			
STR	Street Cleaning	streets	5/1/2007	Active	No	
Current Condition:	Good Condition - Pacesette					
Current Condition.	Pacesetter Homes cleaned			•		
		_	•	•		
	track out in front of lot 329. Track out was cleaned in front of lot 302 prior to inspection on 10/9/17. Street in between trail entrance and park was cleaned prior to inspection on 5/9/18. Dostal Construction cleaned the					
			•			
	streets prior to inspection o	n 6/4/19. Pacesetter Hor	nes cleaned the street in i	ront of Lot 81 pr	ior to the	
	9/30/19 inspection.			1		
CWDDD Cian	Signa	1 aign on aita	0 10 00	A otivo	Na	
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition - 48th and	PIICUMOOA DLING				
James Verlind		0	Su			
Inspector Signature:			Reviewed By:			
		ı				