E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

Environmental Services Dept. Mar		2005.198.000		igineering Answ	
Increasion Druge Wright	E&A - F	2005.196.000			Stogo
Inspector: Bryce Wright		<b>A</b>	<b>-</b>		Stage
		Clearwater	Falls		3
Project Name:		CSW-20170	1144		0
For Week Ending:		22			
Project Location:	A8th an	60400			
Froject Location.	4001 an	d Fairview Road- Bellev	ue, NE (Salpy County)		68123
Grading:	100%	100%			
Sanitary Sewer:	100%				
Storm Sewer:	100%	100%			
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	99%	100%			
	Amount in tenths	Deta incerente d	Weather Ore differen	Time	
RAIN FALL AMOUNTS		Date inspected	Weather Conditions	Time	Week '
Sunday:	0.00"				Week
Monday	0.00"	ł			
Tuesday	0.00"				
Wednesday	0.53"				
Thursday	0.03"				
Friday	0.00"				
Saturday	0.00"				
					Week 2
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
					Week 3
Sunday:	0.00"				
Monday	0.22"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 4
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"	11/2/2022	Sunny 75	2:45 PM	
Thursday	0.00"				
Friday	1.03"				
Saturday	0.00"				
					Week 5
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"	1			
Friday	0.00"	1			
Saturday	0.00"	1			
			· · · · · · · · · · · · · · · · · · ·		
Complaints:	None				
Construction Sequencing:					

Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading completed and entire site seeded prior to 2005. Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009). Entire site is now inactive for major grading activities as of the inspection on 11/20/2013. Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.								
Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.								
Which portion(s) (i.e. drainage basins) of the site do not h	ave grading, earthwork, or groun	nd disturbance scheduled in th	e next 14 days?					
Frading completed and entire site seeded prior to 2005. Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009). Entire site is now inactive for major grading activities as of the inspection on 11/20/2013. Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17. Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.								
What temporary or permanent stabilization measures list	ed in this section are being imple	mented?						
Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014); John Navarro installed the erosion control matting 1 & 2 for the trail project (1/17/18). Park Area has been seeded and matted (5/9/18). Storm Sewer Installed and disturbed area has been seeded and matted (5/9/18). Area surrounding new sidewalk in NE portion of site has been seeded and matted (7/5/18).								
Checklist Questions:								
Are receiving waters adjacent to the project free of any si Yes Create Corrective Action?	gnificant signs of erosion or sedi	iment that would be associated	d with the construction activity?	•				
N/A								
Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Yes Create Corrective Action? N/A								
Are waste materials (concrete, construction material, haz	ardous, etc.) being managed pror	nerly?						
Yes								
Create Corrective Action? N/A								
Are construction entrances and adjacent streets being ma Yes	aintained adequately?							
Create Corrective Action?								
N/A								
Is dust associated with the construction activity adequate	ely controlled on the site?							
Yes Create Corrective Action?								
N/A								
Comments:								
Comments: Inactive built out residential subdivision.								
Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) No maintenance is required in the BMP Section.								
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CW 5	Concrete Washout	Lot 387		Removed				
Current Condition: CW 6	Removed - Celebrity Home Concrete Washout	s removed the concrete v Lot 359	vashout prior to inspection	on 11/12/2015. Removed				
Current Condition:	Removed - Washout pit wa		lomes prior to 3/30/2016.					
CW 7	Concrete Washout	Lot 361		Removed				
Current Condition:	Removed - due to the prog Builders will washout on the to install a washout.							
Lot 81	Individual Lot	Lot 81		Removed				
Current Condition: Lot 297	Removed - Pacesetter Hon Individual Lot	Lot 297	b inspection on 9/30/19.	Removed				
Current Condition:	Removed - Pacesetter Hon	nes sodded the lot prior to	o inspection on 8/12/19.					
Pod F Current Condition:	Silt Fence Removed - Lots 427 and 42	Lots 426-454 28 were sodded prior to 1	2/1/2015 by Celebrity Hom	Removed nes.				
Pod G	Silt Fence	Lots 404-425		Removed				
Current Condition: Pod H	Removed - Lot 404 was so Silt Fence	dded prior to 6/29/2016. F Lots 455-473	Pod has been built out.	Removed				
Current Condition:	Removed - Lot 460 was so	dded by Celebrity Homes	prior to the inspection on	4/25/2015.				
Pod I Current Condition:	Silt Fence Removed - Lot 355 was so	Lots 346-355	v Celebrity Homes	Removed				
Gurrent Gonuidon.	Internoveu - Lot 355 was so	aada prior to 0/10/2015 D	y Gelebility Hollies.					

Pod J	Silt Fence	Lots 381-394		Removed		
Current Condition:	Removed - Pod J is built or					
Pod K	Silt Fence	Lots 372-403		Removed		
Current Condition:	Removed - Celebrity Home		11/22/16 completing the p			
Pod L	Silt Fence	Lots 371-356		Removed		
Current Condition:	Removed - Celebrity Home Sediment Basin	Outlot "M"	In Place	d. Active	No	
SB 1						
Current Condition:	Good Condition - 0% Filled	0				
	by the SID prior to inspection	0				
	inspection on 9/19/17. Basin conversion was occurring during the inspection on 2/15/22. Basin slope was seeded and matted prior to the inspection on 10/3/22.					
SB 2	Sediment Basin	Outlot "L"	2. 11/17/2009	Active	No	
Current Condition:	Good Condition - 16% Fille		11/17/2009	Active	INU	
Current Condition.	- JC Excavating installed p		2/00			
SB 3	Sediment Basin	School Lot 165		A ativo	Nie	
	Good Condition - 21% Fille		In Place	Active	No	
Current Condition:		a				
	- Cleaned out 02/06					
		ater Falls Trail				
CD 1	Check Dam	Northern side of site		Removed		
Current Condition:	Removed - The check dam	•			• •	
	running through the Clearw	ater Falls Trail project are	ea, however it will no longe	er be inspected a	as a temporary	
	erosion control BMP.					
EM 1	Erosion Control Matting	East side of site		Removed		
Current Condition:	Removed - Due to establis	hment of vegetation, eros	ion control matting will no	longer be inspe	cted as a	
	BMP.			_		
EM 2	Erosion Control Matting	West side of site		Removed		
Current Condition:	Removed - Due to establis	hment of vegetation, eros	ion control matting will no	longer be inspe	cted as a	
SF 1	BMP.	Couthorn side of site		Demostrad		
Current Condition:	Silt Fence Removed - BMP no longer	Southern side of site	avec of stabilization of an	Removed		
SF 2	Silt Fence	Southern side of site	ause of stabilization of are	Removed		
Current Condition:	Removed - BMP no longer		ause of stabilization of are			
SF 3	Silt Fence	Southern side of site		Removed		
Current Condition:	Removed - John Navarro s		inspection on 3/6/18 and		no longer	
	required.	·····				
SF 4	Silt Fence	Northern side of site		Removed		
Current Condition:	Removed - BMP no longer		ause of stabilization of are			
IP 1	Inlet Protection	Southern side of site		Removed		
Current Condition:	Removed - BMP no longer	being recommended bec	ause of stabilization of are	ea.		
STR	Street Cleaning	streets	5/1/2007	Active	No	
Current Condition:	Good Condition - Pacesette	er Homes scraped up dirt	from the street in front of	lot 297 prior to 6	/19/17.	
	Pacesetter Homes cleaned	I the track out from along	lot 292 prior to 7/13/17. R	egency Homes of	cleaned the	
	track out in front of lot 329.	Track out was cleaned in	front of lot 302 prior to in	spection on 10/9	/17. Street in	
	between trail entrance and	park was cleaned prior to	inspection on 5/9/18. Do	stal Constructior	cleaned the	
	streets prior to inspection of	on 6/4/19. Pacesetter Hor	mes cleaned the street in f	front of Lot 81 pr	ior to the	
	9/30/19 inspection.					
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition - 48th and		d = U = 44= = h == = = = 4 =			
Certification Statement:	"I certify, under penalty of la					
	direction or supervision in a		0			
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or					
	persons who manage the system or those persons directly responsible for gathering the information,					
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility					
			milling raise mormation in	icluding the pos	sidility	
of fines and imprisonment for knowing violations."						
	Broga M Waght			Porto Sul		
Inspector Signature:	pul 1		Reviewed By:			