E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

	E&A	A - P2005.198.000			_
Inspector: Ethan Anderson					Stage
		Clearwater	Falls		
Project Name:		CSW-20170	1144		3
		6/10/202			
For Week Ending:		68123			
Project Location:	48th a	48th and Fairview Road- Bellevue, NE (Sarpy County)			
Grading:	100%	6 100%			
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	99%	6 100%			
RAIN FALL AMOUNTS	Amount in tenths	Data increased	Masthan Canditions	Inanastian Time	Storm Event Duration
RAIN FALL AMOUNTS	Amount in tentis	Date inspected	Weather Conditions	Inspection Time	
Sunday	0.00"				Week
Monday	0.00"				
Tuesday	0.01"	1			1
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
2	0.00#				Weel
Sunday Monday	0.00" 0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Weel
Sunday	0.00"				
Monday	0.03"				
Tuesday	0.00"				
Wednesday Thursday	0.00" 0.38"				
Friday	0.13"	6/2/2023	Thunderstorm 89/65	9:50 AM	10:55 PM - 11:55 PI
Saturday	0.04"	0/2/2020	Triandorotorini corco	0.00748	12:00 AM - 12:55 AI
					Weel
Sunday	0.56"				2:55 PM - 3:55 PM
Monday	0.00"	6/5/2023	Sunny 89/63	9:55 AM	
Tuesday	0.00"				
Wednesday	0.00"				
Thursday Friday	0.00" 0.00"				
Saturday	0.66"				2:55 PM - 7:55 PM
outui uuy	0.00				Weel
Sunday	N/A				Wee
Monday	N/A				
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A	1			
Friday	N/A	1			
Saturday	N/A				
- mini may	INCS.			1	
Complaints:	None				

## Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.

Which portion(s) (i.e. drainage basins) of the site do not have grading earthwork, or ground disturbance scheduled in the payt 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.

## What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014); John Navarro installed the erosion control matting 1 & 2 for the trail project (1/17/18). Park Area has been seeded and matted (5/9/18). Storm Sewer Installed and disturbed area has been seeded and matted (7/5/18). NW corner of site has been seeded and matted (7/5/18).

## Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately

Yes

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

## Comments:

Comments:

Built out residential subdivision.

Playground maintenance was completed prior to inspection on 6/2/23.

Site was active for utility maintenance along 44th st during inspection on 6/2/23.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is required in the BMP Section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
CW 5	Concrete Washout	Lot 387		Removed			
Current Condition:	Removed - Celebrity Homes removed the concrete washout prior to inspection on 11/12/2015.						
CW 6	Concrete Washout	Lot 359		Removed			
Current Condition:	Removed - Washout pit was removed by Celebrity Homes prior to 3/30/2016.						
CW 7	Concrete Washout	Lot 361		Removed			
Current Condition:	Removed - due to the progression of the site, individual lots will be responsible for their concrete waste. Builders will						
	washout on their own lots, if a washout becomes needed the inspector will inform the applicant to install a washout.						
Lot 81	Individual Lot	Lot 81		Removed			
Current Condition:	Removed - Pacesetter Homes sodded the lot prior to inspection on 9/30/19.						
Lot 297	Individual Lot	Lot 297		Removed			
Current Condition:	Removed - Pacesetter Homes sodded the lot prior to inspection on 8/12/19.						
Pod F	Silt Fence	Lots 426-454		Removed			
Current Condition:	Removed - Lots 427 and 428 were sodded prior to 12/1/2015 by Celebrity Homes.						
Pod G	Silt Fence	Lots 404-425		Removed			
Current Condition:	Removed - Lot 404 was sodded prior to 6/29/2016. Pod has been built out.						
Pod H	Silt Fence	Lots 455-473		Removed			
Current Condition:	Removed - Lot 460 was sodded by Celebrity Homes prior to the inspection on 4/25/2015.						
Pod I	Silt Fence	Lots 346-355		Removed			
Current Condition:	Removed - Lot 355 was sodded prior to 8/18/2015 by Celebrity Homes.						
Pod J	Silt Fence	Lots 381-394		Removed			
Current Condition:	Removed - Pod J is built out as of 8/12/2016.						
Pod K	Silt Fence	Lots 372-403		Removed			
Current Condition:	Removed - Celebrity Homes sodded lot 379 prior to 11/22/16 completing the pod.						
Pod L	Silt Fence	Lots 371-356		Removed			

Current Condition:	Removed - Celebrity Home	es sodded lots 364, and 36	1-359 completing the pod.				
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No		
Current Condition:	Good Condition - 0% Filled	I. Vegetation was removed	from the basin and the slop	oes were seeded ar	nd matted by the SID		
	conversion was occurring o	8/14. Vegetation was removeduring the inspection on 2/1 installed in basin prior to	5/22. Basin slope was seed				
CD 2	Codingont Dooin	Outlot "L"	14/47/2000	A stills	NI=		
SB 2	Sediment Basin		11/17/2009	Active	No		
Current Condition:	Good Condition - 16% Filled - JC Excavating installed prior to inspection on 11/18/09.						
SB 3	Sediment Basin	School Lot 165	In Place	Active	No		
Current Condition:	Good Condition - 21% Fille - Cleaned out 02/06 Basin	ed is very overgrown as of 6	6/2/23 inspection.				
	CI	earwater Falls Trail					
CD 1	Check Dam	Northern side of site		Removed			
Current Condition:	Removed - The check dam	will remain in place as a poroject area, however it will		eature in the draina			
EM 1	Erosion Control Matting	East side of site		Removed			
Current Condition:	Removed - Due to establis BMP.	hment of vegetation, erosio	n control matting will no lo	nger be inspected a	as a		
EM 2	Erosion Control Matting	West side of site		Removed			
Current Condition:	Removed - Due to establis BMP.	hment of vegetation, erosion	n control matting will no lo	nger be inspected a	as a		
SF 1	Silt Fence	Southern side of site		Removed			
Current Condition:	Removed - BMP no longer	being recommended becar	use of stabilization of area.				
SF 2	Silt Fence	Southern side of site		Removed			
Current Condition:		being recommended becar	use of stabilization of area.				
SF 3	Silt Fence	Southern side of site		Removed			
Current Condition:	Removed - John Navarro s	Removed - John Navarro stabilized the area prior to inspection on 3/6/18 and the silt fence is no longer required.					
SF 4	Silt Fence	Northern side of site		Removed			
Current Condition:	Removed - BMP no longer	being recommended becar	use of stabilization of area.				
IP 1	Inlet Protection	Southern side of site		Removed			
Current Condition:		being recommended becar	use of stabilization of area.				
STR	Street Cleaning	streets	5/1/2007	Active	No		
Current Condition:	cleaned the track out from out was cleaned in front of	8. Dostal Construction clea	17. Regency Homes cleane on 10/9/17. Street in betwee ned the streets prior to insp	ed the track out in fr en trail entrance an	ont of lot 329. Track d park was cleaned		
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No		
Current Condition:	Good Condition - 48th and	,	1 0 10 00	710070	110		
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	En Carlo		Reviewed By:	G. 4 S. 1.	,		