E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

& A CONSULTING GR
Engineering Ans

	1				_	
Inspector: Ethan Anderson		Stage				
	Clearwater Falls					
Project Name:		CSW-201701144				
•						
For Week Ending:		7/8/2023				
Project Location:		18th and Fairview Road- Be	ellevue, NE (Sarpy County)		68123	
Grading:		100%	00%	T	T	
Sanitary Sewer:		100%	N/A			
Storm Sewer:			00%			
Paving:			00%			
Seeding:		100%	00%			
Jtilities:		100%	N/A			
Overall Development:		99% 1	00%			
				1		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration	
· · · · · · · · · · · · · · · · · · ·	0.20"				Week	
Sunday	0.30"	8/48/8855		0.72.22	2:00 AM - 3:00AM	
Monday	0.00"	6/12/2023	Sunny 76/50	9:40 AM		
Tuesday	0.00"			-	-	
Nednesday	0.00"				+	
Thursday	0.00"			+	+	
Friday	0.00"					
Saturday	0.00				Week	
Sunday	0.00"				VVCCN	
Monday	0.00"					
Tuesday	0.00"					
Nednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.06"				7:30 AM - 8:00 AM	
					Week	
Sunday	0.00"				11001	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.96"				7:55 AM - 8:55 AM	
Friday	1.05"	6/30/2023	Cloudy 84/68	10:50 AM	3:55 AM - 6:55 AM	
Saturday	2.42"				2:55 AM - 6:55 PM	
					Week	
Sunday	0.00"					
Monday	0.00"	7/3/2023	Sunny 88/67	9:55 AM		
Гuesday	0.03"					
Wednesday	0.05"					
Thursday	0.00"					
Friday	1.52"	7/7/2023	Thunderstorm 73/59	3:30 PM	7:55 AM - 6:55 PM	
Saturday	0.00"					
Sunday	N/A				Week	
Sunday	N/A					
Monday	N/A				+	
Гuesday	N/A					
N ednesday	N/A			1		
Thursday	N/A				1	
Friday	N/A					
Saturday	N/A					
	<u> </u>		<u> </u>	<u> </u>	<u> </u>	
		· · · · · · · · · · · · · · · · · · ·				
Samuel at the control of the control	N					
Complaints:	None					

E&A - P2005.198.000

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.

Which particularly is decinage basing of the site do not have grading parthwork or ground disturbance calculated in the part 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014); John Navarro installed the erosion control matting 1 & 2 for the trail project (1/17/18). Park Area has been seeded and matted (5/9/18). Storm Sewer Installed and disturbed area has been seeded and matted (7/5/18). NW corner of site has been seeded and matted (7/5/18).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly

Yes

Create Corrective Action2

N/A

Are construction entrances and adjacent streets being maintained adequately

Yes

Create Corrective Action?

N/A

s dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

1.) Built out residential subdivision.

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

1.) No maintenance is required in the BMP Section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
CW 5	Concrete Washout	Lot 387		Removed		
Current Condition:	Removed - Celebrity Homes removed the concrete washout prior to inspection on 11/12/2015.					
CW 6	Concrete Washout	Lot 359		Removed		
Current Condition:	Removed - Washout pit was removed by Celebrity Homes prior to 3/30/2016.					
CW 7	Concrete Washout	Lot 361		Removed		
Current Condition:	Removed - due to the progre	ession of the site, individua	I lots will be responsible for	their concrete w	aste. Builders will	
	washout on their own lots, if a washout becomes needed the inspector will inform the applicant to install a washout.					
Lot 81	Individual Lot	Lot 81		Removed		
Current Condition:	Removed - Pacesetter Home		spection on 9/30/19.			
Lot 297	Individual Lot	Lot 297		Removed		
Current Condition:	Removed - Pacesetter Home		spection on 8/12/19.			
Pod F	Silt Fence	Lots 426-454		Removed		
Current Condition:	Removed - Lots 427 and 428		1/2015 by Celebrity Homes.			
Pod G	Silt Fence	Lots 404-425		Removed		
Current Condition:	Removed - Lot 404 was sodded prior to 6/29/2016. Pod has been built out.					
Pod H	Silt Fence	Lots 455-473		Removed		
Current Condition:	Removed - Lot 460 was sodded by Celebrity Homes prior to the inspection on 4/25/2015.					
Pod I	Silt Fence	Lots 346-355		Removed		
Current Condition:	Removed - Lot 355 was sodded prior to 8/18/2015 by Celebrity Homes.					
Pod J	Silt Fence	Lots 381-394		Removed		
Current Condition:	Removed - Pod J is built out as of 8/12/2016.					
Pod K	Silt Fence	Lots 372-403		Removed		
Current Condition:	Removed - Celebrity Homes sodded lot 379 prior to 11/22/16 completing the pod.					
Pod L	Silt Fence	Lots 371-356		Removed		
Current Condition:	Removed - Celebrity Homes sodded lots 364, and 361-359 completing the pod.					
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No	

Current Condition:	prior to inspection on 10/23 conversion was occurring d	. Vegetation was removed fr /14. Vegetation was remove uring the inspection on 2/15, stalled in basin prior to inspe	ed from the basin by the S /22. Basin slope was see	SID prior to inspection	on 9/19/17. Basin
SB 2	Sediment Basin	Outlot "L"	11/17/2009	Active	No
Current Condition:	Good Condition - 16% Filled		11/11/2000	7.00.70	
Garrone Gorialdon.		ior to inspection on 11/18/09	9		
SB 3	Sediment Basin	School Lot 165	In Place	Active	No
Current Condition:	Good Condition - 21% Filled		III Flace	Active	INU
Current Condition:	-	u s very overgrown as of 6/2/2	23 inspection.		
		earwater Falls Trail			
CD 1	Check Dam	Northern side of site		Removed	
Current Condition:		will remain in place as a per roject area, however it will n			
EM 1	Erosion Control Matting	East side of site		Removed	
Current Condition:	Removed - Due to establish BMP.	nment of vegetation, erosion	control matting will no lo	nger be inspected as	a
EM 2	Erosion Control Matting	West side of site		Removed	
Current Condition:	Removed - Due to establish BMP.	nment of vegetation, erosion	control matting will no lo	nger be inspected as	а
SF 1	Silt Fence	Southern side of site		Removed	
Current Condition:	Removed - BMP no longer l	being recommended becaus	se of stabilization of area.		
SF 2	Silt Fence	Southern side of site		Removed	
Current Condition:		being recommended because	se of stabilization of area		
SF 3	Silt Fence	Southern side of site		Removed	
Current Condition:	Removed - John Navarro st	abilized the area prior to ins	spection on 3/6/18 and the	e silt fence is no longe	er required.
SF 4	Silt Fence	Northern side of site		Removed	
Current Condition:	Removed - BMP no longer	being recommended because	se of stabilization of area.		
IP 1	Inlet Protection	Southern side of site		Removed	
Current Condition:	Removed - BMP no longer l	being recommended becaus	se of stabilization of area		
STR	Street Cleaning	streets	5/1/2007	Active	No
Current Condition:	cleaned the track out from a out was cleaned in front of I prior to inspection on 5/9/18	er Homes scraped up dirt fro along lot 292 prior to 7/13/17 ot 302 prior to inspection on 3. Dostal Construction clean f Lot 81 prior to the 9/30/19	7. Regency Homes cleane 1 10/9/17. Street in betwe ed the streets prior to ins	ed the track out in fron en trail entrance and p	nt of lot 329. Track Dark was cleaned
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No
Current Condition:	Good Condition - 48th and I	Birchwood Drive			
Certification Statement:	direction or supervision in a properly gathered and evalu persons who manage the sy the information submitted is	aw, that this document and a accordance with a system de uated the information submit ystem or those persons dired to the best of my knowled nificant penalties for submitt or knowing violations."	esigned to assure that qua tted. Based on my inquiry ctly responsible for gathe ge and belief, true, accura	alified personnel of the person or ring the information, ate, and complete. I	
Inspector Signature:	En Carlon		Reviewed By:	Gt 54)	