E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services Dept. Manager Engineering Answers							
Increatory Zoch Dozo		E&A- P2006.056.019			Stage		
Inspector: Zach Roza		Courtyards @ Iron Horse CSW-202207403					
Project Name:		68003					
For Week Ending:		2/3/2024 South Lakeview Way and Courtyard Court - Ashland, NE (Saunders County)					
Project Location:	South Lakeview	way and Courtyard Court - A	sniand, NE (Saunders Cou	nty)			
Grading:		80%					
Sanitary Sewer:		0%					
Storm Sewer:		0%					
Paving:		0%					
Seeding: Utilities:		10% 0%					
Overall Development:		10%					
		10/0					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration		
					Week 1		
Sunday: Monday:	0.00"						
Monday: Tuesday:	0.00"						
Wednesday:	0.00"	1/31/2024	Mostly Sunny 58 / 25	10:45 AM			
Thursday:	0.00"			-			
Friday:	0.00"						
Saturday:	0.00"						
Complaints:	Complaints:						
Grubbing began (7/5/23). Gradi	ns) of the site have had a temporary or permane ing began (9/13/23). Grading ceased (11/ ins) of the site do not have grading, earthwork, o	22/23).		t 14 days?			
	ing began (9/13/23). Grading ceased (11/						
	lization measures listed in this section are bein osion Matting 1,2,3,4,6,7 installed (11/1/2		ing (11/1/23).				
Checklist Questions:							
	t to the project free of any significant s	igns of erosion or sediment	that would be associated v	vith the construction	n activity?		
Yes Create Corrective Action?							
N/A							
Have disturbed areas been so prevent erosion. Yes Create Corrective Action?	eeded or otherwise stabilized as requir	ed? List inactive portions of	the project and if stabilizat	ion measure are ad	equate or needed to		
N/A Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?							
Yes Create Corrective Action? N/A							
Are construction entrances and adjacent streets being maintained adequately?							
No Create Corrective Action? No- See BMP Section							
Is dust associated with the construction activity adequately controlled on the site? Yes							
Create Corrective Action? N/A							
Comments:							
Comments: 1.) Site was inactive during the last inspection.							
Findings / Corrective Actions	(Date):						

Findings / Corrective Actions (Date): There are some findings in the BMP Section.						
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
ČE 01	Construction Entrance	Off 113th Street	9/20/2023	Pending	Yes	
Current Condition:	Pending - Pruss Excavation installed a construction entrance prior to the inspection on 9/20/23. Pruss Excavation removed the construction					

	Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
	CE 01	Construction Entrance	Off 113th Street	9/20/2023	Pending	Yes
	Current Condition:	Pending - Pruss Excavation installed a c		the inspection on 9/20/23.	Pruss Excavation ren	noved the construction
		entrance prior to the inspection on 10/25	/23.			
		Or an effective sector and a should be as insta				
		Construction entrance should be re-insta	lied with berm of slit fence sr	iouid be installed to preven	t sediment running or	ito street.
		Pruss Excavation was informed to comp	lete by 11/1/23. Not done as	of the last inspection. Prus	s Excavation was ren	ninded on 12/7/23
		Thus Excavation was informed to comp	lete by Th hzb. Not done as	or the last hispection. I rus		
	DB 01	Diversion Berm	North Side of Site	10/11/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal				INO
	DB 02	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal	led a diversion berm prior to	the inspection on 10/18/23.		
	DB 03	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal	led a diversion berm prior to	the inspection on 10/18/23.		
	FT 01	Fuel Tank	On Site		Removed	
	Current Condition:	Removed- Pruss Excavation removed th		tion on 11/1/23	Removed	
	IP 1 - 2	Inlet Protection	Along Courtyard Court	11/8/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal		pection on 11/8/23.		
	IP 3 - 4	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No
	Current Condition:	Pending- Inlet protection will be installed	once paving is complete.			
	IP 5 - 6	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No
	Current Condition:	Pending- Inlet protection will be installed		0/0/2020	i onding	
	IP 7	Inlet Protection	Along Courtyard Court	8/5/2023	Danding	No
		Pending- Inlet protection will be installed		6/5/2023	Pending	INU
	Current Condition:					
		Erosion Matting	South East portion of the	11/1/2023	Active	No
<u> </u>	MT 01		site			
	Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/23	3.	
		Erosion Matting	South East portion of the	11/1/2023	Active	No
	MT 02	, , , , , , , , , , , , , , , , , , ,	site			NO
	Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/23	3.	
			South West portion of the			
	MT 03	Erosion Matting	site	11/1/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal		to the inspection on 11/1/23	3.	
-	MT 04	Erosion Matting	ADJ to Private Drive	11/1/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal				NU
				· · · · · · · · · · · · · · · · · · ·		
	MT 05	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No
	Current Condition:	Pending- Erosion Matting will be installed				
	MT 06	Erosion Matting	North of Courtyard Court	11/1/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/23	3.	
	MT 07	Erosion Matting	North of Courtyard Court	11/1/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/23	3.	
_	PT 01	Portable Toilet	On Site		Removed	
_	Current Condition:	Removed- Pruss Excavation removed th		I spection on 11/1/23	Removed	
	SF 01 - 09	Silt Fence	Eastern Perimeter	11/1/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal			7101170	
	SF 10 - 14	Silt Fence	Northern Checks	7/12/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal	led SF 11 prior to the inspect	ion on 7/12/23. Pruss exca	vation removed SF 1	1 due to grading prior to
		the inspection on 9/20/23. Due to erosion				
		be recommended as of 11/2/23. Pruss E	xcavation installed silt fence	11 and 14 prior to the inspe	ection on 11/8/23.	
\vdash	SF 15 - 18	Silt Fence	Western Perimeter	11/1/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal			7,01170	110
	SF 19	Silt Fence	Northern Perimeter	7/12/2023	Active	No
	Current Condition:	Good Condition- Pruss Excavation instal				
						-
<u> </u>	ourion condition.	inspection on 9/27/23. Pruss Excavation				
			repaired the silt fence prior to	o the inspection on 11/8/23		
	SF 20 - 30	inspection on 9/27/23. Pruss Excavation Silt Fence			Pending	No
⊢			repaired the silt fence prior to Southern Half of Courtyard Court	o the inspection on 11/8/23		No
1	SF 20 - 30	Silt Fence Pending- Silt fence will be installed once	repaired the silt fence prior to Southern Half of Courtyard Court grading starts.	o the inspection on 11/8/23		No
	SF 20 - 30 Current Condition:	Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard	o the inspection on 11/8/23		No
	SF 20 - 30 Current Condition: SF 31 - 34	Silt Fence Pending- Silt fence will be installed once Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court	o the inspection on 11/8/23 8/5/2023	Pending	
	SF 20 - 30 Current Condition:	Silt Fence Pending- Silt fence will be installed once	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court	o the inspection on 11/8/23 8/5/2023	Pending	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court	o the inspection on 11/8/23 8/5/2023	Pending	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023	Pending Pending	No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023	Pending Pending	No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 ne inspection on 11/1/23.	Pending Pending Active	No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023	Pending Pending	No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western Perimeter	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active	No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western Perimeter led Silt fence 35-42 prior to th	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active Active	No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western Perimeter led Silt fence 35-42 prior to th West of Courtyard Court	b the inspection on 11/8/23 8/5/2023 11/1/2023 he inspection on 11/1/23. 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active	No No No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition: SF 49 - 51	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western Perimeter led Silt fence 35-42 prior to th West of Courtyard Court led Silt fence 35-42 prior to th	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 be inspection on 11/1/23. 11/1/2023 11/1/2023 be inspection on 11/1/23. 11/1/2023 be inspection on 11/1/23. 11/1/2023 be inspection on 11/1/23. 11/1/2023	Pending Pending Active Active	No No No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition: SF 49 - 51 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th West of Courtyard Court led Silt fence 35-42 prior to th West of Courtyard Court led Silt fence 35-42 prior to th Northern Half of Western	b the inspection on 11/8/23 8/5/2023 11/1/2023 he inspection on 11/1/23. 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active Active	No No No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition: SF 49 - 51 Current Condition: SF 52 - 55	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to tf Southern Half of Western Perimeter led Silt fence 35-42 prior to tf West of Courtyard Court led Silt fence 35-42 prior to tf Northern Half of Western Perimeter	a the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 ne inspection on 11/1/23. 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active Active Active	No No No
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition: SF 49 - 51 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to tf Southern Half of Western Perimeter led Silt fence 35-42 prior to tf West of Courtyard Court led Silt fence 35-42 prior to tf Northern Half of Western Perimeter	a the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 ne inspection on 11/1/23. 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active Active Active	No No No

Current Condition:	Good Condition- Streets were clean durin	ng the inspection on 11/22/23				
SWPPP Sign	SWPPP Sign	On Site	10/11/2023	Active	No	
Current Condition:	Good Condition- E&A inspector installed a SWPPP sign during the inspection on 10/11/23.					
WO 01	Concrete Washout	On Site		Removed		
Current Condition:	Removed- Pruss Excavation removed the concrete washout prior to the inspection on 11/22/23.					
WS 01	Waste Storage Area	On Site	8/5/2023	Pending	No	
Current Condition:	Pending- Waste storage will be installed as necessary.					
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
Inspector Signature:	Joh Ray			Georgeneer Reviewed By:	to See	