E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



A like CDESC CISEC

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager				Engineering Answers			
	<u> </u>	E&A- P2006.056.026	<u> </u>				
Inspector: Ethan Anderson							
Project Name:		1 68003					
For Week Ending:							
Project Location:	8/3/2024 68003 South Lakeview Way and Courtyard Court - Ashland, NE (Saunders County)						
Grading:	80%	,		T			
Sanitary Sewer:	100%						
Storm Sewer:	5%						
Paving:	0%						
Seeding:	80%						
Utilities:	0%						
Overall Development:	10%						
	107						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration		
					Weel		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.45"	7/31/2024	Sunny 93/76	10:40 AM	5:39 PM - 8:04 PM		
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"						
Complaints:	None						
Construction Sequencing:							
	of the site have had a temporary or permanent ce	• •	. •				
Grubbing began (7/5/23). Gradino began (5/1/24). Storm sewer inst	g began (9/13/23). Grading ceased (11/22/2 callation began (6/12/24).	3). Sanitary Installation be	gan (3/20/24). Sanitary inst	allation complete (5/1/2	24). Water installation		
Grubbing began (7/5/23). Grading	of the site do not have grading, earthwork, or group began (9/13/23). Grading ceased (11/22/2)			allation complete (5/1/2	24). Water installation		
began (5/1/24). Storm sewer inst	allation began (6/12/24)						
20gan (0, 1/2 i). Greim Gemei iner	anation bogain (6/12/24).						

Existing Vegetation (7/5/23). Erosion Matting 1,2,3,4,6,7 installed (11/1/23). Seeding under erosion matting (11/1/23). Entire site seeded (3/13/24).

## Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?
No- See BMP Section

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments: Comments:

1.) Site was active for sanitary installation during the last inspection. Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):
1.) Some maintenance is required in the BMP section.

			I	Ι	T		
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 01 Current Condition:	Construction Entrance	Off 113th Street	9/20/2023	Pruss Excavation rer	Yes		
ourrent condition.	Pending - Pruss Excavation installed a construction entrance prior to the inspection on 9/20/23. Pruss Excavation removed the construction entrance prior to the inspection on 10/25/23. Great Plains Contractor Services installed silt fence to prevent sediment from leaving the site						
	prior to the inspection on 4/24/24. Great Plains Contractor services installed silt fence checks and a berm to prevent sediment from leaving the						
	site through the entrance prior to the inspection on 6/5/24.						
	A rock construction entrance should be installed.						
	Great Plains Contractor Services was in	formed to complete by 6/19/2	4. Not done as of last insp	ection. Great Plains	Contractor Services was		
PD 04	reminded on 6/26/24, 8/2/24		<u> </u>				
DB 01 Current Condition:	Diversion Berm  Fair Condition- Pruss Excavation installe	North Side of Site d a diversion berm prior to the	10/11/2023 le inspection on 10/11/23.	Active	Yes		
		· ·					
	Berm should be repaired in multiple loca	tions.					
	Great Plains Contractor Services was in	formed to complete by 7/3/24	. Not done as of last inspe	ection. Great Plains (	Contractor Services was		
DB 02	reminded on 8/2/24 Diversion Berm	Eastern Side of Site	10/18/2023	Active	l No		
Current Condition:	Good Condition- Pruss Excavation instal				I NO		
DB 03 Current Condition:	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No		
FT 01	Good Condition- Pruss Excavation instal	On Site	7/10/2024	Active	No		
Current Condition:	Good Condition - Great Plains Contracto						
IP 1 - 2 Current Condition:	Inlet Protection Fair Condition - Pruss Excavation installe	Along Courtyard Court and 2 prior to the insp	11/8/2023 ection on 11/8/23. Great F	Active Plains Contractor Serv	Yes vices cleaned out and		
	replaced out the inlets prior to the inspec						
	Inlets should be cleaned out.						
	milete sheard be dicarred eat.						
	Great Plains Contractor Services was in	formed to complete by 7/3/24	. Not done as of last inspe	ection. Great Plains (	Contractor Services was		
IP 3 - 4	reminded on 8/2/24 Inlet Protection	Along Courtyard Court	7/24/2024	Active	No		
Current Condition:	Good Condition - Great Plains Contracto						
IP 5 - 6 Current Condition:	Inlet Protection Pending- Inlet protection will be installed	Along Courtyard Court once paving is complete.	8/5/2023	Pending	No		
IP 7	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Inlet protection will be installed	once paving is complete.  South East portion of the					
MT 01	Erosion Matting	site	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior South East portion of the	·		I		
MT 02	Erosion Matting	site	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior South West portion of the	to the inspection on 11/1/2	!3. I	ı		
MT 03	Erosion Matting	site	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal				1		
MT 04 Current Condition:	Erosion Matting Good Condition- Pruss Excavation instal	ADJ to Private Drive	11/1/2023 to the inspection on 11/1/2	Active 3.	No		
MT 05	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No		
Current Condition: MT 06	Pending- Erosion Matting will be installed Erosion Matting	North of Courtyard Court	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/2	3.			
MT 07 Current Condition:	Erosion Matting Good Condition- Pruss Excavation instal	North of Courtyard Court	11/1/2023 to the inspection on 11/1/2	Active	No		
PT 01	Portable Toilet	On Site	7/10/2024	Active	Yes		
Current Condition:	Fair Condition - Great Plains Contractor	Services installed and secure	ed a portable toilet prior to	the inspection on 7/1	0/24.		
	Portable toilet should be secured.						
SF 01 - 09	Great Plains Contractor Services was Silt Fence	Eastern Perimeter	11/1/2023	Active	Yes		
Current Condition:	Fair Condition- Pruss Excavation installe						
	section of silt fence 2 prior to the inspect	ion on 7/24/24.					
	Silt fence should be repaired.						
	Count Dining Country 1 Co.		Not done or 61 11	-ti On- ( Divi	2		
	Great Plains Contractor Services was in reminded on 8/2/24	formed to complete by 7/3/24	. Not done as of last inspe	ection. Great Plains C	Contractor Services was		
SF 10 - 14	Silt Fence	Northern Checks	7/12/2023	Pending	No		
Current Condition:	Pending - Pruss Excavation installed SF inspection on 9/20/23. Due to erosion materials						
	recommended as of 11/2/23. Pruss Exc	avation installed silt fence 11	and 14 prior to the inspect	tion on 11/8/23. SF 11	was removed and SF 14		
	was damaged prior to the inspection on 50 and 51 being extended, re-installation				spection. Due to silt fence		
	Joo and 51 being extended, re-installation	io. or ir and 14 will no long	or be recommended as of	0///24.			
SF 15 - 18	Silt Fence	Western Perimeter	11/1/2023	Active	Yes		

Current Condition:	Fair Condition- Pruss Excavation installed Silt fence 15-18 prior to the inspection on 11/1/23. Great Plains Contractor Services repaired the damaged portion of SF 15 prior to the inspection on 5/1/24.						
	Silt fence should be repaired.						
SF 19	Great Plains Contractor Services w Silt Fence	vas informed to complete by 8  Northern Perimeter	8 <mark>/7/24.</mark> 7/12/2023	Active	l No		
Current Condition:							
Surrent Schallon.	Good Condition - Pruss Excavation installed the silt fence prior to the inspection on 7/12/23. Part of the silt fence was down during the inspection on 9/27/23. Pruss Excavation repaired the silt fence prior to the inspection on 11/8/23. Great Plains Contractor Services repaired						
	the silt fence prior to the inspection on 7/24/24.						
SF 20 - 30	Silt Fence	Southern Half of Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Silt fence will be installed on						
SF 31 - 34	Silt Fence	Northern Half of Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Silt fence will be installed on	nce grading starts.	ı	ı	Γ		
SF 35 - 42	Silt Fence	Eastern Perimeter Checks	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation ins		ne inspection on 11/1/23.	T	T		
SF 43 - 48	Silt Fence	Southern Half of Western Perimeter	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation ins			A -45	V		
SF 49 - 51  Current Condition:	Silt Fence Fair Condition- Pruss Excavation insta	West of Courtyard Court	11/1/2023	Active	Yes Services extended silt		
	Great Plains Contractor Services was was reminded on 8/2/24		24. Not done as of last insp	pection. <b>Great Plains</b>	Contractor Services		
SF 52 - 55	Silt Fence	Northern Half of Western Perimeter	11/1/2023	Active	No		
Current Condition: STR	Good Condition- Pruss Excavation ins	stalled Silt fence 35-42 prior to the ADJ and Internal Streets		Active	Yes		
Current Condition:	Fair Condition- Streets were clean du						
	side of the site prior to the inspection on 6/5/24.  1.) Adjacent streets should be cleaned. 2.) Trail should be cleaned off in multiple locations.  1.) Great Plains Contractor Services was informed to complete by 4/18/24. Not done as of the last inspection. Great Plains Contractor Services was reminded on 5/10/24, 5/23/24, 6/14/24, 6/26/24, 8/2/24  2.) Great Plains Contractor Services was informed to complete by 6/27/24. Not done as of last inspection. Great Plains Contractor Services was reminded on 8/2/24						
SWPPP Sign	SWPPP Sign	On Site	10/11/2023	Active	No		
Current Condition:	Good Condition- E&A inspector install		spection on 10/11/23.		Γ		
WO 01	Concrete Washout	On Site		Removed			
Current Condition:	Removed- Pruss Excavation removed			1			
WS 01	Waste Storage Area	On Site	8/5/2023	Pending	No		
Current Condition: Certification Statement	Pending- Waste storage will be installed as necessary.  "I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	En Carlon	·		Reviewed By:	Get Soly		