E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

**Engineering Answers** 

		E&A- P2006.056.	)26				
Inspector: Ethan Anderson		Stage					
Project Name:		Courtyards @ Iron Horse CSW-202207403 11/2/2024					
For Week Ending:							
Project Location:	South Lakeview V	South Lakeview Way and Courtyard Court - Ashland, NE (Saunders County)					
Grading:	80%			1			
Sanitary Sewer:	100%						
Storm Sewer:	5%						
Paving:	40%						
Seeding:	80%						
Utilities:	0%						
Overall Development:	10%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration		
	0.00				Week		
Sunday:	0.00"						
Monday: Tuesday:	0.00"						
Wednesday:	0.62"	10/30/2024	Cloudy 77/48	11:40 AM	10:55 AM - 5:55 PM		
Thursday:	0.06"	10/30/2024	Cloudy 11146	11.40 AW	10.33 ANI - 3.33 F NI		
Friday:	0.00"						
Saturday:	0.06"						
Complaints:	None						

## **Construction Sequencing:**

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grubbing began (7/5/23). Grading began (9/13/23). Grading ceased (11/22/23). Sanitary Installation began (3/20/24). Sanitary installation complete (5/1/24). Water installation began (5/1/24). Storm sewer installation began (6/12/24).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grubbing began (7/5/23). Grading began (9/13/23). Grading ceased (11/22/23). Sanitary Installation began (3/20/24). Sanitary installation complete (5/1/24). Water installation began (5/1/24). Storm sewer installation began (6/12/24).

Existing Vegetation (7/5/23). Erosion Matting 1,2,3,4,6,7 installed (11/1/23). Seeding under erosion matting (11/1/23). Entire site seeded (3/13/24).

Checklist Questions

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Yes

**Create Corrective Action?** 

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

**Create Corrective Action?** 

N/A

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?
No- See BMP Section

Is dust associated with the construction activity adequately controlled on the site?

**Create Corrective Action?** 

N/A

Comments:
Comments:
1.) Site was active for grading and paving during the last inspection.
Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
1.) Some maintenance is required in the BMP section.

		I	T		T		
Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
ČE 01	Construction Entrance	Off 113th Street		Removed			
Current Condition:	Removed - Great Plains Contra		ntrance prior to the insp	ection on 10/30/24.			
DB 01	Diversion Berm	North Side of Site	10/11/2023	Active	No		
Current Condition:	Good Condition - Pruss Excavat		n prior to the inspection or	n 10/11/23. Pruss Exc	cavation repaired the		
	berm prior to the inspection on 9						
DB 02	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No		
Current Condition:	Good Condition - Pruss Excavat				T		
DB 03	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No		
Current Condition: FT 01	Good Condition - Pruss Excavat	On Site		1 10/18/23. Active	N <sub>a</sub>		
Current Condition:	Good Condition - Great Plains C		7/10/2024		No No		
IP 1 - 2	Inlet Protection	Along Courtyard Court	11/8/2023	Active	0/24. No		
Current Condition:							
our ent condition.	Condition: Good Condition - Pruss Excavation installed IP 1 and 2 prior to the inspection on 11/8/23. Great Plains Contractor Sout and replaced out the inlets prior to the inspection on 6/5/24. Great Plains Contractor Services cleaned out the in						
	the inspection on 8/7/24.		in Grout Flumb Contracto	or Corvidos sisterios s	at the iniet intere prior		
IP 3 - 4	Inlet Protection	Along Courtyard Court	7/24/2024	Active	Yes		
Current Condition:	Fair Condition - Great Plains Con						
	Inlet and inlet protection should be Great Plains Contractor Services		oy 10/16/24. Not done as o	of last inspection.			
IP 5 - 6	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending - Inlet protection will be						
IP 7	Inlet Protection	Along Courtyard Court	8/7/2024	Active	No		
Current Condition:	Good Condition - Great Plains C						
IP 8	Area Inlet Protection	N of Courtyard Court	8/28/2024	Active	No		
Current Condition:	Good Condition - Pruss Excava				Great Plains Contractor		
	Services repaired the silt fence						
IP 9	Area Inlet Protection	NW of DB 02	10/9/2024	Active	No		
Current Condition:	Good Condition - Great Plains C						
IP 10	Area Inlet Protection	W of DB 02	8/28/2024	Active	No		
Current Condition:	Good Condition - Great Plains C		a silt fence around the are	a inlet prior to the ins	pection on 8/28/24.		
MT 04	Erosion Matting	South East portion of the	11/1/2023	Active	No		
MT 01		site	i	44/4/00			
Current Condition:	Good Condition - Pruss Excavat		ing prior to the inspection	on 11/1/23.	I		
MT 02	Erosion Matting	South East portion of the site	11/1/2023	Active	No		
Current Condition:	Good Condition - Pruss Excavat		ing prior to the inspection	on 11/1/23			
Current Condition.		South West portion of the					
MT 03	Erosion Matting	site	11/1/2023	Active	No		
Current Condition:	Good Condition - Pruss Excavat		ing prior to the inspection	on 11/1/23			
MT 04	Erosion Matting	ADJ to Private Drive	11/1/2023	Active	No		
Current Condition:	Good Condition - Pruss Excavat						
MT 05	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No		
Current Condition:	Pending - Erosion Matting will be	installed once grading is co	mplete.				
MT 06	Erosion Matting	North of Courtyard Court		Active	No		
Current Condition:	Good Condition - Pruss Excavat	ion installed the erosion matt	ing prior to the inspection	on 11/1/23.			
MT 07	Erosion Matting	North of Courtyard Court		Active	No		
Current Condition:	Good Condition - Pruss Excavat						
PT 01	Portable Toilet	On Site	7/10/2024	Active	No		
Current Condition:	Good Condition - Great Plains C		•		tion on 7/10/24. Great		
05.04.00	Plains Contractor Services secui						
SF 01 - 09	Silt Fence	Eastern Perimeter	11/1/2023	Active	Yes		
Current Condition:	Fair Condition - Pruss Excavation removed a section of silt fence 2 Silt fence should be repaired.  Great Plains Contractor Services	prior to the inspection on 7/	24/24.				
	Services was reminded on 8/2/2		, as a on a on	opecatori. Creat			
SF 10 - 14	Silt Fence	Northern Checks	7/12/2023	Pending	No		
Current Condition:	Pending - Pruss Excavation instato the inspection on 9/20/23. Dutwill no longer be recommended a 11 was removed and SF 14 was the 4/3/24 inspection. Due to silt of 6/7/24.	alled SF 11 prior to the inspe e to erosion matting, diversion as of 11/2/23. Pruss Excavat damaged prior to the inspec	ction on 7/12/23. Pruss ex on berms, and other silt fer ion installed silt fence 11 a tion on 3/20/24 due to sar	ccavation removed S nce being installed, s and 14 prior to the ins nitary installation. SF	F 11 due to grading prior ilt fence 11,13, and 14 spection on 11/8/23. SF 14 was removed prior to		
SF 15 - 18	Silt Fence	Western Perimeter	11/1/2023	Active	Yes		
JI 13 - 10	J Sill Felice	western Fermietel	11/1/2023	ACTIVE	162		

Current Condition:	Fair Condition - Pruss Excavation repaired the damaged portion of			1/1/23. Great Plains 0	Contractor Services	
	Silt fence should be repaired.					
	Great Plains Contractor Services Services was reminded on 8/29/		by 8/7/24. Not done as of l	ast inspection. Great	Plains Contractor	
SF 19	Silt Fence	Northern Perimeter	7/12/2023	Active	No	
Current Condition:	Good Condition - Pruss Excavation installed the silt fence prior to the inspection on 7/12/23. Part of the silt fence was down during the inspection on 9/27/23. Pruss Excavation repaired the silt fence prior to the inspection on 11/8/23. Great Plains Contractor Services repaired the silt fence prior to the inspection on 7/24/24.					
SF 20 - 30	Silt Fence	Southern Half of Courtyard Court		Pending	No	
Current Condition:	Pending- Silt fence will be install					
SF 31 - 34	Silt Fence	Northern Half of Courtyard Court	8/5/2023	Pending	No	
Current Condition:	Pending- Silt fence will be install	ed once grading starts.	•			
SF 35 - 42	Silt Fence	Eastern Perimeter Checks	11/1/2023	Active	No	
Current Condition:	Good Condition - Pruss Excavat	ion installed Silt fence 35-42	prior to the inspection on	11/1/23.		
SF 43 - 48	Silt Fence	Southern Half of Western Perimeter	11/1/2023	Active	No	
Current Condition:	Good Condition - Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23. Great Plains Contractor Services removed sections of silt fence 47 due to grading in the area prior to the inspection on 9/25/24. E&A inspector will monitor.					
SF 49 - 51	Silt Fence	West of Courtyard Court	11/1/2023	Active	No	
Current Condition:	Good Condition - Pruss Excavate extended silt fence 50 and 51 prusor to grading in the area prior to the 51 due to grading in the area prior.	ior to the inspection on 6/5/2 e inspection on 9/18/24. Grea or to the inspection on 9/25/2	4. Great Plains Contractor at Plains Contractor Service	Services removed a ces removed sections	section of silt fence due	
SF 52 - 55	Silt Fence	Northern Half of Western Perimeter	11/1/2023	Active	No	
Current Condition:	Good Condition - Pruss Excavat					
STR Current Condition:	Streets Fair Condition - Streets were cle	ADJ and Internal Streets		Active	Yes	
	the north side of the site prior to on 10/8/24.  Adjacent streets should be clear Great Plains Contractor Services Services was reminded on 5/10/	ned. s was informed to complete b	oy 4/18/24. Not done as of	the last inspection. G		
SWPPP Sign	SWPPP Sign	On Site	10/11/2023	Active	No	
Current Condition:	Good Condition - E&A inspector					
WO 01	Concrete Washout	On Site	9/25/2024	Active	No	
Current Condition:	Good Condition - Great Plains Contractor Services installed a lined concrete washout pit prior to the inspection on 9/25/24. Great Plains Contractor Services removed the lined concrete washout pit prior to the inspection on 10/23/24. Great Plains Contractor Services added the concrete waste from the pit to a concrete waste pile prior to the inspection on 10/23/24.					
WS 01	Waste Storage Area	On Site	8/5/2023	Pending	No	
Current Condition:	Pending- Waste storage will be i	•				
Certification Statement	"I certify, under penalty of law, the accordance with a system designed assed on my inquiry of the persinformation, the information substitute are significant penalties for violations."	ned to assure that qualified p on or persons who manage th mitted is, to the best of my kr	ersonnel properly gathere he system or those persor nowledge and belief, true,	d and evaluated the ins directly responsible accurate, and comple	nformation submitted. for gathering the ete. I am aware that	
Inspector Signature:	En Carlon			Reviewed By:	Sto Sul	