E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Yes

N/A

**Create Corrective Action?** 

**Engineering Answers** 

Inspector: Josh Ellington					Stage	
	Diers 8th Addition					
David Marke	CSW 202207520					
Project Name:						
For Week Ending:		10/28/2023				
Project Location:	E 22nd Street and Deer Crossing, Fremont, NE (Dodge County)					
Grading:	80%					
Sanitary Sewer:	15%					
Storm Sewer:	2%					
Paving:	0%					
Seeding:	0%					
Utilities:	0%					
Overall Development:	20%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
					Wee	
Sunday:	0.00"					
Monday	0.00"	10/23/2023	Sunny 60	10:00 AM		
Tuesday	0.00"					
Wednesday	0.04"					
Thursday	0.04"					
Friday	0.21"					
Saturday	0.00"					
	None					
Complaints:						
Construction Sequencing:						
Which portion(s) (i.e. drainage basin						
Stripping and grading began (6, Crossing (6/26/2023).	/5/2023). Grading along Elkhor	n Drive east of Deer	Crossing (6/12/2023). G	ading along Elkhorn Dr	ive west of Deer	
Which portion(s) (i.e. drainage basin	s) of the site do not have grading.	arthwork, or ground dis	turbance scheduled in the ne	ext 14 days?		
Stripping and grading began (6, Crossing (6/26/2023).					ive west of Deer	
What temporary or permanent stabil	ization measures listed in this secti	on are being implemente	d?			
Existing vegetation.						
Checklist Questions:						

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes					
Create Corrective Action?					
N/A					
Are waste materials (concrete, cor	nstruction material, haza	ardous, etc.) being ma	naged properly?		
Yes					
Create Corrective Action?					
N/A					
Are construction entrances and ac	djacent streets being ma	intained adequately?			
Yes					
Create Corrective Action?  N/A					
N/A					
Is dust associated with the constr	uotion activity adequate	ly controlled on the ci	ho2		
Yes	uction activity adequate	ly controlled on the Si	le r		
Create Corrective Action?					
N/A					
Comments:					
Comments:					
1.) Site was active for storm sewer in	stallation during the curre	ent inspection.			
•					
Findings / Corrective Actions (Dat					
Findings / Corrective Actions (Dat					
1.) Some maintenance is required in	the BMP section.				
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
Berm	Dirt Berm	On Site	-	Removed	
Current Condition:	Removed - A berm in the	e northwest portion of th	e site was installed in lieu	of silt fence as peri	meter control prior to
	the 6/12/23 inspection. T	he berm in the northwe	st portion of the site was r	emoved prior to the	6/26/23 inspection
	due to grading, SF 3 will	now be recommended.	A berm was installed to t	he west prior to the 6	6/26/23 inspection.
	BMP was changed as of	7/06/23.			
B 1	Berm	See SWPPP		Removed	
Current Condition:	= = : : : :		ctivity prior to the 9/11/23		
Current Condition.	Tremoved - Berni was re		Cuvity prior to the 9/11/25	mspection.	
B 2	Berm	See SWPPP		Removed	
Current Condition:	Removed - Berm was re	moved due to grading a	ctivity prior to the 9/11/23	inspection.	
B 3	Berm	See SWPPP		Removed	
			estivity prior to the 0/11/22		
Current Condition:	Removed - beilli was ie		ctivity prior to the 9/11/23		
B 4	Berm	See SWPPP		Removed	
Current Condition:	Removed - Berm was re	moved due to grading a	ctivity prior to the 9/11/23	inspection.	
CE 1	Construction Entrance	N Luther Road	7/3/2023	Active	No
Current Condition:			removed prior to the 7/17		
Guitoiti Goilattioni.	1		on either side of the entr		
05.0				·	•
CE 2	Construction Entrance	Elkhorn Drive	9/25/2023	Pending	Yes
Current Condition:			porary barricade for the e	ntrance prior to the 1	0/9/23 inspection
Current Condition:	Thompson Construction	will install a rock entran	ce once soil compaction i	ntrance prior to the 1	0/9/23 inspection
Current Condition:		will install a rock entran	ce once soil compaction i	ntrance prior to the 1	0/9/23 inspection
Current Condition:	Thompson Construction moved the barricade pr	will install a rock entran rior to the 10/24/23 ins	ce once soil compaction i pection.	ntrance prior to the 1	0/9/23 inspection
Current Condition:	Thompson Construction	will install a rock entran rior to the 10/24/23 ins	ce once soil compaction i pection.	ntrance prior to the 1	0/9/23 inspection
Current Condition:	Thompson Construction moved the barricade properties of the construction moved the barricade or in the construction moved the barricade or in the construction of the construction of the construction moved the construction	will install a rock entran rior to the 10/24/23 ins	ce once soil compaction in pection. entrance.	ntrance prior to the 1	0/9/23 inspection
Current Condition:	Thompson Construction moved the barricade pr	will install a rock entran rior to the 10/24/23 ins	ce once soil compaction in pection. entrance.	ntrance prior to the 1	0/9/23 inspection
	Thompson Construction moved the barricade properties of the barricade or in the construction of the constr	will install a rock entran rior to the 10/24/23 ins install a construction on on was informed to co	ce once soil compaction in pection. entrance. mplete by 10/30/23.	ntrance prior to the 1 s achieved. <b>Thomp</b>	0/9/23 inspection son Construction
CE 3	Thompson Construction moved the barricade properties of the barricade or in the construction Construction Entrance	will install a rock entrangior to the 10/24/23 install a construction each mass informed to construction to Elk Lane	ce once soil compaction in pection. entrance. mplete by 10/30/23. 10/16/2023	ntrance prior to the 1 s achieved. <b>Thomp</b> Pending	0/9/23 inspection son Construction
	Thompson Construction moved the barricade properties of the barricade or in the construction Construction Entrance Pending - Construction entrance	will install a rock entrantion to the 10/24/23 install a construction on was informed to collect Elk Lane entrance not necessary	ce once soil compaction in pection.  entrance.  mplete by 10/30/23.  10/16/2023 vias of 10/16/23 inspection	ntrance prior to the 1 s achieved. <b>Thomp</b> Pending	0/9/23 inspection son Construction
CE 3	Thompson Construction moved the barricade properties of the barricade or in the construction Construction Entrance	will install a rock entrantion to the 10/24/23 install a construction on was informed to collect Elk Lane entrance not necessary	ce once soil compaction in pection.  entrance.  mplete by 10/30/23.  10/16/2023 vias of 10/16/23 inspection	ntrance prior to the 1 s achieved. <b>Thomp</b> Pending	0/9/23 inspection son Construction
CE 3	Thompson Construction moved the barricade properties of the barricade or in the construction Construction Entrance  Pending - Construction entemporary entrance barrical Diversion	will install a rock entrantion to the 10/24/23 install a construction of the second was informed to control to the second entrance not necessary arrier prior to the 10/23.  See SWPPP	ce once soil compaction in pection.  entrance.  mplete by 10/30/23.  10/16/2023 vias of 10/16/23 inspection	Pending Pending Pending	No No No

See SWPPP

Diversion

D 2

**Current Condition:** 

7/3/2023

Pending - The diversion will be installed once grading in the area begins. E&A inspector will continue to monitor.

Pending

D 3	Diversion	See SWPPP	7/3/2023	Pending	No
Current Condition:	Pending - The diversion		rading in the area begins.	E&A inspector will c	ontinue to monito
FT	Fuel Tank	On Site	9/11/2023	Active	No
Current Condition:			led a fuel tank with secor e drainage plug to the fue		
IF 1	Inlet Filter	See SWPPP	7/6/2023	Active	No
Current Condition:	Good Condition - Sawye	r Construction installed	the inlet filter prior to the	inspection on 7/06/2	3.
IF 2	Inlet Filter	See SWPPP	7/6/2023	Active	No
Current Condition:			the inlet filter prior to the et filter prior to the 9/11/20		3. Sawyer
IF 3	Inlet Filter	See SWPPP	7/3/2023	Pending	No
Current Condition:	Pending - The inlet filter	will be installed on site	when necessary. E&A ins	spector will continue	to monitor.
IF 4	Inlet Filter	See SWPPP	7/3/2023	Pending	No
<b>Current Condition:</b>	Pending - The inlet filter	will be installed on site	when necessary. E&A ins	spector will continue	to monitor.
PT	Portable Toilet	On Site	9/11/2023	Pending	No
Current Condition:	Pending - Thompson Co	nstruction installed a po	ortable toilet prior to the ir	nspection on 9/11/23.	Thompson
			the 9/18/23 inspection; E		
MS 01	Material Storage	On Site	7/3/2023	Pending	No
Current Condition:	Pending - The material s				
SF 01	Silt Fence	P22 to L7	7/3/2023 s of the 9/11/23 due to the	Pending	No
Current Condition:		A inspector will monitor	for installation as necess	ary.	buller and the lia
SF 02	Silt Fence	X21 to T24	7/3/2023	Pending	No
Current Condition:	grade of the project; E&/		s of the 9/11/23 due to the for installation as necess		buffer and the fla
SF 03	Silt Fence	M7 to T7	7/3/2023	Pending	No
Current Condition:	grade of the project; E&/	A inspector will monitor	s of the 9/11/23 due to the for installation as necess		buffer and the fla
SF 04	Silt Fence	J15 to M18	7/3/2023	Pending	No
Current Condition:			s of the 9/11/23 due to the for installation as necess		buffer and the fla
SF 05	Silt Fence	J15 to M17	7/3/2023	Pending	No
Current Condition:	_		s of the 9/11/23 due to the for installation as necess		buffer and the fla
SF 06	Silt Fence			Pending	No
Current Condition:			s of the 9/11/23 due to the for installation as necess		buffer and the fla
	Silt Fence	M18 to P 22		Donalina	N.
SF 07			7/3/2023	Pending	No
SF 07 Current Condition:	Pending - Silt fence will	not be recommended as	7/3/2023 s of the 9/11/23 due to the for installation as necess	e existing vegetative	
	Pending - Silt fence will	not be recommended as	s of the 9/11/23 due to the	e existing vegetative	
Current Condition:	Pending - Silt fence will grade of the project; E&/	not be recommended as A inspector will monitor ADJ and Internal	s of the 9/11/23 due to the for installation as necession	e existing vegetative ary.	buffer and the fla
Current Condition:	Pending - Silt fence will grade of the project; E&/ Streets Fair Condition - Track out should be re	not be recommended as A inspector will monitor  ADJ and Internal Streets	s of the 9/11/23 due to the for installation as necess:  7/3/2023  Orive.	e existing vegetative ary.	buffer and the fla
STR Current Condition:	Pending - Silt fence will grade of the project; E&/ Streets  Fair Condition - Track out should be re Thompson Construction	not be recommended as A inspector will monitor  ADJ and Internal Streets  moved from Elkhorn Elements  on was informed to co	s of the 9/11/23 due to the for installation as necession 7/3/2023  Orive.  mplete by 10/24/23.	e existing vegetative ary.  Active	buffer and the fla
STR Current Condition:  STR SWPPP Sign 01	Pending - Silt fence will grade of the project; E&/ Streets  Fair Condition - Track out should be re Thompson Construction SWPPP Signs	A inspector will monitor  ADJ and Internal Streets  Moved from Elkhorn I Don was informed to co	orive.  6/30/2023  s of the 9/11/23 due to the for installation as necessary.  7/3/2023  Orive.  6/30/2023	e existing vegetative ary.  Active	buffer and the fla
STR Current Condition:  SWPPP Sign 01 Current Condition:	Pending - Silt fence will grade of the project; E&/ Streets Fair Condition - Track out should be re Thompson Construction SWPPP Signs Good Condition - E&A in	not be recommended as A inspector will monitor  ADJ and Internal Streets  moved from Elkhorn I on was informed to co  East entrance aspector installed the SV	of the 9/11/23 due to the for installation as necession 7/3/2023  Orive.  mplete by 10/24/23.  6/30/2023  WPPP sign during the 6/3	e existing vegetative ary.  Active  Active  Active  30/23 inspection.	Yes  No
STR Current Condition:  STR Current Condition:  SWPPP Sign 01 Current Condition:  WO 01	Pending - Silt fence will grade of the project; E&/ Streets  Fair Condition - Track out should be re Thompson Construction SWPPP Signs Good Condition - E&A in Concrete Washout	not be recommended as A inspector will monitor  ADJ and Internal Streets  moved from Elkhorn Element to consider the Streets  East entrance aspector installed the Streets  On site	or installation as necessions of the 9/11/23 due to the for installation as necessions 7/3/2023  Orive.  mplete by 10/24/23.  6/30/2023  WPPP sign during the 6/37/3/2023	e existing vegetative ary.  Active	buffer and the fla
STR Current Condition:  SWPPP Sign 01 Current Condition:	Pending - Silt fence will grade of the project; E&/ Streets Fair Condition - Track out should be re Thompson Construction SWPPP Signs Good Condition - E&A in	not be recommended as A inspector will monitor  ADJ and Internal Streets  moved from Elkhorn Element to consider the Streets  East entrance aspector installed the Streets  On site	or installation as necessions of the 9/11/23 due to the for installation as necessions 7/3/2023  Orive.  mplete by 10/24/23.  6/30/2023  WPPP sign during the 6/37/3/2023	e existing vegetative ary.  Active  Active  Active  30/23 inspection.	Yes  No

Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.					
Inspector Signature:	HE		Reviewed By:	Get Sil		