E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Engineering Answers

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager E & A CONSULTING GROUP, INC. ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept.		A - P2004.245.000		
Inspector: Alex Emerson				Stage
-		Elkhorn Vi	ew	3
Drainet Name:		NER1106		
Project Name:				
For Week Ending:		12/14/201		
Project Location:	192nd 8	Bedford Ave- Omaha,	NE (Douglas County)	68022
One dia au		4000/	I	
Grading: Sanitary Sewer:		100%		
Storm Sewer:		100% 100%		
Paving:		100%		
Seeding:		100%		
Utilities:		100%		
Overall Development:		44%		
•				
RAIN FALL AMOUNTS	Amount in inches	Date inspected		
				Week 1
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 2
Sunday:	0.02"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
outurday	0.00			Week 3
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 4
Sunday:	0.00"			
Monday	0.01"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday Friday	0.00"	12/06/13		
Saturday	0.00"	12/00/13		
	0.00			Week 5
Sunday:	0.01"			Meen J
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			

	None				
Complaints:					
	—				
Construction Convencing:					
Construction Sequencing: Which portion(s) (i.e. drainage basins) of	the site have had a temperaturer par	nonont opposition of grading	a conthwork or a	round disturbance	in the last 14 days?
which portion(s) (i.e. drainage basilis) of	the site have had a temporary or perio	naneni cessation of gradinų	j, earthwork, or g		in the last 14 days !
Entire site; grading completed and	site seeded Spring 2005				
Entire site, grading completed and s	site seeded Spring 2003.				
Which portion(s) (i.e. drainage basins) of	the site do not have grading, earthwo	rk, or ground disturbance s	cheduled in the r	next 14 days? :	•
Entire site; grading completed and	site seeded Spring 2005.				
					1
	n measures listed in this section are l	haing implemented?			
What temporary or permanent stabilizatio					
Paving, dense vegetation and lands	scaping were completed on site.				
Comments:		ł	L	Į	!
Comments:					
Home construction is active on a fe	w lots.				
Findings / Corrective Actions (Da	te):				
Findings / Corrective Actions (Da					
1) Some maintenance is required in					
2) Lot 35 and 36 were entered inco	rectly in previous reports. Lot a	35 should be lot 34 and	Lot 36 should	be lot 35. These	changes have
been made in the BMP section.					
			Projected		
Unique Name	Туре	Location	Install Date	Status	Maintenance
• • •		N41d17m09s			
CE 1	Construction Entrance	W96d12m58s		Removed	
Current Condition:	Removed	Weddinzinood		Romovou	
Current Condition.	Kenioved	N41d17m09s	1	l	
	Construction Entropos			Demovied	
CE 2	Construction Entrance	W96d13m05s		Removed	
Current Condition:	Removed - Entrance Paved		1	Demonst	1
Lot 25	Silt Fence	Lot 25	<u> </u>	Removed	
Current Condition:	Lot was sodded prior to insp		Marque Homes		1
Lot 33	Misc/Other	Lot 33		Removed	
Current Condition:	Lot was sodded prior to insp				1
Lot 34	Misc/Other	Lot 34	10/16/2013	Active	No
Current Condition:	Active construction by Zych				
	No BMP required due to veg	getative buffer strip and	<mark>l no signs of ru</mark>	n off.	
Lot 35	Misc/Other	Lot 35	11/7/2013	Active	No
Current Condition:	Active construction-Concept		<u> </u>		
	No BMP required due to year			n off.	
Lot 26	No BMP required due to veg	getative buffer strip and	l no signs of ru		Vos
Lot 36	Silt Fence			n off. Pending	Yes
Lot 36 Current Condition:	·	getative buffer strip and	l no signs of ru		Yes
	Silt Fence Pending	getative buffer strip and Lot 36	l no signs of ru 12/13/2013	Pending	Yes
	Silt Fence Pending 1) There is active constructi	getative buffer strip and Lot 36 on and no BMP in plac	I no signs of ru 12/13/2013 e as of inspect	Pending	Yes
	Silt Fence Pending	getative buffer strip and Lot 36 on and no BMP in plac	I no signs of ru 12/13/2013 e as of inspect	Pending	Yes
	Silt Fence Pending 1) There is active constructi 2) There is a stockpile in the	getative buffer strip and Lot 36 on and no BMP in place ROW as of inspection	I no signs of ru 12/13/2013 e as of inspect on 12/6/13.	Pending ion on 12/6/13.	
	Silt Fence Pending 1) There is active constructi 2) There is a stockpile in the 1) Complete Custom Homes	getative buffer strip and Lot 36 on and no BMP in place ROW as of inspection s was requested to insta	I no signs of ru 12/13/2013 e as of inspect on 12/6/13.	Pending ion on 12/6/13.	
	Silt Fence Pending 1) There is active constructi 2) There is a stockpile in the 1) Complete Custom Homes the South side by 12/13/13.	getative buffer strip and Lot 36 on and no BMP in plac e ROW as of inspection s was requested to inst	I no signs of ru 12/13/2013 e as of inspect on 12/6/13. all silt fence on	Pending ion on 12/6/13. I the Southwest o	
	Silt Fence Pending 1) There is active constructi 2) There is a stockpile in the 1) Complete Custom Homes	getative buffer strip and Lot 36 on and no BMP in plac e ROW as of inspection s was requested to inst	I no signs of ru 12/13/2013 e as of inspect on 12/6/13. all silt fence on	Pending ion on 12/6/13. I the Southwest o	
Current Condition:	Silt Fence Pending 1) There is active constructi 2) There is a stockpile in the 1) Complete Custom Homes the South side by 12/13/13. 2) Complete Custom Homes	getative buffer strip and Lot 36 on and no BMP in place ROW as of inspection s was requested to inst s was requested to rem	I no signs of ru 12/13/2013 e as of inspect on 12/6/13. all silt fence on	Pending ion on 12/6/13. I the Southwest o ille by 12/13/13.	
Current Condition: Lot 43	Silt Fence Pending 1) There is active constructi 2) There is a stockpile in the 1) Complete Custom Homes the South side by 12/13/13. 2) Complete Custom Homes Berm	getative buffer strip and Lot 36 on and no BMP in place ROW as of inspection s was requested to inst s was requested to rem Lot 43	t no signs of ru 12/13/2013 e as of inspect on 12/6/13. all silt fence on ove the stockp	Pending ion on 12/6/13. the Southwest o ille by 12/13/13. Removed	
Current Condition: Lot 43 Current Condition:	Silt Fence Pending 1) There is active constructi 2) There is a stockpile in the 1) Complete Custom Homes the South side by 12/13/13. 2) Complete Custom Homes Berm Removed-Lot was sodded by	on and no BMP in place on and no BMP in place ROW as of inspection s was requested to insta s was requested to rem Lot 43 by Malibu Homes prior t	t no signs of ru 12/13/2013 e as of inspect on 12/6/13. all silt fence on ove the stockp	Pending ion on 12/6/13. the Southwest o ile by 12/13/13. Removed n 12/6/13.	
Current Condition: Lot 43 Current Condition: Lot 47	Silt Fence Pending 1) There is active constructi 2) There is a stockpile in the 1) Complete Custom Homes the South side by 12/13/13. 2) Complete Custom Homes Berm Removed-Lot was sodded b Misc/Other	getative buffer strip and Lot 36 on and no BMP in place ROW as of inspection s was requested to insta s was requested to rem Lot 43 by Malibu Homes prior t Lot 47	t no signs of ru 12/13/2013 e as of inspect on 12/6/13. all silt fence on ove the stockp o inspection or	Pending ion on 12/6/13. the Southwest of ile by 12/13/13. Removed 12/6/13. Removed	
Current Condition: Lot 43 Current Condition:	Silt Fence Pending 1) There is active constructi 2) There is a stockpile in the 1) Complete Custom Homes the South side by 12/13/13. 2) Complete Custom Homes Berm Removed-Lot was sodded by	getative buffer strip and Lot 36 on and no BMP in place ROW as of inspection s was requested to insta s was requested to rem Lot 43 by Malibu Homes prior t Lot 47	t no signs of ru 12/13/2013 e as of inspect on 12/6/13. all silt fence on ove the stockp o inspection or	Pending ion on 12/6/13. the Southwest of ile by 12/13/13. Removed 12/6/13. Removed	

Current Condition:	Fair Condition - The silt fence was removed by Quest Construction prior to inspection on 11/7/13.						
	The sincence was removed by guest construction prior to inspection on T1/1/13.						
	There are some concrete s	spoils in the ROW as c	of inspection on 9/	4/2013.			
	Tom with Quest Constructi	on was requested to re	emove the concre	te spoils by 9/11/	2013. Not de		
	Tom with Quest Construction was requested to remove the concrete spoils by 9/11/2013. Not do as of last inspection. Tom with Quest Construction was sent a reminder email on 10/7/13, 10/17						
	12/6/13 requesting to complete this maintenance ASAP.						
Lot 57	Silt Fence	Lot 57		Removed			
Current Condition:	Removed-Filter socks are I	U	· .		NI-		
Lot 58 Current Condition:	Silt Fence Good Condition	Lot 58	10/16/2013	Active	No		
Current Condition:	-Silt fence was installed on 10/16/13.	the west side of the lo	ot by Landmark Ho	omes prior to insp	ection on		
Lot 69	Silt Fence	Lot 69	10/16/2013	Pending	No		
Current Condition:	Good Condition -Silt fence was installed on 10/16/13.			<u> </u>	tion on		
Lot 73	Silt Fence	Lot 73	9/11/2013	Active	No		
Current Condition:	Good Condition						
	 Mike with Malibu Homes Silt fence was installed by 						
Lot 76	Misc/Other	Lot 76	12/6/2013	Active	Yes		
Current Condition:	Active -The silt fence was removed and the lot was sodded by Malibu Homes prior to inspection on 12/9/13.						
	 The portable toilet is not staked down as of inspection on 9/12/13. There is construction debris on lot 77 as of inspection on 12/6/13. 						
	1) Mike with Malibu Homes inspection. Mike with Malib	ou Homes was remind	<mark>led on 10/7/13, 12</mark>	/6/13.			
		ou Homes was remind	<mark>led on 10/7/13, 12</mark>	/6/13.			
OLB	inspection. Mike with Malik 2) Mike with Malibu Homes Silt fence	bu Homes was remind was requested to ren OLB	led on 10/7/13, 12 nove the construct	/6/13. tion debris by 12/ Removed	13/13.		
OLB Current Condition:	inspection. Mike with Malik 2) Mike with Malibu Homes	ou Homes was remind was requested to ren OLB removed prior to inspe	led on 10/7/13, 12 nove the construct	/6/13. tion debris by 12/ Removed	13/13.		
Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes.	ou Homes was remind was requested to ren OLB removed prior to inspo N41d17m09s	led on 10/7/13, 12 nove the construction construction on 11/5/12	/6/13. tion debris by 12/ Removed [by Mark Hopkins	13/13. w/ Marque		
Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin	ou Homes was remind was requested to ren OLB removed prior to inspo N41d17m09s W96d13m14s	led on 10/7/13, 12 nove the construct	/6/13. tion debris by 12/ Removed	13/13.		
Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes.	Du Homes was remind was requested to ren OLB removed prior to inspect N41d17m09s W96d13m14s	led on 10/7/13, 12 nove the construction ection on 11/5/12	/6/13. tion debris by 12/ Removed by Mark Hopkins Active	13/13. w/ Marque		
Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille	Du Homes was remind was requested to ren OLB removed prior to inspect N41d17m09s W96d13m14s oleted de-vegetation prior	led on 10/7/13, 12 nove the construction ection on 11/5/12	/6/13. tion debris by 12/ Removed by Mark Hopkins Active	13/13. w/ Marque		
Current Condition: SB A	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille	Du Homes was remind was requested to ren OLB removed prior to inspect N41d17m09s W96d13m14s	led on 10/7/13, 12 nove the construction ection on 11/5/12	/6/13. tion debris by 12/ Removed by Mark Hopkins Active	13/13. w/ Marque		
Current Condition: SB A Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp	Du Homes was remind was requested to ren OLB removed prior to inspective N41d17m09s W96d13m14s oleted de-vegetation prior N41d17m12s W96d13m15s or to inspection on 8/1	led on 10/7/13, 12 nove the construct ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense veg	13/13. w/ Marque No		
Current Condition: SB A Current Condition: SF 1	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed pri- Falcone was notified that the	Du Homes was remind was requested to ren OLB removed prior to inspective N41d17m09s W96d13m14s oleted de-vegetation prior N41d17m12s W96d13m15s or to inspection on 8/1	led on 10/7/13, 12 nove the construct ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense veg	13/13. w/ Marque No		
Current Condition: SB A Current Condition: SF 1 Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed priv Falcone was notified that th area.	Du Homes was remind was requested to ren OLB removed prior to inspective N41d17m09s W96d13m14s vd N41d17m12s W96d13m15s or to inspection on 8/1 nis silt fence is to be referred N41d17m10s W96d13m03s	led on 10/7/13, 12 nove the construct ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed	13/13. w/ Marque No		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed pric Falcone was notified that th area. Silt Fence Silt Fence Silt Fence	Du Homes was remind was requested to ren OLB removed prior to inspective N41d17m09s W96d13m14s vd Deted de-vegetation prior N41d17m12s W96d13m15s or to inspection on 8/1 nis silt fence is to be ren N41d17m10s W96d13m03s ed. All drainage area is N41d17m18s	led on 10/7/13, 12 nove the construct ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed grass growing.	13/13. w/ Marque No		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition: ST B	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed pri Falcone was notified that the area. Silt Fence Silt Fence Silt Fence Silt Fence Silt fence has been removed Sediment Trap	Du Homes was remind was requested to ren OLB removed prior to inspective N41d17m09s W96d13m14s vd Deted de-vegetation prior N41d17m12s W96d13m15s or to inspection on 8/1 nis silt fence is to be ren N41d17m10s W96d13m03s ed. All drainage area is	led on 10/7/13, 12 nove the construct ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed	13/13. w/ Marque No		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed pric Falcone was notified that th area. Silt Fence Silt Fence Silt Fence	Du Homes was remind was requested to ren OLB removed prior to inspection N41d17m09s W96d13m14s voleted de-vegetation proved prior to inspection on 8/1 N41d17m12s W96d13m15s or to inspection on 8/1 nis silt fence is to be reference N41d17m10s W96d13m03s ed. All drainage area is N41d17m18s W96d13m14s	led on 10/7/13, 12 nove the construct ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed grass growing.	13/13. w/ Marque No		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition: ST B Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt Fence Silt fence was removed price Falcone was notified that the area. Silt Fence Silt Fence Silt Fence Silt fence has been removed Sediment Trap Trap closed August 2006.	Du Homes was remind was requested to removed prior to inspection of the second prior to inspection prior to inspection on 8/1 N41d17m12s W96d13m15s or to inspection on 8/1 N41d17m10s W96d13m03s ed N41d17m10s W96d13m03s ed N41d17m10s W96d13m03s ed N41d17m18s W96d13m14s	led on 10/7/13, 12 nove the construction ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho s seeded and has	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed grass growing. Removed	13/13. w/ Marque No getation. To is active in		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition: ST B Current Condition: ST B Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed price Falcone was notified that the area. Silt Fence Silt fence has been removed Sediment Trap Trap closed August 2006.	Du Homes was remind was requested to removed prior to inspection N41d17m09s W96d13m14s oleted de-vegetation prior N41d17m12s W96d13m15s or to inspection on 8/1 N41d17m10s W96d13m03s ed N41d17m10s W96d13m03s ed N41d17m10s W96d13m03s All drainage area is N41d17m18s W96d13m14s	led on 10/7/13, 12 nove the construct ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed grass growing.	13/13. w/ Marque No		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition: ST B Current Condition: STR Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed pric Falcone was notified that the area. Silt Fence Silt fence has been removed Sediment Trap Trap closed August 2006. Streets Good Condition- No major	Du Homes was remind was requested to removed prior to inspection N41d17m09s W96d13m14s oleted de-vegetation provide the second se	led on 10/7/13, 12 nove the construction ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho s seeded and has 8/1/2005	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed grass growing. Removed due to dense vegome construction	13/13. w/ Marque No getation. Too is active in Yes		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition: ST B Current Condition: ST B Current Condition:	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed price Falcone was notified that the area. Silt Fence Silt fence has been removed Sediment Trap Trap closed August 2006.	Du Homes was remind was requested to removed prior to inspection N41d17m09s W96d13m14s oleted de-vegetation prior N41d17m12s W96d13m15s or to inspection on 8/1 N41d17m10s W96d13m03s ed N41d17m10s W96d13m03s ed N41d17m10s W96d13m03s All drainage area is N41d17m18s W96d13m14s	led on 10/7/13, 12 nove the construction ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho s seeded and has	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed grass growing. Removed	13/13. w/ Marque No getation. Tor is active in		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition: ST B Current Condition: STR Current Condition: STR Current Condition: SWPPP Sign	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed pri- Falcone was notified that th area. Silt Fence Silt fence has been remove Sediment Trap Trap closed August 2006. Streets Good Condition- No major	Du Homes was remind was requested to removed prior to inspection of the i	led on 10/7/13, 12 nove the construction ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho s seeded and has 8/1/2005	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed grass growing. Removed due to dense vegome construction	13/13. w/ Marque No getation. Too is active in Yes		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition: ST B Current Condition: STR Current Condition: STR Current Condition: SWPPP Sign	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed pri- Falcone was notified that th area. Silt Fence Silt fence has been remove Sediment Trap Trap closed August 2006. Streets Good Condition- No major Signs Good Condition:	Du Homes was remind was requested to removed prior to inspection of the i	led on 10/7/13, 12 nove the construction ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho s seeded and has 8/1/2005	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed grass growing. Removed Active Active	13/13. w/ Marque No getation. To is active in Yes No		
Current Condition: SB A Current Condition: SF 1 Current Condition: SF 2 Current Condition: ST B Current Condition: STR Current Condition: STR Current Condition: SWPPP Sign	inspection. Mike with Malit 2) Mike with Malibu Homes Silt fence Silt fence in the outlot was Homes. Sediment Basin Good Condition - 36% Fille Commercial Seeding comp Silt Fence Silt fence was removed pri- Falcone was notified that th area. Silt Fence Silt fence has been remove Sediment Trap Trap closed August 2006. Streets Good Condition- No major Signs Good Condition:	Du Homes was remind was requested to removed prior to inspection of the i	led on 10/7/13, 12 nove the construction ection on 11/5/12 In place rior to inspection of 8/09 by Tim Geis e-installed once ho s seeded and has 8/1/2005	/6/13. tion debris by 12/ Removed by Mark Hopkins Active on 7/8/09. Removed due to dense vegome construction Removed grass growing. Removed due to dense vegome construction	13/13. w/ Marque No getation. Too is active in Yes No		