E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Saturday

0.00"



## E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept.	Manager	ENGINEERING	• PLANNING • ENVIRONMENTAL 8	FIELD SERVICES	
		E&A - P2004.245.00	0		
Inspector: Alex Emerson				Stage	
		Elkhorn	View	3	
Project Name:		NER110687			
For Week Ending:	9/13/2014				
Project Location:	1921	192nd & Bedford Ave- Omaha, NE (Douglas County)			
•			, , ,	68022	
Grading:		100%			
Sanitary Sewer:		100%			
Storm Sewer:		100%			
Paving:		100%			
Seeding:		100%			
Utilities:		100%			
Overall Development:		55%			
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions		
	les com			Week 1	
Sunday:	0.23"				
Monday	0.03"				
Tuesday	0.02"				
Wednesday	0.00"				
Thursday Friday	0.00"				
Saturday	0.00"				
Saturday	0.00			Week 2	
Sunday:	0.00"			Week 2	
Monday	0.04"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.04"				
Friday	0.26"				
Saturday	1.53"				
				Week 3	
Sunday:	0.00"				
Monday	0.00"	08/25/14	80/68 Partly Cloudy		
Tuesday	1.36"				
Wednesday	1.58"				
Thursday	1.92"	00/00/4 4	70/00 01		
Friday	0.29"	08/29/14	78/68 Cloudy		
Saturday	0.00"			Week 4	
Sunday:	0.23"			week 4	
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.16"				
Saturday	0.00"				
				Week 5	
Sunday:	0.00"				
Monday	0.03"				
Tuesday	1.26"				
Wednesday	0.00"				
Thursday	0.05"	09/11/14	55/52 Cloudy		
Friday	0.45"				

09/13/14

63/44 Sunny

	,				
	None				
Complaints:					
Construction Sequencings			•	L.	
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the	alta have had a tampagery or name			hanas in the las	4 4 4 days 2
which portion(s) (i.e. drainage basins) of the	site nave nad a temporary or perm	anent cessation of grading	g, earthwork, or ground distur	bance in the las	st 14 days?
Entire site; grading completed and site	seeded Spring 2005.				
Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthwor	k, or ground disturbance s	scheduled in the next 14 days	?:	
Entire site; grading completed and site	seeded Spring 2005.				
What temporary or permanent stabilization m	easures listed in this section are b	eing implemented?			
Paving, dense vegetation and landsca	ping were completed on site.				
Comments:	-				
Comments:					
Home construction is active on a few k	ote. Due to recognizing rain ov	ante the rain increatio	on for 9/26/14 9/29/14 wa	c completed	on 9/20/14
		ents, the rain inspectio	011101 6/20/14-6/26/14 Wa	s completed	JII 0/29/14.
Findings / Corrective Actions (Date)	:				
Findings / Corrective Actions (Date)	:				
1) Some maintenance is required in the	e BMP Section.				
,					
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
o inque i i aine	.,,,,,	N41d17m09s	l rejected metan zate	0.0.0.0	
CE 1	Construction Entrance	W96d12m58s		Removed	
		W 900 12111305	<u> </u>	Removed	
Current Condition:	Removed	N144 147 00	1		
		N41d17m09s		_	
CE 2	Construction Entrance	W96d13m05s		Removed	
Current Condition:	Removed - Entrance Paved				
Lot 8	Individual Lot	Lot 8	8/1/2014	Pending	No
Current Condition:	Pending-There is no constru-	ction activity on the lot	as of inspection on 8/1/1	4. A silt fend	e was installed
	on the back of the lot by unk				
	on the sack of the let sy think	party prior to mor	5 5 5 6 7 7 7 1 1 1		
Lot 9	Individual Lot	Lot 9	6/28/2014	Active	No
Current Condition:	Good Condition-Silt fence an	nd a diversion ditch wer	re installed on the back o	f the lot by D	ave Paik
	Builders prior to inspection o	n 8/1/14.			
•					
Lot 17	Silt Fence	Lot 17		Removed	
Current Condition:	Removed-SF was removed,			s, and sidewa	alk was cleaned
	by Ramm Construction prior	to inspection on 6/23/1	14.		
Lot 25	Silt Fence	Lot 25		Removed	
Current Condition:	Lot was sodded prior to inspe		Margue Homes	rtomovod	
Lot 29	Individual Lot	Lot 29	8/1/2014	Active	No
Current Condition:	Good Condition-Silt fence was extended to the SW corner and straw wattles were installed along the curb				
			corrier and otrait mattice		3
	by R&A Builders prior to insp	ection on 8/29/14.	oomor and onaw wattoo		3
	by R&A Builders prior to insp	pection on 8/29/14.	comor ana onaw wattoo		J
Lot 33			To the state water		
Lot 33	Misc/Other	Lot 33		Removed	
Current Condition:	Misc/Other Lot was sodded prior to inspe	Lot 33 ection on 11/26/12 by I		Removed	
Current Condition: Lot 34	Misc/Other Lot was sodded prior to inspending Misc/Other	Lot 33 ection on 11/26/12 by I Lot 34	RAMM Construction.	Removed Removed	
Current Condition:  Lot 34  Current Condition:	Misc/Other Lot was sodded prior to inspuniesc/Other Removed-The lot was sodde	Lot 33 ection on 11/26/12 by I Lot 34 d by Zych Construction	RAMM Construction.	Removed Removed //23/14.	
Current Condition:  Lot 34  Current Condition:  Lot 35	Misc/Other Lot was sodded prior to insp Misc/Other Removed-The lot was sodde Misc/Other	Lot 33 ection on 11/26/12 by I Lot 34 ed by Zych Construction Lot 35	RAMM Construction.	Removed Removed /23/14. Removed	
Current Condition:  Lot 34  Current Condition:	Misc/Other Lot was sodded prior to insponsor Misc/Other Removed-The lot was sodded Misc/Other Removed-Concept Homes a	Lot 33 ection on 11/26/12 by I Lot 34 ed by Zych Construction Lot 35 nd Designs sodded the	RAMM Construction.  n prior to inspection on 6. e lot prior to inspection or	Removed Removed /23/14. Removed	
Current Condition:  Lot 34  Current Condition:  Lot 35  Current Condition:  Lot 36	Misc/Other Lot was sodded prior to insp Misc/Other Removed-The lot was sodde Misc/Other	Lot 33 ection on 11/26/12 by I Lot 34 ed by Zych Construction Lot 35	RAMM Construction.	Removed Removed /23/14. Removed	Yes
Current Condition:  Lot 34  Current Condition:  Lot 35  Current Condition:	Misc/Other Lot was sodded prior to insponsor Misc/Other Removed-The lot was sodded Misc/Other Removed-Concept Homes a	Lot 33 ection on 11/26/12 by I Lot 34 ed by Zych Construction Lot 35 nd Designs sodded the	RAMM Construction.  n prior to inspection on 6. e lot prior to inspection or	Removed Removed /23/14. Removed o 8/25/14.	
Current Condition:  Lot 34  Current Condition:  Lot 35  Current Condition:  Lot 36	Misc/Other Lot was sodded prior to insponsor Misc/Other Removed-The lot was sodded Misc/Other Removed-Concept Homes a Silt Fence	Lot 33 ection on 11/26/12 by I Lot 34 ed by Zych Construction Lot 35 nd Designs sodded the	RAMM Construction.  n prior to inspection on 6. e lot prior to inspection or	Removed Removed /23/14. Removed o 8/25/14.	
Current Condition:  Lot 34  Current Condition:  Lot 35  Current Condition:  Lot 36	Misc/Other Lot was sodded prior to inspunisc/Other Removed-The lot was sodded Misc/Other Removed-Concept Homes a Silt Fence Fair Condition-	Lot 33 ection on 11/26/12 by I Lot 34 ed by Zych Construction Lot 35 nd Designs sodded the Lot 36	RAMM Construction.  n prior to inspection on 6.  e lot prior to inspection or 12/13/2013	Removed Removed /23/14. Removed 18/25/14. Active	Yes
Current Condition:  Lot 34  Current Condition:  Lot 35  Current Condition:  Lot 36	Misc/Other Lot was sodded prior to insponsion Misc/Other Removed-The lot was sodded Misc/Other Removed-Concept Homes a Silt Fence Fair Condition- Silt fence was removed on the	Lot 33 ection on 11/26/12 by I Lot 34 ed by Zych Construction Lot 35 nd Designs sodded the Lot 36  ne South side for sidew	RAMM Construction.  n prior to inspection on 6.  e lot prior to inspection or 12/13/2013	Removed Removed /23/14. Removed 18/25/14. Active	Yes
Current Condition:  Lot 34  Current Condition:  Lot 35  Current Condition:  Lot 36	Misc/Other Lot was sodded prior to inspunisc/Other Removed-The lot was sodded Misc/Other Removed-Concept Homes a Silt Fence Fair Condition-	Lot 33 ection on 11/26/12 by I Lot 34 ed by Zych Construction Lot 35 nd Designs sodded the Lot 36  ne South side for sidew	RAMM Construction.  n prior to inspection on 6.  e lot prior to inspection or 12/13/2013	Removed Removed /23/14. Removed 18/25/14. Active	Yes
Current Condition:  Lot 34  Current Condition:  Lot 35  Current Condition:  Lot 36	Misc/Other Lot was sodded prior to insponsion of the Misc/Other Removed-The lot was sodde Misc/Other Removed-Concept Homes a Silt Fence Fair Condition- Silt fence was removed on the areas as of inspection on 8/1	Lot 33 ection on 11/26/12 by P Lot 34 d by Zych Construction Lot 35 nd Designs sodded the Lot 36 ne South side for sidew 1/14.	RAMM Construction.  In prior to inspection on 6, perior to inspection or 12/13/2013  valk installation and dama	Removed Removed /23/14. Removed in 8/25/14. Active	Yes ack in a few
Current Condition:  Lot 34  Current Condition:  Lot 35  Current Condition:  Lot 36	Misc/Other Lot was sodded prior to inspendisc/Other Removed-The lot was sodded Misc/Other Removed-Concept Homes a Silt Fence Fair Condition- Silt fence was removed on the areas as of inspection on 8/1 Concept Homes and Designs	Lot 33 ection on 11/26/12 by I Lot 34 d by Zych Construction Lot 35 nd Designs sodded the Lot 36 ne South side for sidew 1/14. s was requested to rep	RAMM Construction.  In prior to inspection on 6, perior to inspection or 12/13/2013  Valk installation and dama are the silt fence in the base of the silt fence in the	Removed Removed /23/14. Removed in 8/25/14. Active	Yes ack in a few
Current Condition:  Lot 34  Current Condition:  Lot 35  Current Condition:  Lot 36	Misc/Other Lot was sodded prior to insponsion of the Misc/Other Removed-The lot was sodde Misc/Other Removed-Concept Homes a Silt Fence Fair Condition- Silt fence was removed on the areas as of inspection on 8/1	Lot 33 ection on 11/26/12 by I Lot 34 d by Zych Construction Lot 35 nd Designs sodded the Lot 36 ne South side for sidew 1/14. s was requested to rep	RAMM Construction.  In prior to inspection on 6, perior to inspection or 12/13/2013  Valk installation and dama are the silt fence in the base of the silt fence in the	Removed Removed /23/14. Removed in 8/25/14. Active	Yes ack in a few

Current Condition:	Pending-The home is occur	nied as of inspection on	9/13/14		
Guirent Gonation.	1 ending-The nome is occupied as of inspection on 3/13/14.				
	There lot needs final stabilization as of inspection on 9/13/14.				
	John Caniglia was requested to sod the lot by 9/27/14.				
1.110	N.C. (O.)	1 1 10	T		
Lot 43  Current Condition:	Misc/Other	Lot 43	inapartian an 10/0/10	Removed	alala tailat waa
Current Condition:	Removed-Lot was sodded to removed as of 2/4/14.	by Mailbu Hornes prior to	o inspection on 12/6/13 a	and the porate	able tollet was
Lot 47	Misc/Other	Lot 47		Removed	
Current Condition:	Removed-Lot was sodded by		or to inspection on 12/6/		
Lot 49	Individual Lot	Lot 49	8/1/2014	Active	No
Current Condition:	Active-Matrix Homes has a				
	requested on the lot due to	the lot being flat as of in	spection on 8/1/14. Ins	pector will mo	nitor.
			<del>1</del>	i	
Lot 56	Misc/Other	Lot 56		Removed	
Current Condition:	Removed-All BMPs have be on 3/6/14.	een removed from the ic	ot and there is no constri	uction activity	as of inspection
Lot 57	Silt Fence	Lot 57		Removed	
Current Condition:	Removed-Filter socks are b	eing used on lot 58 by L	andmark Homes.		
Lot 58	Silt Fence	Lot 58	10/16/2013	Active	Yes
Current Condition:	Fair Condition-				
	1) Cilt fonce is full and requi	iron aloon out on the aid	la and needs ratiod in th	o front oo of i	annotion on
	1) Silt fence is full and requ 6/4/14.	ires clean out on the sid	le and needs retied in the	e front as of ir	ispection on
	2) Silt fence is undermined	in the front as of inspect	tion on 6/23/14.		
	2) One for look to disacriffing a	in the none do or inopoor	1011 011 0/20/11.		
	1) Landmark Homes was re	equested to complete the	e maintenance items by	6/11/14. Not	done as of last
	inspection. Steve with Land				
	2) Steve with Landmark Homes was requested to repair the undermined silt fence by 6/30/14. Not done				
	as of last inspection.				
Lot 69	Silt Fence	Lot 69		Removed	
Current Condition:	Removed-Ramm Construct		dded the lot prior to insp		14.
Lot 73	Silt Fence	Lot 73		Removed	
Current Condition:	Removed-SF was removed 6/23/14.	, riii was repaired and io	t was sodded by Maiibu	nomes prior	to inspection on
Lot 76	Misc/Other	Lot 76		Removed	
Current Condition:	Removed-The disturbed are				
OLB		ea on lot 77 has establis	ned natural vegetation a	as of inspection	on on 8/1/14.
OLB	Silt fence	OLB		Removed	
Current Condition:		OLB		Removed	
	Silt fence	OLB removed prior to inspect		Removed	
Current Condition:	Silt fence Silt fence in the outlot was i	OLB emoved prior to inspect N41d17m09s	ion on 11/5/12 by Mark	Removed Hopkins w/ M	arque Homes.
Current Condition:  SB A	Silt fence Silt fence in the outlot was i	OLB removed prior to inspect  N41d17m09s W96d13m14s	ion on 11/5/12 by Mark	Removed Hopkins w/ M Active	arque Homes.
Current Condition:	Silt fence Silt fence in the outlot was i Sediment Basin Good Condition - 36% Filled	OLB removed prior to inspect N41d17m09s W96d13m14s d. An unknown contracto	ion on 11/5/12 by Mark  In place or was in the process of	Removed Hopkins w/ M  Active removing volu	arque Homes.  No unteer trees from
Current Condition:  SB A	Silt fence Silt fence in the outlot was i	OLB removed prior to inspect N41d17m09s W96d13m14s d. An unknown contracto	ion on 11/5/12 by Mark  In place or was in the process of	Removed Hopkins w/ M  Active removing volu	arque Homes.  No unteer trees from
Current Condition:  SB A	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Filler the basin as of inspection of	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector	ion on 11/5/12 by Mark  In place or was in the process of	Removed Hopkins w/ M  Active removing volu	arque Homes.  No unteer trees from
Current Condition:  SB A  Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Fillet the basin as of inspection of 8/1/14.	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s	ion on 11/5/12 by Mark  In place or was in the process of	Removed Hopkins w/ M  Active removing volumark during ir	arque Homes.  No unteer trees from
SB A Current Condition:  SB A Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Fillet the basin as of inspection of 8/1/14.  Silt Fence	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s	In place or was in the process of repainted the cleanout	Removed Hopkins w/ M  Active removing volumark during in	No unteer trees from aspection on
Current Condition:  SB A  Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Fillet the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed price	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0	In place or was in the process of repainted the cleanout	Removed Hopkins w/ M  Active removing volumark during in  Removed ense vegetation	No unteer trees from aspection on
SB A Current Condition:  SB A Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Fillet the basin as of inspection of 8/1/14.  Silt Fence	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0	In place or was in the process of repainted the cleanout	Removed Hopkins w/ M  Active removing volumark during in  Removed ense vegetation	No unteer trees from aspection on
SB A Current Condition:  SB A Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Fillet the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed price	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0	In place or was in the process of repainted the cleanout	Removed Hopkins w/ M  Active removing volumark during in  Removed ense vegetation	No unteer trees from aspection on
SB A Current Condition:  SB A Current Condition:  SF 1 Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Filler the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed pric was notified that this silt fence	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0 ice is to be re-installed of N41d17m10s W96d13m03s	In place or was in the process of repainted the cleanout  29 by Tim Geis due to depice home construction	Active removing volumark during in  Removed ense vegetatiis active in thi	No unteer trees from aspection on
SB A Current Condition:  SB A Current Condition:  SF 1 Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Filler the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed pricy was notified that this silt fen	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0 ice is to be re-installed of N41d17m10s W96d13m03s d. All drainage area is s	In place or was in the process of repainted the cleanout  29 by Tim Geis due to depice home construction	Active removing volumark during in  Removed ense vegetatiis active in thi	No unteer trees from aspection on
SB A Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Filler the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed pric was notified that this silt fer  Silt Fence Silt fence has been remove	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0 ice is to be re-installed of N41d17m10s W96d13m03s d. All drainage area is s N41d17m18s	In place or was in the process of repainted the cleanout  29 by Tim Geis due to depice home construction	Active removing volumark during in  Removed ense vegetation active in this sective in this removed owing.	No unteer trees from aspection on
SB A Current Condition:  SB A Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:  ST B	Silt fence Silt fence in the outlot was in  Sediment Basin Good Condition - 36% Filled the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed pric was notified that this silt fence was removed Silt fence has been removed Sediment Trap	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0 ice is to be re-installed of N41d17m10s W96d13m03s d. All drainage area is s	In place or was in the process of repainted the cleanout  29 by Tim Geis due to depice home construction	Active removing volumark during in  Removed ense vegetatiis active in thi	No unteer trees from aspection on on. Tom Falcone
SB A Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Filler the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed pric was notified that this silt fer  Silt Fence Silt fence has been remove	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0 ice is to be re-installed of  N41d17m10s W96d13m03s d. All drainage area is s  N41d17m18s W96d13m14s	In place or was in the process of repainted the cleanout  29 by Tim Geis due to depice home construction	Active removing volumark during in  Removed ense vegetation active in this sective in this removed owing.	No unteer trees from aspection on
SB A Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:  ST B Current Condition:	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Filler the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed pric was notified that this silt fence Silt Fence Silt fence has been removed Sediment Trap Trap closed August 2006.	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0 ice is to be re-installed of N41d17m10s W96d13m03s d. All drainage area is s N41d17m18s W96d13m14s  N41d17m09s	In place or was in the process of repainted the cleanout  O9 by Tim Geis due to de once home construction  eeded and has grass grass	Active removing volumark during in  Removed ense vegetation active in this  Removed ense vegetation active in this  Removed ense Removed ense vegetation active in this  Removed ense vegetation active in this  Removed	No unteer trees from espection on  on. Tom Falcone is area.
SB A Current Condition:  SB A Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:  ST B	Silt fence Silt fence in the outlot was in  Sediment Basin Good Condition - 36% Filled the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed pric was notified that this silt fence was removed Silt fence has been removed Sediment Trap	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0 ice is to be re-installed of N41d17m10s W96d13m03s d. All drainage area is s N41d17m18s W96d13m14s  N41d17m09s W96d13m05s	In place or was in the process of repainted the cleanout  O9 by Tim Geis due to donce home construction  eeded and has grass grass  8/1/2005	Active  Removed  Active removing volumark during in  Removed ense vegetations active in this  Removed owing.  Removed Active	No unteer trees from espection on  on. Tom Falcone s area.
SB A Current Condition:  SF 1 Current Condition:  SF 2 Current Condition:  ST B Current Condition:  STR	Silt fence Silt fence in the outlot was i  Sediment Basin Good Condition - 36% Filler the basin as of inspection of 8/1/14.  Silt Fence Silt fence was removed pric was notified that this silt fence Silt Fence Silt fence has been removed Sediment Trap Trap closed August 2006.  Streets	OLB removed prior to inspect  N41d17m09s W96d13m14s d. An unknown contractor n 8/1/14. E&A inspector  N41d17m12s W96d13m15s or to inspection on 8/18/0 ice is to be re-installed of N41d17m10s W96d13m03s d. All drainage area is s N41d17m18s W96d13m14s  N41d17m09s W96d13m05s	In place or was in the process of repainted the cleanout  O9 by Tim Geis due to donce home construction  eeded and has grass grass  8/1/2005	Active  Removed  Active removing volumark during in  Removed ense vegetations active in this  Removed owing.  Removed Active	No unteer trees from espection on  on. Tom Falcone s area.

Current Condition:	Good Condition:			
	192nd and Miami / 192nd ar	nd Corby		
	23			Zachany L. Gilek
Inspector Signature:			Reviewed By:	