E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Environmental Services Dept.	E	&A - P2004.245.000)			
Inspector: Alex Emerson					Stage	
Project Name:		Elkhorn View NER110687				
For Week Ending:		1/9/2016				
Project Location:	192r	nd & Bedford Ave- Omal	ha, NE (Douglas County))	68022	
•	1		· · · · · · · · · · · · · · · · · · ·	•		
Grading:		100%				
Sanitary Sewer:		100%				
Storm Sewer:		100%				
Paving:		100%				
Seeding:		100%				
Utilities:		100%				
Overall Development:		56%				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions			
					Week	
Sunday:	1.80"					
Monday	0.97"					
Tuesday	0.00"	12/15/15	43/35 Cloudy	total 3.40"		
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.76"					
Thursday	0.33"					
Friday	0.00"					
Saturday	0.10"	12/26/15	35/26 Cloudy			
					Week	
Sunday:	0.00"					
Monday	0.04"					
Tuesday	0.02"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				WI-	
Cundou	0.00"				Week	
Sunday:	0.00"			+		
Monday Tuesday	0.00"					
-				+		
Wednesday Thursday	0.00" 0.43"			+		
Friday	0.43			+		
Saturday	0.00"					
	0.00				Week	
Sunday:	N/A	N/A	N/A		- Week	
Monday	N/A	N/A	N/A			
Tuesday	N/A	N/A	N/A			
Wednesday	N/A	N/A	N/A			
Thursday	N/A	N/A	N/A			
Friday	N/A	N/A	N/A			
Saturday	N/A	N/A	N/A	+		

Complaints:	None					
Complaints.						
Construction Sequencing:						
Which portion(s) (i.e. drainage basins) of the	site have had a temporary or pern	nanent cessation of grading	, earthwork, or ground distu	rbance in the la	st 14 days?	
Entire site; grading completed and site	seeded Spring 2005.					
, , , , , , , , , , , , , , , , , , ,	J					
Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthwo	rk, or ground disturbance s	cheduled in the next 14 days	?:		
Entire site; grading completed and site	seeded Spring 2005.					
What temporary or permanent stabilization m		being implemented?				
Paving, dense vegetation and landsca	ping were completed on site.					
Summary Questions:						
Are approved entrances and adjacent streets	being maintained adequately?					
Yes						
Are receiving waters adjacent to the project t	free of any significant signs of ero	sion or sediment that would	d be associated with the con-	struction activit	y?	
Yes						
Checklist Questions:						
Are waste materials (concrete, construction n	naterial, hazardous, etc.) being ma	anaged properly?				
Yes						
Is dust associated with the construction activ	rity adequately controlled on the s	site?	•	•		
Yes						
Comments:		<u> </u>				
Comments:						
Home construction is active on a few lo	ots.					
Note: The sediment basin closure is co	omplete as of inspection on 1	0/20/15 All builders wil	I he required to install sil	t fence and c	onstruction	
entrances going forward.	implete as of inspection on t	10/20/13. All bullders wil	i be required to install sil	t icricc and c	onstruction	
Due to snow cover during the inspection	on following rainfall on 12/23/	15, not all BMPs could	be inspected.			
Findings / Corrective Actions (Date)						
Findings / Corrective Actions (Date)						
1) Some maintenance is required in the						
Hadana Nama	T	1 4:	Duning stand Investell Dusta	04-4	M-:	
Unique Name Lot 8	Type Silt Fence	Location Lot 8	Projected Install Date	Status Removed	Maintenance	
Current Condition:	Removed - Hildy Homes so		7/28/15 inspection.	Ttomovou		
Lot 9	Individual Lot	Lot 9	•	Removed		
Current Condition:	Removed-Dave Paik sodde		ion on 4/21/15.	Damana		
Lot 29 Current Condition:	Individual Lot Removed-R&A removed the	Lot 29	the lot prior to inspection	Removed		
Lot 30	Individual Lot	Lot 30	Inc lot phor to inspection	Removed		
Current Condition:	Removed-Hildy Homes sode	ded the lot prior to inspe				
Lot 37	Silt Fence	Lot 37	12/22/2015	Pending	Yes	
Current Condition:	Pending					
	1) Silt fence should be installed on the southwest corner.					
	2) A rocked construction entrance needs to be installed.					
	1) Hildy Homes was requested to install silt fence by 12/22/15. Not verified due to snow cover during last					
	inspection. 2) Hildy Homes was requested to install a rocked entrance by 12/22/15. Not verified due to snow cover					
	during last inspection.				35 5545.	
Lot 38	Individual Lot	Lot 38		Removed		
Current Condition:	Removed-Inspire sodded th		on 4/2/15.	Memoved		
Lot 40	Silt Fence	Lot 40	8/26/2015	Pending	Yes	

Current Condition:	Pending-Hildy Homes pave	d the driveway prior to i	nspection on 12/15/15.			
	Silt fence should be installed on the southwest corner.					
	Hildy Homes was requested to install silt fence by 8/26/15. Not done as of last inspection. Hildy Homes was reminded on 10/20/15, 12/16/15.					
Lot 42	Temp. Seeding	Lot 42	12/29/2015	Pending	Yes	
Current Condition:	Pending	20172	12/20/2010	i criding	100	
Carrent Condition.	The lot was disturbed during construction on lot 30.					
	Hildy Homes was requested inspection.	I to stabilize the lot by 1	2/29/15. Not verified du	ie to snow cover	during last	
Lot 44	Silt Fence	Lot 44		Removed		
Current Condition:	Removed - Zych sodded the		inspection.			
Lot 45	Silt Fence	Lot 45		Removed		
Current Condition:	Removed - Ramm Construc					
Lot 49	Individual Lot	Lot 49	8/1/2014	Removed		
Current Condition:	Removed- Matrix Homes so	odded the lot prior to ins	spection on 6/24/15			
Lot 50	Silt Fence	Lot 50	11/20/2015	Pending	Yes	
Current Condition:	Fair Condition-Showcase	Homes installed silt fe	ence on the south side	and southwest	corner prior	
	to inspection on 12/15/15. A rocked construction entra Showcase Homes was requ			Not done as of I	ast inspection	
Lot 67	Silt Fence	Lot 67		Removed		
Current Condition:	Removed-Prestige Homes		aspection on 12/15/15	Ttomovou		
Lot 77	Silt Fence	Lot 77	11/13/2015	Active	Yes	
Current Condition:	Fair Condition-Ramm Cons					
	A rocked construction entrance needs to be installed. Ramm Construction was requested to install the entrance by 11/20/15. Not done as of last inspection.					
Lot 79	Silt Fence	Lot 79	11/13/2015	Active	No	
Current Condition:	Good Condition-Homestead check on the southwest cor			13/15 and installe	ed a silt fence	
Lot 80	Silt Fence	Lot 80		Removed		
Current Condition:	Removed-PHI sodded the le		10/9/15.			
Lot 81	Temp. Seeding	Lot 81	12/29/2015	Pending	Yes	
Current Condition:	Pending The lot was disturbed during Malibu Homes was requested inspection.			due to snow cove	er during last	
1 105	·	1 100		1.5		
Lot 82	Silt Fence	Lot 82		Removed		
Current Condition:	Removed-Malibu Homes so			A ation	NI-	
Lot 87	Silt Fence	Lot 87	4/21/2015	Active	No otion on	
Current Condition:	Good Condition-Marc David 8/19/15. The lot is not active	e for home construction	-		ction on	
Lot 88	Individual Lot	Lot 88		Removed		
Current Condition:	Removed-Marc David sodd	ed the lot prior to inspect	ction on 8/19/15. 12/22/2015	Pending	V	
Lot 91 Current Condition:	Pending 1) Silt fence should be installed on the northwest corner of the lot. 2) A rocked construction entrance should be installed.					
	John Caniglia Homes wa during last inspection. John Caniglia Homes wa snow cover during last insp	s requested to install a	·			

Current Condition: SWPPP Sign Current Condition:	Good Condition-No major si SWPPP Notification Sign Good Condition: 192nd and	2 signs	8/19/2008	to inspection o	n 4/2/15. No
STR	Streets	N41d17m09s W96d13m05s	8/1/2005	Active	No
SF 1 Current Condition:	Silt Fence Good Condition - SF on the	W96d13m14s back of lot 77 has been	10/9/2015	Active evel BMP.	No
Current Condition:	Removed-The sediment bas	sin was closed by Tom F N41d17m09s	Falcone prior to inspect	ion on 10/20/1	5.
SB A	Sediment Basin	N41d17m09s W96d13m14s		Removed	

Inspector Signature:

Reviewed By: