E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Aaron Tulley		E&A - P2018.109.002				
		Gallery 23 East				
	CSW-201702253 (Mass Grading)					
	CSW-210	802622 (Intersed	tion Improv-Pendir	ng)	2	
	CSW-20	01802623 (Water	Main Improvements	3)		
Project Name:		SW-201802624 (E	-	′		
For Week Ending:			,			
For Week Enaling.		3/23/2019				
Project Location:	County Road	County Road U and Lincoln Highway- Fremont, NE (Dodge County)				
	Gallery 23 East	Water Main Project	Lift Station & Force Main	Intersection Impr.		
Grading:	85%			0%		
Sanitary Sewer: Storm Sewer:	70%		99% N/A	0% 0%		
Storm Sewer: Paving:	0%		N/A N/A	0%		
Seeding:	1%		99%	0%		
Utilities:	60%		N/A	0%		
Overall Development:	20%	92%	99%	0%		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions			
		3, 0000			Wee	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.20"					
Wednesday	0.54"	3/13/2019	Thunderstorms 59/41			
Thursday	0.14"					
Friday	0.00"					
Saturday	0.00"					
					Wee	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.08"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.32"				Wee	
Sunday:	N/A				- 1100	
Monday	N/A					
Гuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
Complaints:						
Construction Sequencies:						
Construction Sequencing:	s) of the site have had a temporary or perm	anont acception of marillan	continuous or ground disturbance	o in the lest 44 days		

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19)

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occured in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection.

Highway 30 intersection improvements have not begun as of last inspection.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occured in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection

Highway 30 intersection improvements have not begun as of last inspection.

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/18). Seeding around banks of E side of lake (11/6/18).

Summary Questions

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Checklist Questions:

nstruction material, hazardous, etc.) being managed properly

No - See Findings Section

Is dust associated with th

Yes

Comments:

The site was inactive during the last inspection for the Gallery 23 East project. Interior sanitary work is occurring by Thompson and major grading activities have ceased with the Gallery 23 East project by Pruss Excavation. Grading for water tie in along Rd 25 as of last inspection. Grading has ceased.

Lift Station and Sanitary Force Main projects are nearing completion. Work is occurring on the southeast intersection of County Road U and the project. County Road U Blvd and East 16th Street ditches will be stabilized in the coming weeks as of 8/30/2018. E&A will continue to monitor. Street ditches were seeded and matted prior to inspection on 9/19/18. During inspection on 3/13/19, the road side ditches on the E side of Hwy 275 for the sanitary project were filled with water, therefore the status of the wattles could not be visually verified.

Water Improvements project has begun as of last inspection. Dirt piles from water main improvement project are being moved over to Gallery 23 East project in low areas. Dirt will be spread at a later date (2/7/19). Water project was inactive during last inspection.

Highway 30 intersection improvements project has not been transferred to E&A Consulting Group. Inc. for inspections or construction observation. E&A will continue to monitor and update when more permitting information is known.

According to Jim Hammit, the E&A Construction monitor on site, the project is currently in a winter shutdown stage and no new work should be occurring until Spring.

Work for overhead electric occurring during inspection on 1/10/19 by Fremont Public Works around perimeter of Gallery 23 East.

During inspection on 3/13/19 portion of the site were inaccessible due to flooding.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1. See BMP section for required maintenance.
- 2. Diesel fuel tanks need to be bermed on site as of 8/30/2018. Pruss Excavation will be informed to complete by 9/6/2018. Not done as of last inspection. Thompson Construction was informed to complete by 10/16/18. Not done as of last inspection.
- 3. One portable toilet on the site needs to be staked down. Thompson Construction will be informed to complete when conditions allow as of 12/19/18. Not done as of the last inspection.
- 4. The fuel tank on site has a leak. E&A inspector notified Jim Hammit with E&A to monitor and inform Thompson to repair tank. Not done as of the last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
Gallery 23 East						
CE 1	Construction Entrance	County Road Blvd U	8/30/2018	Active	No	
Current Condition:	Good Condition - 70% effective. Pruss is off site as of 10/8/18. Thompson Construction added rock to the entrance prior to inspection on 11/6/18.					

		ı	1			
	Co	unty Road				
CE 2		Highway 30 8/30/2018	Active	No		
Current Condition:	Good Condition - 70% effective - Rock entrance was installed off Highway 30 prior to 8/30/2018.					
CP #1	Culvert protection Central	portion of site 8/30/2018	Pending	No		
Current Condition:	Pending - Culvert protection will be in	nstalled at a later date.				
CP #2	Culvert protection South	neast corner 8/30/2018	Pending	No		
Current Condition:	Pending - Culvert protection will be in	nstalled at a later date.				
CW	Concrete Washout Gall	ery 23 East 8/30/2018	Pending	No		
Current Condition:	Pending - Washouts will be installed		, committee			
DW #1 Current Condition:	Ditch Wattle Checks Mid Pending - Ditch wattle checks will be	dle Central 8/30/2018	Pending	No		
Guirent Gondition.	r chaining Bhori Wattie oricons will be	instance when grading has chace.				
DW #2	Ditch Wattle Checks South	nwest corner 8/30/2018	Pending	No		
Current Condition:	Pending - Ditch wattle checks will be	installed when grading has ended.				
DW #3	Ditch Wattle Checks South	neast corner 8/30/2018	Active	No		
Current Condition:		re installed on the southeast side prior				
DD #1		orner of Lake 11/6/2018 ation, as of 1/10/19 inspection, wattles/c	Active	No		
Current Condition:	Good Condition - After further evalua	ition, as of 1/10/19 inspection, watties/c	checks will no longer be re	ecommenaea		
DD #2	Diversion Ditch W s	ide of Lake	Active			
Current Condition:		removed the diversion ditch prior to insp				
DD #3		orner of lake	Active			
Current Condition:	•	removed the diversion ditch prior to insp	·			
DD #4 Current Condition:	Diversion Ditch S S	ide of lake removed the diversion ditch prior to insp	Active			
DD #5		ide of lake	Active			
Current Condition:		removed the diversion ditch prior to insp				
DD #6		orner of lake 8/30/2018	Active	No		
Current Condition:	Good Condition - After further evalua	ation, as of 1/10/19 inspection, wattles/c	checks will no longer be re	ecommended		
DD #7	Diversion Ditch N s	ide of lake 9/25/2018	Active	No		
Current Condition:		e lot and an access road being installed	l, silt fence or straw bale of	checks will no		
EB #2	be recommended at this time. E&A v		Danding I	N.		
Current Condition:		neast corner 8/30/2018 d seeding will be installed when grading	Pending named	No		
- Curront Conditions	-	d Lake (Outlot	J III			
EB #3	Erosion Blanket	B) 8/30/2018	Pending	No		
Current Condition:	Pending - Erosion control matting an	d seeding will be installed when grading	g has ended.			
CD #1	Sediment Basin Central	nortion of site 9/20/2019	Danding	No		
SB #1 Current Condition:		portion of site 8/30/2018 e grading has commenced at a later da	Pending te	No		
	•			N _a		
SB #2 Current Condition:		neast corner 8/30/2018 e grading has commenced at a later da	Pending te.	No		
SF #1		neast corner 8/30/2018	Pending	No		
Current Condition:	Pending - Silt Fence will be installed					
SF #2		neast corner 8/30/2018	Pending	No		
Current Condition:	Pending - Silt Fence will be installed	at a rater date.				
STR	<u> </u>	Off-Site In Place	Active	No		
Current Condition:	Good Condition - No signs of trackou					
SWPPP Sign-SI		Intrances 10/9/2018	Pending	Yes		
Current Condition:	at the County Rd U Blvd entrance at	SWPPP signs during inspection on 10/9	1/18. Other SWPPP sign v	will be installe		
	The SWPPP sign blew off the t-post	prior to inspection on 2/7/19 and needs	s reinstalled			
	Inspector will reinstall during next ins	spection when conditions allow. Not don	ne as of the last inspection	n.		
	Sanitary Lift Station and Force Main					
CE 1		Road Blvd U	Removed			

Current Condition:	Removed - See CE1 for Gal	llery 23 project as of 8/3	0/2018.		
CW	Concrete Washout	County Road Blvd U		Removed	
Current Condition:	Removed - See CW for Gall	lery 23 project as of 8/3	0/2018. No concrete is being	g poured for the sa	anitary lift projec
DO #4	Distance Marila Observa	01	1 0/40/0040	I A-C	I No.
DC #1 Current Condition:	Ditch Wattle Checks Good Condition - Ditch wattl	Sheet C-603	9/13/2018	Active	No
			<u> </u>		
DC #2	Ditch Wattle Checks	Sheet C-604	9/13/2018	Active	No
Current Condition:	Good Condition - Ditch wattl		<u> </u>		
DC #3	Ditch Wattle Checks	Sheet C-605	9/13/2018	Active	No
Current Condition:	Good Condition - Ditch wattl		<u> </u>		
DC #4	Ditch Wattle Checks Good Condition - Ditch wattl	Sheet C-606	9/13/2018	Active	No
Current Condition:	Good Condition - Ditch watti		r prior to inspection on 9/19/	10	
ED #4	Francis Blanket	Along ditch between Rd 25 and lift station	0/43/3049	Activo	No.
EB #1 Current Condition:	Erosion Blanket Good Condition - Erosion co		9/13/2018	Active	No
Current Condition.	Good Condition - Erosion Co		•	T T T T T T T T T T T T T T T T T T T	
EB #2	Erosion Blanket	Along ditch W of 25 E of Hwy 275	9/13/2018	Active	No
Current Condition:	Good Condition - Erosion co				140
EB #3	Erosion Blanket	E of Roundabout	9/25/2018	Active	No
Current Condition:	Good Condition - Erosion co				110
			• •		
STR	Street cleaning	Off-Site	In Place	Active	No
Current Condition:	Good Condition - No signs of	or trackout.			
SWPPP Sign-SI	Signs	2 Entrances		Removed	1
Current Condition:	Removed - See SWPPP sig		st project	Removed	!
		·			
	Water	Main Extens			
CW	Concrete Washout	County Road Blvd U	10/4/2018	Pending	No
Current Condition:	Pending - Washouts will be	installed when concrete	WORK OCCURS.		
SF #1	Silt Fence	Area #1		Removed	
Current Condition:	Removed - There is no silt f	ence in this area, see IF	1 and IP 2 for BMPs in Are	ea #1	
		N side of 24th St			
IP 1	Inlet Protection	(Enlarged Area #1)	10/23/2018	Active	Yes
Current Condition:	The inlet protection was d		led inlet protection prior to i		3/18.
Current Continue.		amaged prior to inspe	ction on 3/13/19 and need		3/18.
Current Continue.	The inlet protection was d	amaged prior to inspe	ction on 3/13/19 and need		3/18.
IP 2	The inlet protection was d H.R. Bookstrom was inform Inlet Protection	amaged prior to inspe med to complete by 3/ S side of 24th St (Enlarged Area #1)	20/19 as conditions allow 10/23/2018	s repaired Active	Yes
	The inlet protection was d	amaged prior to inspe med to complete by 3/ S side of 24th St (Enlarged Area #1)	20/19 as conditions allow 10/23/2018	s repaired Active	Yes
IP 2	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books	amaged prior to inspe med to complete by 3/. S side of 24th St (Enlarged Area #1) trom Construction insta	20/19 as conditions allow 10/23/2018 led inlet protection prior to i	Active	Yes 3/18.
IP 2	The inlet protection was d H.R. Bookstrom was inform Inlet Protection	amaged prior to inspe med to complete by 3/. S side of 24th St (Enlarged Area #1) trom Construction insta	20/19 as conditions allow 10/23/2018 led inlet protection prior to i	Active	Yes 3/18.
IP 2	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d	amaged prior to inspe med to complete by 3/. S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspe	20/19 as conditions allow 10/23/2018 led inlet protection prior to i	Active	Yes 3/18.
IP 2 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform	amaged prior to inspe med to complete by 3/. S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspe med to complete by 3/	20/19 as conditions allow 10/23/2018 led inlet protection prior to incident on 3/13/19 and needs 20/19 as conditions allow	Active nspection on 10/23 s repaired/replace	Yes 3/18.
IP 2 Current Condition: SF #2	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence	amaged prior to inspe med to complete by 3/. S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspe med to complete by 3/. Area #2	20/19 as conditions allow 10/23/2018 led inlet protection prior to incident on 3/13/19 and needs 20/19 as conditions allow 10/4/2018	Active	Yes 3/18.
IP 2 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform	amaged prior to inspe med to complete by 3/. S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspe med to complete by 3/. Area #2	20/19 as conditions allow 10/23/2018 led inlet protection prior to incident on 3/13/19 and needs 20/19 as conditions allow 10/4/2018	Active nspection on 10/23 s repaired/replace	Yes 3/18.
IP 2 Current Condition: SF #2	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence	amaged prior to inspermed to complete by 3/ S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/ Area #2 Installed when grading residue.	20/19 as conditions allow 10/23/2018 led inlet protection prior to i ction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area.	Active nspection on 10/23 s repaired/replace	Yes 3/18.
IP 2 Current Condition: SF #2	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/2 Area #2 Installed when grading restalled across the roads	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to incident on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. Side ditch on the E side of Allow 20/19 and needs 20/19 as conditions allow	Active Inspection on 10/2:	Yes 3/18. ed Yes
IP 2 Current Condition: SF #2	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informed	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/2 Area #2 Installed when grading restalled across the roads	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to incident on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. Side ditch on the E side of Allow 20/19 and needs 20/19 as conditions allow	Active Inspection on 10/2:	Yes 3/18. ed Yes
IP 2 Current Condition: SF #2 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer	amaged prior to inspermed to complete by 3/ S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/ Area #2 Installed when grading restalled across the roads and to complete by 11/20	20/19 as conditions allow 10/23/2018 led inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. side ditch on the E side of Alloy 1/18. Not done as of last inspect	Active Inspection on 10/23 Since repaired/replace Pending Inspection on 40/23 Since repaired/replace Inspection on 40/23 Since repaired on 40	Yes 3/18. ed Yes
IP 2 Current Condition: SF #2 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informereminded on 12/19/18. Silt Fence	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/2 Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 ided ditch on the E side of Allow 10/4/2018	Active Inspection on 10/2:	Yes 3/18. ed Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer	amaged prior to inspermed to complete by 3/ S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/ Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled to complete by 11/200 prior to insperment	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 ided ditch on the E side of Allow 10/4/2018	Active Inspection on 10/23 Since repaired/replace Pending Inspection on 40/23 Since repaired/replace Inspection on 40/23 Since repaired on 40	Yes 3/18. ed Yes sstrom was
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence	amaged prior to inspermed to complete by 3/ S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/ Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled w	20/19 as conditions allow 10/23/2018 led inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area.	Active Inspection on 10/23 Since repaired/replace Pending Inspection on 40/23 Since repaired/replace Inspection on 40/23 Since repaired on 40	Yes 3/18. ed Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in	amaged prior to inspermed to complete by 3/ S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/ Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled w	20/19 as conditions allow 10/23/2018 led inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area.	Active Inspection on 10/23 Serepaired/replace Pending rea #2 Dection. H.R. Book	Yes 3/18. ed Yes strom was
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	The inlet protection was d H.R. Bookstrom was information Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was information Silt Fence Pending - Silt fence will be in H.R. Bookstrom was information in the inlet protection was d H.R. Bookstrom was information in the inlet protection was information was information with the inlet protection was information was information with the inlet protection with the inlet protection was information with the inlet protection was information with the inlet protection with the inlet protection was information with the inlet protection with the inlet protection with the inlet protection with t	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/2 Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 Eaches area. 10/4/2018 Eaches area. 10/4/2018 Eaches area. 10/4/2018 Eaches area.	Active Inspection on 10/23 Serepaired/replace Pending rea #2 Dection. H.R. Book	Yes 3/18. ed Yes strom was
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/2 Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 Eaches area. 10/4/2018 Eaches area. 10/4/2018 Eaches area. 10/4/2018 Eaches area.	Active Inspection on 10/23 Serepaired/replace Pending rea #2 Dection. H.R. Book	Yes 3/18. ed Yes strom was
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informereminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction install amaged prior to inspermed to complete by 3/2 Area #2 nstalled when grading restalled across the roads and to complete by 11/20 Area #3 nstalled when grading restalled	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4	Active Inspection on 10/23	Yes 3/18. ed Yes No Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	The inlet protection was d H.R. Bookstrom was information Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was information Silt Fence Pending - Silt fence will be in H.R. Bookstrom was information in the inlet protection was d H.R. Bookstrom was information in the inlet protection was information was information with the inlet protection was information was information with the inlet protection with the inlet protection was information with the inlet protection was information with the inlet protection with the inlet protection was information with the inlet protection with the inlet protection with the inlet protection with t	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction install amaged prior to inspermed to complete by 3/2 Area #2 nstalled when grading restalled across the roads and to complete by 11/20 Area #3 nstalled when grading restalled	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4	Active Inspection on 10/23	Yes 3/18. ed Yes Strom was No Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt fence should be installed H.R. Bookstrom was informer.	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction install amaged prior to inspermed to complete by 3/2 Area #2 nstalled when grading restalled across the roads and to complete by 11/20 Area #3 nstalled when grading restalled	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4	Active Inspection on 10/23	Yes 3/18. ed Yes Strom was No Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt fence will be in Silt fence will be in Silt fence should be installed H.R. Bookstrom was informer reminded on 12/19/18.	amaged prior to inspermed to complete by 3/ S side of 24th St (Enlarged Area #1) trom Construction install amaged prior to inspermed to complete by 3/ Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled	20/19 as conditions allow 10/23/2018 led inlet protection prior to i ction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. Area #4 1/18. Not done as of last insp	Active Inspection on 10/23	Yes 3/18. ed Yes sstrom was No Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be i Silt Fence Pending - Silt fence will be i Silt Fence Pending - Silt fence will be i Silt Fence Pending - Silt fence will be i Silt Fence Pending - Silt fence will be i Silt Fence Silt fence will be i Silt Fence Silt Fence Silt Fence Pending - Silt Fence Silt Fence	amaged prior to inspermed to complete by 3/ S side of 24th St (Enlarged Area #1) trom Construction install amaged prior to inspermed to complete by 3/ Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled to complete by 11/20	20/19 as conditions allow 10/23/2018 led inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. Area #4 1/18. Not done as of last inspections area. 10/4/2018 eaches area. 10/4/2018 eaches area.	Active Inspection on 10/23	Yes 3/18. ed Yes Strom was No Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt fence should be installed H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence	amaged prior to inspermed to complete by 3/ S side of 24th St (Enlarged Area #1) trom Construction install amaged prior to inspermed to complete by 3/ Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled to complete by 11/20	20/19 as conditions allow 10/23/2018 led inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. Area #4 1/18. Not done as of last inspections area. 10/4/2018 eaches area. 10/4/2018 eaches area.	Active Inspection on 10/23	Yes 3/18. ed Yes Strom was No Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt fence should be installed H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/2 Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled to complete by 11/20 Area #4 Installed when grading restalled when g	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. Area #4 10/18. Not done as of last inspections of last inspections area. 10/4/2018 eaches area. Area #4 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4	Active Inspection on 10/2: Is repaired/replace I Pending	Yes 3/18. ed Yes Sistrom was No Yes Sistrom was Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer eminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt fence will be in Silt fence should be installed H.R. Bookstrom was informer eminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt fence should be installed Silt fence should be installed H.R. Bookstrom was informer eminded on 12/19/18.	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/2 Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled to complete by 11/20 Area #4 Installed when grading restalled when g	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. Area #4 10/18. Not done as of last inspections of last inspections area. 10/4/2018 eaches area. Area #4 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4	Active Inspection on 10/2: Is repaired/replace I Pending	Yes 3/18. ed Yes Sistrom was No Yes Sistrom was Yes
IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition:	The inlet protection was d H.R. Bookstrom was inform Inlet Protection Fair Condition - H.R. Books The inlet protection was d H.R. Bookstrom was inform Silt Fence Pending - Silt fence will be in H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt fence should be installed H.R. Bookstrom was informer reminded on 12/19/18. Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence Pending - Silt fence will be in Silt Fence	amaged prior to inspermed to complete by 3/2 S side of 24th St (Enlarged Area #1) trom Construction instal amaged prior to inspermed to complete by 3/2 Area #2 Installed when grading restalled across the roads and to complete by 11/20 Area #3 Installed when grading restalled to complete by 11/20 Area #4 Installed when grading restalled when g	20/19 as conditions allow 10/23/2018 Ided inlet protection prior to inction on 3/13/19 and needs 20/19 as conditions allow 10/4/2018 eaches area. Area #4 10/18. Not done as of last inspections of last inspections area. 10/4/2018 eaches area. Area #4 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4	Active Inspection on 10/2: Is repaired/replace I Pending	Yes 3/18. ed Yes Sistrom was No Yes Sistrom was Yes

Current Condition:	Pending - Silt fence will be	Pending - Silt fence will be installed when grading reaches area.					
STR	Street cleaning	Off-Site	In Place	Active	No		
Current Condition:	Good Condition - Streets sh	Good Condition - Streets showed signs of improvement, however, some street cleaning is still necessary. H.R.					
	Bookstrom Construction cleaned the streets at 24th St prior to inspection on 1/10/19.						
SWPPP Sign-SI	Signs	2 Entrances		Removed			
Current Condition:	Removed - See SWPPP sig	Removed - See SWPPP signs under Gallery 23 East project					
Inspector Signature:	L-77		Reviewed By:	But Su			