E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Joe Manning		E&A - P2018	.109.002		Stage	
		Gallery 23	3 Fast			
	C	CSW-201702253 (Mass Grading)				
		•	- ·			
Project Name:	CSW-210802622 (Intersection Improvements)					
For Week Ending:	7/10/2021					
Project Location:	County Road U and Lincoln Highway- Fremont, NE (Dodge County)				68025	
	Gallery 23 East	Intersection Impr.				
Grading:	96%	100%				
Sanitary Sewer:	97%	N/A				
Storm Sewer:	95%	N/A				
Paving: Seeding:	99%	100% 85%				
Seeding: Utilities:	99%	05% N/A				
Overall Development:	45%	90%				
				<u> </u>		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time	Week	
Sunday:	0.01"				Weel	
Monday	0.01"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
	0.00"					
Saturday	0.00				Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.39"					
Thursday	0.00"					
Friday	0.13"	7/9/2021	Mostly Sunny 90/68	11:30 AM		
Saturday	3.71"	7/10/2021	Thunderstorms 75/64	4:00 PM		
·					Week	
Sunday:	N/A					
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
Complaints:						
Construction Sequencing:						
) of the site have had a temporary or perma	ment ecception of grading	continuous or around disturban	an in the last 44 decemb		

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/19). Fine grading throughout the site in preparation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching/excavation in the southeast portion of the site for utility installation (10/22/19). Trenching throughout site for utility installation (11/27/20).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19).

Grading for Highway 30 intersection improvements has begun (7/27/20). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/20). Stockpiling on Block 1 Lot 9 (4/20/21).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/19). Fine grading throughout the site in preparation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching/excavation in the southeast portion of the site for utility installation (10/22/19). Trenching throughout site for utility installation (11/27/20).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19).

Grading for Highway 30 intersection improvements has begun (7/27/20). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/20). Stockpiling on Block 1 Lot 9 (4/20/21).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/18). Seeding around banks of E side of lake (11/6/18). Seeding for Highway 30 Intersection Improvements (10/18/20). Reseeding along the Highway 30 Improvements (3/15/21).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A - Luxa seeded along the Highway 30 intersection improvements. Seeding along highway was inadequate. ROW was reseeded prior to the inspection on 3/15/21. E&A inspector will continue to monitor.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No - See Findings Section and BMP Section (CW on Lots 1-10, Block 1, Replat 2).

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMP Section and Findings Section (#5).

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

The site was active during the last inspection for home construction.

Lift Station and Sanitary Force Main projects are closed.

Water Improvements project is closed.

Highway 30 intersection improvements project was inactive during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1. See BMP section for required maintenance.
- 2. The areas of the intersection improvements where work has ceased should be stabilized. Jim Hammitt was informed to contact Luxa on 10/06/20. Luxa seeded along the intersection improvements and along the Highway 30 ditch prior to the inspection on 10/18/20. The seeding along the highway is not sufficient coverage as of the inspection on 3/08/21. Commercial Seeding re-seeded the area along the highway improvements prior to the inspection on 3/15/21. E&A inspector will continue to monitor the vegetation growth as of the 5/03/21 inspection. Seeding has mostly established along Highway 30 improvements prior to the inspection on 5/27/21.
- 3. Trackout was observed on Eastgate Road and Highway 30 from the RTG Lot. Trackout should be cleaned from the street. White Lotus Group was informed to complete by 1/12/21. No trackout was observed from the lot during the inspection on 3/08/21. Trackout was observed during the inspection on 3/15/21. Ronco Construction was informed to clean the street by 3/16/21. Not done as of the last inspection. Ronco Construction was reminded on 4/21/21, 5/18/21. Ronco Construction cleaned the street prior to the inspection on 6/09/21. Trackout should be cleaned from the street as of the inspection on 6/25/21. Ronco Construction was informed to complete by 6/26/21. **Not done as of the last inspection.**
- 4. Ronco Construction was stockpiling dirt on Block 1 Lot 9 from grading activities on Lot 2 Replat 1. A construction entrance should be installed or access to this lot should be blocked. Ronco Construction was informed to complete by 4/27/21. Not done as of the last inspection. Ronco Construction was reminded on 5/18/21. Block 1 Lot 9 was not being accessed as of the inspection on 6/09/21. E&A inspector will monitor.
- 5. Concrete waste from the RTG Lot was observed outside of the lot. Concrete waste should be kept on the lot. Ronco Construction was informed to remove the concrete waste by 7/02/21. **Not done as of the last inspection.**

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
Offique Name	•			Status	wantenance
	Ga	Ilery 23 East			
CE 1	Construction Entrance	County Road Blvd U		Removed	
Current Condition:	Removed - Thompson Cons	struction removed the co	onstruction entrance in prep	aration for paving p	rior to
	inspection on 9/9/19.				
		County Road			
CE 2	Construction Entrance	25/Highway 30		Removed	
Current Condition:	Removed - Pruss was remo	ving the construction er	ntrance during inspection on	6/18/19 in prepara	tion for paving.
		·			
		NE Corner - Hwy 30 &			
CE 3	Construction Entrance	Christine Drive		Removed	
Current Condition:	Removed - The construction	entrance was removed	as a part of the Highway 3	0 intersection impro	ovements prior
	to the inspection on 8/05/20	. E&A inspector will mo	nitor and recommend reinst	allation at a later da	ate if necessary.
	·	•			•
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection	will be installed at a lat	er date.		•
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection	will be installed at a lat	er date.		•
		Northeast corner of			
CW	Concrete Washout	site		Removed	
Current Condition:	Removed - The concrete wa	ashout pits were remove	ed prior to inspection on 10/2	21/19. No paving is	underway at
	this time. E&A will monitor t	he need for reinstallation	n.		
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle chec	ks will be installed when	grading has ended.		
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle chec	ks will be installed when	grading has ended.		
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No
Current Condition:	Good Condition - Wattles ch	necks were installed on	the southeast side of the sit	e prior to 8/30/2018	3.
DD #1	Diversion Ditch	NW Corner of Lake		Removed	
Current Condition:	Removed - The diversion di	tch was removed during	g regrading/paving in the are	ea prior to inspectio	n on 12/30/19.
DD #2	Diversion Ditch	W side of Lake		Removed	
Current Condition:	Removed - Thompson Cons	struction removed the di	version ditch prior to inspec	tion on 9/19/18.	
DD #3	Diversion Ditch	SW corner of lake		Removed	
Current Condition:	Removed - Thompson Cons	struction removed the di	version ditch prior to inspec	tion on 9/19/18.	
DD #4	Diversion Ditch	S Side of lake		Removed	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec		
DD #5	Diversion Ditch	E side of lake		Removed	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec		
DD #6	Diversion Ditch	NE corner of lake		Removed	

Current Condition:	Removed - The diversion di	tch was removed during	g regrading/paving in the are	ea prior to inspection	n on 12/30/19.
 DD #7	Diversion Ditch	N side of lake		Removed	
Current Condition:	Removed - The diversion di		g regrading/paving in the are		n on 12/30/19.
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m		be installed when grading h	as ended.	
EB #3	Erosion Blanket	Around Lake (Outlot B)	8/30/2018	Pending	No
Current Condition:	Pending - Erosion control m	atting and seeding will	be installed when grading h	as ended.	•
IP 1	Inlet Protection	Area Inlet in SE portion of the site		Removed	
Current Condition:	Removed - The area east of longer needed at this time.	f the area inlet naturally	stabilized prior to the 8/05/2	20 inspection. Inlet	Protection no
IP 2	Curb Inlet protection	W Curb inlet on Christine Dr		Removed	
Current Condition:	Removed - The Home Com		ior to the inspection on 6/10		n is no longer
	required.	. , .	,	•	ŭ
		E Curb inlet on			
IP 3	Curb Inlet protection	Christine Dr		Removed	
Current Condition:	Removed - The Home Com	pany sodded lots 1-8 pr	ior to the inspection on 6/10	0/20. Inlet protection	n is no longer
	required.				
		Block 1, Replat 2			
1 / 4 / 2 51 1 2 5 1 4 2		(Northeast corner of			
Lots 1-10, Block 2, Replat 2	Individual Lots	site)		Removed	
Current Condition:	Removed - Block 2 was mis	Block 2, Replat 2	I	1	
		(Northeast corner of			
Block 1 Replat 2, Lots 1-10	Individual Lots	site)	1/11/2021	Active	Yes
Current Condition:	Fair Condition - The Home (
Block 3 Replat 2, Lots 9-12 Current Condition:	Company secured the porta 1 and 2 prior to the inspectit to the inspection on 5/17/21 1.) Silt fence or straw wattle stabilized. 2.) The streets surrounding 3.) Silt fence should be insta 1.) The Home Company was Company was reminded on 2.) The Home Company was Company was reminded on 3.) The Home Company was Company was reminded on Individual Lots Active - An unknown builder	s should be installed alored the lots should be clear alled along the backs of sinformed to complete 4/21/21, 6/10/21 sinformed to complete 4/21/21, 6/10/21 sinformed to complete 6/10/21 Block 3 began construction on	company removed the corporation of Lots 9 and . Lots 1-2 and 9-10 (or Lots 9 by 3/15/21. Not done as of the by 3/09/21. Not done as of the by 4/27/21.	and 10 or the lots of and 10 should be the last inspection. The last inspection. Active ction on 6/09/21. D	should be stabilized). The Home The Home The Home No ue to the
	vegetation surrounding the linspector will monitor.	lots and the grade in the	e area, no BMPs will be reco	ommended at this ti	ime. E&A
Block 3 Replat 2, Lots 13-16	Individual Lots Pending - An unknown build	Block 3	6/9/2021	Pending	Yes
Current Condition:	1.) Silt fence should be ins 2.) The street in front of th 1.) The E&A inspector will Not done as of the last ins 2.) The E&A inspector will Not done as of the last ins	stalled along the front e lot should be cleane make an attempt to id spection. make an attempt to id	of the lots. Id. Id. Id. Identify the builder and info	rm them to compl	ete by 7/16/21.
Block 7, Lots 2 & 3	Individual Lots	Block 7		Removed	
Current Condition:	Removed - The Home Com		prior to the inspection on 6		
Block 7, Lot 6	Individual Lots	Block 7	3/24/2021	Active	No
Current Condition:	Good Condition - Rick Wal Walkup Construction secure Construction removed the d was cleaned prior to the in	ed a portable toilet on th irt piles from the ROW p	ne lot prior to the inspection	on 3/24/21. Rick W	/alkup
Block 6, Lot 24	Individual Lots	Block 6	4/20/2021	Active	Yes
•	•	•	•		

Current Condition:	Fair Condition - Jeff Wearden Homes began construction on the lot prior to the inspection on 4/20/21. Jeff Wearden Homes installed silt fence at the back of the lot prior to the inspection on 5/17/21. The street in front of the lot was cleaned prior to the inspection on 6/09/21. Jeff Wearden Homes removed the concrete waste, secured the portable toilet, and trenched in the silt fence at the back of the lot prior to the inspection on 7/09/21. The silt fence should be cleaned out and repaired at the back of the lot.				
	Jeff Wearden Homes wa	s informed to complete	hv 7/17/21	I I	
SB #1	Sediment Basin	Central portion of site	8/30/2018	Pending	No
Current Condition:	Pending - Basin will be ins	talled once grading has	commenced at a later date a	nd when deemed n	ecessary
SB #2	Sediment Basin	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Basin will be ins	talled once grading has	commenced at a later date a	and when deemed n	ecessary
SF #1	Silt Fence	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Silt Fence will b				
SF #2	Silt Fence	Northeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Silt Fence will b				
STR	Street cleaning	Off-Site	In Place	Active	No
Current Condition:	Good Condition - The stre time of the inspection on 1		n at time of inspection on 7/8	3/19. The streets we	re clean at the
SWPPP Sign	Signs	2 Entrances	10/9/2018	Active	No
	inspection on 9/19/19. The	E&A inspector reinstalle	er date. The E&A inspector reed the SWPPP sign during the	ne 2/24/20 inspection	n. The E&A
	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection	E&A inspector reinstalle WPPP sign prior to the in In Improvements prior to		ne 2/24/20 inspection WPPP sign was ren &A inspector will re	on. The E&A noved during
	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection construction allows. E&A i	E E&A inspector reinstalle WPPP sign prior to the ir in Improvements prior to inspector reinstalled the setting the setting in	ed the SWPPP sign during the appection on 3/31/20. The SV the inspection on 8/17/20. ESWPPP sign during the inspection on 8/17/20. ESWPPP sign during the inspection of the in	ne 2/24/20 inspection WPPP sign was ren &A inspector will re	n. The E&A noved during
05.4	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection construction allows. E&A i	E E&A inspector reinstalle WPPP sign prior to the ir in Improvements prior to inspector reinstalled the S Etion Improve West of Gallery East	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on the inspection on the inspection of the inspection of the inspection of the inspection of the inspec	ne 2/24/20 inspection WPPP sign was ren &A inspector will re ection on 8/31/20.	on. The E&A noved during install as
SF 1	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectic construction allows. E&A i	E E&A inspector reinstalle WPPP sign prior to the ir on Improvements prior to nspector reinstalled the S tion Improve West of Gallery East Drive culvert	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection during the inspection during the inspection.	ne 2/24/20 inspection WPPP sign was rentle and inspector will reflection on 8/31/20. Pending	on. The E&A noved during install as
SF 1 Current Condition:	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection construction allows. E&A i Intersection Silt Fence Pending - Silt Fence will be	E&A inspector reinstalle WPPP sign prior to the ir on Improvements prior to nspector reinstalled the S Etion Improve West of Gallery East Drive culvert e installed at a later date	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on the inspection on the inspection of	ne 2/24/20 inspection WPPP sign was rentle and inspector will reflection on 8/31/20. Pending	on. The E&A noved during install as
	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectic construction allows. E&A i	E&A inspector reinstalle WPPP sign prior to the ir on Improvements prior to nspector reinstalled the S Etion Improve West of Gallery East Drive culvert e installed at a later date d due to imminent regrad	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on the inspection on the inspection of	ne 2/24/20 inspection WPPP sign was rentle and inspector will reflection on 8/31/20. Pending	on. The E&A noved during install as
Current Condition:	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection construction allows. E&A i Intersection Silt Fence Pending - Silt Fence will be longer needs to be installed.	E&A inspector reinstalle WPPP sign prior to the ir on Improvements prior to nspector reinstalled the S Etion Improve West of Gallery East Drive culvert e installed at a later date d due to imminent regrad West of Farm Field	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on 8/17/20. ESWPPP sign during the inspection of the ins	ne 2/24/20 inspection WPPP sign was rentled. WPPP sign was rentled. WPPP sign was rentled. We have a sign was rent	on. The E&A noved during install as No he silt fence no
Current Condition:	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectic construction allows. E&A i Intersec Silt Fence Pending - Silt Fence will b longer needs to be installed.	E&A inspector reinstalle WPPP sign prior to the ir on Improvements prior to nspector reinstalled the S Etion Improve West of Gallery East Drive culvert e installed at a later date d due to imminent regrac West of Farm Field Road culvert	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on 8/17/20. ESWPPP sign during the inspection of the ins	ne 2/24/20 inspection WPPP sign was rentled. WPPP sign was rentled. WPPP sign was rentled. WPPP sign was rentled. We have a sign was rentled.	on. The E&A noved during install as No he silt fence no
Current Condition:	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectic construction allows. E&A i Intersec Silt Fence Pending - Silt Fence will b longer needs to be installe Silt Fence Pending - Silt Fence will b	E&A inspector reinstalle WPPP sign prior to the ir on Improvements prior to nspector reinstalled the S Etion Improve West of Gallery East Drive culvert e installed at a later date d due to imminent regrac West of Farm Field Road culvert e installed at a later date	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on 8/17/20. ESWPPP sign during the inspection of the ins	ne 2/24/20 inspection WPPP sign was rentled. WPPP sign was rentled. WPPP sign was rentled. WPPP sign was rentled. We have a sign was rentled.	on. The E&A noved during install as No he silt fence no
Current Condition:	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectic construction allows. E&A i Intersec Silt Fence Pending - Silt Fence will b longer needs to be installed.	E&A inspector reinstalle WPPP sign prior to the ir on Improvements prior to nspector reinstalled the S Etion Improve West of Gallery East Drive culvert e installed at a later date d due to imminent regrac West of Farm Field Road culvert e installed at a later date d due to imminent regrace	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on 8/17/20. ESWPPP sign during the inspection of the ins	ne 2/24/20 inspection WPPP sign was rentled. WPPP sign was rentled. WPPP sign was rentled. WPPP sign was rentled. We have a sign was rentled.	on. The E&A noved during install as No he silt fence no
SF 2 Current Condition:	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection construction allows. E&A i Intersection Silt Fence Pending - Silt Fence will be longer needs to be installed longer needs lo	E&A inspector reinstalle WPPP sign prior to the ir on Improvements prior to inspector reinstalled the S Etion Improve West of Gallery East Drive culvert e installed at a later date d due to imminent regrac West of Farm Field Road culvert e installed at a later date d due to imminent regrac East of Farm Field	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on 8/17/20. ESWPPP sign during the inspection of the ins	Pending Pending Pending Pending Hammitt on 4/1/20 ti	on. The E&A noved during install as No he silt fence no No he silt fence no
SF 2 Current Condition: SF 3	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectic construction allows. E&A i Intersection allows. E&A i Silt Fence Pending - Silt Fence will b longer needs to be installed longer needs to be installed longer needs to be installed Silt Fence Silt Fence Silt Fence will b longer needs to be installed longer needs to be installed Silt Fence	E&A inspector reinstalle WPPP sign prior to the ir on Improvements prior to inspector reinstalled the S Etion Improve West of Gallery East Drive culvert e installed at a later date d due to imminent regrace West of Farm Field Road culvert e installed at a later date d due to imminent regrace East of Farm Field Road culvert East of Farm Field Road culvert	ed the SWPPP sign during the propertion on 3/31/20. The State inspection on 8/17/20. E SWPPP sign during the inspection on 8/17/20. E SWPPP sign during the inspection of the	Pending Pending Pending Active Active	nn. The E&A noved during install as No he silt fence no he silt fence no
SF 2 Current Condition:	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection construction allows. E&A in the Highway 30 Intersection construction construction allows. E&A in the Highway 30 Intersection construction constructi	E&A inspector reinstalle WPPP sign prior to the ir Improvements prior to Inspector reinstalled the S Etion Improve West of Gallery East Drive culvert Installed at a later date Industry East West of Farm Field Road culvert Installed at a later date Industry East Installed at a later date Installed at a	ed the SWPPP sign during the appection on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on 8/17/20. ESWPPP sign during the inspection of the ins	Pending Hammitt on 4/1/20 to Active north entrances of	No he silt fence no Yes the
SF 2 Current Condition: SF 3	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection construction allows. E&A in the Highway 30 Intersection construction co	E&A inspector reinstalle WPPP sign prior to the ir Improvements prior to Inspector reinstalled the Section Improve West of Gallery East Drive culvert Installed at a later date Industry East West of Farm Field Road culvert Installed at a later date Ins	ed the SWPPP sign during the propertion on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on 8/17/20. ESWPPP sign during the inspection of inspec	Pending Hammitt on 4/1/20 t Active north entrances of the inspection on 8/4/20.	No he silt fence no Yes the
SF 2 Current Condition: SF 3	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection construction allows. E&A in the Highway 30 Intersection construction co	E&A inspector reinstalle WPPP sign prior to the ir Improvements prior to Inspector reinstalled the Section Improve West of Gallery East Drive culvert Installed at a later date Industry East West of Farm Field Road culvert Installed at a later date Ins	the SWPPP sign during the propertion on 3/31/20. The State inspection on 8/17/20. ESWPPP sign during the inspection on 8/17/20. ESWPPP sign during the inspection of the inspe	Pending Hammitt on 4/1/20 t Active north entrances of the inspection on 8/4/20.	No he silt fence no Yes the
SF 2 Current Condition: SF 3	inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection construction allows. E&A in the Highway 30 Intersection construction co	E&A inspector reinstalle WPPP sign prior to the ir Improvements prior to Inspector reinstalled the Section Improve West of Gallery East Drive culvert Installed at a later date Industry East West of Farm Field Road culvert Installed at a later date Ins	the SWPPP sign during the propertion on 3/31/20. The State inspection on 8/17/20. EswPPP sign during the inspection on 8/17/20. EswPPP sign during the inspection of the inspe	Pending Hammitt on 4/1/20 t Active north entrances of the inspection on 8/4/20.	No he silt fence no Yes the