E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept.	manager			igineering Answ	
Inspector: Joe Manning	E&A - P2018.109.002				Stage
		Gallery 23 East			
Project Name:	CS		(Mass Grading)		3
For Week Ending:					
Project Location:	10/8/2022 County Road U and Lincoln Highway- Fremont, NE (Dodge County)				68025
i roject zecation.	Journy Road S	ana Emooni ingini	ray Tromont, N2 (Boago	oounty)	55525
	Gallery 23 East				
Grading:	96% 97%				
Sanitary Sewer: Storm Sewer:	95%				
Paving:	99%				
Seeding:	1%				
Utilities:	99%				
Overall Development:	45%				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time	
	0.00				Week '
Sunday:	0.00"				-
Monday Tuesday	0.00" 0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.73"				
Conde	0.00				Week 2
Sunday: Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.04"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				Week 3
Sunday:	0.00"				week
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday Saturday	0.00"				
Saturday	0.00				Week 4
Sunday:	0.00"				WCCK -
Monday	0.00"				
Tuesday	0.00"				
Wednesday Thursday	0.00"	10/5/2022	Sunny 74/51	12:30 PM	-
Friday	0.00"				-
Saturday	0.00"				
					Week 5
Sunday:	N/A				
Monday	N/A				
Tuesday Wednesday	N/A N/A				
Thursday	N/A N/A				
Friday	N/A				
Saturday	N/A				
Complaints:					
Construction Sequencing:					
) of the site have had a temporary or perma	anent cessation of gradi	ng, earthwork, or ground distur	bance in the last 14 days	?
. ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				,	

Grading has begun on Gallery 23 East project in Phases I. II. and III (8/2017), Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No - See Findings BMP Section (CW on Lots 1-10, Block 1, Replat 2 and Block 7 Lot 6)

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

No - See BMPs Section.

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments

Comments:

The site was active during the last inspection for home construction.

Lift Station, Sanitary Force Main, and the Intersection Improvements projects are closed.

Water Improvements project is closed.

Highway 30 intersection improvements project is closed.

As of 11/12/2020, E&A was not hired by White Lotus Group to inspect Lot 2 Replat 1.

Due to overall site stabilization and the number of currently active lots, Gallery 23 East will be inspected on a monthly basis as of 12/08/21. E&A inspector will monitor site activity and increase inspection frequency as necessary.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) See BMP section for required maintenance.
- 2.) An above-ground concrete washout pit was installed in the southern portion of the development prior to the inspection on 9/6/22 by an unknown builder. The washout pit should be dug down and any concrete waste should be removed. E&A inspector will send this maintenance to all builders. Not done as of the last inspection.
- 3.) Waste storage containers should be emptied when the full line is reached and any litter should be picked up. All developers were informed to complete

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
•		allery 23 Eas	•		•
CE 1	Construction Entrance			Removed	
Current Condition:		,	construction entrance in prep		prior to
	inspection on 9/9/19.				, ,
CE 3	Construction Entrance	County Road 25/Highway 30		Removed	
CE 2 Current Condition:			I entrance during inspection of		ration for paving
Current Condition.	itemoved - i russ was re	moving the construction e	entrance during inspection of	11 0/10/19 III prepe	nation for paving.
		NE Corner - Hwy 30 &	ı		
CE 3	Construction Entrance			Removed	
Current Condition:			ed as a part of the Highway		
	to the inspection on 8/05	/20. E&A inspector will mo	onitor and recommend reins	tallation at a later	date if necessary
				T	1
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No
Current Condition:		tion will be installed at a la			
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protect	tion will be installed at a la	ater date.		•
		Northeast corner of			
CW	Concrete Washout	site		Removed	
Current Condition:			ed prior to inspection on 10	/21/19. No paving	is underway at
	this time. E&A will monitor	or the need for reinstallation	on.		
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No
Current Condition:		ecks will be installed whe			
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No
Current Condition:		necks will be installed whe			•
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No
Current Condition:			the southeast side of the si)18.
DD #1	Diversion Ditch	NW Corner of Lake		Removed	
Current Condition:	Removed - The diversion	n ditch was removed durin	ng regrading/paving in the ar	ea prior to inspec	tion on 12/30/19.
DD #2	Diversion Ditch	W side of Lake		Removed	
Current Condition:	Removed - Thompson C	onstruction removed the o	diversion ditch prior to inspe-	ction on 9/19/18.	
DD #3	Diversion Ditch	SW corner of lake		Removed	
Current Condition:			diversion ditch prior to inspe-		•
DD #4	Diversion Ditch	S Side of lake		Removed	
Current Condition:			diversion ditch prior to inspe-		_
DD #5	Diversion Ditch	E side of lake		Removed	
Current Condition:			diversion ditch prior to inspe-		_
DD #6	Diversion Ditch	NE corner of lake		Removed	
Current Condition:	Removed - The diversion	n ditch was removed durin	ng regrading/paving in the ar	ea prior to inspec	tion on 12/30/19.
DD #7	Diversion Ditch	N side of lake		Removed	
Current Condition:			ng regrading/paving in the ar		tion on 12/30/19.
Carroll Condition	The second of the second of		.g g		
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No
		ol matting and seeding will	0,00,00		1

		Around Lake (Outlot		1	1	
EB #3	Erosion Blanket	B)	8/30/2018	Pending	No	
Current Condition:	Pending - Erosion control m	/				
	<u> </u>	Area Inlet in SE	J. J. J.			
IP 1	Inlet Protection	portion of the site		Removed		
Current Condition:	Removed - The area east o	f the area inlet naturally	stabilized prior to the 8/05	/20 inspection. Inle	Protection no	
	longer needed at this time.	T 14/0 1 1 1 1	T	1	1	
ID 0	Overhalista and satisface	W Curb inlet on		D		
IP 2 Current Condition:	Curb Inlet protection Removed - The Home Com	Christine Dr	rior to the inequation on 6/1	Removed	n io no longor	
Current Condition:	required.	ipany souded lots 1-6 p	nor to the inspection on 6/1	0/20. Inlet protection	in is no longer	
	required.	E Curb inlet on	1	ı	1	
IP 3	Curb Inlet protection	Christine Dr		Removed		
Current Condition:	Removed - The Home Com		rior to the inspection on 6/1		n is no longer	
ourrent condition.	required.	ipariy soddod iolo i o p	nor to the inspection on or i	0/20. Iffict protection	in is no longer	
		Block 2, Replat 2				
		(Northeast corner of				
Block 1 Replat 2, Lots 1-10	Individual Lots	` site)		Removed		
Current Condition:	Removed - The Home Com	pany sodded the lots p	rior to the inspection on 7/1	1/22.		
Block 3 Replat 2, Lots 1-7	Individual Lots	Block 3	10/5/2022	Active	No	
Current Condition:	Active - Hubbell Homes be	egan construction on	the lots prior to the inspec	ction on 10/05/22.	Due to the	
	grade of the lots, no BMP	s will be recommende	d at this time.			
Block 3 Replat 2, Lots 9-12	Individual Lots	Block 3		Removed		
Current Condition:	Removed - Hubbell Homes	sodded the lots prior to	the inspection on 7/11/22.		•	
Block 3 Replat 2, Lots 13-16	Individual Lots	Block 3		Removed	1	
Current Condition:	Removed - Hubbell Homes		the inspection on 7/11/22	Removed		
Block 4 Replat 2, Lots 8-12	Individual Lots	Block 4		Domoved		
Current Condition:	Removed - Hubbell Home		romoved portable toilete	Removed	tion on	
Current Condition.	10/05/22.	s souded the lots and	removed portable tollets	prior to the inspec	LIOH OH	
Disab 4 Damini O Late 5 7		Disab 4	4.0/5/0000	A = 1"	N.	
Block 4 Replat 2, Lots 5-7	Individual Lots	Block 4	10/5/2022	Active	No	
Current Condition:	Active - Hubbell Homes be grade of the lots, no BMP			ction on 10/05/22.	Due to the	
Block 4 Replat 2, Lots 13-16	Individual Lots	Block 4	10/5/2022	Active	No	
Current Condition:			the lots prior to the inspec	ction on 10/05/22.	Due to the	
	grade of the lots, no BMP					
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5	10/5/2022	Active	No	
Current Condition:	Active - Hubbell Homes be			ction on 10/05/22.	Due to the	
	grade of the lots, no BMP		d at this time.			
Block 6, Lot 9	Individual Lots	Block 6		Removed		
Current Condition:	Removed - Hubbell Homes		•			
Block 6, Lot 23	Individual Lots	Block 6	1/3/2022	Active	Yes	
Current Condition:	Active - Hubbell Homes be					
	the concrete waste from the					
	prior to the inspection on 10/05/22. No evidence of vehicular access was observed on the lot during the					
	inspection on 10/05/22. Due to the front of the lot being flat, straw wattles will no longer be recommended					
	as of 10/05/22. The street was cleaned prior to the inspection on 10/05/22.					
	Waste storage should be emptied.					
	waste storage should be emplied.					
	Hubbell Homes was informed to complete by 6/27/22. Not done as of last inspection. Hubbell Homes was					
	reminded on 7/11/22 8/8/23		22. Not done as or last map	ection. Hubbell Ho	nes was	
Block 6, Lot 24	Individual Lots	Block 6		Removed		
Current Condition:			prior to the inspection on 1/0			
Block 6, Lot 25	Individual Lots	Block 6		Removed		
Current Condition:	Removed - Rick Walkup C		<u>'</u>	า 6/20/22.		
Block 6, Lot 26	Individual Lots	Block 6	1/3/2022	Active	No	
Current Condition:	Active - Hubbell Homes be					
	the street in front of the lot prior to the inspection on 7/11/22. Hubbell Homes emptied the waste storage and					
	removed litter from the lot p					
	the lot during the inspecti		the front of the lot being	flat, straw wattles	will no longer	
Disability 1 of 0	be recommended as of 10			D	1	
Block 7, Lot 6	Individual Lots	Block 7	ot and ramayed the resident	Removed	nonoctica aa	
Current Condition:	Removed - Rick Walkup Co	onstruction sodded the I	or and removed the portabl	e tollet prior to the	rispection on	
Block 2 Replat 3, Lot 16	9/27/21.	Block 2, Lot 16	5/22/2022	Activo	Voc	
BIOCK 2 REDIST 3 LOT 16	Individual Lots	DIUCK Z, LOT TO	5/23/2022	Active	Yes	

Current Condition:	Active - An unknown builder began construction on the lot prior to the inspection on 5/23/22. Due to the grade of the lot and the surrounding vegetation, no BMPs will be recommended at this time. E&A inspector will monitor. The street should be cleaned on the southeast corner of the lot. E&A inspector will inform when the builder is identified.					
Block 3 Replat 3, Lot 10	Individual Lots	Block 3, Lot 10	5/23/2022	Active	Yes	
Current Condition:			the lot prior to the inspection			
	the lot and the surrounding vegetation, no BMPs will be recommended at this time. E&A inspector will monitor.					
	-					
	The street should be cleaned on the southeast corner of the lot.					
	E&A inspector will inform	when the builder is identif	fied.			
Block 12 Replat 3, Lot 4	Individual Lots	Block 12 Replat 3, Lot 4	8/8/2022	Active	No	
Current Condition:	Good Condition - D R Horton began construction on the lot prior to the inspection on 8/8/22. DR Horton installed straw wattles on the lot prior to the inspection on 8/8/22. Damage was observed to the straw wattles during the inspection on 8/8/22; since the lot is relatively flat, E&A inspector will monitor and recommend maintenance as necessary.					
Block 13 Replat 3, Lot 1	Individual Lots	Block 13 Replat 3, Lot	8/8/2022	Activo	No	
Current Condition:	Good Condition - D.R.Hr	orton began construction (on the lot prior to the inspec	Active	No Horton installed	
Garrent Gondition.			8/22. Damage was observe			
	inspection on 8/8/22; since	e the lot is relatively flat, E	E&A inspector will monitor a	and recommend ma	aintenance as	
	,		ring the inspection on 9/6/2			
		the street, and repaired	the straw wattles around	d the lot prior to th	e inspection on	
Block 13 Replat 3, Lot 2	10/05/22.	Block 13 Replat 3, Lot		I		
Block 15 Replat 5, Lot 2	Individual Lots	2	8/8/2022	Active	No	
Current Condition:	Good Condition - D R Ho		on the lot prior to the inspec		Horton installed	
	straw wattles on the lot prior to the inspection on 8/8/22. Damage was observed to the straw wattles during the					
	inspection on 8/8/22; since the lot is relatively flat, E&A inspector will monitor and recommend maintenance as					
	necessary. Minor concrete waste was observed during the inspection on 9/6/22. DR Horton removed the concrete waste, cleaned the street, and repaired the straw wattles around the lot prior to the inspection on					
	10/05/22.	the street, and repaired	the straw watties around	a the lot prior to tr	e inspection on	
Block 13 Replat 3, Lot 3	Individual Lots	Block 13 Replat 3, Lot				
		3	8/8/2022	Active	No	
Current Condition:	Good Condition - D R Horton began construction on the lot prior to the inspection on 8/8/22. DR Horton installed					
	straw wattles on the lot prior to the inspection on 8/8/22. Damage was observed to the straw wattles during the inspection on 8/8/22; since the lot is relatively flat, E&A inspector will monitor and recommend maintenance as					
	necessary. Minor concrete waste was observed during the inspection on 9/6/22. DR Horton removed the					
	concrete waste, cleaned the street, and repaired the straw wattles around the lot prior to the inspection or					
	10/05/22.					
STR						
	Street cleaning	Off-Site	In Place	Active	No	
Current Condition:	Good Condition - The stre	ets near CE 2 were clean	In Place at time of inspection on 7/			
Current Condition:	Good Condition - The stre time of the inspection on 1	ets near CE 2 were clean 10/05/20.	at time of inspection on 7/	8/19. The streets w	ere clean at the	
Current Condition: SWPPP Sign	Good Condition - The stre time of the inspection on 1 Signs	ets near CE 2 were clean 10/05/20. 2 Entrances	n at time of inspection on 7/	8/19. The streets w	ere clean at the	
Current Condition:	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspecto	ets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP	n at time of inspection on 7/ 10/9/2018 signs during inspection on	8/19. The streets w Active 10/9/18. Other SW	No /PPP sign will be	
Current Condition: SWPPP Sign	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspector installed at the County Rd	tets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP U Blvd entrance at a late	n at time of inspection on 7/	8/19. The streets w Active 10/9/18. Other SW reinstalled the SWI	No /PPP sign will be	
Current Condition: SWPPP Sign	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspector installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S	tets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP U Blvd entrance at a late e E&A inspector reinstalle SWPPP sign prior to the in	10/9/2018 I signs during inspection on 7/ r date. The E&A inspector at the SWPPP sign during inspection on 3/31/20. The S	8/19. The streets w Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspects SWPPP sign was re	No //PPP sign will be PPP sign during ion. The E&A emoved during	
Current Condition: SWPPP Sign	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspector installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection	tets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP U Blvd entrance at a late to E&A inspector reinstalle twPPP sign prior to the intent Improvements prior to	10/9/2018 I signs during inspection on ar date. The E&A inspector date SWPPP sign during inspection on 3/31/20. The Sthe inspection on 8/17/20.	Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was reE&A inspector will i	No //PPP sign will be PPP sign during ion. The E&A emoved during reinstall as	
Current Condition: SWPPP Sign	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspector installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection	tets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP U Blvd entrance at a late to E&A inspector reinstalle twPPP sign prior to the intent Improvements prior to	10/9/2018 I signs during inspection on 7/ r date. The E&A inspector at the SWPPP sign during inspection on 3/31/20. The S	Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was reE&A inspector will i	No //PPP sign will be PPP sign during ion. The E&A emoved during reinstall as	
Current Condition: SWPPP Sign	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspector installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersection	tets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP U Blvd entrance at a late to E&A inspector reinstalle twPPP sign prior to the intent Improvements prior to	10/9/2018 I signs during inspection on ar date. The E&A inspector date SWPPP sign during inspection on 3/31/20. The Sthe inspection on 8/17/20.	Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was reE&A inspector will i	No //PPP sign will be PPP sign during ion. The E&A emoved during reinstall as	
Current Condition: SWPPP Sign	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspecto installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectio construction allows. E&A	rets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP U Blvd entrance at a late e E&A inspector reinstalle SWPPP sign prior to the irron Improvements prior to inspector reinstalled the Sweet aw, that this document ar	10/9/2018 2 signs during inspection on 7/ 2 signs during inspection on a date. The E&A inspector and the SWPPP sign during inspection on 3/31/20. The Sthe inspection on 8/17/20. SWPPP sign during the inspection of all attachments were presented at the support of the support o	Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was re E&A inspector will rection on 8/31/20.	No /PPP sign will be PPP sign during ion. The E&A emoved during einstall as	
Current Condition: SWPPP Sign Current Condition:	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspecto installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectio construction allows. E&A i	rets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP Used to the Use of the U	10/9/2018 2 signs during inspection on 7/ 2 signs during inspection on the date. The E&A inspector and the SWPPP sign during inspection on 3/31/20. The State inspection on 8/17/20. SWPPP sign during the inspection of the inspection of the inspection of all attachments were present assure that qualified personal and all attachments were present assure that qualified personal and signs and signs are the signs and signs are the signs a	Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was re E&A inspector will rection on 8/31/20. Pared under my direction pared under my direction pared under my direction on pared under my direction on pared under my direction pared under my direction on	No //PPP sign will be PPP sign during ion. The E&A emoved during reinstall as ection or hered and	
Current Condition: SWPPP Sign Current Condition:	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspecto installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectio construction allows. E&A i	rets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP Used Used Used Used Used Used Used Used	10/9/2018 2 signs during inspection on 7/ 2 signs during inspection on a date. The E&A inspector and the SWPPP sign during inspection on 3/31/20. The Sthe inspection on 8/17/20. SWPPP sign during the inspection on a dall attachments were presented assure that qualified perinquiry of the person or per	Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was re E&A inspector will rection on 8/31/20. Pared under my direction pared under my direction properly gat sons who manage	No //PPP sign will be PPP sign during ion. The E&A emoved during reinstall as ection or hered and the system or	
Current Condition: SWPPP Sign Current Condition:	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspecto installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectio construction allows. E&A i	rets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP Used Used E&A inspector reinstalled WPPP sign prior to the iron Improvements prior to inspector reinstalled the Sweet E&A inspector rei	10/9/2018 2 signs during inspection on 7/ 2 signs during inspection on a date. The E&A inspector and the SWPPP sign during inspection on 3/31/20. The State inspection on 8/17/20. SWPPP sign during the inspection on a dall attachments were presented assure that qualified persinquiry of the person or persinformation, the information	Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was re E&A inspector will rection on 8/31/20. Active 10/9/18. Other SW reinstalled the SWI inspector will rection on 8/31/20. Appared under my direction on the sonnel properly gat sons who manage on submitted is, to till	No //PPP sign will be PPP sign during ion. The E&A emoved during einstall as ection or hered and the system or ne best of my	
Current Condition: SWPPP Sign Current Condition:	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspecto installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectic construction allows. E&A i	rets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP Used Used Used Used Used Used Used Used	10/9/2018 2 signs during inspection on 7/ 2 signs during inspection on a date. The E&A inspector and the SWPPP sign during inspection on 3/31/20. The Sthe inspection on 8/17/20. SWPPP sign during the inspection on a dall attachments were presented assure that qualified perinquiry of the person or per	Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was reE&A inspector will rection on 8/31/20. Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was reE&A inspector will rection on 8/31/20. Appared under my direction on the sonnel properly gat sons who manage in submitted is, to the significant penaltie	No //PPP sign will be PPP sign during ion. The E&A emoved during einstall as ection or hered and the system or ne best of my	
Current Condition: SWPPP Sign Current Condition:	Good Condition - The stre time of the inspection on 1 Signs Good Condition - Inspecto installed at the County Rd inspection on 9/19/19. The inspector reinstalled the S the Highway 30 Intersectic construction allows. E&A i	rets near CE 2 were clean 10/05/20. 2 Entrances or installed 1 of 2 SWPPP Used Used Used Used Used Used Used Used	10/9/2018 2 signs during inspection on 7/ 2 signs during inspection on a date. The E&A inspector and the SWPPP sign during inspection on 3/31/20. The Sthe inspection on 8/17/20. SWPPP sign during the inspection on a dall attachments were present assure that qualified person or per a information, the information. I am aware that there are not imprisonment for knowin	Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was reE&A inspector will rection on 8/31/20. Active 10/9/18. Other SW reinstalled the SWI the 2/24/20 inspect SWPPP sign was reE&A inspector will rection on 8/31/20. Appared under my direction on the sonnel properly gat sons who manage in submitted is, to the significant penaltie	No //PPP sign will be PPP sign during ion. The E&A emoved during einstall as ection or hered and the system or ne best of my	