E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Josh Ellington			Stage		
Project Name:	Gallery 23 East CSW-201702253 (Mass Grading)				
•			2024		
Project Location:	County Road	68025			
	Gallery 23 East				
Grading:	98%				
Sanitary Sewer:	99%				
Storm Sewer:	99%				
Paving:	99%				
Seeding:	35%				
Utilities:	99%				
Overall Development:	60%				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time	
					Wee
Sunday:	0.00"				
Monday:	0.00"	7/29/2024	Sunny 95/71	11:50 AM	
Tuesday:	0.01"				
Wednesday:	0.02"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
		<u> </u>			
Complaints:	None				
Construction Sequencing:	L				
	of the site have had a temporary or perm				

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Vac

Create Corrective Action?

N/A

4.) Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMPs section

5.) Is dust associated with the construction activity adequately controlled on the site?

 $|_{\nabla_{\alpha\alpha}}$

Create Corrective Action?

N/A

Comments:

Comments:

The site was active during the last inspection for home construction.

Based on the amount of lot construction active in the development as of the 4/26/23 inspection, Gallery 23 East will be inspected at the Stage 1 frequency. E&A inspector will monitor and adjust inspection frequency as necessary.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) See BMP section for required maintenance.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
		Sallery 23 Eas	st			
CE 1	Construction Entrance	County Road Blvd U		Removed		
Current Condition:	Removed - Thompson Construction removed the construction entrance in preparation for paving prior to inspection of 9/9/19.					
CE 2	Construction Entrance	County Road 25/Highway 30		Removed		
Current Condition:	Removed - Pruss was remo	oving the construction en	trance during inspection on	6/18/19 in prepara	tion for paving.	
CE 3	Construction Entrance	NE Corner - Hwy 30 & Christine Drive		Removed		
Current Condition:	Removed - The constructio inspection on 8/05/20.	n entrance was removed	l as a part of the Highway 30) intersection impro	vements prior to t	
CIP 1	Curb Inlet protection	Sammy Road		Removed		
Current Condition:	Removed - DR Horton rem	oved the inlet protection	prior to the inspection on 1/	17/23.		
CIP 2	Curb Inlet protection	Sammy Road		Removed		
Current Condition:	Removed - DR Horton rem	oved the inlet protection	prior to the 11/6/23 inspection	on.		
CIP 3	Curb Inlet protection	East 18th Avenue		Removed		
Current Condition:	Removed - DR Horton rem	oved the curb inlet filter p	orior to the 7/15/24 inspection	n.		
CIP 4	Curb Inlet protection	Kara Way		Removed		
Current Condition:	Removed - DR Horton rem	oved the inlet protection	prior to the 10/16/23 inspec	tion.		
CIP 5	Curb Inlet protection	East 18th Avenue		Removed		
Current Condition:	Removed - DR Horton rem	oved the curb inlet filter	orior to the 7/15/24 inspection	n.		
CIP 6	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No	
Current Condition:	Good Condition - DR Horto 6/19/23. DR Horton reposit		n northeast of the concrete to the 6/10/24 inspection.	washout pit prior to	the inspection on	
CIP 7	Curb Inlet protection	Taylor Lane	6/19/2023	Active	No	
Current Condition:	Good Condition - DR Horton removed the inlet protection prior to the 10/16/23 inspection. DR Horton reinstalled the protection prior to the 10/30/23 inspection.					
CIP 8	Curb Inlet protection	Aaron Way	3/25/2024	Active	No	
Current Condition:		24 inspection. DR Hortor	or to the 3/25/24 inspection. In removed the inlet protection 5/24 inspection.			
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No	
Current Condition:	Pending - Culvert protection	n will be installed at a lat				
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No	

Current Condition:	Pending - Culvert protection	will be installed at a lat	er date				
CW	Concrete Washout	Block 9, Lot 1	9/6/2022	Active	No		
Current Condition:	Good Condition - DR Horton	·		n on 9/06/22. DR H	orton removed the		
	concrete washout and installed a new washout with a berm and plastic liner prior to the inspection on 3/13/23. DR						
	Horton cleaned out the concrete washout prior to the inspection on 4/10/23. DR Horton cleaned out the						
	washout and the surrounding area prior to the 6/19/23 inspection. DR Horton removed the concrete w						
			6/23 inspection. DR Horton relocated the concrete washout to				
	Block 7 Lot 1 prior to the 11	·			· ·		
	prior to the 11/27/23 inspec	tion. DR Horton remove	d concrete waste outside of	the pit prior to the 6	6/10/24 inspection.		
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No		
Current Condition:	Pending - Ditch wattle chec			Tending	110		
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No		
Current Condition:	Pending - Ditch wattle chec			l reliaing	INO		
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No		
Current Condition:	Good Condition - Wattles cl						
DD #1	Diversion Ditch	NW Corner of Lake		Removed	•		
Current Condition:	Removed - The diversion di		l regrading/paying in the are		on 12/30/19		
DD #2	Diversion Ditch	W side of Lake		Removed	1011 12/00/10.		
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec				
DD #3	Diversion Ditch	SW corner of lake	T	Removed			
Current Condition:	Removed - Thompson Cons		l version ditch prior to inspec				
DD #4	Diversion Ditch	S Side of lake		Removed			
Current Condition:	Removed - Thompson Cons		l version ditch prior to inspec				
DD #5	Diversion Ditch	E side of lake	TVC131011 GILOTI PHOT LO INSPEC	Removed			
Current Condition:	Removed - Thompson Cons		l version ditch prior to inspec				
DD #6	Diversion Ditch	NE corner of lake	Version diten prior to inspec	Removed			
Current Condition:	Removed - The diversion di		regrading/paying in the are		on 12/30/19		
			Tograding/paving in the are		1011 12/00/10.		
DD #7	Diversion Ditch	N side of lake		Removed			
Current Condition:	Removed - The diversion di	tch was removed during	g regrading/paving in the are	ea prior to inspection	n on 12/30/19.		
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No		
Current Condition:	Pending - Erosion control m	atting and seeding will l	be installed when grading h	as ended.			
		A					
		Around Lake (Outlot					
EB #3	Erosion Blanket	В) `	8/30/2018	Pending	No		
EB #3 Current Condition:	Erosion Blanket Pending - Erosion control m	B) atting and seeding will l			No		
Current Condition:	Pending - Erosion control m	B) atting and seeding will I		as ended.	No		
Current Condition:	Pending - Erosion control m	B) natting and seeding will I Area Inlet in SE portion of the site	be installed when grading h	as ended. Removed			
Current Condition:	Pending - Erosion control m Inlet Protection Removed - The area east o	B) natting and seeding will I Area Inlet in SE portion of the site	be installed when grading h	as ended. Removed			
Current Condition:	Pending - Erosion control m	B) atting and seeding will latting and seeding will late Area Inlet in SE portion of the site f the area inlet naturally	be installed when grading h	as ended. Removed			
Current Condition: IP 1 Current Condition:	Pending - Erosion control m Inlet Protection Removed - The area east o needed at this time.	B) natting and seeding will lead and seeding and seeding will lead	be installed when grading h	Removed 20 inspection. Inlet F			
Current Condition: IP 1 Current Condition: IP 2	Pending - Erosion control m Inlet Protection Removed - The area east o needed at this time. Curb Inlet protection	B) natting and seeding will lead from the site portion of the site f the area inlet naturally W Curb inlet on Christine Dr	be installed when grading has been stabilized prior to the 8/05/2	Removed Removed Removed Removed	Protection no longer		
Current Condition: IP 1 Current Condition:	Pending - Erosion control m Inlet Protection Removed - The area east o needed at this time.	B) natting and seeding will lead from the site portion of the site f the area inlet naturally W Curb inlet on Christine Dr	be installed when grading has been stabilized prior to the 8/05/2	Removed Removed Removed Removed	Protection no longer		
Current Condition: IP 1 Current Condition: IP 2	Pending - Erosion control m Inlet Protection Removed - The area east o needed at this time. Curb Inlet protection	B) natting and seeding will lead to the site portion of the site of the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr	be installed when grading has been stabilized prior to the 8/05/2	Removed Removed Removed Removed	Protection no longer		
Current Condition: IP 1 Current Condition: IP 2 Current Condition:	Pending - Erosion control m Inlet Protection Removed - The area east o needed at this time. Curb Inlet protection Removed - The Home Com	B) natting and seeding will lead of the site portion of the site of the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr	be installed when grading has been stabilized prior to the 8/05/2	Removed 20 inspection. Inlet I Removed Removed 1/20. Inlet protection	Protection no longer		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3	Pending - Erosion control m Inlet Protection Removed - The area east o needed at this time. Curb Inlet protection Removed - The Home Com Curb Inlet protection	B) natting and seeding will lead to seed in the site portion of the site of the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr	stabilized prior to the 8/05/2	Removed Removed Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition:	Pending - Erosion control m Inlet Protection Removed - The area east o needed at this time. Curb Inlet protection Removed - The Home Com	B) natting and seeding will lead to seed in the site portion of the site of the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr	stabilized prior to the 8/05/2	Removed Removed Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition:	Pending - Erosion control manual Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Command Curb Inlet protection Curb Inlet protection Removed - The Home Command Removed - The Home Removed - The Home Command Removed - The Home Removed - The	B) natting and seeding will i Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr	stabilized prior to the 8/05/2	Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16	Pending - Erosion control manual Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Command Curb Inlet protection Curb Inlet protection Removed - The Home Command Individual Lots	B) natting and seeding will lead to seed in the site portion of the site of the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16	stabilized prior to the 8/05/2	Removed Removed Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition:	Pending - Erosion control manual Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added in	B) natting and seeding will lead to the area inlet in SE portion of the site of the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23.	stabilized prior to the 8/05/2	Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection Removed //20. Inlet protection	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10	Pending - Erosion control m Inlet Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Comm Curb Inlet protection Removed - The Home Comm Individual Lots Removed - Lot was added if Individual Lots	B) latting and seeding will latting and seeding latting l	stabilized prior to the 8/05/2	Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition:	Pending - Erosion control manual Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Commandal Protection Curb Inlet protection Removed - The Home Commandal Protection Removed - The Home Commandal Protection Individual Lots Removed - Lot was added if Individual Lots Removed - Lot was added if Re	B) natting and seeding will lead to the area inlet in SE portion of the site of the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 on error as of 5/10/23. Block 3, Lot 10 on error as of 5/10/23.	stabilized prior to the 8/05/2	Removed Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7	Pending - Erosion control m Inlet Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Comm Curb Inlet protection Removed - The Home Comm Individual Lots Removed - Lot was added if Individual Lots Removed - Lot was added if Individual Lots	B) latting and seeding will I Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23. Block 3, Lot 10 n error as of 5/10/23. Block 3	stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10	Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition:	Pending - Erosion control m Inlet Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Comm Curb Inlet protection Removed - The Home Comm Individual Lots Removed - Lot was added if Individual Lots Removed - Lot was added if Individual Lots Removed - Lot was added if Individual Lots Removed - Hubbell Homes	B) latting and seeding will I Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23. Block 3, Lot 10 n error as of 5/10/23. Block 3 sodded the lots prior to	stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10	Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7	Pending - Erosion control m Inlet Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Comm Curb Inlet protection Removed - The Home Comm Individual Lots Removed - Lot was added if Individual Lots Removed - Lot was added if Individual Lots	B) latting and seeding will I Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23. Block 3, Lot 10 n error as of 5/10/23. Block 3 sodded the lots prior to	stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10	Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7	Pending - Erosion control m Inlet Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Comm Curb Inlet protection Removed - The Home Comm Individual Lots Removed - Lot was added if Individual Lots Removed - Lot was added if Individual Lots Removed - Lot was added if Individual Lots Removed - Hubbell Homes	B) latting and seeding will I Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23. Block 3, Lot 10 n error as of 5/10/23. Block 3 sodded the lots prior to	stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10	Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition:	Pending - Erosion control manual linet Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Commandal linet Protection Removed - The Home Commandal linet Protection Removed - The Home Commandal linet Protection Removed - Lot was added in Individual Lots Removed - Lot was added in Individual Lots Removed - Lot was added in Individual Lots Removed - Hubbell Homes toilet prior to the 8/21/23 institutions	B) natting and seeding will I Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23. Block 3, Lot 10 n error as of 5/10/23. Block 3 sodded the lots prior to spection. Block 4	stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10 the 8/14/23 inspection, clear	Removed 20 inspection. Inlet I Removed 20. Inlet protection Removed 20. Inlet protection Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4 Current Condition:	Pending - Erosion control manual Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Command Protection Individual Lots Removed - Lot was added in Individual Lots Removed - Lot was added in Individual Lots Removed - Hubbell Homes toilet prior to the 8/21/23 insumption of the Individual Lots Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes	B) latting and seeding will latting and seeding a	stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10 the 8/14/23 inspection, clear	Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection Removed Removed Removed Removed Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4 Current Condition: Block 4 Replat 2, Lots 5-7	Pending - Erosion control manual Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Command Protection Individual Lots Removed - Lot was added in Individual Lots Removed - Lot was added in Individual Lots Removed - Hubbell Homes toilet prior to the 8/21/23 instituted in Individual Lots Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes Individual Lots	B) latting and seeding will latting and seeding a	stabilized prior to the 8/05/2 stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10 the 8/14/23 inspection, clear the 8/14/23 inspection.	Removed 20 inspection. Inlet I Removed 20. Inlet protection Removed 20. Inlet protection Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4 Current Condition: Block 4 Replat 2, Lots 5-7 Current Condition:	Pending - Erosion control manual language of the protection of the	B) latting and seeding will latting and seeding a	stabilized prior to the 8/05/2 stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10 the 8/14/23 inspection, clear the 8/14/23 inspection.	Removed Removed Removed //20. Inlet protection Removed //20. Inlet protection Removed Removed Removed Removed Removed Removed Removed Removed Removed	Protection no longer is no longer required.		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4 Current Condition: Block 4 Replat 2, Lots 5-7 Current Condition: Block 4 Replat 3, Lots 5-7 Current Condition: Block 4 Replat 3, Lots 15 & 16	Pending - Erosion control manual language of the protection of the	B) latting and seeding will latting and seeding a	stabilized prior to the 8/05/2 stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10 the 8/14/23 inspection, clear the 8/14/23 inspection.	Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed	Protection no longer is no longer required. is no longer required. removed the portable		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4 Current Condition: Block 4 Replat 2, Lots 5-7 Current Condition:	Pending - Erosion control manual language of the protection of the	B) latting and seeding will I Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23. Block 3, Lot 10 n error as of 5/10/23. Block 3 sodded the lots prior to spection. Block 4 sodded the lots prior to Block 4 were sodded prior to the	stabilized prior to the 8/05/2 stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10 the 8/14/23 inspection, clear the 8/14/23 inspection. the 8/14/23 inspection.	Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed	Protection no longer is no longer required. is no longer required. removed the portable		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4 Current Condition: Block 4 Replat 2, Lots 5-7 Current Condition: Block 4 Replat 3, Lots 5-7 Current Condition: Block 4 Replat 3, Lots 15 & 16	Pending - Erosion control manual Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Command Protection Individual Lots Removed - Lot was added in Individual Lots Removed - Hubbell Homes to to the 8/21/23 instantial Individual Lots Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes Individual Lots Removed - Lots 13 and 14 Maye been updated to Block	B) latting and seeding will I Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23. Block 3, Lot 10 n error as of 5/10/23. Block 3 sodded the lots prior to spection. Block 4 sodded the lots prior to Block 4 were sodded prior to the	stabilized prior to the 8/05/2 stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10 the 8/14/23 inspection, clear the 8/14/23 inspection. the 8/14/23 inspection.	Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed	Protection no longer is no longer required. is no longer required. removed the portable		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4 Current Condition: Block 4 Replat 2, Lots 5-7 Current Condition: Block 4 Replat 3, Lots 5-7 Current Condition: Block 2 Replat 3, Lots 15 & 16 Current Condition:	Pending - Erosion control manual Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Command Protection Removed - Lot was added in Individual Lots Removed - Lot was added in Individual Lots Removed - Hubbell Homes toilet prior to the 8/21/23 instantial Individual Lots Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes Individual Lots Removed - Lots 13 and 14 maye been updated to Block Replat 3, Lots 15 & 16.	B) latting and seeding will I Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23. Block 3, Lot 10 n error as of 5/10/23. Block 3 sodded the lots prior to spection. Block 4 sodded the lots prior to Block 4 were sodded prior to the call the sodded the lots prior to t	stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10 the 8/14/23 inspection, clear the 8/14/23 inspection. the 8/14/23 inspection. 2 5/24/23 inspection. As of 4 and Block 4 Replat 2, Lots	Removed Removed Removed /20. Inlet protection Removed /20. Inlet protection Removed Removed	Protection no longer is no longer required. is no longer required. removed the portable plat 2, Lots 15 & 16 updated to Block 2		
Current Condition: IP 1 Current Condition: IP 2 Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4 Current Condition: Block 4 Replat 2, Lots 5-7 Current Condition: Block 4 Replat 3, Lots 15 8 16	Pending - Erosion control manual Protection Removed - The area east of needed at this time. Curb Inlet protection Removed - The Home Command Protection Individual Lots Removed - Lot was added in Individual Lots Removed - Hubbell Homes to to the 8/21/23 instantial Individual Lots Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes Individual Lots Removed - Lots 13 and 14 Maye been updated to Block	B) latting and seeding will I Area Inlet in SE portion of the site f the area inlet naturally W Curb inlet on Christine Dr pany sodded lots 1-8 pr E Curb inlet on Christine Dr pany sodded lots 1-8 pr Block 2, Lot 16 n error as of 5/10/23. Block 3, Lot 10 n error as of 5/10/23. Block 3 sodded the lots prior to spection. Block 4 sodded the lots prior to Block 4 were sodded prior to the	stabilized prior to the 8/05/2 stabilized prior to the 8/05/2 ior to the inspection on 6/10 ior to the inspection on 6/10 the 8/14/23 inspection, clear the 8/14/23 inspection. the 8/14/23 inspection.	Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed	Protection no longer is no longer required. is no longer required. removed the portable		

Current Condition:	Pending - Hubbell Homes graded the lots prior to the 11/6/23. Due to the grade of the lots, no BMPs will be recommended at this time. Streets were scraped prior to the 1/11/24 inspection. Hubbell Homes removed the concrete waste from the lot prior to the 3/25/24 inspection. As of 4/10/24, Block 4 Replat 2, Lots 23-25 have been updated to Block 2 Replat 3, Lots 7-9.					
	Straw wattles should be insta	alled along the perimete	er of the lots.			
	Hubbell Homes was informed to complete by 5/13/24. Not done as of last inspection. Hubbell Homes was reminded on 5/29/24, 7/23/24					
Block 2 Replat 3, Lots 10 & 11	Individual Lots	Block 2	7/31/2023	Pending	Yes	
Current Condition:	no BMPs will be recommend relocated the portable toilets have been updated to Block inspection. Hubbell Homes re	Pending - Hubbell Homes began construction on the lots prior to the inspection on 7/31/23. Due to the grade of the lots, no BMPs will be recommended at this time. Streets were scraped prior to the 1/11/24 inspection. Hubbell Homes relocated the portable toilets to these lots prior to the 2/26/24 inspection. As of 4/10/24, Block 4 Replat 2, Lots 20-22 have been updated to Block 2 Replat 3, Lots 10 & 11. Hubbell Homes secured the portable toilets prior to the 4/15/24 inspection. Hubbell Homes removed the portable toilets prior to the 7/1/24 inspection. Straw wattles should be installed along the perimeter of the lots.				
	5/29/24, 7/23/24	a to complete by or lorg	-4. Not done as of last mape	otion. Habbon Hon	ios was reminaed on	
Block 2 Replat 3, Lots 12-14	Individual Lots	Block 2		Removed		
Current Condition:	Removed - Hubbell Homes s	sodded the lots prior to	the 6/10/24 inspection.	•	•	
Block 3 Replat 3, Lots 1-6	Individual Lots	Block 3		Removed		
Current Condition:	Removed - Hubbell Homes s	sodded the lots prior to	the 6/10/24 inspection.			
Block 5 Replat 2, Lots 7-9	Individual Lots	Block 5		Removed		
Current Condition:	Removed - Hubbell Homes s	sodded the lots prior to	the inspection on 12/11/23.			
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5		Removed		
Current Condition:	Removed - Hubbell Homes s		aned the streets prior to the		23.	
Block 6, Lot 23	Individual Lots	Block 6		Removed		
Current Condition:	Removed - Hubbell Homes s	sodded the lot prior to the	ne 6/5/23 inspection.			
Block 6, Lot 26	Individual Lots	Block 6		Removed		
Current Condition:	Removed - Hubbell Homes s	•	ne 5/24/23 inspection.			
Block 6, Lot 27	Individual Lots	Block 6		Removed		
Current Condition:	Removed - TJL Consulting Ir	-			_	
Block 6, Lot 6	Individual Lots	Block 6	7/8/2024	Active	No	
Current Condition:	Good Condition - DR Horton	<u> </u>	<u> </u>	24 inspection.		
Block 7, Lot 1	Individual Lots	Block 7	7/1/2024	Active	No	
Current Condition:	Good Condition - DR Horton straw wattles along the per				Horton installed	
Block 7, Lot 4	Individual Lots	Block 7	7/1/2024	Active	No	
Current Condition:	Good Condition - DR Horton wattles along the west and so	began foundation work		4 inspection. DR H		
Block 7, Lot 5	Individual Lots	Block 7	7/1/2024	Active	No	
Current Condition:	Good Condition - DR Horton wattles along the south and			4 inspection. DR H	lorton installed straw	
Block 7, Lot 7	Individual Lots	Block 7	6/10/2024	Active	No	
Current Condition:	Good Condition - DR Horton wattles along the north and e			24 inspection. DR	Horton installed straw	
Block 7, Lot 8	Individual Lots	Block 7	6/10/2024	Active	No	
Current Condition:	Active - DR Horton began for	undation work on the lo	t prior to the 6/10/24 inspec	tion.		
Block 7, Lot 9	Individual Lots	Block 7	5/13/2024	Active	No	
Current Condition:	Good Condition - DR Horton wattles along the western side			24 inspection. DR	Horton installed straw	
Block 7, Lot 10	Individual Lots	Block 7	5/13/2024	Active	No	
Current Condition:	Good Condition - DR Horton wattles along the western sig			24 inspection. DR	Horton installed straw	
Block 7, Lot 11	Individual Lots	Block 7	5/13/2024	Active	No	
Current Condition:	Active - DR Horton began for	undation work on the lo	t prior to the 5/13/24 inspec	tion.		

Block 7, Lot 12	Individual Lots	Block 7	4/15/2024	Active	No	
Current Condition:	Good Condition - DR Horton wattles along the eastern significant.			5/24 inspection. DR	Horton installed stra	
Block 7, Lot 13	Individual Lots	Block 7	3/11/2024	Active	No	
Current Condition:	Good Condition - DR Horton foundation work on the lot p wattles along the eastern side Lot 6 prior to the 7/8/24 insp	orior to the 4/15/24 inspendent of the lot prior to the	ection. DR Horton secured	the portable toilet ar	nd installed straw	
Block 7, Lot 14	Individual Lots	Block 7		Removed		
Current Condition:	Removed - DR Horton sod	ded the lot prior to the	e inspection on 7/29/24.			
Block 7, Lot 15	Individual Lots	Block 7		Removed		
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 7/	15/24 inspection.			
Block 7, Lot 16	Individual Lots	Block 7		Removed		
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 5/	13/24 inspection.	-		
Block 7, Lot 17	Individual Lots	Block 7		Removed	1	
Current Condition:	Removed - DR Horton sodd	ded the lot prior to the 5/	/13/24 inspection.		-1	
Block 7, Lot 18	Individual Lots	Block 7	12/18/2023	Active	Yes	
Current Condition:	Fair Condition - DR Horton the back of the lot prior to the 3/25/24 inspection. The lot should be stabilized DR Horton was informed to 7/23/24	ne 12/18/23 inspection.	DR Horton installed straw v	wattles along the fro	nt of the lot prior to	
Block 7, Lot 19	Individual Lots	Block 7	12/18/2023	Active	Yes	
Current Condition:	Fair Condition - DR Horton					
Block 7, Lot 20	DR Horton was informed to 7/23/24 Individual Lots	complete by 6/10/24. N Block 7	lot done as of last inspectio	Active	eminded on 6/25/24	
Current Condition:	Fair Condition - DR Horton the back of the lot prior to the to the east prior to the 3/4/2 The lot should be stabilized DR Horton was informed to 7/23/24	ne 11/13/23 inspection. 44 inspection.	DR Horton fine-graded the	lot and relocated th	e straw wattles fart	
Block 7, Lot 21	Individual Lots	Block 7	11/6/2023	Active	Yes	
Current Condition:	Fair Condition - DR Horton began grading the lot prior to the 11/6/23 inspection. DR Horton partially installed straw wattles at the back of the lot prior to the 11/6/23 inspection. DR Horton began foundation work prior to the 11/13/23 inspection. DR Horton cleaned the street prior to the 12/11/23 inspection. DR Horton fine-graded the lot and relocated the straw wattles farther to the east prior to the 3/4/24 inspection. The lot should be stabilized. DR Horton was informed to complete by 4/1/24. Not done as of last inspection. DR Horton was reminded on 5/1/24, 6/4/24, 6/25/24, 7/23/24					
Block 7, Lot 22	Individual Lots	Block 7	10/23/2023	Active	Yes	
Current Condition:	Fair Condition - DR Horton the back of the lot prior to the 11/27/23 inspection. DR Ho inspection.	began construction on to the 10/30/23 inspection. Forton fine-graded the lot	the lot prior to the 10/23/23 DR Horton reinstalled strav	inspection. DR Hor w wattles at the back	ton installed wattles	
	The lot should be stabilized DR Horton was informed to		t dans as of last inspection	DD Hartan was re	5/4/04	

Block 7, Lot 23	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 5/	13/24 inspection.	-	
Block 7, Lot 24	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 5/	13/24 inspection.		
Block 7, Lot 25	Individual Lots	Block 7		Removed	
Current Condition:	Removed - DR Horton sodd		13/24 inspection.	1100104	
Block 8, Lot 1	Individual Lots	Block 8	<u>'</u>	Removed	
Current Condition:	Removed - DR Horton sodd		13/24 inspection	Removed	
			10/24 inopediion.		I
Block 9, Lot 1	Individual Lots	Block 9	1/4.0/00 in a set in a	Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 12	2/18/23 inspection.		
Block 10, Lot 1	Individual Lots	Block 10, Lot 1		Removed	
Current Condition:	Removed - DR Horton sodd		1/20/23 inspection.		
Block 10, Lot 2	Individual Lots	Block 10, Lot 2	24/22 1 //	Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 5/	24/23 inspection.		
Block 10, Lot 4	Individual Lots	Block 10, Lot 4		Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 5/	13/24 inspection.		
Block 10, Lot 5	Individual Lots	Block 10, Lot 5		Removed	
Current Condition:	Removed - DR Horton sodd		spection on 7/06/23.	Ttomovou	
Block 10, Lot 6	Individual Lots	Block 10, Lot 6		Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the in	spection on 11/6/23.		
Block 10, Lot 7	Individual Lots	Block 10, Lot 7		Removed	
Current Condition:	Removed - DR Horton sodd		2/18/23 inspection.		
Block 10, Lot 8	Individual Lata	Block 10. Lot 8	· 	Removed	
Current Condition:	Individual Lots Removed - DR Horton sodd		13/24 inspection	Removed	
	rtemoved - Dit Horton sodd		15/24 inspection.		
Block 10, Lot 9	Individual Lots	Block 10, Lot 9		Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 11	1/20/23 inspection.		
Block 10, Lot 10	Individual Lots	Block 10, Lot 10		Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 10	0/16/23 inspection.		
Block 10, Lot 11	Individual Lots	Block 10, Lot 11		Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 8/	14/23 inspection.		
Block 10, Lot 12	Individual Lots	Block 10, Lot 12		Removed	
Current Condition:	Removed - DR Horton sodd	led the lot prior to the 12	2/18/23 inspection.		
Block 11, Lot 1	Individual Lots	Block 11, Lot 1		Removed	
Current Condition:	Removed - DR Horton sodd		I I/20/23 inspection.	Ttomovou	
		·	I	D	
Block 11, Lot 2	Individual Lots Removed - DR Horton sodd	Block 11, Lot 2	anastian an 4/10/22	Removed	
Current Condition: Block 12, Lot 1	Individual Lots	Block 12, Lot 1	spection on 4/19/23.	Romovod	
Current Condition:	Removed - DR Horton sodd		enection on 4/19/23	Removed	
Block 12, Lot 2	Individual Lots	Block 12, Lot 2	10/20	Removed	
Current Condition:	Removed - DR Horton sodd		24/23 inspection.	1101110100	
Block 12, Lot 3	Individual Lots	Block 12, Lot 3		Removed	
Current Condition:	Removed - DR Horton sodd	-	24/23 inspection.	Ttomovou	
STR	Street cleaning	Off-Site	In Place	Active	Yes
Current Condition:	Fair Condition - DR Horton				
	prior to the 4/8/24 inspection				
	1.) Streets along all active lo				
	2.) Streets along all active lo	ots should be cleaned.			
	1.) Hubbell Homes were info	ormed to complete by 2	/06/24 Not done as of last in	espection Hubbell I	Homes was reminded
	on 2/13/24, 3/12/24, 4/9/24,			ispection. Hubbell I	Tiomes was reminded
	2.) DR Horton was informed			on. DR Horton was	reminded on 6/4/24,
	6/25/24, 7/2/24, 7/23/24				
CWDDD Cirri	Ciana	Collory Foot Dairy	10/0/2010	Active	No
SWPPP Sign	Signs	Gallery East Drive	10/9/2018	Active	No

Current Condition:	Good Condition - Inspector installed 1 of 2 SWPPP signs during inspection on 10/9/18. Other SWPPP sign will be installed at the County Rd U Blvd entrance at a later date. The E&A inspector reinstalled the SWPPP sign during inspection on 9/19/19. The E&A inspector reinstalled the SWPPP sign during the 2/24/20 inspection. The E&A inspector reinstalled the SWPPP sign prior to the inspection on 3/31/20. The SWPPP sign was removed during the Highway 30 Intersection Improvements prior to the inspection on 8/17/20. E&A inspector reinstalled the SWPPP sign during the inspection on 8/31/20.					
WSX	Waste Storage	On Site	11/6/2023	Active	No	
Current Condition:	Good Condition - Hubbell He Hubbell Homes emptied the waste storage containers pr 1/11/24 inspection. Hubbell emptied the waste storage oprior to the 4/29/24.	waste storage containe ior to the 12/11/23 inspe Homes emptied the was	ers prior to the 11/20/23 inspection. DR Horton installed votes storage containers prior	pection. Hubbell How waste storage conta to the 1/29/24 inspe	mes emptied the hiners prior to the ection. DR Horton	
Certification Statement:	I certify, under penalty of lav accordance with a system d submitted. Based on my inq for gathering the information complete. I am aware that the and imprisonment for knowing	esigned to assure that outry of the person or per n, the information subminere are significant pena	qualified personnel properly rsons who manage the syste tted is, to the best of my kno	gathered and evaluem or those persons owledge and belief,	lated the information s directly responsible true, accurate, and	
Inspector Signature:	Je		Reviewed By:	to Sul		