Inches and the Ballion I have been a	<u> </u>	P2006.056.01	Stage		
Inspector: Mike Jacobson	Iron Horse- Ashland, NE				
Project Name:	ire	68003			
For Week Ending:		12/12/2009	66003		
Grading:	100	%			
Sanitary Sewer:	90'				
Storm Sewer:	90'				
Paving:	90'				
Seeding: Utilities:	100				
Overall Development:	50				
RAIN FALL AMOUNTS	Amount in inches	Date inspected			
			Week 1		
Sunday: Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
Sunday:	0.00"		Week 2		
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"		Week 3		
Sunday:	0.00"		1100110		
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday Friday	0.00"				
Saturday	0.00"	+			
,			Week 4 / 5		
Sunday:	0.19"				
Monday	0.08"	10/00/00			
Tuesday	0.72" 0.02"	12/08/09			
Wednesday Thursday	0.02				
Friday	0.00"				
Saturday	0.00"				
Compleinte	None				
Complaints:					
Construction Sequencing:	I	ı l	I		
	of the site have had a tempo	orary or permanent cessation of grading, earthwe	ork, or ground disturbance		
Entire site; grading completed and	d stabilized prior to Spring	g 2005.			
Which portion(s) (i.e. drainage basins)	of the site do not have grad	ing, earthwork, or ground disturbance scheduled	d in the next 14 days? :		
Entire sites grading completed as	d stabilized prior to Ci-	~ 2005			
Entire site; grading completed an	a stabilized prior to Spring	g 2005.			
What temporary or permanent stabilize			·		
Dense Vegetation, seeding/soddi	ng, matting, Re-seeding	b/2006, paving, and landscaping.			
Comments:					
Comments:					
Site is in overall good condition. H		ve on site.			
Findings / Corrective Actions (Date):				

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

- Silt fence check East of lot 128 is undermined and needs to be backfilled and compacted. Boyer Young was informed to complete by 10/30/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP.
 Maintenance not completed as of last inspection.
- 2) Silt fence checks West of lot 128 are undermined and needs to be backfilled and compacted. Boyer Young was informed to complete by 10/30/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.
- 3) A pile of rock in the street in South view Circle needs to be removed. Boyer Young was informed to complete by 10/30/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. Rock pile was removed from the street prior to inspection on 12/8/09 by Boyer Young.
- 4) Varies empty lots have concrete/debris on them and it needs to be cleaned up. Boyer Young was informed to complete by 3/18/09. Maintenance not completed as of last inspection.
- 5) Silt fence needs to be installed on the back of lot 118. Boyer Young was informed to complete maintenance by 3/18/09. Ma
- 6) It is recommended to Boyer Young that silt fence should be installed on the front of lot 60. Boyer Young was informed to co 7) Lot 123 has active home construction and it needs lot level silt fence installed on the lot. Steve w/ Landmark Homes was in
- 8) Some maintenance is required in the BMP section.

			Projected Install			Description of		
Unique Name	Туре	Location	Date	Status	Maintenance	Maintenance/Activity		
•	Permanent	N00d00m00s				Í		
PDP A	Detention Pond	W00d00m00s	In Place	Active	No	Repairs Needed/Plan		
Current Condition:	Good Condition		_	r	1			
SF 1	Silt Fence	N00d00m00s W00d00m00s	In Place	Active	Yes			
Current Condition:	Fair Condition- Pro	tecting run-on from ad	jacent corn field.					
	Boyer & Young to r	emove silt fence or m	b be repaired or remove aintenance by 3/21/08. ASAP. Maintenance no	On 3/13/09 Boyer				
		N00d00m00s						
SF 2	Silt Fence	W00d00m00s		Removed				
Current Condition:		Removed due to good vegetation, but will need to be reinstalled once home construction starts up in this						
	area.	N00d00m00s				-		
SF 3	Silt Fence	W00d00m00s	In Place	Active	Yes			
Current Condition:	Fair Condition- Par	tially removed due to g	good vegetation, but wil	I need to be reinsta	alled once home			
	Boyer Young was i	own/damaged and ne	naintenance by 7/24/08					
	inspection.	tenance needs to be o	completed ASAP. Maint	enance not compl	eted as of last			
05.4	074 5	N00d00m00s						
SF 4 Current Condition:	Silt Fence Removed due to go	W00d00m00s		Removed		_		
Current Condition:	Removed due to go		1					
05.5	0:4 5	N00d00m00s	In Diana	A -4:	V			
SF 5 Current Condition:	Silt Fence Fair Condition	W00d00m00s	In Place	Active	Yes			
	One area is down/o							
		N00d00m00s						
SF 6	Silt Fence	W00d00m00s		Removed		4		
Current Condition:	Removed due to de		I	I		4		
05.7	0.14 5	N00d00m00s		Dames .				
SF 7 Current Condition:	Silt Fence	W00d00m00s	<u> </u>	Removed		4		
Current Condition:	Removed due to de					1		
STR	Streets	N00d00m00s W00d00m00s	In Place	Active	No			
Current Condition:		major signs of track o		HOUVE	INO	-		
SWPPP Sign	SWPPP Sign	Three signs of site	8/8/2008	Active	No	=		
Current Condition:			ed at Club House Drive			_		
Carrent Solidition.	Hwy 6. South Lake During inspection of	view Way & South Be n 4/29/09 inspector fo		a pile of concrete d	lebris at the entrance	,		
pector Signature:	beel Jawlan			Reviewed By: '	Zadnany L. Jilda			