

E&A Consulting Group, Inc.
 330 North 117th Street
 Omaha, NE 68154-2509
 tel 402.895.4700
 fax 402.895.3599
 www.eacg.com



E&A CONSULTING GROUP, INC.
 ENGINEERING • PLANNING • FIELD SERVICES

Zachary A. Jilek, CPESC, CISEC
 Erosion Control Specialist- Manager

E&A- P2006.056.001

Inspector: Mike Jacobson, CISEC		Stage 3
Project Name:	Iron Horse NER110574	
For Week Ending:	12/11/2010	
Project Location:	Hwy 6 & Iron Horse Drive- Ashland, NE (Sanders County)	68003


Grading:	100%			
Sanitary Sewer:	90%			
Storm Sewer:	90%			
Paving:	90%			
Seeding:	100%			
Utilities:	90%			
Overall Development:	50%			

RAIN FALL AMOUNTS	Amount in tenths	Date inspected		
				Week 1
Sunday:	0.00"			
Monday	Trace			
Tuesday	0.00"			
Wednesday	0.01"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 2
Sunday:	0.00"			
Monday	0.02"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 3
Sunday:	0.00"			
Monday	Trace	11/29/10		
Tuesday	Trace			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 4
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	Trace			
Saturday	0.03"			
				Week 5
Sunday:	N/A	N/A		
Monday	N/A	N/A		
Tuesday	N/A	N/A		
Wednesday	N/A	N/A		
Thursday	N/A	N/A		
Friday	N/A	N/A		
Saturday	N/A	N/A		

Complaints:	None
Construction Sequencing:	

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?					
Entire site; grading completed and stabilized prior to Spring 2005.					
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :					
Entire site; grading completed and stabilized prior to Spring 2005.					
What temporary or permanent stabilization measures listed in this section are being implemented?					
Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.					
Comments:					
Comments:					
Site is in overall good condition. Home construction is active on site.					
Findings / Corrective Actions (Date):					
Findings / Corrective Actions (Date):					
1) There is dirt piled in the street in Southview Circle and it needs to be removed. Boyer Young was informed to remove from the street by 5/1/10. On 6/30/10 and again on 9/17/10 Boyer Young was sent a maintenance plan and reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.					
2) Some maintenance is required in the BMP section.					

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
Lot 19	Silt Fence	Lot 19		Removed	
Current Condition:	Lot was sodded prior to inspection on 11/29/10 by Aspen Builders.				
Lot 87	Silt Fence	Lot 87	7/5/2010	Active	No
Current Condition:	Good Condition- Straw wattle has been installed on the back of the lot.- Active home construction on this lot. Dirt piled in the R.O.W. was removed prior to inspection on 7/20/10 by Buhr Homes.				
Lot 138	Silt Fence	Lot 138	5/4/2010	Active	Yes
Current Condition:	Fair Condition- Silt fence is installed on the back of the vacant lot. Silt fence is down/damaged and needs to be repaired or it can be removed. Boyer Young was informed to complete maintenance by 4/27/2010. Maintenance not completed as of inspection on 4/30/10, but due to the wet and muddy conditions another seven days is given to complete maintenance until 5/6/10. On 6/30/10 and again on 9/17/10 Boyer Young was sent a maintenance plan and reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.				
Lot 192	Silt Fence	Lot 192	5/4/2010	Active	Yes
Current Condition:	Fair Condition- Active home construction on lot. Lot was sodded prior to inspection on 8/16/10 by Owner/General Contractor Duane Hodge There is three rows of silt fence still on the back of the lot. The two front rows of silt fence are down/damaged or full and they need to be repaired and cleaned out or removed. As of inspection on 9/15/10 all three rows of silt fence are either full and/or damaged and need to be repaired. On 8/16/10 owner/general contractor Duane Hodge was informed to complete maintenance by 8/25/10. But due to the back one being in good condition the other two are not going to be repaired at this time per owner/general contractor Duane Hodge. Maintenance not completed as of last inspection.				
Lot 201	Silt Fence	Lot 201	12/5/2010	Pending	Yes
Current Condition:	No BMP's installed on the lot.- Active home construction on lot. 1) Dirt piled in the R.O.W. and it needs to be removed or silt fence needs to be installed around it. 2) Lot level silt fence needs to be installed on the lot. 1) Novotny Builders was called and left a message and informed to complete maintenance by 12/5/10. 2) Novotny Builders was called and left a message and informed to complete maintenance by 12/5/10.				
Outlot	Silt Fence	Outlot behind lot 128	5/4/2010	Active	Yes

Current Condition:	<p>Fair Condition- Two silt fence checks in outlot behind lot 128</p> <p>Both silt fence checks are undermined and need to be backfilled and compacted or they can be removed due to good vegetation in the area.</p> <p>Boyer Young was informed to complete by 10/30/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. On 5/3/10, 6/30/10 and again on 9/17/10 Boyer Young was sent a maintenance plan and reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.</p>				
PDP A	Permanent Detention Pond	N00d00m00s W00d00m00s	In Place	Active	No
Current Condition:	Good Condition				
SF 1	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Silt fence was removed prior to inspection on 4/5/10 by Boyer Young as it is no longer needed.				
SF 2	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Removed due to good vegetation, but will need to be reinstalled once home construction starts up in this area.				
SF 3	Silt Fence	N00d00m00s W00d00m00s	In Place	Active	Yes
Current Condition:	<p>Fair Condition- Partially removed due to good vegetation, but will need to be reinstalled once home construction start up in this area.</p> <p>A few areas area down/damaged and needs to be repaired or stilt fence can be removed.</p> <p>Boyer Young was informed to complete maintenance by 7/24/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. On 5/3/10, 6/30/10 and again on 9/17/10 Boyer Young was sent a maintenance plan and reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.</p>				
SF 4	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Removed due to good vegetation.				
SF 5	Silt Fence	N00d00m00s W00d00m00s	In Place	Active	Yes
Current Condition:	<p>Fair Condition</p> <p>One area is down/damaged and full and needs to be repaired and cleaned out.</p> <p>Boyer Young was informed to complete by 6/6/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. On 5/3/10, 6/30/10 and again on 9/17/10 Boyer Young was sent a maintenance plan and reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.</p>				
SF 6	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Removed due to development.				
SF 7	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Removed due to development.				
STR	Streets	N00d00m00s W00d00m00s	In Place	Active	Yes
Current Condition:	<p>Fair Condition</p> <p>Some minor signs of run off coming from vacant lot 60 and it needs to be cleaned up.</p> <p>Boyer Young was informed to clean up by 9/2/10 and again on 9/15/10. Street not cleaned up as of last inspection.</p>				
SWPPP Sign	SWPPP Sign	Three signs of site	8/8/2008	Active	No
Current Condition:	<p>Good Condition - A sign has been installed at Club House Drive and Hwy 6 and at Iron Horse Drive and Hwy 6. South Lakeview Way & South Bend Road entrance.</p> <p>During inspection on 4/29/09 inspector found a SWPPP sign in a pile of concrete debris at the entrance at South Lakeview Way & South Bend Road and re-installed during inspection. Therefore there are know three signs on site.</p>				
Inspector Signature: 			Reviewed By: 