

E&A Consulting Group, Inc.
 330 North 117th Street
 Omaha, NE 68154-2509
 tel 402.895.4700
 fax 402.895.3599
 www.eacg.com



E&A CONSULTING GROUP, INC.
 ENGINEERING • PLANNING • FIELD SERVICES

Zachary A. Jilek, CPESC, CISEC
 Erosion Control Specialist- Manager

E&A- P2006.056.001

Inspector: Mike Jacobson, CISEC		Stage 3
Project Name:	Iron Horse NER110574	
For Week Ending:	5/12/2012	
Project Location:	Hwy 6 & Iron Horse Drive- Ashland, NE (Sanders County)	68003

Grading:	100%				
Sanitary Sewer:	90%				
Storm Sewer:	90%				
Paving:	90%				
Seeding:	100%				
Utilities:	90%				
Overall Development:	50%				

RAIN FALL AMOUNTS	Amount in tenths	Date inspected			
					Week 1
Sunday:	0.07"	04/15/12			
Monday	Trace	04/16/12			
Tuesday	0.01"				
Wednesday	0.03"				
Thursday	0.23"				
Friday	0.00"				
Saturday	Trace				
					Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	Trace				
Wednesday	0.00"				
Thursday	Trace				
Friday	0.18"				
Saturday	0.00"				
					Week 3
Sunday:	0.11"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.56"	05/02/12			
Thursday	0.57"	05/03/12			
Friday	0.00"				
Saturday	0.00"				
					Week 4
Sunday:	0.68"	05/06/12			
Monday	0.00"				
Tuesday	0.00"	05/08/12			
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 5
Sunday:	N/A	N/A			
Monday	N/A	N/A			
Tuesday	N/A	N/A			
Wednesday	N/A	N/A			
Thursday	N/A	N/A			
Friday	N/A	N/A			
Saturday	N/A	N/A			

Complaints:	None

Construction Sequencing:
 Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire site; grading completed and stabilized prior to Spring 2005.


What temporary or permanent stabilization measures listed in this section are being implemented?

Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.

Comments:

Comments: Home construction is active on a few lots.
Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date): 1) Some maintenance is required in the BMP section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
Lot 138	Silt Fence	Lot 138	5/4/2010	Active	Yes
Current Condition:	Fair Condition- Silt fence is down/damaged and needs to be repaired or it can be removed. Boyer Young was informed to complete maintenance by 4/27/2010. Maintenance not completed as of inspection on 4/30/10, but due to the wet and muddy conditions another seven days is given to complete maintenance until 5/6/10. On 6/30/10, 9/17/10, 4/21/11, 8/10/11 and again on 3/6/12 Boyer Young was sent a maintenance plan and reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.				
Lot 159	Silt Fence	Lot 159	8/19/2011	Active	Yes
Current Condition:	Fair Condition- 1) Silt fence needs to be installed on the front of the lot. 2) Silt fence on the back of the lot is down/damaged and it needs to be replaced. As of inspection on 5/2/12 silt fence was replaced but it was not trenched in and it needs to be trenched in. 1) On 11/10/11 Mike Cerny w/ United Country Reality was informed to complete maintenance by 11/16/11. On 11/28/11, 1/4/12, 1/30/12, 4/2/12, 4/16/12 and again on 5/2/12 Mike Cerny w/ United Country Reality was informed to complete overdue maintenance ASAP. Maintenance not completed as of last inspection. 2) Mike Cerny w/ United Country Reality was informed to complete maintenance by 11/16/11. On 11/28/11, 1/4/12, 1/30/12, 4/2/12, 4/16/12 and again on 5/2/12 Mike Cerny w/ United Country Reality was informed to complete overdue maintenance ASAP. Maintenance not completed as of last inspection.				
Outlot	Silt Fence	Outlot behind lot 128	5/4/2010	Active	Yes
Current Condition:	Fair Condition- Two silt fence checks in outlot behind lot 128 Both silt fence checks are undermined and need to be backfilled and compacted or they can be removed due to good vegetation in the area. Boyer Young was informed to complete by 10/30/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. On 5/3/10, 6/30/10, 9/17/10, 4/21/11, 8/10/11 and again on 3/6/12 Boyer Young was sent a maintenance plan and reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.				
PDP A	Permanent Detention Pond	N00d00m00s W00d00m00s	In Place	Active	No
Current Condition:	Good Condition				
POD A	Silt Fence	Lots 4-12	5/6/2012	Active	Yes
Current Condition:	Good Condition Silt fence checks needs to be installed on the front of lot 9. Hearthstone was informed to complete maintenance by 4/22/12. Silt fence check was installed on lot 9 prior to inspection on 5/6/12 by Hearthstone.				
SF 1	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Silt fence was removed prior to inspection on 4/5/10 by Boyer Young as it is no longer needed.				
SF 2	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Removed due to good vegetation, but will need to be reinstalled once home construction starts up in this area.				
SF 3	Silt Fence	N00d00m00s W00d00m00s	In Place	Active	Yes
Current Condition:	Fair Condition- Partially removed due to good vegetation, but will need to be reinstalled once home construction start up in this area. A few areas area down/damaged and needs to be repaired or silt fence can be removed. Boyer Young was informed to complete maintenance by 7/24/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. On 5/3/10, 6/30/10, 9/17/10, 4/21/11, 8/10/11 and again on 3/6/12 Boyer Young was sent a maintenance plan and reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.				
SF 4	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Removed due to good vegetation.				
SF 5	Silt Fence	N00d00m00s W00d00m00s	In Place	Active	Yes

Current Condition:	<p>Fair Condition</p> <p>One area is down/damaged and full and needs to be repaired and cleaned out.</p> <p>Boyer Young was informed to complete by 6/6/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. On 5/3/10, 6/30/10, 9/17/10, 4/21/11, 8/10/11 and again on 3/6/12 Boyer Young was sent a maintenance plan and reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.</p>				
SF 6	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Removed due to development.				
SF 7	Silt Fence	N00d00m00s W00d00m00s		Removed	
Current Condition:	Removed due to development.				
STR	Streets	N00d00m00s W00d00m00s	In Place	Active	Yes
Current Condition:	<p>Good Condition-</p> <p>There is some minor run off on Mumm Road and it needs to be cleaned up.</p> <p>Hearthstone was informed to complete maintenance by 4/16/12. Street was cleaned up prior to inspection on 5/8/2012.</p>				
SWPPP Sign	SWPPP Sign	Three signs of site	8/8/2008	Active	No
Current Condition:	Good Condition - A sign has been installed at Club House Drive and Hwy 6 and at Iron Horse Drive and Hwy 6. South Lakeview Way & South Bend Road entrance.				
Inspector Signature: 					Reviewed By: 