

E & A Consulting Group, Inc.  
 10909 Mill Valley Road, Suite 100  
 Omaha, NE 68154  
 tel 402.895.4700  
 fax 402.895.3599  
 www.eacg.com



**E & A CONSULTING GROUP, INC.**

*Engineering Answers*

Zachary A. Jilek, CPESC, CISEC  
 Environmental Services Dept. Manager

**E&A- P2006.056.001**

Inspector: Matthew Russell					Stage
Project Name:	<b>Iron Horse NER110574</b>				3
For Week Ending:	<b>4/14/2018</b>				
Project Location:	<b>Hwy 6 &amp; Iron Horse Drive- Ashland, NE (Saunders County)</b>				<b>68003</b>
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	90%				
Seeding:	100%				
Utilities:	90%				
Overall Development:	70%				
<b>RAIN FALL AMOUNTS</b>					
	Amount in tenths	Date inspected	Weather Conditions		
					<b>Week 1</b>
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.83"				
Saturday	0.00"	03/17/18	Snow 40/34		
					<b>Week 2</b>
Sunday:	0.18"				
Monday	0.27"				
Tuesday	0.11"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.10"				
Saturday	0.68"				
					<b>Week 3</b>
Sunday:	0.03"				
Monday	0.60"				
Tuesday	0.00"	03/27/18	P Cloudy 53/37		
Wednesday	0.01"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					<b>Week 4</b>
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.01"				
Saturday	0.00"				
					<b>Week 5</b>
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.07"				
<b>Complaints:</b>					
None					
<b>Construction Sequencing:</b>					

<b>Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?</b>					
Entire site; grading completed and stabilized prior to Spring 2005.					
<b>Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :</b>					
Entire site; grading completed and stabilized prior to Spring 2005.					
<b>What temporary or permanent stabilization measures listed in this section are being implemented?</b>					
Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.					
<b>Summary Questions:</b>					
<b>Are approved entrances and adjacent streets being maintained adequately?</b>					
Yes					
<b>Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?</b>					
Yes					
<b>Checklist Questions:</b>					
<b>Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?</b>					
Yes					
<b>Is dust associated with the construction activity adequately controlled on the site?</b>					
Yes					
<b>Comments:</b>					
<b>Comments:</b> Home construction is active on a few lots.					
<b>Findings / Corrective Actions (Date):</b>					
<b>Findings / Corrective Actions (Date):</b> 1) Some maintenance is required in the BMP section.					

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
Lot 7	Silt Fence	Lot 7		Removed	
<b>Current Condition:</b>	Removed - The lot is sodded and there are no signs of runoff in the golf course turf as of inspection on 4/20/15.				
Lot 8	Silt Fence	Lot 8		Removed	
<b>Current Condition:</b>	Active - The lot owned by PHI has become vegetated and is covered in gravel. Due to this level of stabilization, silt fence will not be recommended in the back of the lot at this time. E&A inspector will continue to monitor.				
Lot 18	Silt Fence	Lot 18		Removed	
<b>Current Condition:</b>	Removed - MK Builders sodded the lot prior to inspection on 8/17/17.				
Lot 33	Straw Wattles	Lot 33	1/15/2015	Active	No
<b>Current Condition:</b>	Good Condition - Nathan Homes had straw wattles installed along the curb line due to the lot being disturbed during construction on lot 118 prior to inspection on 1/15/15.				
Lot 36	Individual Lot	Lot 36		Removed	
<b>Current Condition:</b>	Fair Condition-Silverstone sodded the lot prior to inspection on 7/27/15.				
Lot 37	Silt Fence	Lot 37		Removed	
<b>Current Condition:</b>	Removed-Kendel Homes sodded the lot prior to inspection on 12/15/15.				
Lot 38	Silt Fence	Lot 38		Removed	
<b>Current Condition:</b>	Removed - The lot is vegetated and no longer needs to be stabilized by Kindle Homes as of 6/4/16 inspection.				
Lot 61	Individual Lot	Lot 61		Removed	
<b>Current Condition:</b>	Removed-The disturbed portion of the lot is vegetated with natural vegetation as of inspection on 10/29/15.				
Lot 89	Silt Fence	Lot 089		Removed	
<b>Current Condition:</b>	Removed- MK Builders sodded the lot prior to 9/27/16.				
Lot 93	Silt fence	Lot 93		Removed	
<b>Current Condition:</b>	Removed- Al Belt sodded the lot prior to inspection on 8/20/16.				
Lot 113	Silt Fence	Lot 113	8/17/2017	Active	Yes
<b>Current Condition:</b>	Fair Condition-  Silt fence in the rear of the lot needs to be cleaned out and repaired.  Boyer Young was informed to complete by 8/24/2017. Not done as of last inspection. Boyer Young was reminded on 10/09/17, 12/19/17, 1/26/18, 2/21/18, 3/21/18.				
Lot 114	Silt Fence	Lot 114	8/19/2015	Active	Yes

<b>Current Condition:</b>	<p>Fair Condition- Gaver Const. sodded the front and sides of the lot prior to 4/20/17, the rear of the lot is still exposed with silt fence in place. Lot ownership was changed to Brian Mikkelsen on 8/23/17. <b>Brian Mikkelsen removed silt from the inlets that are on his property as of inspection on 3/27/18.</b></p> <p>The silt fence at the rear of the property need to be backfilled.</p> <p>Gaver Construction was informed to complete by 10/4/16. Not done as of last inspection. Gaver Construction was reminded on 11/9/16, 11/25/16. Gaver Const. was reminded via voice mail on 12/21/16. Gaver Construction was reminded on 12/27/16 via email and on 1/19/17, 3/24/17, 5/12/17. Brian Mikkelsen was reminded on 8/23/17, 12/19/17, 1/26/18, 2/21/18, <b>3/21/18.</b></p>				
Lot 119/120	Silt Fence	119/120		Removed	
<b>Current Condition:</b>	Removed - The silt fence is listed in the report as SF 9 as of 12/19/17.				
Lot 139	Silt Fence	Lot 139		Removed	
<b>Current Condition:</b>	Removed-Mick Smith Construction sodded the lot prior to inspection on 6/12/15.				
Lot 147	Silt Fence	Lot 147		Removed	
<b>Current Condition:</b>	Removed-PHI removed the silt fence and sodded the lot prior to inspection on 5/6/15.				
Lot 153	Individual Lot	Lot 153		Removed	
<b>Current Condition:</b>	Removed-Widhalm Custom Homes sodded the lot prior to inspection on 7/27/15.				
Lot 154	Silt Fence	Lot 154	8/19/2015	Active	Yes
<b>Current Condition:</b>	<p>Fair Condition- Widhalm Custom Homes installed more silt fence prior to inspection on 4/15/16.</p> <p>Due to established vegetation, the silt fence can be removed from the lot.</p> <p>Boyer Young was informed to complete by 6/26/17. Not done as of last inspection. Boyer Young was reminded on 9/19/17, 10/09/17, 12/19/17, 1/26/18, 2/21/18, <b>3/21/18.</b></p>				
Lot 158	Silt Fence	Lot 158		Removed	
<b>Current Condition:</b>	Removed - The lot was sodded prior to inspection on 12/5/17.				
Lot 159	Silt Fence	Lot 159		Removed	
<b>Current Condition:</b>	Removed- The Home Company sodded the lot prior to inspection on 6/3/16.				
Lot 160	Individual Lot	Lot 160	3/10/2016	Removed	
<b>Current Condition:</b>	Removed - The lot was sodded, silt fence installed along the lot 159/160 boundary to protect the inlet prior to inspection on 8/13/16. The streets around the lot need to be cleaned. See STR section.				
Lot 161	Individual Lot	Lot 161		Removed	
<b>Current Condition:</b>	Removed- THC sodded the lot prior to 6/19/17.				
Lot 162	Individual Lot	Lot 162		Removed	
<b>Current Condition:</b>	Removed- THC sodded the lot prior to 6/19/17.				
Lot 163	Individual Lot	Lot 163		Removed	
<b>Current Condition:</b>	Removed- THC sodded the lot prior to 6/19/17.				
Lot 164	Individual Lot	Lot 164		Removed	
<b>Current Condition:</b>	Removed- THC sodded the lot prior to 6/19/17.				
Lot 165	Silt Fence	Lot 165		Removed	
<b>Current Condition:</b>	Removed- THC sodded the lot prior to 6/19/17.				
Lot 188	Silt Fence	Lot 188		Removed	
<b>Current Condition:</b>	Removed- Terry Bouge sodded the lot and removed the silt fence prior to inspection on 6/4/16. The adjacent lots vegetation appears adequate and no temporary seeding is needed.				
Lot 189	Silt Fence	Lot 189		Removed	
<b>Current Condition:</b>	Removed - The lot was sodded as of last inspection on 9/19/2017.				
Lot 197	Silt Fence	Lot 197	9/19/2017	Active	Yes
<b>Current Condition:</b>	<p>Fair Condition - Builder was identified as MK Builders Custom Homes</p> <p>1. Silt fence needs to be cleaned out and repaired in the back of the lot. 2. Sediment needs to be removed from the curb line.</p> <p>1. MK Custom Homes was requested to complete by 10/2/17. Not done as of the last inspection. MK Builders was reminded on 12/19/17, 1/26/18, 2/21/18, <b>3/21/18.</b> 2. MK Custom Homes was informed to complete by 3/24/18. <b>Not done as of last inspection.</b></p>				
Lot 207	Silt Fence	Lot 207		Removed	
<b>Current Condition:</b>	Removed - THC sodded the lot prior to inspection on 12/5/17.				
PDP A	Permanent Detention Pond	41°02'43.47"N 96°20'36.65"W	In Place	Active	No
<b>Current Condition:</b>	Good Condition - <b>This is a pond as of 1993.</b>				
SB 1	Sediment Basin	Lot 109	In Place	Active	No

<b>Current Condition:</b>	Good Condition- The sediment basin was not known of when E&A took over the project and was covered by dense vegetation. It was discovered when looking at problems silting in the golf course. Boyer Young removed the trash rack and cleaned out the basin prior inspection on 8/31/16 as the basin had no water storage or sediment capacity. Silt fence is behind the sediment basin riser.				
SF 3	Silt Fence	Lot 197		Removed	
<b>Current Condition:</b>	Removed- the inspector removed the silt fence during the inspection on 3/22/17.				
SF 5	Silt Fence	South side of lake		Removed	
<b>Current Condition:</b>	Removed- the inspector removed the silt fence during the inspection on 3/22/17.				
SF 8	Silt Fence	40' South of SF 5		Removed	
<b>Current Condition:</b>	Removed- the inspector removed the silt fence during the inspection on 3/22/17.				
SF 9	Silt Fence	East of Lots 119 and 120	In Place	Active	<b>Yes</b>
<b>Current Condition:</b>	Fair Condition - Boyer Young repaired and partially removed the silt fence prior to inspection on 12/5/17. The sit fence is full and needs to be cleaned behind lots 114 and 115. Boyer Young was informed to complete by 3/24/18. <b>Not done as of last inspection.</b>				
SF 10	Silt Fence	Behind Lot 190	In Place	Active	No
<b>Current Condition:</b>	Good Condition - The silt fence was installed by Boyer Young to protect the golf course trail prior to the inspection on 10/11/17. E&A inspector will continue to monitor.				
STR	Streets	41°02'28.55"N 96°20'36.35"W	In Place	Active	No
<b>Current Condition:</b>	Good Condition - Streets do not have significant trackout on them as of the last inspection on 10/11/17. E&A inspector will continue to monitor.				
SWPPP Sign	SWPPP Sign	Three signs on site	8/8/2008	Active	No
<b>Current Condition:</b>	Good Condition - A sign has been installed at Club House Drive and Hwy 6 and at Iron Horse Drive and Hwy 6. South Lakeview Way & South Bend Road entrance.				
<b>Inspector Signature:</b>				<b>Reviewed By:</b>	