

E & A Consulting Group, Inc.  
 10909 Mill Valley Road, Suite 100  
 Omaha, NE 68154  
 tel 402.895.4700  
 fax 402.895.3599  
 www.eacg.com



**E & A CONSULTING GROUP, INC.**

*Engineering Answers*

Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

**E&A- P2006.056.001**

Inspector: Avery Dresser		Stage
Project Name:	<b>Iron Horse NER110574</b>	3
For Week Ending:	<b>3/14/2020</b>	
Project Location:	<b>Hwy 6 &amp; Iron Horse Drive- Ashland, NE (Saunders County)</b>	<b>68003</b>

Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	72%			


RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					<b>Week 1</b>
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.05"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					<b>Week 2</b>
Sunday:	0.00"				
Monday	0.02"				
Tuesday	0.00"				
Wednesday	0.08"	2/19/2020	Overcast 31/15	1:30 p.m.	
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					<b>Week 3</b>
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					<b>Week 4</b>
Sunday:	0.00"				
Monday	0.01"				
Tuesday	0.00"				
Wednesday	0.01"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					<b>Week 5</b>
Sunday:	0.00"				
Monday	0.30"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.04"				
Saturday	0.45"				

Complaints:	None

**Construction Sequencing:**

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and stabilized prior to Spring 2005.					
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :					
Entire site; grading completed and stabilized prior to Spring 2005.					
What temporary or permanent stabilization measures listed in this section are being implemented?					
Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.					
<b>Checklist Questions:</b>					
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?					
Yes					
Create Corrective Action?					
N/A					
Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.					
Yes					
Create Corrective Action?					
N/A					
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?					
Yes					
Create Corrective Action?					
N/A					
Are construction entrances and adjacent streets being maintained adequately?					
No					
Create Corrective Action?					
No - See BMP Section					
Is dust associated with the construction activity adequately controlled on the site?					
Yes					
Create Corrective Action?					
N/A					
<b>Comments:</b>					
<b>Comments:</b>					
Home construction is active on a few lots.					
<b>Findings / Corrective Actions (Date):</b>					
<b>Findings / Corrective Actions (Date):</b>					
1) Some maintenance is required in the BMP section.					
2) There is disturbed ground on either side of the newly-sodded Lot 32 as of inspection on 7/23/19. The lot is flat and doesn't have runoff potential to waterbodies or the street therefore immediate stabilization or installation of BMPs is not necessary at this time. E&A inspector will continue to monitor the area for revegetation.					
<b>Unique Name</b>	<b>Type</b>	<b>Location</b>	<b>Projected Install Date</b>	<b>Status</b>	<b>Maintenance</b>
IF 1	Inlet	Lot 110	In Place	Active	No
<b>Current Condition:</b>	Active - This structure was previously referred to as a sediment basin, but is actually functioning as a slope drain/area inlet. As-of the 11/26/18 inspection, silt fence is in place behind the structure and straw wattles are located downhill from the outlet pipe.				
Lot 2	Individual Lot	Lot 2		Removed	
<b>Current Condition:</b>	Removed - Pacesetter Homes removed the silt fence and sodded the lot prior to the inspection on 11/06/19.				
Lot 32	Individual Lot	Lot 32		Removed	
<b>Current Condition:</b>	Removed - Nathan Homes removed the concrete debris and sodded the lot prior to inspection on 7/23/19.				
Lot 90	Individual Lot	Lot 90		Removed	
<b>Current Condition:</b>	Removed - Grace Homes sodded the lot prior to inspection on 7/02/19.				
Lot 113	Silt Fence	Lot 113	8/17/2017	Active	No
<b>Current Condition:</b>	Good Condition - Boyer Young repaired the silt fence on the lot prior to the 7/3/18 inspection. Boyer Young removed some of the damaged silt fence and repaired the runs left in place prior to inspection on 7/02/19. As of the inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seeding is no longer required at this time.				
Lot 126	Individual Lot	Lot 126		Removed	
<b>Current Condition:</b>	Removed - The Homeowners removed the silt fence and sodded the lot prior to inspection on 9/20/19.				
Lot 130	Individual Lot	Lot 130		Removed	
<b>Current Condition:</b>	Removed - The homeowners sodded the lot prior to inspection on 5/29/19.				
Lot 137	Individual Lot	Lot 137		Removed	
<b>Current Condition:</b>	Removed - The Home Company sodded the lot and removed the silt from the adjacent lot prior to inspection on 8/13/19.				
Lot 138	Individual Lot	Lot 138		Removed	
<b>Current Condition:</b>	Removed - The Home Company removed the portable toilet and sodded the lot prior to inspection on 8/13/19.				
Lot 155	Silt Fence	Lot 155	9/3/2018	Active	No
<b>Current Condition:</b>	Good Condition - Widhalm Custom Homes installed silt fence on the lot to protect sodded lot 154 prior to inspection on 9/3/18.				
Lot 163	Silt Fence	Lot 163	9/20/2019	Active	Yes

<b>Current Condition:</b>	<p>Fair Condition - Hubbell Homes excavated the lot and installed silt fence along the south side of the lot prior to inspection on 9/20/19. Hubbell Homes removed the dirt pile from the ROW prior to the inspection on 11/06/19.</p> <p>1. The silt fence should be extended to border the back side of the lot.  2. The silt fence should be cleaned out where full.  3. Silt should be removed from the golf course.  4. The damaged end of the silt fence should be repaired.  <b>5. The street in front of the lot should be cleaned off.</b></p> <p>1. Hubbell Homes was informed to complete by 10/03/19. Not done as of the last inspection. Hubbell Homes was reminded on 10/08/19, 11/06/19, 12/04/19, 12/31/19, <b>2/19/20</b>  2. Hubbell Homes was informed to complete by 10/03/19. Not done as of the last inspection. Hubbell Homes was reminded on 10/08/19, 11/06/19, 12/04/19, 12/31/19, <b>2/19/20</b>  3. Hubbell Homes was informed to complete by 10/14/19. Not done as of the last inspection. Hubbell Homes was reminded on 11/06/19, 12/04/19, 12/31/19, <b>2/19/20</b>  4. Hubbell Homes was informed to complete by 1/07/19. Not done as of the last inspection. <b>Hubbell Homes was reminded on 2/19/20</b>  <b>5. Hubbell Homes was informed to complete by 2/20/20.</b></p>				
Lot 193	Silt Fence	Lot 193	9/20/2019	Active	Yes
<b>Current Condition:</b>	<p>Fair Condition - An unknown builder excavated the lot and installed straw wattles around the back side of the lot prior to inspection on 9/20/19. The homeowners (Danielson) are listed as the lot owner on the Saunders County Assessor's website, and will therefore be assumed to be responsible for maintenance unless they communicate otherwise. The shifted wattle was restaked, and buried by additional dirt prior to the inspection on 12/04/19. The wattle should be cleaned off, along with the other full wattles (See maintenance item #1). The homeowners (Danielson) cleaned the street, partially cleaned out the wattles on the east side of the lot, partially staked down the new wattles, and replaced the damaged wattle to close the gap on the back side of the lot prior to the inspection on 12/31/19. <b>Murray Custom Homes secured the portable toilet prior to the inspection on 2/19/20.</b></p> <p>1. The wattles should be cleaned out where full on the north side of the lot.  2. The new wattles on the back side of the lot should be staked down.</p> <p>1. The homeowners (Danielson) were informed to complete by 10/14/19. Not done as of the last inspection. The homeowners (Danielson) were reminded on 12/05/19, 1/24/20  2. The homeowners (Danielson) were informed to complete by 12/10/19. Not done as of the last inspection. The homeowners (Danielson) were reminded on 1/24/20.</p>				
PDP A	Permanent Detention Pond	41°02'43.47"N 96°20'36.65"W	In Place	Active	No
<b>Current Condition:</b>	Good Condition - This is a pond as of 1993.				
SB 1	Sediment Basin	Lot 109		Removed	
<b>Current Condition:</b>	Removed - Following the 11/26/18 inspection, this structure is no longer being considered a basin as it does not have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information.				
SF 3	Silt Fence	Lot 197		Removed	
<b>Current Condition:</b>	Removed- the inspector removed the silt fence during the inspection on 3/22/17.				
SF 5	Silt Fence	South side of lake		Removed	
<b>Current Condition:</b>	Removed- the inspector removed the silt fence during the inspection on 3/22/17.				
SF 8	Silt Fence	40' South of SF 5		Removed	
<b>Current Condition:</b>	Removed- the inspector removed the silt fence during the inspection on 3/22/17.				
SF 9	Silt Fence	East of Lots 119 and 120	In Place	Active	Yes
<b>Current Condition:</b>	<p>Fair Condition - Boyer Young repaired and partially removed the silt fence prior to inspection on 12/5/17. The sediment was removed from the golf course and cart path prior to inspection on 4/29/19.</p> <p>The silt fence is full and needs to be cleaned behind lots 114 and 115.</p> <p>Boyer Young was informed to complete by 3/24/18. Not done as of last inspection. Boyer Young was reminded on 6/28/18, 9/24/18, 3/19/19, 6/06/19, 8/15/19, 12/04/19</p>				
SF 10	Silt Fence	Behind Lot 190	12/5/2018	Active	No
<b>Current Condition:</b>	Good Condition - The silt fence was mistakenly removed from the report in July, however it is still in place and in good condition. E&A will monitor.				
STR	Streets	41°02'28.55"N 96°20'36.35"W	In Place	Active	No
<b>Current Condition:</b>	Good Condition - No signs of trackout were observed during the last inspection.				
SWPPP Sign	SWPPP Sign	Two signs on site	8/8/2008	Active	No
<b>Current Condition:</b>	Good Condition - A sign has been installed at Iron Horse Drive and Hwy 6. South Lakeview Way & South Bend Road entrance. The sign at the South Lakeview Way and South Bend Road entrance was visible again due to the surrounding grass being mowed prior to inspection on 7/02/19. The SWPPP sign by Hwy 6 and Iron Horse Drive had been knocked over prior to inspection on 7/23/19. E&A inspector reinstalled the downed SWPPP sign during inspection on 7/23/19.				
Inspector Signature: 				Reviewed By: 