E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

nspector: Joe Manning		E&A- P2000			Stage
nopoliti. The Mailling		l,	on Horse		Stage
Project Name:			V-201701133		3
or Week Ending:		2	2/12/2022		
Project Location:	Hwy	6 & Iron Horse Driv	ve- Ashland, NE (Saunders C	County)	68003
-					
Grading:	100%				
anitary Sewer: storm Sewer:	100% 100%				
Paving:	1007				
Seeding:	1007				
Itilities:	100%				
verall Development:	72%	5			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	We
unday:	0.00"				vve
londay	0.00"				
uesday	0.00"				
Vednesday	0.00"				
hursday	0.00"				
riday	0.12"				
Saturday	0.02"				
<u> </u>	0.00#				We
Sunday:	0.00"	4/48/2222	Macdinol 1 (A)	0.40 514	
Monday	0.00"	1/17/2022	Mostly Cloudy 40/24	3:10 PM	
uesday	0.00"				
Vednesday 'hursday	0.00"				
riday	0.00"				
Saturday	0.00"				
, attai uuy	0.00				We
Sunday:	0.00"				We
Monday	0.00"				
Tuesday	0.00"				
Vednesday 	0.00"				
hursday	0.00"				
riday	0.00"				
Saturday	0.00"				
					We
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Vednesday	0.00"				
- Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					We
Sunday:	0.00"				
Monday	0.00"				
uesday	0.00"				
Vednesday	0.00"				
hursday	0.02"				
riday	0.22"				
aturday	0.00"			+	
raturuay	10.00	1			
	None				
Complaints:	1				
JUHUMHUS.					
omplants.					
ompiants.					

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site; grading completed and stabilized prior to Spring 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Dense Vegetation, seeding/sodding, matting, re-seeding 5/2006, paving, and landscaping.

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action

No - See Findings Section.

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMP Section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

Home construction is active on a few lots.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) A portable toilet was secured on Lot 30 prior to the inspection on 5/28/21. The portable toilet was unsecured prior to the inspection on 8/25/21. Ms. Suzanne Sapp (owner of 1630 East Ridge Way) was informed to complete by 9/08/21. Not done as of the last inspection.

drain/area inlet. A	Location Lot 110	Projected Install Date In Place	Status	Maintenance
Current Condition: Active - This structure drain/area inlet. A		In Place	A 11	
drain/area inlet. A	ture was previously refer		Active	No
	s-of the 11/26/18 inspecti om the outlet pipe.	red to as a sediment basin, bion, silt fence is in place behi	nd the structure and	
Lot 4 R IV Silt Fence	Lot 4 R IV		Removed	
cleaned by rain p	ior to the inspection on 7	lot prior to the inspection on /15/21. The disturbed area w	est of the lot has ve	
Lot 6 R II Silt Fence	Lot 6 R II		Removed	
		and removed the concrete w		
Lot 57 Silt Fence	Lot 57	6/1/2020	Active	No
as of 10/05/20. Ti	own builder began construe lot is currently vacant.	uction on the lot prior to the i	•	0. The lot has vegetated
Lot 61 Silt Fence Current Condition: Good Condition -	Lot 61	9/28/2021 n construction on the lot prior	Active	No
Platinum Solution inspection on 10/2	s removed the dirt pile fro 28/21.	uilder was actively excavatin om the ROW and secured a p	portable toilet on the	e lot prior to the
Lot 82 Silt Fence	Lot 82	5/28/2021	Active	Yes
installed silt fence of silt fence along along the front of and from Lot 47 p and from Lot 47. 1.) The silt fence 2.) The street in f. 3.) The silt fence 1.) Paradise Hom reminded on 6/25. 2.) Paradise Hom reminded on 8/27.	along the back side of the the front of the lot prior to the inspection on 1 prior to the inspection of the lot prior to the inspection of the lot should be contended to be trenched in a cont of the lot should be coalong the front of the lot should be	and repaired along the back a leaned. should be repaired/reinstalle lete by 6/04/21. Not done as	n 5/28/21. Paradise Paradise Homes ex mes removed the demoved the concruind sides of the lot. d. of the last inspection of the last inspection	e Homes installed a run tended the silt fence irt pile from the ROW ete waste from the lot on. Paradise Homes was
Lot 1 R VI Silt Fence	Lot 1 R VI	8/17/2017	Active	No

Current Condition:	some of the damaginspection on 7/02/longer required at inspection on 11/1 posts during the in	yed silt fence and repaire (19, volunteer vegetation this time. Boyer Young re 1/20. Lot was formerly id spection on 6/24/21. E&	silt fence on the lot prior to the d the runs left in place prior in has filled in sufficiently to premoved the damaged runs of lentified as Lot 113. Some poor A inspector retied a portion condations for the remainder of	to inspection on 7/0 revent erosion, ther f silt fence from the ortions of the silt fer of the silt fence durin	02/19. As of the efore seeding is no lot prior to the ace were loose from the tag the inspection on
Lot 152	Individual Lot	Lot 152	11/23/2021	Active	No
Current Condition:	Good Condition - C to the inspection of Homes was active	itadel Homes began col n 11/23/21. A dirt pile wa y excavating the lot duri	instruction on the lot and instraction on the lot and instract is observed in the ROW during the inspection. E&A inspections of the inspector retied portions of the	alled silt fence alono ng the current inspe ector will monitor an	the back of the lot prior ection; however, Citadel d make
Lot 155	Silt Fence	Lot 155	9/3/2018	Active	Yes
Current Condition:	on 9/3/18. The silt fence shou Widhalm Custom F	dhalm Custom Homes in	nstalled silt fence on the lot to the lot to the lot to the lot.		
Lot 156	Silt Fence	Lot 155	9/3/2018	Active	Yes
Current Condition:	the dirt pile from the Silt fence should b	e ROW prior to the inspose installed along the bac informed to complete I	ion on the lot prior to the inspection on 10/14/21. Is and east sides of the lot. by 10/05/21. Not done as of the lot.		
Lot 184	Individual Lot	Lot 184	11/23/2021	Active	Yes
Current Condition:	installed silt fence the ROW of the lo The dirt pile should	along the back of the lot of prior to the inspection to the inspection the removed from the R		/20/21. The dirt pil	
Lot 186	Individual Lot	Lot 186	I	Removed	
Current Condition:			ot and removed the portable		spection on 11/23/21
Lot 209	Individual Lot	Lot 209	1/17/2022	Active	No
Current Condition:	vegetation on the will monitor.		struction on the lot prior to ne lot. No BMPs will be rec		
PDP A	Permanent Detention Pond	96°20'36.65"W	In Place	Active	No
Current Condition:		his is a pond as of 1993		Active	INO
SB 1	Sediment Basin	Lot 109	,. 	Removed	
Current Condition:	Removed - Followi	ng the 11/26/18 inspecti storage capacity and a	on, this structure is no longe opears to be an area inlet/slo	r being considered	
SF 3	Silt Fence	Lot 197		Removed	
Current Condition: SF 5	Removed- the insp	ector removed the silt fe South side of lake	ence during the inspection or	3/22/17. Removed	
Current Condition:			I ence during the inspection or		<u> </u>
SF 8	Silt Fence	40' South of SF 5	aumig and mopodadit of	Removed	
Current Condition:	Removed- the insp	ector removed the silt fe	ence during the inspection or	3/22/17.	
		East of Lots 119 and			
SF 9	Silt Fence	120	In Place d partially removed the silt fe	Active	No No 12/5/17 The
Current Condition:	sediment was remo	oved from the golf cours the inspection on 8/10/	e and cart path prior to inspe	ection on 4/29/19. T	
SF 10 Current Condition:	Silt Fence	Behind Lot 190	I or to the inspection on 9/01/2	Removed	
Current Condition.	rtemoved - The sir	41°02'28.55"N			
STR	Streets	96°20'36.35"W	In Place	Active	No
Current Condition:	Good Condition - T Homes cleaned the	rademark Homes clean e streets at lot 153 prior	ed the street in front of Lot 5 to the inspection on 3/23/21.		
SWPPP Sign	SWPPP Sign	Two signs on site	8/8/2008	Active	No No
Current Condition:	Road entrance. The surrounding grass	e sign at the South Lake being mowed prior to ins over prior to inspection	at Iron Horse Drive and Hw eview Way and South Bend I spection on 7/02/19. The SW on 7/23/19. E&A inspector re	Road entrance was PPP sign by Hwy 6	visible again due to the and Iron Horse Drive

Certification Statement:	supervision in accor evaluated the inform those persons direc knowledge and belie	benalty of law, that this document and all attachments were prepared under my direction or accordance with a system designed to assure that qualified personnel properly gathered and information submitted. Based on my inquiry of the person or persons who manage the system or directly responsible for gathering the information, the information submitted is, to the best of my belief, true, accurate, and complete. I am aware that there are significant penalties for submitting in including the possibility of fines and imprisonment for knowing violations.	
Inspector Signature:	Mini	Reviewed By:	