E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Entire site; grading completed and stabilized prior to Spring 2005.

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

**Engineering Answers** Environmental Services Dept. Manager

Environmental Services Dept. M	lanager	E&A- P2006	056.001			
Inspector: Joe Manning		2071 1 2000			Stage	
Project Name:		Iron Horse CSW-201701133				
For Week Ending:		3/12/2022				
Project Location:	Hwv	Hwy 6 & Iron Horse Drive- Ashland, NE (Saunders County)				
			7.0, 1.2 (0.0			
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer: Paving:	100% 100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	72%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
Sunday	0.00"				Week 1	
Sunday: Monday	0.00"	2/14/2022	Sunny 39/21	2:15 PM		
Tuesday	0.00"	2:17/2022	Guilly 03/21	2.1011		
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				Wook 2	
Sunday:	0.00"				Week 2	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				Week 2	
Sunday:	0.00"				Week 3	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.60"					
Saturday	0.23"					
					Week 4	
Sunday:	0.00"					
Monday	0.01"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				Week 5	
Sunday:	N/A				vveek 5	
Monday	N/A					
Tuesday	N/A			1		
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
	<u> </u>	•		•	·	
Complaints:	None					
Construction Sequencing:						
Which portion(s) (i.e. drainage basins) o	f the site have had a tempora	ry or permanent cessation	on of grading, earthwork, or grou	and disturbance in the last	14 days?	

Nhat temporary or permanent stabilization measures listed in this section are being implemented?

Dense Vegetation, seeding/sodding, matting, re-seeding 5/2006, paving, and landscaping.

## Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

#### Yes

N/A

Are construction entrances and adjacent streets being maintained adequately?

No

No - See BMP Section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

### Comments:

### Comments:

Home construction is active on a few lots.

# Findings / Corrective Actions (Date):

### Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) A portable toilet was secured on Lot 30 prior to the inspection on 5/28/21. The portable toilet was unsecured prior to the inspection on 8/25/21. Ms. Suzanne Sapp (owner of 1630 East Ridge Way) was informed to complete by 9/08/21. Not done as of the last inspection. The portable toilet was removed prior to the inspection on 2/14/22.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
IF 1	Inlet	Lot 110	In Place	Active	No
Current Condition:	Active - This structure was previously referred to as a sediment basin, but is actually functioning as a slope drain/area inlet. As-of the 11/26/18 inspection, silt fence is in place behind the structure and straw wattles are located downhill from the outlet pipe.				
Lot 4 R IV	Silt Fence	Lot 4 R IV		Removed	
Current Condition:	Removed - Trademark Homes sodded the lot prior to the inspection on 5/11/21. The street in front of the lot was cleaned by rain prior to the inspection on 7/15/21. The disturbed area west of the lot has vegetated as of 7/15/21.				
Lot 6 R II	Silt Fence	Lot 6 R II		Removed	
Current Condition:			and removed the concrete w		
Lot 57	Silt Fence	Lot 57	6/1/2020	Active	No
Current Condition:	as of 10/05/20. The	e lot is currently vacant.	uction on the lot prior to the i	•	
Lot 61  Current Condition:	Silt Fence	Lot 61	9/28/2021 n construction on the lot prio	Active	No
Lot 82		removed the dirt pile fro	uilder was actively excavatin m the ROW and secured a p		
			nstruction on the lot prior to		
Current Condition:	installed silt fence a of silt fence along the front of the and from Lot 47 pri from Lot 47 pr	along the back side of the he front of the lot prior to the inspection or to the inspection on 1 the inspection on 1/17/2 eeds to be trenched in a port of the lot should be clong the front of the lot should be clong the lot sh	e lot prior to the inspection of the inspection on 8/25/21. Join on 9/28/21. Paradise Ho 0/14/21. Paradise Homes re 22.  Indeed a long the back a leaned. Hould be repaired/reinstalled.	on 5/28/21. Paradise Paradise Homes ex mes removed the dimoved the concrete and sides of the lot.	e Homes installed a run tended the silt fence irt pile from the ROW e waste from the lot and
	reminded on 6/25/2 2.) Paradise Home reminded on 8/27/2	21, 7/16/21, 8/27/21, 10/ s was informed to comp 21, 10/15/21, 12/22/21 s was informed to comp	ete by 6/04/21. Not done as 15/21, 12/22/21 ete by 7/22/21. Not done as ete by 9/01/21. Not done as	of the last inspection	on. Paradise Homes was

		الممير
Current Condition:	Fair Condition - Boyer Young repaired the silt fence on the lot prior to the 7/3/18 inspection. Boyer Young removement of the damaged silt fence and repaired the runs left in place prior to inspection on 7/02/19. As of the inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seeding is no longer required at this time. Boyer Young removed the damaged runs of silt fence from the lot prior to the inspection on 11/11/20. Lot was formerly identified as Lot 113. Some portions of the silt fence were loose from 1 posts during the inspection on 6/24/21. E&A inspector retied a portion of the silt fence during the inspection on 8/10/21. E&A inspector will make recommendations for the remainder of the loose portion of silt fence once the becomes active.	the t-
Lot 152	Individual Lot Lot 152 11/23/2021 Active Yes	
Current Condition:	Fair Condition - Citadel Homes began construction on the lot and installed silt fence along the back of the lot to the inspection on 11/23/21. A dirt pile was observed in the ROW during the current inspection; however, Cita Homes was actively excavating the lot during the inspection. E&A inspector will monitor and make recommendations as necessary. The E&A inspector retied portions of the silt fence during the inspection on 12/20/21.  The silt fence should be repaired/retied where loose along its length.	
	Citadel Hames was informed to complete by 2/04/20	
1 -4 455	Citadel Homes was informed to complete by 2/21/22.	
Lot 155	Silt Fence Lot 155 9/3/2018 Active Yes	
Current Condition:	Fair Condition - Widhalm Custom Homes installed silt fence on the lot to protect sodded lot 154 prior to inspect on 9/3/18.  The silt fence should be repaired or removed from the lot.  Widhalm Custom Homes was informed to complete by 12/14/20. Not done as of the last inspection. Widhalm	ion
	Custom Homes was reminded on 3/02/21, 6/25/21, 10/15/21	
Lot 156	Silt Fence Lot 155 9/3/2018 Active Yes	
Current Condition:	Pending - McCaul Homes began construction on the lot prior to the inspection on 9/28/21. McCaul Homes remo	havo
	the dirt pile from the ROW prior to the inspection on 10/14/21.  Silt fence should be installed along the back and east sides of the lot.  McCaul Homes was informed to complete by 10/05/21. Not done as of the last inspection. McCaul Homes was	
	reminded on 12/22/21	
Lot 184	Individual Lot Lot 184 11/23/2021 Active Yes	
Current Condition:	Fair Condition - Hubbell Homes began construction on the lot prior to the inspection on 11/23/21. Hubbell Ho	mes
	<ol> <li>1.) The dirt pile should be removed from the ROW of Lot 185.</li> <li>2.) The portable toilet should be secured.</li> <li>1.) E&amp;A will attempt to identify the builder. Not done as of the last inspection. Hubbell Homes was reminded of 2/15/22.</li> </ol>	on
	2.) Hubbell Homes was informed to complete by 2/21/22.	
Lot 186	Individual Lot Lot 186 Removed	
Current Condition:	Removed - Woodland Homes sodded the lot and removed the portable toilet prior to the inspection on 11/23/21	1.
Lot <b>194</b>	Individual Lot Lot 194 1/17/2022 Active No	
Current Condition:	Active - An unknown builder began construction on the lot prior to the inspection on 1/17/22. Due to vegetation the lot and the grade of the lot. No BMPs will be recommended at this time. E&A inspector will monitor.	on
PDP A	Permanent 41°02'43.47"N Detention Pond 96°20'36.65"W In Place Active No	
Current Condition:	Good Condition - This is a pond as of 1993.	-
SB 1	Sediment Basin Lot 109 Removed	$\neg$
Current Condition:	Removed - Following the 11/26/18 inspection, this structure is no longer being considered a basin as it does no	
Garront Gonation.		nt t
	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information	
SF 3	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence Lot 197 Removed	
Current Condition:	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	
Current Condition: SF 5	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	
Current Condition: SF 5 Current Condition:	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	
Current Condition: SF 5 Current Condition: SF 8	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	
Current Condition: SF 5 Current Condition:	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	
Current Condition: SF 5 Current Condition: SF 8 Current Condition:	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	
Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	n
Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	n
Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	n
Current Condition: SF 5  Current Condition: SF 8  Current Condition: SF 9  Current Condition:  SF 10  Current Condition: SF 10	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	n.
Current Condition: SF 5  Current Condition: SF 8  Current Condition: SF 9  Current Condition:  SF 10  Current Condition: STR  Current Condition:	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	n.
Current Condition: SF 5  Current Condition: SF 8  Current Condition: SF 9  Current Condition:  SF 10  Current Condition:  SF 10  SF 10  Current Condition:	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information  Silt Fence	n.

Current Condition:	d Condition - A sign has been installed at Iron Horse Drive and Hwy 6. South Lakeview Way & South Bend d entrance. The sign at the South Lakeview Way and South Bend Road entrance was visible again due to the ounding grass being mowed prior to inspection on 7/02/19. The SWPPP sign by Hwy 6 and Iron Horse Drive been knocked over prior to inspection on 7/23/19. E&A inspector reinstalled the downed SWPPP sign during ection on 7/23/19.		
Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.		
Inspector Signature:	Reviewed By:		