E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Zach Roza		E&A- P2000			Stage	
	Iron Horse					
Project Name:		CSW-202206238				
For Week Ending:		2	2/10/2024			
Project Location:	Hwy	Hwy 6 & Iron Horse Drive- Ashland, NE (Saunders County)				
Grading:	100%	1				
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	85%					
RAIN FALL AMOUNTS	Amount in tenths/Storm Duration	Date inspected	Weather Conditions	Time	Week [,]	
Sunday:	0.00"				Week	
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					
Sunday:	0.00"				Week 2	
Sunday: Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					
·					Week :	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					
	0.00"				Week 4	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.02"	2/7/2024	Cloudy 56 / 43	11:20 AM		
Thursday:	0.01"					
Friday:	0.00"					
Saturday:	0.00"					
Sunday:	N/A				Week	
Monday:	N/A					
Tuesday:	N/A	1				
Wednesday:	N/A					
Thursday:	N/A					
Friday:	N/A					
Saturday:	N/A				<u> </u>	
	I.					
Complaints:	None					

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; grading completed and stabilized prior to Spring 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Dense Vegetation, seeding/sodding, matting, re-seeding 5/2006, paving, and landscaping.

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No

Create Corrective Action?

No, See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

NIO

Create Corrective Action?

No - See BMP Section.

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMP Section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

1.) Home construction is active on a few lots.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
IF 1	Inlet	Lot 110	In Place	Active	No	
Current Condition:	Active - This structure was previously referred to as a sediment basin, but is actually functioning as a slope					
	drain/area inlet. As-of the 11/26/18 inspection, silt fence is in place behind the structure and straw wattles are					
	located downhill fro					
Lot 25	Individual Lot	Lot 25		Removed		
Current Condition:	Removed - Marque	Removed - Marque Custom Homes sodded the lot prior to the inspection on 12/18/23.				
Lot 33	Individual Lot	Lot 33		Removed		
Current Condition:	Removed - The lot	Removed - The lot was sodded prior to the inspection on 12/18/23.				
Lot 47	Individual Lot	Lot 47	12/14/2022 In construction on the lot price	Active	Yes	
	Chapter Homes se	<mark>cured a portable toilet o</mark>	ncrete waste from the lot prion the lot prion to the inspection on 7/04/23. Now Chapter H	on on 2/14/23. New	on 1/03/23. New Chapter Homes sto	
	Chapter Homes se up the portable toile the inspection on 7 8/09/23. New Chap The areas adjoining removed.	cured a portable toilet of et prior to the inspection //12/23. New Chapter Hoter Homes sodded the g the lot disturbed for comes was informed to come		on on 2/14/23. New omes resecured the bilet on the lot prior 8/28/23. led and construction	on 1/03/23. New Chapter Homes store portable toilet prior to the inspection on a debris should be	
Lot 57	Chapter Homes setup the portable toild the inspection on 7 8/09/23. New Chapter Homes adjoining removed. New Chapter Homes setup the portable to the portable	cured a portable toilet of et prior to the inspection //12/23. New Chapter Hoter Homes sodded the g the lot disturbed for comes was informed to come	n the lot prior to the inspection on 7/04/23. New Chapter Homes resecured a portable to lot prior to the inspection on onstruction should be stabilized.	on on 2/14/23. New omes resecured the bilet on the lot prior 8/28/23. led and construction	Chapter Homes sto e portable toilet prior to the inspection on n debris should be	
Lot 57 Current Condition:	Chapter Homes secup the portable toile the inspection on 7 8/09/23. New Chapter Homes was remind Silt Fence Active - An unknown	cured a portable toilet of et prior to the inspection //12/23. New Chapter Hoter Homes sodded the g the lot disturbed for college was informed to comded on 11/22/23. Lot 57	n the lot prior to the inspection on 7/04/23. New Chapter Homes resecured a portable to lot prior to the inspection on enstruction should be stabilized plete by 9/04/23. Not done a 6/1/2020 uction on the lot prior to the	on on 2/14/23. New omes resecured the older on the lot prior 8/28/23. ed and construction of the last inspective. Active	on 1/03/23. New Chapter Homes store portable toilet prio to the inspection on a debris should be tion. New Chapter	

Current Condition:	Good Condition - Boyer Young repaired the silt fence on the lot prior to the 7/3/18 inspection. Boyer Young removed some of the damaged silt fence and repaired the runs left in place prior to inspection on 7/02/19. As of the inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seeding is no longer required at this time. Boyer Young removed the damaged runs of silt fence from the lot prior to the inspection on 11/11/20. Lot was formerly identified as Lot 113. Some portions of the silt fence were loose from the t-posts during the inspection on 6/24/21. E&A inspector retied a portion of the silt fence during the inspection on 8/10/21. E&A inspector will make recommendations for the remainder of the loose portion of silt fence once the lot becomes active.				
Lot 2 R VI	Individual Lot	Lot R VI	10/4/2023	Active	Yes
Current Condition:	Fair Condition - An unknown contractor began excavation on the lot prior to the inspection on 10/04/23. Due to the grade of the lot and vegetation, no BMPs will be recommended at this time. Malibu Homes installed and secured a portable toilet prior to the inspection on 11/8/23. Malibu Homes installed silt fence along the back of the lot prior to the inspection on 11/22/23. Adjacent streets should be cleaned. Malibu Homes was informed to complete by 2/8/24.				
Lot 152	Individual Lot	Lot 152	L	Removed	
Current Condition:	to the inspection of Concrete waste re	n 5/19/23. Citadel Home moval recommendations	prior to the inspection on 10/es removed the silt fence from s will be made once Lot 151	n the lot prior to the becomes active.	e inspection on 6/02/23.
Lot 155	Silt Fence	Lot 155	9/3/2018	Active	No
Current Condition:	on 9/3/18. Silt fenerecommend repair	ce recommendations will s once lot becomes dist		28/23. E&A inspect	or will monitor and
Lot 175	Individual Lot	Lot 175	10/2/2023	Active	No
Current Condition:	of the lot and activ	re excavation, no BMPs	avation on the lot prior to the will be recommended at this	time. E&A inspecto	or will monitor.
Lot 176	Individual Lot	Lot 176	10/2/2023	Active	No
Current Condition:	of the lot and active secured a portable	re excavation, no BMPs toilet prior to the inspec		time. Gateway Hor	mes installed and
Lot 177	Individual Lot	Lot 177	4/12/2023	Active	No
Current Condition:	Active - Gateway		on on the lot prior to the insp		
Lot 178	Individual Lot	Lot 178		Removed	
Current Condition:			t prior to the inspection on 1		
Lot 179	Individual Lot	Lot 179		Removed	
Current Condition: Lot 180	Individual Lot	ay Homes sodded the lo	t prior to the inspection on 1	1/10/23. Removed	
Current Condition:			I of prior to the inspection on 1		
Lot 181	Individual Lot	Lot 181	T prior to the inspection on t	Removed	
Current Condition:			t prior to the inspection on 1		
Lot 182	Individual Lot	Lot 182	3/17/2023	Active	Yes
Current Condition:			enstruction on the lot prior to		
	observed in the ROW during the inspection on 3/17/23. A portable toilet was on the lot during the inspection on 3/17/23. JD Builders, Inc. removed the dirt pile from the ROW prior to the inspection on 4/12/23. JD Builders, Inc. stood up the portable toilet prior to the inspection on 4/17/23. JD Builders, Inc. cleaned the street along the lot prior to the inspection on 6/29/23. JD Builders, Inc. secured the portable toilet prior to the inspection on 11/10/23 1.) The street along the lot should be cleaned. 2.) Concrete waste should be removed from the lot and surrounding streets. 1.) JD Builders, Inc. was informed to complete by 8/10/23. Not done as of the last inspection. JD Builders, Inc. was reminded on 11/22/23. 2.) JD Builders, Inc. was informed to complete by 11/29/23. Not done as of the last inspection.				
Lot 183	Individual Lot	Lot 183	Laboratoria de la compansión de la compa	Removed	
Current Condition: Lot 185	Removed - David Individual Lot	A.D. Homes Inc. sodded Lot 185	I the lot prior to the inspectio	n on 11/10/23. Removed	
Current Condition:			I or to the inspection on 11/22		
Lot 190	Individual Lot	Lot 190	8/28/2023	Active	Yes
Current Condition:	Fair Condition - An unknown contractor disturbed the lot prior to the inspection on 8/28/23. Homeowner removed the concrete waste from the lot prior to the inspection on 11/22/23. Homeowner installed and secured a portable toilet on the lot prior to the inspection on 12/27/23. Homeowner installed silt fence along the rear and east side of the lot prior to the inspection on 1/10/24. Homeowner installed silt fence along the majority of the front of the lot prior to the inspection on 2/7/24. Silt fence along the front of the lot should be repaired. Homeowner was informed to complete by 2/14/24.				
1			•	A (
Lot 195	Individual Lot	Lot 195	12/18/2023	Active	Yes

Current Condition:		Fair Condition - An unknown contractor began construction on the lot, secured a portable toilet and installed silt fence along the back of the lot prior to the inspection on 12/18/23.				
		1.) Straw wattles should be installed along the front of the lot.				
	2.) Adjacent streets should be cleaned. 1.) MK Builders was informed to complete by 2/14/24.					
	2.) MK Builders w	as informed to comple	ete by 2/8/24.			
Lot 199	Individual Lot	Lot 199		Removed		
Current Condition:		Removed - MK Builders sodded the lot prior to the inspection on 11/22/23.				
Lot 200	Individual Lot	Lot 200		Removed		
Current Condition:			prior to the 8/14/23 inspection	n.		
	Permanent	41°02'43.47"N				
PDP A	Detention Pond	96°20'36.65"W	In Place	Active	No	
Current Condition:		his is a pond as of 1993	3.			
SB 1	Sediment Basin	Lot 109	<u> </u>	Removed		
Current Condition:			ion, this structure is no longe			
	have any sedimen	t storage capacity and a	ppears to be an area inlet/sl	ope drain. See IF 1	for further information.	
SF 3	Silt Fence	Lot 197		Removed		
Current Condition:			ence during the inspection o			
SF 5	Silt Fence	South side of lake		Removed		
Current Condition:			ence during the inspection o			
SF 8	Silt Fence	40' South of SF 5		Removed		
Current Condition:	Removed- the insp		ence during the inspection o	n 3/22/17.		
		East of Lots 119 and				
SF 9	Silt Fence	120	In Place	Active	No No	
Current Condition:		Good Condition - Boyer Young repaired and partially removed the silt fence prior to inspection on 12/5/17. The				
SF 10	Silt Fence	Behind Lot 190		Removed		
Current Condition:	Removed - The SII	41°02'28.55"N	or to the inspection on 9/01/	Z1.	I	
STR	Streets	96°20'36.35"W	In Place	Active	No	
Current Condition:			ed the street in front of Lot 5			
SWPPP Sign	SWPPP Sign	Three signs on site	8/8/2008	Active	No No	
Current Condition:		Good Condition - A sign has been installed at Iron Horse Drive and Hwy 6. South Lakeview Way & South Bend				
	Road entrance. The sign at the South Lakeview Way and South Bend Road entrance was visible again surrounding grass being mowed prior to inspection on 7/02/19. The SWPPP sign by Hwy 6 and Iron Ho					
			•	0 , ,		
	had been knocked over prior to inspection on 7/23/19. E&A inspector reinstalled the downed SWPPP sign du					
	inspection on 7/23/19. E&A inspector installed a SWPPP sign in the parking lot of the Iron Horse Clubl				n Horse Clubhouse on	
	6/06/22.					
0416141	[]	-166 414 41-1- 1			n many alima asti a re	
Certification Statement:			ument and all attachments w			
			esigned to assure that quali			
			d on my inquiry of the personering the information, the inf			
		knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.				
	iaise illioilliation ir	iolading the possibility o	i inies and imprisoninent for	MIOWING VIOLATIONS	·	
	1 .2				Posts Sul	
Inspector Signature:	3 h Ry			Reviewed By:	Sits De	
Inspector Signature:		l .		nevieweu by:		