E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

| | | E&A- P2006 | .056.001 | | | |
|---------------------------|------------------------------|---|----------------------|----------|---------------------|--|
| Inspector: Zach Roza | | | | | Stage | |
| Project Name: | Iron Horse CSW-202206238 | | | | 1 | |
| For Week Ending: | | | | | | |
| Project Location: | Hwy | Hwy 6 & Iron Horse Drive- Ashland, NE (Saunders County) | | | | |
| Grading: | 100% | I | | 1 | 1 | |
| Sanitary Sewer: | 100% | | | | | |
| Storm Sewer: | 100% | | | | | |
| Paving: | 100% | | | | | |
| Seeding: | 100% | | | | | |
| Utilities: | 100% | | | | | |
| Overall Development: | 85% | | | | | |
| RAIN FALL AMOUNTS Sunday: | tenths/Storm Duration 0.45" | Date inspected | Weather Conditions | Time | 9:35 PM - 12:00 AM | |
| | 0.450 | | | | | |
| Monday: | 0.01" | | | | 3.33 1 W - 12.00 AW | |
| Tuesday: | 0.01 | 5/14/2024 | Mostly Sunny 76 / 49 | 1:50 PM | | |
| Wednesday: | 0.92" | 5/15/2024 | Cloudy 73 / 60 | 10:15 AM | 4:35 PM - 5:55 PM | |
| Thursday: | 0.00" | 0/10/2024 | Cloudy 10 7 00 | 10.1074 | 4.001 111 0.001 111 | |
| Friday: | 0.00" | | | | | |
| Saturday: | 0.00" | | | | | |
| Complaints: | None | | | | | |
| | | | | | | |
| Construction Sequencing: | | | | | | |

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; grading completed and stabilized prior to Spring 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Dense Vegetation, seeding/sodding, matting, re-seeding 5/2006, paving, and landscaping.

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No

Create Corrective Action?

No, See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMP Section.

Is dust associated with the construction activity adequately controlled on the site?

| Yes | | | | | | |
|--|--|---------------------------|---|--|--|--|
| Create Corrective Action? | | | | | | |
| N/A | | | | | | |
| Comments: | | | | | | |
| Comments: | | | | | | |
| 1.) Home construction is active on a fev | w lots. | | | | | |
| Findings / Corrective Actions (Date): | | | | | | |
| Findings / Corrective Actions (Date): | | | | | | |
| 1.) Some maintenance is required in the | | . lat 05 ab and 1 b a man | and Marrier Oracles Harris | | | |
| 2.) Lot 24 should be stabilized and condone as of the last inspection. | struction debris from | 1 lot 25 should be remov | /ed. Marque Custom Homes | was informed to co | omplete by 4/1/24. Not | |
| 3.) Project will be treated as a stage | 1 with weekly insp | ections as of 5/15/24. | | | | |
| | | | | | | |
| Unique Name | Туре | Location | Projected Install Date | Status | Maintenance | |
| IF 1 | Inlet | Lot 110 | In Place | Active | No | |
| Current Condition: | | | rred to as a sediment basin, | | | |
| | located downhill fro | • | tion, silt fence is in place bel | iind the structure a | nu straw watties are | |
| Lot 1 | Individual Lot | Lot 1 | 4/26/2024 | Active | No | |
| Current Condition: | | | avation on the lot prior to the | | | |
| | | | this time. E&A inspector will | monitor and make | recommendations when | |
| 1 = 4 2 | the builder is ider | | 1 4/00/0004 | A ative | l Na | |
| Lot 2 Current Condition: | Individual Lot | Lot 2 | 4/26/2024 eavation on the lot prior to the | Active | No N | |
| Current Condition. | | | this time. E&A inspector will | | | |
| | the builder is iden | ntified. | <u> </u> | | | |
| Lot 33 | Individual Lot | Lot 33 | | Removed | | |
| Current Condition: Lot 47 | Removed - The lot Individual Lot | was sodded prior to the | e inspection on 12/18/23. 12/14/2022 | Active | Yes | |
| Current Condition: | | | an construction on the lot price | | | |
| | grade of the lot, no BMPs will be recommended at this time. New Chapter Homes removed the dirt pile from the | | | | | |
| | ROW, cleaned the street, and removed concrete waste from the lot prior to the inspection on 1/03/23. New | | | | | |
| | Chapter Homes secured a portable toilet on the lot prior to the inspection on 2/14/23. New Chapter Homes stood up the portable toilet prior to the inspection on 7/04/23. New Chapter Homes resecured the portable toilet prior to | | | | | |
| | the inspection on 7/12/23. New Chapter Homes resecuted a portable toilet on the lot prior to the inspection on 8/09/23. New Chapter Homes sodded the lot prior to the inspection on 8/28/23. The areas adjoining the lot disturbed for construction should be stabilized and construction debris should be removed. | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | New Chapter Hom | es was informed to com | plete by 9/04/23. Not done a | s of the last inspec | tion. New Chapter | |
| | Homes was remine | ded on 11/22/23, 3/8/24 | , 5/10/24. | | | |
| Lot 57 | Silt Fence | Lot 57 | 6/1/2020 | Active | No | |
| Current Condition: | | | ruction on the lot prior to the | inspection on 6/01/ | 20. The lot has | |
| L | | /05/20. The lot is curren | | Active | Vaa | |
| Lot 1 R VI Current Condition: | Silt Fence | | 8/17/2017 silt fence on the lot prior to t | | Yes n. Bover Young removed | |
| Current Condition. | | , , , | ed the runs left in place prior | The second secon | , | |
| | inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seeding is no | | | | | |
| | longer required at this time. Boyer Young removed the damaged runs of silt fence from the lot prior to the | | | | | |
| | inspection on 11/11/20. Lot was formerly identified as Lot 113. Some portions of the silt fence were loose from the t-posts during the inspection on 6/24/21. E&A inspector retied a portion of the silt fence during the inspection on | | | | | |
| | | | the lot prior to the inspection | | aring the inspection on | |
| | | J | ' ' | | | |
| | Adjacent streets st | nould be cleaned. | | | | |
| | Homoownor was in | oformed to complete by | E/2/24 Not done so of the la | et inapaction | | |
| | Homeowner was in | normed to complete by | 5/3/24. Not done as of the la | ist inspection. | | |
| Lot 2 R VI | Individual Lot | Lot 2 R VI | 10/4/2023 | Active | Yes | |
| Current Condition: | | | gan excavation on the lot pr | | | |
| | grade of the lot and vegetation, no BMPs will be recommended at this time. Malibu Homes installed and secured a portable toilet prior to the inspection on 11/8/23. Malibu Homes installed silt fence along the back of the lot prior | | | | | |
| | | | es cleaned the streets prior | | | |
| | along the back of t | he lot was partially dam | aged/collapsed prior to the i | nspection on 4/26/2 | 24. | |
| Ī. | | | | | | |

The silt fence along the back of the lot should be cleaned out and repaired where damaged.

Malibu Homes was informed to complete by 5/9/24. Not done as of the last inspection.

Lot 34

5/2/2024

Yes

Active

Lot 34

Individual Lot

| Current Condition: | Pending - Dirt from | ı lot 1 R VI was being st | ockpiled on the lot during the | e 5/2/24 inspection. | |
|-------------------------------|---|--|--|-----------------------|---|
| | | | | | |
| | Dirt pile should be meantime. | removed from the lot ar | nd silt fence should be install | ed around the perir | neter of the lot in the |
| | meantime. | | | | |
| | Homeowner of lot | 1 R VI was informed to | complete by 5/9/24. Not don | e as of the last ins | spection. |
| Lot 61 | Individual Lot | Lot 61 | 5/2/2024 | Active | No |
| Current Condition: | | | vation on the lot prior to the | | |
| | | | s of the lot prior to the inspec | ction on 5/2/24. Hor | neowner installed and |
| | | <u> </u> | to the inspection on 5/2/24. | | |
| Lot 152 Current Condition: | Individual Lot | Lot 152 | prior to the inspection on 10 | Removed | a north atabilized prior |
| Current Condition. | | | es removed the silt fence from | | |
| | • | | s will be made once Lot 151 | • | , |
| Lot 155 | Silt Fence | Lot 155 | 9/3/2018 | Active | Yes |
| Current Condition: | | | led silt fence on the lot to pro | | |
| | | | o longer be made as of 8/28/2 ction on 5/14/24. Gateway 0 | | |
| | | | he inspection on 5/15/24. | Justom Homes Ten | noved the shi lence |
| | ŭ | · | | | |
| | | ld be removed from th | | | |
| | | ıld be re-installed alon ıld be installed along t | g the south side of the lot. | | |
| | 3.) Silt leffce shot | ilu be ilistalled along t | the real of the lot. | | |
| | 1.) Gateway Custo | om Homes was inform | ed to complete by 5/22/24. | | |
| | | | ed to complete by 5/22/24. | | |
| 1.1475 | | | ed to complete by 5/22/24. | A saline | N : |
| Lot 175 Current Condition: | Individual Lot | Lot 175 | 10/2/2023 cavation on the lot prior to the | Active | No No No No No No No No No No No No No N |
| Current Condition. | | | will be recommended at this | | |
| | | | | • | |
| Lot 176 | Individual Lot | Lot 176 | 10/2/2023 | Active | No |
| Current Condition: | | | cavation on the lot prior to the | | |
| | | toilet prior to the inspec | will be recommended at this ction on 11/10/23 | line. Galeway noi | nes installed and |
| Lot 177 | Individual Lot | Lot 177 | 4/12/2023 | Active | No |
| Current Condition: | | lomes began constructi | on on the lot prior to the insp | | |
| Lot 178 | Individual Lot | Lot 178 | <u> </u> | Removed | |
| Current Condition: Lot 179 | Individual Lot | Lot 179 | ot prior to the inspection on 1 | Removed | |
| Current Condition: | | | ot prior to the inspection on 1 | | |
| Lot 180 | Individual Lot | Lot 180 | | Removed | |
| Current Condition: Lot 181 | Removed - Gatewa Individual Lot | ay Homes sodded the lo | ot prior to the inspection on 1 | 1/10/23. Removed | |
| Current Condition: | | | ot prior to the inspection on 1 | | |
| Lot 182 | Individual Lot | Lot 182 | 3/17/2023 | Active | No |
| Current Condition: | | | construction on the lot prior t | | |
| | observed in the ROW during the inspection on 3/17/23. A portable toilet was on the lot during the inspection on 3/17/23. JD Builders, Inc. removed the dirt pile from the ROW prior to the inspection on 4/12/23. JD Builders, Inc. | | | | |
| | stood up the portable toilet prior to the inspection on 4/17/23. JD Builders, Inc. cleaned the street along the lot | | | | |
| | 1. | | ders, Inc. secured the portal | • | • |
| | JD Builders cleane to the inspection or | • | e prior to the inspection on 3 | /6/24. JD Builders o | leaned the streets prior |
| 1.1.100 | | | 1 | Dem | |
| Lot 183 | Individual Lot | Lot 183 | I the lot prior to the inspection | Removed | |
| Current Condition: Lot 185 | Individual Lot | Lot 185 | a the lot prior to the inspection | Removed | |
| Current Condition: | | | or to the inspection on 11/22 | | |
| Lot 190 Current Condition: | Individual Lot | Lot 190 | 8/28/2023 | Active | Yes Hamasurar ramayad |
| Current Condition: | | | sturbed the lot prior to the instance inspection on 11/22/23. Ho | | |
| | | the state of the s | 2/27/23. Homeowner installe | | |
| | | | Homeowner installed silt fend | e along the majority | of the front of the lot |
| | prior to the inspect | ion on 2/7/24. | | | |
| | 1.) Silt fence along | the front and side of the | e lot should be repaired. | | |
| | Silt fence along the front and side of the lot should be repaired. Silt fence along the rear of the lot should be repaired. | | | | |
| | | | | | |
| | | | by 2/14/24. Not done as of t | ne last inspection. I | Homeowner was |
| | reminded on 3/15/24, 3/29/24, 5/10/24. 2.) Homeowner was informed to complete by 4/1/24. Not done as of the last inspection. Homeowner was reminded on 5/10/24. | | | | omeowner was |
| | | | | | |
| Lot 195 | Individual Lot | Lot 195 | 12/18/2023 | Active | Yes |
| | | | | | |

| Current Condition: | Fair Condition - An unknown contractor began construction on the lot, installed a portable toilet and installed silt fence along the back of the lot prior to the inspection on 12/18/23. MK Builders cleaned the streets prior to the inspection on 5/14/24. | | | | | | |
|---|--|--|---|--|---|--|--|
| | 1.) Straw wattles sl | 1.) Straw wattles should be installed along the front of the lot. | | | | | |
| | | | uld be repaired where dama | ged. | | | |
| | 3.) The portable to | The portable toilet on the lot should be secured. MK Builders was informed to complete by 2/14/24. Not done as of the last inspection. MK Builders was reminded on 3/15/24, 4/17/24, 5/17/24. | | | | | |
| | | | | | | | |
| | | 2.) MK Builders was informed to complete by 4/24/24. Not done as of the last inspection. MK Builders was | | | | | |
| | reminded on 5/17/24. | | | | | | |
| | 3.) MK Builders w | as informed to comple | • | | | | |
| Lot 196 | Individual Lot | Lot 196 | 5/7/2024 | Active | No | | |
| Current Condition: | | • | vation on the lot prior to the the inspection on 5/7/24. | inspection on 5/7/24 | 4. MK Builders installed | | |
| Lot 199 | Individual Lot | Lot 199 | | Removed | | | |
| Current Condition: | Removed - MK Bui | lders sodded the lot prid | or to the inspection on 11/22 | 2/23. | • | | |
| Lot 200 | Individual Lot | Lot 200 | | Removed | | | |
| Current Condition: | | | prior to the 8/14/23 inspection | on. | | | |
| | Permanent | 41°02'43.47"N | | | | | |
| PDP A | Detention Pond | 96°20'36.65"W | In Place | Active | No | | |
| Current Condition: | | his is a pond as of 1993 | 3. | T | T | | |
| SB 1 Current Condition: | Sediment Basin | Lot 109 | I ion, this structure is no long | Removed | 1 - 1 : : | | |
| | have any sediment | storage capacity and a | ppears to be an area inlet/s | lope drain. See IF 1 | | | |
| SF 3 | Silt Fence | Lot 197 | <u> </u> | Removed | | | |
| Current Condition: | | ector removed the silt for South side of lake | ence during the inspection of | | | | |
| SF 5 | Silt Fence | South side of take | | | | | |
| | Damasusal Aba inam | | | Removed | | | |
| Current Condition: | | ector removed the silt fe | I ence during the inspection o | on 3/22/17. | <u> </u> | | |
| Current Condition: SF 8 | Silt Fence | ector removed the silt for 40' South of SF 5 | | on 3/22/17. Removed | | | |
| Current Condition: | Silt Fence | ector removed the silt for 40' South of SF 5 ector removed the silt for the silt fo | I ence during the inspection of bence during the inspection of I | on 3/22/17. Removed | | | |
| Current Condition: SF 8 | Silt Fence Removed- the insp | ector removed the silt for 40' South of SF 5 | ence during the inspection of | on 3/22/17. Removed on 3/22/17. | No | | |
| Current Condition: SF 8 Current Condition: SF 9 | Silt Fence Removed- the insp | ector removed the silt fe 40' South of SF 5 ector removed the silt fe East of Lots 119 and 120 | ence during the inspection o | on 3/22/17. Removed on 3/22/17. Active | | | |
| Current Condition: SF 8 Current Condition: | Silt Fence Removed- the insp | ector removed the silt fe 40' South of SF 5 ector removed the silt fe East of Lots 119 and 120 | ence during the inspection of | on 3/22/17. Removed on 3/22/17. Active | | | |
| Current Condition: SF 8 Current Condition: SF 9 Current Condition: | Silt Fence Removed- the insp Silt Fence Good Condition - E Silt Fence | ector removed the silt fe 40' South of SF 5 ector removed the silt fe East of Lots 119 and 120 Boyer Young repaired ar Behind Lot 190 | ence during the inspection o | n 3/22/17. Removed on 3/22/17. Active fence prior to inspec | | | |
| Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 10 | Silt Fence Removed- the insp Silt Fence Good Condition - E Silt Fence | ector removed the silt fe 40' South of SF 5 ector removed the silt fe East of Lots 119 and 120 Boyer Young repaired ar Behind Lot 190 | ence during the inspection of the line of | n 3/22/17. Removed on 3/22/17. Active fence prior to inspec | | | |
| Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: SF 17 | Silt Fence Removed- the insp Silt Fence Good Condition - E Silt Fence Removed - The silt Streets | ector removed the silt fe 40' South of SF 5 ector removed the silt fe East of Lots 119 and 120 soyer Young repaired ar Behind Lot 190 tence was removed pri 41°02'28.55"N 96°20'36.35"W | In Place In place In place In place In place In partially removed the silt In place In partially removed the silt In place | n 3/22/17. Removed n 3/22/17. Active fence prior to inspect Removed /21. Removed | | | |
| Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: | Silt Fence Removed- the insp Silt Fence Good Condition - E Silt Fence Removed - The silt Streets Removed- Streets | ector removed the silt fe 40' South of SF 5 ector removed the silt fe East of Lots 119 and 120 eoyer Young repaired ar Behind Lot 190 I fence was removed pri 41'02'28.55"N 96'20'36.35"W E will be tracked on a lot | In Place In partially removed the silt or to the inspection on 9/01. | n 3/22/17. Removed n 3/22/17. Active fence prior to inspect Removed /21. Removed 4. | ction on 12/5/17. The | | |
| Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign | Silt Fence Removed- the insp Silt Fence Good Condition - E Silt Fence Removed - The silt Streets Removed- Streets SWPPP Sign | ector removed the silt fe 40' South of SF 5 ector removed the silt fe East of Lots 119 and 120 soyer Young repaired ar Behind Lot 190 tence was removed pri 41"02"28.55"N 96"20"36.35"W will be tracked on a le Three signs on site | In Place In partially removed the silt or to the inspection on 9/01. or to by lot basis as of 5/17/2. 8/8/2008 | nn 3/22/17. Removed nn 3/22/17. Active fence prior to inspect Removed //21. Removed 4. Active | ction on 12/5/17. The | | |
| Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: | Silt Fence Removed- the insp Silt Fence Good Condition - E Silt Fence Removed - The silt Streets Removed- Streets SWPPP Sign Good Condition - A Road entrance. Th surrounding grass had been knocked | ector removed the silt fe 40' South of SF 5 ector removed the silt fe East of Lots 119 and 120 Boyer Young repaired ar Behind Lot 190 fence was removed pri 41"02'28.55"N 96"20'36.35"W swill be tracked on a le Three signs on site a sign has been installed e sign at the South Lake being mowed prior to in over prior to inspection | In Place In partially removed the silt or to the inspection on 9/01. | n 3/22/17. Removed n 3/22/17. Active fence prior to inspec Removed /21. Removed 4. Active wy 6. South Lakevie Road entrance was WPPP sign by Hwy reinstalled the dowr | No Way & South Bend s visible again due to tl 6 and Iron Horse Drive hed SWPPP sign durin | | |
| Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign | Silt Fence Removed- the insp Silt Fence Good Condition - E Silt Fence Removed - The silt Streets Removed- Streets SWPPP Sign Good Condition - A Road entrance. Th surrounding grass had been knocked inspection on 7/23, 6/06/22. I certify, under pen supervision in acco evaluated the infor those persons dire knowledge and bel | ector removed the silt fe 40' South of SF 5 ector removed the silt fe East of Lots 119 and 120 Boyer Young repaired ar Behind Lot 190 fence was removed pri 41'02'28.55"N 96'20'36.35"W swill be tracked on a le Three signs on site a sign has been installed e sign at the South Lake being mowed prior to in over prior to inspection '19. E&A inspector instal alty of law, that this doc ordance with a system d mation submitted. Base ctly responsible for gath ief, true, accurate, and | In Place In | n 3/22/17. Removed n 3/22/17. Active fence prior to inspect Removed /21. Removed 4. Active wy 6. South Lakevie Road entrance was WPPP sign by Hwy reinstalled the dowr arking lot of the Iror were prepared under iffied personnel propon or persons who more the significant in th | No W Way & South Bend s visible again due to the Gand Iron Horse Driven on Horse Clubhouse on the Toron or perly gathered and nanage the system or dis, to the best of my penalties for submitting penalties for submitting | | |