

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

| E&A - P2019.032.000 | | | | | | | |
|--|--|----------------|--------------------|--------------|------------------|--|--|
| Inspector: Bryce Wright | | | | | Stage | | |
| Project Name: | Kempten Creek 2 CSW-202106167 | | | | 1 | | |
| For Week Ending: | 10/21/2023 | | | | | | |
| Project Location: | North 168th Street and Bennington Road - Bennington, NE (Douglas County) | | | | | | |
| | North Tooth Street a | | | gias county) | 68007 | | |
| Grading | 100% | | | | | | |
| Grading: Sanitary Sewer: | 100% | | | | | | |
| | | | | | | | |
| Storm Sewer: | <u>60%</u> | | | | | | |
| Paving: | 0% | | | | | | |
| Seeding: | 40% | | | | | | |
| Utilities: | 0% | | | | | | |
| Overall Development: | 15% | | | | | | |
| | | • | | | | | |
| RAIN FALL AMOUNTS | Amount in tenths | Date inspected | Weather Conditions | Time | Storm event time | | |
| | | | | | Week 1 | | |
| Sunday: | 0.00" | | | | | | |
| Monday | 0.00" | | | | | | |
| Tuesday | 0.00" | 10/17/2023 | Sunny 38 | 12:20 PM | | | |
| Wednesday | 0.01" | | | | | | |
| Thursday | 0.00" | | | | | | |
| Friday | 0.00" | | | | | | |
| Saturday | 0.00" | | | | | | |
| | | | | | | | |
| Complaints: | | | | | | | |
| | | | | | | | |
| Construction Sequencing: Which portion(s) (i.e. drainage basin last 14 days? | | | | | | | |
| Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). | | | | | | | |
| Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? | | | | | | | |
| Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). | | | | | | | |
| What temporary or permanent stabilization measures listed in this section are being implemented? | | | | | | | |
| Existing Vegetation (11/29/22). | | | | | | | |
| | | | | | | | |
| Checklist Questions: | | | | | | | |
| Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? | | | | | | | |
| Yes | | | | | | | |
| Create Corrective Action? | | | | | | | |
| N/A | | | | | | | |
| | | | | | | | |
| Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. | | | | | | | |
| Yes | | | | | | | |
| Create Corrective Action? | | | | | | | |
| N/A | | | | | | | |
| Are waste materials (concrete, construction n | naterial, hazardous, etc.) heing man | aged properly? | | | | | |
| Yes | inter a cab, etc., wornig man | | | | | | |

| Create Corrective Action? | | | | | | |
|---------------------------------------|---|---|----------------------------|----------------------|---------------------|--|
| N/A | | | | | | |
| | | | | | | |
| | t streets being maintained adequately? | | | | | |
| 0 | | | | | | |
| reate Corrective Action? | | | | | | |
| lo, See BMP section | | | | | | |
| dust associated with the construction | activity adequately controlled on the sit | te? | | | | |
| /es | | | | | | |
| reate Corrective Action? | | | | | | |
| 1/A | | | | | | |
| | | | | | | |
| Comments: | | | | | | |
| Comments: | | | | | | |
| | er installation during the last inspe | ction. | | | | |
| Findings / Corrective Actions (E | | | | | | |
| Findings / Corrective Actions (| | | | | | |
| 1.) Some maintenance is required | I in the BMP section at this time. | | | | | |
| | | T | 1 | r | T | |
| Unique Name | Туре | Location | Projected Install Date | Status | Maintenance | |
| CE 1 | Construction Entrance | X-11 | 11/4/2022 | Pending | Yes | |
| Current Condition: | Pending - Site is being acce | ssed through Morgan Ri | dge as of 6/27/23. No cons | truction entrance is | needed at this time | |
| | | | | | | |
| | Construction entrance sho | ould be installed. | | | | |
| | K2 Construction was infor | med to complete by 40 | NO 4/00 | | | |
| | K2 Construction was infor | med to complete by 10 | 1/24/23. | | | |
| D1 | Diversion | D-8 to K-8 | 5/23/2023 | Active | No | |
| Current Condition: | Good Condition - HRC Deve | | | | | |
| D2 | | East of SB B | 5/23/2023 | Active | Yes | |
| Current Condition: | Diversion | | | | | |
| Current Condition. | Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. K2 Construction remove sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23. Diversion should be reinstalled where removed for sanitary installation. K2 Construction was informed to complete by 9/19/23. Not done as of the last inspection. K2 Construction was | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | reminded on 10/18/23 | | | | | |
| D3 | Diversion | Southeast of SB A | 5/23/2023 | Active | Yes | |
| Current Condition: | | | | | | |
| | Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. Diversion should be extended east across Kempten Creek Drive to prevent sediment from washing onto the | | | | | |
| | | | | | | |
| | street. | | | | | |
| | | | | | | |
| | K2 Construction was infor | med to complete by 10 | /24/23. | | | |
| D4 | Diversion | South of SB A | 5/23/2023 | Active | Yes | |
| Current Condition: | Fair Condition - HRC Develo | | | | instruction removed | |
| | sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23. | | | | | |
| | Diversion should be reinstalled where removed for sanitary installation. | | | | | |
| | | | | | | |
| | | | | | | |
| | | K2 Construction was informed to complete by 9/19/23. Not done as of the last inspection. K2 Construction was reminded on 10/18/23 | | | | |
| ET 1 | Erosion Control Terraces | B-9 to G-10 | 6/6/2023 | Active | No | |
| Current Condition: | Good Condition - HRC Deve | | | | | |
| ET 2 | Erosion Control Terraces | B-9 to I-10 | 6/6/2023 | Active | No | |
| Current Condition: | Good Condition - HRC Deve | | | | | |
| ET 3 | Erosion Control Terraces | B-7 to K-10 | 6/6/2023 | Active | No | |
| Current Condition: | Good Condition - HRC Deve | | | | | |
| ET 4 | Erosion Control Terraces | I-7 to M-10 | 6/6/2023 | Active | No | |
| Current Condition: | Good Condition - HRC Deve | | | | | |
| ET 5 | Erosion Control Terraces | Q-10 to Q-8 | 6/6/2023 | Active | No | |
| Current Condition: | Good Condition - HRC Deve | | | | | |
| | | 1 | 1 | | | |
| ET 6 | Erosion Control Terraces | R-10 to R-7 | 6/6/2023 | Active | No | |

Good Condition - HRC Development installed the erosion control terrace prior to the inspection on 6/6/23.

Current Condition:

| ET 7 | Erosion Control Terraces | S-7 to U-10 | 6/6/2023 | Active | No |
|---|---|---|---|---|---|
| Current Condition: | Good Condition - HRC Deve | | osion control terrace prior t | o the inspection on | 6/6/23. |
| FT 1 | Fuel Tank | On site | 12/6/2022 | Pending | No |
| Current Condition: | Pending - Ruff Grading broug | | | | |
| | from site during the inspection | | | | |
| | inspection on 4/11/23. Ruff C | | | | |
| | 5/2/23. | - | | | |
| MS 1 | Material Storage Area | On site | 11/4/2022 | Active | No |
| Current Condition: | Good Condition-Material and | | | | |
| PB 1 | Portable toilet | On site | 4/11/2023 | Active | No |
| Current Condition: | Good Condition - Ruff Gradir | | | | |
| | Grading secured the portable | | | | |
| | Morgan Ridge subdivision pr | ior to the inspection on | 5/2/23. K2 Construction ins | talled and secured | a portable toilet or |
| | site prior to the inspection or | n 8/29/23. | | | |
| SB A | Sediment Basin | Z-9 | 3/21/2023 | Pending | Yes |
| Current Condition: | Pending - HRC Developmen | t began shaping the bas | in prior to the inspection or | n 3/21/23. | |
| | | | | | |
| | Basin should be installed per | r plan. | | | |
| | | | | | |
| | HRC Development was infor | med to complete by 3/2 | 8/23. Not done as of the la | st inspection. HRC | Development was |
| | reminded on 5/4/23, 6/21/23 | , 8/22/23, 10/18/23 | | | |
| SB B | Sediment Basin | L-7 | 3/21/2023 | Pending | Yes |
| Current Condition: | Pending - HRC Developmen | <mark>t began shaping the bas</mark> | in prior to the inspection o | า 3/21/23. | |
| | | | | | |
| | Basin should be installed per | r plan. | | | |
| | | | | | |
| | HRC Development was infor | | 8/23. Not done as of the la | st inspection. HRC | Development was |
| | reminded on 5/4/23, 6/21/23 | 1 | | | |
| SF 1 | Silt fence | West edge of site | 11/29/2022 | Active | No |
| Current Condition: | Good Condition - HRC Development installed the silt fence prior to the inspection on 11/29/22. HRC Development cleaned out the silt fence in multiple locations prior to the inspection on 3/6/23. HRC Development installed additional | | | | |
| | | | | | |
| | | nultiple locations prior to | o the inspection on 3/6/23. | | |
| | cleaned out the silt fence in r silt fence checks in multiple | nultiple locations prior to | o the inspection on 3/6/23. | | |
| SF 2 | silt fence checks in multiple Silt fence | multiple locations prior to high flow areas prior to t West edge of site | b the inspection on 3/6/23. he inspection on 3/14/23. | HRC Development | installed additiona |
| SF 2 Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo | nultiple locations prior to high flow areas prior to t West edge of site pment installed the silt f | the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection | HRC Development Active On 11/29/22. HRC | installed additiona |
| | silt fence checks in multiple Silt fence Fair Condition - HRC Develo trenched in the silt fence whe | multiple locations prior to high flow areas prior to t West edge of site pment installed the silt f ere undermined prior to | the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection | HRC Development Active On 11/29/22. HRC | installed additiona |
| | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo | multiple locations prior to high flow areas prior to t West edge of site pment installed the silt f ere undermined prior to | the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection | HRC Development Active On 11/29/22. HRC | installed additiona |
| | silt fence checks in multiple I Silt fence Fair Condition - HRC Develo trenched in the silt fence who prior to the inspection on 3/2 | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f ere undermined prior to 8/23. | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. H | HRC Development Active On 11/29/22. HRC | installed additiona |
| | silt fence checks in multiple Silt fence Fair Condition - HRC Develo trenched in the silt fence whe | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f ere undermined prior to 8/23. | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. H | HRC Development Active On 11/29/22. HRC | installed additiona |
| | silt fence checks in multiple I Silt fence Fair Condition - HRC Develo trenched in the silt fence who prior to the inspection on 3/2 Silt fence should be repaired | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f are undermined prior to 8/23. | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. H | HRC Development Active on 11/29/22. HRC RC Development re | installed additiona Yes Development epaired the silt fen |
| | silt fence checks in multiple I Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informed | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f are undermined prior to 8/23. | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. H | HRC Development Active on 11/29/22. HRC RC Development re | installed additiona |
| Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informer reminded on 10/18/23 | multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f ere undermined prior to 8/23. where damage on the r ed to complete by 9/19/2 | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspectior the inspection on 3/6/23. H north side of the site. | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons | Installed additional Yes Development epaired the silt fen |
| Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f are undermined prior to 8/23. where damage on the r ed to complete by 9/19/2 East edge of site | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspectior the inspection on 3/6/23. H north side of the site. 3. Not done as of the last i 3/14/2023 | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active | Installed additional Yes Development epaired the silt fen struction was |
| Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f are undermined prior to 8/23. where damage on the r ad to complete by 9/19/2 East edge of site lopment installed the silt | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He inspectin o | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active Active on on 3/14/23. Due | Installed additional Yes Development epaired the silt fen struction was |
| Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f are undermined prior to 8/23. where damage on the r ad to complete by 9/19/2 East edge of site lopment installed the silt | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He inspectin o | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active Active on on 3/14/23. Due | Installed additional Yes Development epaired the silt fen struction was |
| Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f are undermined prior to 8/23. where damage on the r ad to complete by 9/19/2 East edge of site lopment installed the silt | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. H north side of the site. 3. Not done as of the last i 3/14/2023 t fence prior to the inspection | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active Active on on 3/14/23. Due | Installed additional Yes Development epaired the silt fen struction was |
| Current Condition: SF 3 Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f are undermined prior to 8/23. where damage on the r ad to complete by 9/19/2 East edge of site lopment installed the silt ar Daniel Street is no loo On site | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He inspection on 3/6/23. 3. Not done as of the last in a set of the inspection of the inspecin of the inspection of the inspecien of the | HRC Development Active On 11/29/22. HRC RC Development re nspection. K2 Cons Active On on 3/14/23. Due 23. | installed additional Yes Development epaired the silt fen struction was No to the grade silt fe |
| Current Condition: SF 3 Current Condition: WO 1 | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f are undermined prior to 8/23. where damage on the r ad to complete by 9/19/2 East edge of site lopment installed the silt ar Daniel Street is no loo On site | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He inspection on 3/6/23. 3. Not done as of the last in a set of the inspection of the inspecin of the inspection of the inspecien of the | HRC Development Active On 11/29/22. HRC RC Development re nspection. K2 Cons Active Active On on 3/14/23. Due 23. Pending | installed additional Yes Development epaired the silt fen struction was No to the grade silt fe |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informer reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area | Multiple locations prior to high flow areas prior to to West edge of site pment installed the silt f are undermined prior to 8/23. where damage on the r ad to complete by 9/19/2 East edge of site lopment installed the silt ar Daniel Street is no loo On site will be installed on site On site | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He inspection on 3/6/23. 3/14/2023 t fence prior to the inspection inger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active on on 3/14/23. Due 23. Pending Pending | installed additional Yes Development epaired the silt fen struction was No to the grade silt fen No No |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently | multiple locations prior to thigh flow areas prior to the silt of present installed the silt of the complete by 9/19/2 East edge of site lopment installed the silt of present in | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He north side of the site. 3. Not done as of the last if 3/14/2023 if fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active on on 3/14/23. Due 23. Pending Pending | installed additional Yes Development paired the silt fen struction was No to the grade silt fe No No No No |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informer reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area | multiple locations prior to thigh flow areas prior to the silt of present installed the silt of the complete by 9/19/2 East edge of site lopment installed the silt of present installed the silt of the | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He north side of the site. 3. Not done as of the last if 3/14/2023 if fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active on on 3/14/23. Due 23. Pending Pending | installed additional Yes Development paired the silt fen struction was No to the grade silt fe No No No No |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently | multiple locations prior to thigh flow areas prior to the silt of present installed the silt of the complete by 9/19/2 East edge of site lopment installed the silt of present in | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection north side of the site. 3. Not done as of the last i 3/14/2023 t fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si ontinue to monitor. | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active on on 3/14/23. Due 23. Pending Pending | installed additional Yes Development paired the silt fen struction was No to the grade silt fe No No No No |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 Current Condition: STR | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently generated or stored on-site; | multiple locations prior to thigh flow areas prior to the silt of present installed the silt of present installed the silt of the s | o the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He north side of the site. 3. Not done as of the last if 3/14/2023 if fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active on on 3/14/23. Due 23. Pending Pending te due to no waste re | installed additional Yes Development paired the silt fen struction was No to the grade silt fe No |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently generated or stored on-site; Streets | multiple locations prior to thigh flow areas prior to the silt of present installed the silt of present installed the silt of the s | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection north side of the site. 3. Not done as of the last i 3/14/2023 t fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si ontinue to monitor. | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active on on 3/14/23. Due 23. Pending Pending te due to no waste re | installed additional Yes Development paired the silt fen struction was No to the grade silt fe No to the grade silt fe No materials being |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 Current Condition: STR | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently generated or stored on-site; Streets | multiple locations prior to thigh flow areas prior to the prior to stand the set of the se | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He north side of the site. 3. Not done as of the last if 3/14/2023 it fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si ontinue to monitor. 11/4/2022 | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active on on 3/14/23. Due 23. Pending Pending te due to no waste re | installed additional Yes Development paired the silt fen struction was No to the grade silt fe No |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 Current Condition: STR | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently generated or stored on-site; Streets Fair Condition - | multiple locations prior to thigh flow areas prior to the prior to stand the set of the se | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He north side of the site. 3. Not done as of the last if 3/14/2023 it fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si ontinue to monitor. 11/4/2022 | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active on on 3/14/23. Due 23. Pending Pending te due to no waste re | installed additional Yes Development paired the silt fen struction was No to the grade silt fe No |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 Current Condition: STR | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently generated or stored on-site; Streets Fair Condition - Exterior streets should be | multiple locations prior to thigh flow areas prior to the prior to stand the set of the se | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He north side of the site. 3. Not done as of the last if 3/14/2023 it fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si ontinue to monitor. 11/4/2022 | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active on on 3/14/23. Due 23. Pending Pending te due to no waste re | installed additional Yes Development paired the silt fen struction was No to the grade silt fe No to the grade silt fe No materials being |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 Current Condition: STR Current Condition: | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently generated or stored on-site; Streets Fair Condition - Exterior streets should be K2 Construction was inform | multiple locations prior to thigh flow areas prior to the silt of present installed the silt of the second complete by 9/19/2 East edge of site lopment installed the silt of complete by 9/19/2 East edge of site lopment installed the silt of complete by 9/19/2 On site will be installed on site On site will be installed on site On site Sector will complete by 10 Cleaned daily or as new med to complete by 10 | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He north side of the site. 3. Not done as of the last if 3/14/2023 it fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si ontinue to monitor. 11/4/2022 | HRC Development Active On 11/29/22. HRC RC Development re Active Active Active Active Pending Pending te due to no waste n Active Active | installed additional Yes Development paired the silt fen struction was No to the grade silt fe No materials being Yes |
| Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 Current Condition: STR | silt fence checks in multiple l Silt fence Fair Condition - HRC Develo trenched in the silt fence whe prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was informe reminded on 10/18/23 Silt fence Good Condition - HRC Deve along the edge of the site ne Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently generated or stored on-site; Streets Fair Condition - Exterior streets should be | multiple locations prior to thigh flow areas prior to the silt of present installed the silt of present installed the silt of the s | b the inspection on 3/6/23. he inspection on 3/14/23. 11/29/2022 ence prior to the inspection the inspection on 3/6/23. He north side of the site. 3. Not done as of the last if 3/14/2023 it fence prior to the inspection nger necessary as of 5/23/ 11/4/2022 when paving begins. 11/4/2022 d waste storage area on-si ontinue to monitor. 11/4/2022 dedd. /18/23. 11/4/2022 | HRC Development Active on 11/29/22. HRC RC Development re nspection. K2 Cons Active Active Pending te due to no waste r Active Active Active | installed addition |

| Certification Statement: | direction or supervision in acc properly gathered and evalua persons who manage the sys the information submitted is, | v, that this document and all attachments were prepared cordance with a system designed to assure that quanted the information submitted. Based on my inquiry stem or those persons directly responsible for gather to the best of my knowledge and belief, true, accura ificant penalties for submitting false information incluing knowing violations." | lified personnel of the person or ring the information, ite, and complete. I |
|--------------------------|--|---|---|
| Inspector Signature: | Broya M Elizabet | F | Reviewed By: |