E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

	E	&A - P2019.032.0	00			
Inspector: Bryce Wright		Stage				
Project Name:		1				
For Week Ending:						
Project Location:	North 168th Street	10/28/2023 North 168th Street and Bennington Road - Bennington, NE (Douglas County)				
Grading:	100%				Τ	
Sanitary Sewer:	100%					
Storm Sewer:	60%					
Paving:	0%					
Seeding:	40%					
Utilities:	0%					
Overall Development:	15%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time	
					Week	
Sunday:	0.00"					
Monday	0.00"					
		10/04/0000	C	10:40 AM		
	0.03"	10/24/2023	Sunny 67	10.40 AW		
Tuesday Wednesday	0.04"	10/24/2023	Sunny 67	10.40 AW		
Tuesday Wednesday	0.04" 0.01"	10/24/2023	Sunny 67	10.40 AW		
Tuesday Wednesday Thursday Friday	0.04"	10/24/2023	Sunny 67	10.40 AW		

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (11/29/22).

Checklist Questions:

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Yes

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?						
N/A						
Are construction entrances and adjacent stre	ets being maintained adequately?					
No						
Create Corrective Action?						
No, See BMP section						
Is dust associated with the construction activ	ity adequately controlled on the site	?				
Yes						
Create Corrective Action?						
N/A						
Comments:						
Comments:						
The site was active for storm sewer ins	stallation during the last inspec	tion.				
Findings / Corrective Actions (Date)						
Findings / Corrective Actions (Date)	:					
1.) Some maintenance is required in the	e BMP section at this time.					
Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	X-11	11/4/2022	Pending	Yes	
Current Condition:	Pending - Site is being accessed through Morgan Ridge as of 6/27/23. No construction entrance is needed at this time.					
	Construction entrance should be installed.					
	,					
	K2 Construction was informed	d to complete by 10/24/2	23. Not done as of the last	inspection.		
D1	Diversion	D-8 to K-8	5/23/2023	Active	No	
Current Condition:	Good Condition - HRC Development installed the diversion prior to the inspection on 5/23/23.					
D2	Diversion	East of SB B	5/23/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. K2 Construction removed					
	sections of the diversion for sa	anitary sewer installatio	n prior to the inspection on	8/29/23.		
	Discontinuo de cald le contratelle	11	and the second second second			

CE 1	Construction Entrance	X-11	11/4/2022	Pending	Yes
Current Condition:	Pending - Site is being acces	sed through Morgan Ric	dge as of 6/27/23. No const	truction entrance is	needed at this time.
	Construction entrance should K2 Construction was informed		23. Not done as of the las	et inspection.	
D1	Diversion	D-8 to K-8	5/23/2023	Active	No
Current Condition:	Good Condition - HRC Devel				110
D2	Diversion	East of SB B	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. K2 Construction rel				
	sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23. Diversion should be reinstalled where removed for sanitary installation. K2 Construction was informed to complete by 9/19/23. Not done as of the last inspection. K2 Construction was reminded on 10/18/23				
D3	Diversion	Southeast of SB A	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develor				res
D4	K2 Construction was informe	d to complete by 10/24/ South of SB A	23. Not done as of the las 5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. K2 Construction removed sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23. Diversion should be reinstalled where removed for sanitary installation. K2 Construction was informed to complete by 9/19/23. Not done as of the last inspection. K2 Construction was reminded on 10/18/23				
ET 1	Erosion Control Terraces	B-9 to G-10	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel	opment installed the ero	osion control terrace prior to	the inspection on	6/6/23.
ET 2	Erosion Control Terraces	B-9 to I-10	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel	opment installed the ero	osion control terrace prior to	the inspection on	6/6/23.
ET 3	Erosion Control Terraces	B-7 to K-10	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel	opment installed the ero	osion control terrace prior to	the inspection on	6/6/23.
ET 4	Erosion Control Terraces	I-7 to M-10	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel				6/6/23.
ET 5	Erosion Control Terraces	Q-10 to Q-8	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel				
ET 6	Erosion Control Terraces	R-10 to R-7	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel		sion control terrace prior to	the inspection on	6/6/23.
ET 7	Erosion Control Terraces	S-7 to U-10	6/6/2023	Active	No

Current Condition:	Good Condition - HRC Dev	elopment installed the ero	osion control terrace prior	to the inspection on	6/6/23.
FT 1	Fuel Tank	On site	12/6/2022	Pending	No
Current Condition:	Pending - Ruff Grading bro from site during the inspect inspection on 4/11/23. Ruff 5/2/23.	tion on 3/28/23. Ruff Grad	ling installed a fuel tank a	nd secondary contain	nment prior to the
MS 1	Material Storage Area	On site	11/4/2022	Active	No
Current Condition:	Good Condition-Material ar	nd vehicle staging area oc	curring on-site by Ruff fu	el tanker as of 12/26	/22
PB 1	Portable toilet	On site	4/11/2023	Pending	No
Current Condition:	Pending - Ruff Grading ins secured the portable toilet of subdivision prior to the insp inspection on 8/29/23. K2 0 10/24/23.	during the inspection on 4 pection on 5/2/23. K2 Con	./18/23. Ruff Grading mov struction installed and se	ved the portable toilet cured a portable toile	t to the Morgan Ridget on site prior to the
SB A	Sediment Basin	Z-9	3/21/2023	Pending	Yes
Current Condition:	Pending - HRC Development Basin should be installed put HRC Development was informed on 5/4/23, 6/21/2	er plan. ormed to complete by 3/2	in prior to the inspection	on 3/21/23.	
SB B	Sediment Basin	L-7	3/21/2023	Pending	Yes
Current Condition:	Pending - HRC Developme				
	HRC Development was info	ormed to complete by 3/2	8/23. Not done as of the l	ast inspection. HRC	Development was
SF 1	reminded on 5/4/23, 6/21/2	3, 8/22/23, 10/18/23		-	
SF 1 Current Condition:		3, 8/22/23, 10/18/23 West edge of site relopment installed the silin multiple locations prior to	11/29/2022 It fence prior to the inspecton the inspection on 3/6/23	Active tion on 11/29/22. HR B. HRC Development	No C Development
Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Dev cleaned out the silt fence ir silt fence checks in multiple Silt fence	3, 8/22/23, 10/18/23 West edge of site relopment installed the silf a multiple locations prior to a high flow areas prior to the West edge of site	11/29/2022 If fence prior to the inspect of the inspection on 3/6/23 the inspection on 3/14/23. 11/29/2022	Active tion on 11/29/22. HR B. HRC Development Active	No C Development installed additional
Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Dev cleaned out the silt fence in silt fence checks in multiple	3, 8/22/23, 10/18/23 West edge of site relopment installed the silf in multiple locations prior to be high flow areas prior to the West edge of site dependent installed the silf in the result of th	11/29/2022 It fence prior to the inspect of the inspection on 3/6/23 the inspection on 3/14/23. 11/29/2022 Incerprior to the inspection on 3/6/23. Inorth side of the site.	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re	No CC Development installed additional Yes Development epaired the silt fence
Current Condition: SF 2 Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Development of the silt fence in silt fence in silt fence checks in multiple silt fence checks in multiple silt fence Fair Condition - HRC Development of the silt fence with prior to the inspection on 3/2 Silt fence should be repaired K2 Construction was information in the silt fence with the silt fenc	3, 8/22/23, 10/18/23 West edge of site relopment installed the silt in multiple locations prior to be high flow areas prior to the west edge of site relopment installed the silt in the	11/29/2022 It fence prior to the inspector the inspection on 3/6/23. The inspection on 3/14/23. The inspection on 3/14/23. The inspection on 3/6/23. The inspection on 3/6/23. The inspection on 3/6/23. The inspection on 3/6/23. The inspection of the site. The inspection on 3/6/23. The inspection on 3/6/23. The inspection on 3/6/23.	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re tinspection. K2 Cons	No C Development installed additional Yes Development epaired the silt fence struction was
Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Devecteaned out the silt fence in silt fence checks in multiple Silt fence Fair Condition - HRC Devecteened in the silt fence was prior to the inspection on 3 silt fence should be repaired. K2 Construction was inform	3, 8/22/23, 10/18/23 West edge of site relopment installed the silf in multiple locations prior to be high flow areas prior to the high flow areas prior to the high flow areas prior to the lopment installed the silf in the result of the re	11/29/2022 It fence prior to the inspect of the inspection on 3/6/23. The inspection on 3/14/23. 11/29/2022 Increase prior to the inspection on 3/6/23.	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re tinspection. K2 Cons Active tion on 3/14/23. Due	No IC Development Installed additional Yes Development Epaired the silt fence Struction was No
SF 2 Current Condition: SF 2 Current Condition: SF 3 Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Development of the silt fence in silt fence in silt fence checks in multiple silt fence checks in multiple silt fence Fair Condition - HRC Development of the silt fence with prior to the inspection on 3/2 Silt fence should be repaired to the silt fence with silt fence wi	3, 8/22/23, 10/18/23 West edge of site relopment installed the silf in multiple locations prior to be high flow areas prior to the high flow areas prior to the high flow areas prior to the lopment installed the silf in the result of the re	11/29/2022 It fence prior to the inspect of the inspection on 3/6/23. The inspection on 3/14/23. 11/29/2022 Increase prior to the inspection on 3/6/23.	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re tinspection. K2 Cons Active tion on 3/14/23. Due	No IC Development Installed additional Yes Development Epaired the silt fence Struction was No
SF 2 Current Condition: SF 2 Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Development of the silt fence in silt fence checks in multiple silt fence checks in multiple silt fence Fair Condition - HRC Development of the inspection on 3/2 Silt fence should be repaired to the silt fence with the silt fence of the silt fence with the silt f	West edge of site elopment installed the silt multiple locations prior to the high flow areas prior to	11/29/2022 It fence prior to the inspector the inspection on 3/6/23. The inspection on 3/14/23. 11/29/2022 The inspection on 3/6/23. The inspection	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re tinspection. K2 Cons Active tion on 3/14/23. Due 3/23.	No C Development installed additional Yes Development epaired the silt fence estruction was No to the grade silt fence
SF 2 Current Condition: SF 2 Current Condition: SF 3 Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Development of the silt fence in silt fence checks in multiple. Silt fence Fair Condition - HRC Development of the silt fence with prior to the inspection on 3/2. Silt fence should be repaired. K2 Construction was informated on 10/18/23. Silt fence Good Condition - HRC Development of the site in Concrete Washout. Pending - Concrete washout.	West edge of site elopment installed the silt in multiple locations prior to the high flow areas prior	11/29/2022 It fence prior to the inspector the inspection on 3/6/23. The inspection on 3/14/23. 11/29/2022 The inspection on 3/6/23. The inspection	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re tinspection. K2 Cons Active tion on 3/14/23. Due 3/23. Pending Pending	No IC Development installed additional Yes Development epaired the silt fence struction was No to the grade silt fence No
SF 2 Current Condition: SF 3 Current Condition: WO 1 Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Development of the silt fence in silt fence checks in multiple silt fence checks in multiple silt fence checks in multiple silt fence Fair Condition - HRC Development of the inspection on 3 silt fence with silt fence should be repaired to the inspection on 3 silt fence should be repaired to 10/18/23 Silt fence Good Condition - HRC Development of the silt o	West edge of site elopment installed the silt in multiple locations prior to the high flow areas prior to the lopment installed the silt flow areas prior to the high flow areas prior to the	11/29/2022 It fence prior to the inspect of the inspection on 3/6/23. The inspection on 3/14/23. 11/29/2022 The inspection on 3/14/23. 11/29/2022 The inspection on 3/6/23.	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re tinspection. K2 Cons Active tion on 3/14/23. Due 3/23. Pending Pending	No IC Development installed additional Yes Development epaired the silt fence struction was No to the grade silt fence No
SF 2 Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Development of the silt fence in silt fence checks in multiple. Silt fence Fair Condition - HRC Development of the inspection on 3/2 Silt fence should be repaired. K2 Construction was informed the silt fence of the silt fence. Silt fence should be repaired. K2 Construction was informed the silt fence. Good Condition - HRC Development of the silt fence. Concrete Washout. Pending - Concrete washout. Pending - There is currently generated or stored on-site.	West edge of site elopment installed the silt in multiple locations prior to the high flow areas prior to the lopment installed the silt flow areas prior to the high flow areas prior to the	11/29/2022 It fence prior to the inspector the inspection on 3/6/23. The inspection on 3/14/23. The inspection on 3/14/23. The inspection on 3/6/23. The inspection of the inspection on the inspection on the inspection of i	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re tinspection. K2 Cons Active tion on 3/14/23. Due 3/23. Pending Pending site due to no waste	No IC Development installed additional Yes Development epaired the silt fence estruction was No to the grade silt fence No No materials being
SF 2 Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Development of the silt fence in silt fence checks in multiple. Silt fence Fair Condition - HRC Development of the inspection on 3/2 Silt fence should be repaired K2 Construction was informated on 10/18/23 Silt fence Good Condition - HRC Development on 1/2 Silt fence Good Condition - HRC Development on 1/2 Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently	West edge of site elopment installed the silin multiple locations prior to the high flow areas prior to the locations prior to the high flow areas prior to the h	11/29/2022 It fence prior to the inspector the inspection on 3/6/23. The inspection on 3/14/23. 11/29/2022 In fence prior to the inspection on 3/6/23. The inspection of the inspecti	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re tinspection. K2 Cons Active tion on 3/14/23. Due 3/23. Pending Pending site due to no waste Active	No IC Development installed additional Yes Development epaired the silt fence struction was No to the grade silt fence No
SF 2 Current Condition: SF 3 Current Condition: WO 1 Current Condition: WS 1 Current Condition:	reminded on 5/4/23, 6/21/2 Silt fence Good Condition - HRC Development of the silt fence in silt fence checks in multiple. Silt fence Fair Condition - HRC Development of the inspection on 3/2 Silt fence should be repaired. K2 Construction was informated on 10/18/23 Silt fence Good Condition - HRC Development on the silt fence. Good Condition - HRC Development on the silt fence. Concrete Washout. Pending - Concrete washout. Pending - There is currently generated or stored on-site. Streets Fair Condition - Exterior streets should be contained.	West edge of site elopment installed the silt in multiple locations prior to the high flow areas prior to the lopment installed the silt flow areas prior to the high flow areas prior to the	11/29/2022 It fence prior to the inspector the inspection on 3/6/23. The inspection on 3/14/23. 11/29/2022 In fence prior to the inspection on 3/6/23. The inspection of the inspecti	Active tion on 11/29/22. HR B. HRC Development Active on on 11/29/22. HRC HRC Development re tinspection. K2 Cons Active tion on 3/14/23. Due 3/23. Pending Pending site due to no waste Active	No IC Development installed additional Yes Development epaired the silt fence estruction was No to the grade silt fence No No materials being

Certification Statement:	direction or supervision in acc properly gathered and evalua persons who manage the sys the information submitted is,	v, that this document and all attachments were pre- cordance with a system designed to assure that quated the information submitted. Based on my inquir- stem or those persons directly responsible for gather to the best of my knowledge and belief, true, accur- ificant penalties for submitting false information income r knowing violations."	lalified personnel y of the person or ering the information, rate, and complete. I
Inspector Signature:	Breye M Want		Reviewed By: