

## Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

	E	&A - P2019.032.	000		
Inspector: Bryce Wright					Stage
	Kempten Creek 2				
	•			1	
Project Name:	CSW-202106167				
For Week Ending:	1/6/2024				
Project Location:	North 168th Street and Bennington Road - Bennington, NE (Douglas County)			68007	
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	80%				
Paving:	90%				
Seeding:	40%				
Utilities:	0%				
Overall Development:	30%				
		-			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time
					Week 1
Sunday:	0.00"				
Monday:	0.00"			4.05 DH	
Tuesday:	0.00" 0.00"	1/2/2024	Mostly Cloudy 33	1:25 PM	
Wednesday: Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
					•
Comulainte					
Complaints:					
Construction Sequencing					
Construction Sequencing: Which portion(s) (i.e. drainage basir	s) of the site have had a ten	norary or normana	nt cossistion of grading of	rthwork or group	d disturbanco in the
last 14 days?	is) of the site have had a ten	inportary or permane	in cessation of grading, ea	intriwork, or ground	
	ased (12/20/23), Grading resu	med on site (3/14/23	). Spreading top soil across e	entire site (5/16/23).	Final grade reached
Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began					
(11/14/23). Paving and construction ceased on site (1/2/24).					
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?					
Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached					
and grading began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began					
(11/14/23). Paving and construction ceased on site (1/2/24).					
What temporary or permanent stabilization measures listed in this section are being implemented?					
Existing Vegetation (11/29/22).					
Checklist Questions:					
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes					
Create Corrective Action?					
N/A					
Here also also also also also also also also			and a state of the state of the		
	Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.				
No Create Corrective Action?					
No, See findings section					

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
Yes
Create Corrective Action?
N/A
Are construction entrances and adjacent streets being maintained adequately?
Yes
Create Corrective Action?
N/A
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:
The site was inactive for paving during the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section at this time. 2.) All bare areas on-site that have been inactive for 14 days should be seeded. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenan
CE 1	Construction Entrance	X-11		Removed	
Current Condition:	Removed - Echo Valley pave	ed all entrances prior to	the inspection on 12/5/23.		
D1	Diversion	D-8 to K-8	5/23/2023	Active	No
Current Condition:	Good Condition - HRC Deve	lopment installed the div	ersion prior to the inspectio	n on 5/23/23.	
D2	Diversion	East of SB B	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develo sections of the diversion for s Diversion should be reinstall K2 Construction was informe reminded on 10/18/23, 11/16	sanitary sewer installation ed where removed for side ad to complete by 9/19/2	on prior to the inspection on anitary installation.	8/29/23.	
D3	Diversion	Southeast of SB A	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develo				103
	Development was reminded	on 11/16/23	23. Not done as of the last i	· · · · · · · · · · · · · · · · · · ·	
D4 Current Condition:		South of SB A	5/23/2023 rsion prior to the inspection	Active on 5/23/23. K2 Co	Yes
Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develo           sections of the diversion for sections           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16	South of SB A pment installed the dive sanitary sewer installation ed where removed for sa ed to complete by 9/19/2 23	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 23. Not done as of the last in	Active on 5/23/23. K2 Co 8/29/23.	Yes
Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces	South of SB A pment installed the dive sanitary sewer installation ed where removed for so d to complete by 9/19/2 /23 B-9 to G-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 23. Not done as of the last in 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active	Yes onstruction remo struction was
Current Condition: ET 1 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develo           sections of the diversion for sections           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developted	South of SB A pment installed the dive sanitary sewer installation ed where removed for side d to complete by 9/19/2 /23 B-9 to G-10 lopment installed the erection	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to	Active on 5/23/23. K2 Co 8/29/23. Ispection. K2 Cons Active the inspection on	Yes onstruction remo struction was No 6/6/23.
ET 1 Current Condition: ET 2	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develoption           Erosion Control Terraces           Good Condition - HRC Develoption	South of SB A pment installed the dive sanitary sewer installation ed where removed for so d to complete by 9/19/2 /23 B-9 to G-10 lopment installed the ere B-9 to I-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Active Active the inspection on Active	Yes onstruction remo struction was No 6/6/23. No
ET 1 Current Condition: ET 2 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develop           Erosion Control Terraces           Good Condition - HRC Develop           Erosion Control Terraces           Good Condition - HRC Develop	South of SB A pment installed the dive sanitary sewer installatio ed where removed for se d to complete by 9/19/2 /23 B-9 to G-10 lopment installed the ere B-9 to I-10 lopment installed the ere	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Ispection. K2 Cons Active the inspection on Active the inspection on	Yes onstruction remo struction was No 6/6/23. No 6/6/23.
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develoption           Erosion Control Terraces	South of SB A pment installed the dive sanitary sewer installation ed where removed for so do to complete by 9/19/2 /23 B-9 to G-10 lopment installed the error B-9 to I-10 lopment installed the error B-7 to K-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Active the inspection on Active the inspection on Active the inspection on Active	Yes         onstruction remo         struction was         0/6/23.         0/6/23.         0/6/23.         0/6/23.         0/6/23.         0/6/23.         0/6/23.         0/6/23.         0/6/23.         0/6/23.         0/6/23.         0/6/23.
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develoption	South of SB A pment installed the dive sanitary sewer installatio ed where removed for se d to complete by 9/19/2 /23 B-9 to G-10 lopment installed the ere B-9 to I-10 lopment installed the ere B-9 to K-10 lopment installed the ere B-7 to K-10 lopment installed the ere	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Ispection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active	Yes           onstruction remo           struction was
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develop           Erosion Control Terraces	South of SB A pment installed the dive sanitary sewer installatio ed where removed for se d to complete by 9/19/2 /23 B-9 to G-10 lopment installed the ere B-9 to I-10 lopment installed the ere B-7 to K-10 lopment installed the ere I-7 to M-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Ispection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes           onstruction remo           struction was           No           6/6/23.           6/6/23.           No           6/6/23.           No           6/6/23.           No           6/6/23.           No           6/6/23.           No           6/6/23.
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections should be reinstalled           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developed	South of SB A pment installed the dive sanitary sewer installatio ed where removed for s d to complete by 9/19/2 d to complete by 9/19/2 d B-9 to G-10 lopment installed the ere B-9 to I-10 lopment installed the ere B-7 to K-10 lopment installed the ere I-7 to M-10 lopment installed the ere	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Despection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on	Yes           pnstruction remo           struction was           0/6/23.           6/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections of the diversion for sections           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developed           Erosion Control Terraces	South of SB A pment installed the dive sanitary sewer installatio ed where removed for s d to complete by 9/19/2 B-9 to G-10 lopment installed the ere B-9 to I-10 lopment installed the ere B-7 to K-10 lopment installed the ere I-7 to M-10 lopment installed the	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Inspection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes           onstruction removes           onstruction was           struction was           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.           0/6/23.
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections of the diversion for sections of the diversion for sections and the diversion for sections of the diversion for sections should be reinstalled           K2 Construction was informed reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developed	South of SB A pment installed the dive sanitary sewer installatio ed where removed for s d to complete by 9/19/2 d to complete by 9/19/2 d B-9 to G-10 lopment installed the ere B-9 to I-10 lopment installed the ere B-7 to K-10 lopment installed the ere I-7 to M-10 lopment installed the ere Q-10 to Q-8 lopment installed the ere	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         anitary installation.         3. Not done as of the last in 6/6/2023         osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Inspection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes           pnstruction remo           struction was           No           6/6/23.
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition: ET 5 Current Condition: ET 5 Current Condition: ET 6	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections should be reinstalled           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developed           Erosion Control Terraces <td>South of SB A pment installed the dive sanitary sewer installatio ed where removed for s d to complete by 9/19/2 B-9 to G-10 lopment installed the ere B-9 to I-10 lopment installed the ere B-7 to K-10 lopment installed the ere I-7 to M-10 lopment installed the ere Q-10 to Q-8 lopment installed the ere R-10 to R-7</td> <td>5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023</td> <td>Active on 5/23/23. K2 Co 8/29/23. Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active</td> <td>Yes           pnstruction remo           struction was           No           6/6/23.           No           6/6/23.</td>	South of SB A pment installed the dive sanitary sewer installatio ed where removed for s d to complete by 9/19/2 B-9 to G-10 lopment installed the ere B-9 to I-10 lopment installed the ere B-7 to K-10 lopment installed the ere I-7 to M-10 lopment installed the ere Q-10 to Q-8 lopment installed the ere R-10 to R-7	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes           pnstruction remo           struction was           No           6/6/23.           No           6/6/23.
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developed           sections of the diversion for sections of the diversion for sections of the diversion for sections and the diversion for sections of the diversion for sections should be reinstalled           K2 Construction was informed reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developed	South of SB A pment installed the dive sanitary sewer installatio ed where removed for s d to complete by 9/19/2 B-9 to G-10 lopment installed the ere B-9 to I-10 lopment installed the ere B-7 to K-10 lopment installed the ere I-7 to M-10 lopment installed the ere Q-10 to Q-8 lopment installed the ere R-10 to R-7	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes           pnstruction remo           struction was           No           6/6/23.

Current Condition:	Good Condition - HRC Devel	opment installed the ero	osion control terrace prior to	o the inspection on	6/6/23	
FT 1	Fuel Tank	On site	12/6/2022	Pending	No	
Current Condition:	Pending - Ruff Grading broug					
	from site during the inspectio					
	inspection on 4/11/23. Ruff G	Frading moved the fuel t	ank to the Morgan Ridge si	ubdivision prior to th	ne inspection on	
	5/2/23.					
MS 1	Material Storage Area	On site	11/4/2022	Active	No	
Current Condition:	Good Condition-Material and			1		
PB 1	Portable toilet	On site	4/11/2023	Active	No	
Current Condition:	Good Condition - Ruff Gradin Grading secured the portable Morgan Ridge subdivision pri	e toilet during the inspection on the inspection	tion on 4/18/23. Ruff Gradi 5/2/23. K2 Construction ins	ng moved the porta talled and secured	ble toilet to the a portable toilet on	
	site prior to the inspection on on 10/24/23. Echo Valley inst					
SB A	Sediment Basin	Z-9	11/14/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Develo	pment began shaping th	e basin prior to the inspect	tion on 3/21/23. HR	C Development wa	
	in the process of installing the riser prior to the inspection of 11/28/23. Dewatering holes should be i	n 11/14/23. E&A inspec				
	HRC Development was infor	med to complete by 11/	21/23. Not done as of the la	ast inspection.		
SB B	Sediment Basin	L-7	3/21/2023	Pending	Yes	
Current Condition:	Pending - HRC Development the erosion on the outerbank			3/21/23. HRC Dev	elopment repaired	
	Basin should be installed per plan.					
	HRC Development was inform reminded on 5/4/23, 6/21/23,			st inspection. HRC I	Development was	
SF 1	Silt fence	West edge of site	11/29/2022	Active	No	
Current Condition:	Good Condition - HRC Devel		fence prior to the inspection	on on 11/29/22. HR	C Development	
	cleaned out the silt fence in r silt fence checks in multiple h			HRC Development	installed additional	
SF 2	Silt fence	West edge of site	11/29/2022	Active	No	
Current Condition:	Good Condition - HRC Devel trenched in the silt fence whe prior to the inspection on 3/20 12/12/23.	ere undermined prior to	the inspection on 3/6/23. H	RC Development re	epaired the silt fenc	
SF 3	Silt fence	East edge of site	3/14/2023	Active	No	
Current Condition:	Good Condition - HRC Devel					
	along the edge of the site nea	•			ie ine grade entrei	
WO 1	Concrete Washout	On site	11/21/2023	Pending	No	
Current Condition:	Pending - Echo Valley install					
	second concrete washout pit on site and pile up concrete r	with liner prior to the inst	spection on 12/5/23. Echo	Valley removed the		
WS 1	Waste Storage Area	On site	11/4/2022	Pending	No	
Current Condition:	Pending - There is currently r generated or stored on-site; t	he E&A inspector will c		te due to no waste r	materials being	
OTD	Otwarts	Bennington Road, N.	44/4/0000	A	N	
STR Current Condition:	Streets	168th Street	11/4/2022	Active	No	
Current Condition:	Good Condition - HRC Devel	opment was cleaning a	i interior and exterior street	is during the inspec	uon on 12/19/23.	
SWPPP Sign	SWPPP Notification Sign	Adjacent to CE 1	11/4/2022	Active	No	
Current Condition:	Good Condition - SWPPP ins					
ertification Statement:	"I certify, under penalty of law		d all attachments were pre designed to assure that qu			

Inspector Signature:	
----------------------	--

Broger M Wayht

	Cate Sales
Reviewed By:	