

## Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

	E	E&A - P2019.032.0	000				
Inspector: Bryce Wright					Stage		
		Kempten	Creek 2				
Droject Nome		-			1		
Project Name:	CSW-202106167 3/2/2024						
For Week Ending:							
Project Location:	North 168th Street and Bennington Road - Bennington, NE (Douglas County)         68007						
	1000/						
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving: Seeding:	40%						
Utilities:	0%						
Overall Development:	30%						
	50%	1			1		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time		
		Date mepooled			Week 1		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"	2/27/2024	Partly Cloudy 36	12:15 PM			
Wednesday:	0.00"						
Thursday: Friday:	0.00"						
Saturday:	0.00"						
	0.00				1		
Complaints:							
Complaints.	1						
Construction Sequencing:							
Which portion(s) (i.e. drainage basi	ns) of the site have had a ter	mporary or permane	nt cessation of grading lea	arthwork or group	disturbance in the		
last 14 days?			in coocation of grading, of	in the second			
Grading Began (11/29/22). Grading ce	eased (12/20/23). Grading resu	umed on site (3/14/23)	). Spreading top soil across	entire site (5/16/23).	Final grade reached		
and grading ceased across the entire		installation began (8/2	29/23). Storm sewer installat	ion began (10/9/23).	Paving began		
(11/14/23). Paving and construction c	eased on site (1/2/24).						
Which portion(s) (i.e. drainage basi	ns) of the site do not have g	rading, earthwork, o	r ground disturbance sch	eduled in the next 1	4 days?		
Grading Began (11/29/22). Grading ce	eased (12/20/23). Grading resu	umed on site (3/14/23)	). Spreading top soil across	entire site (5/16/23).	Final grade reached		
and grading ceased across the entire		installation began (8/2	29/23). Storm sewer installat	ion began (10/9/23).	Paving began		
(11/14/23). Paving and construction c							
What temporary or permanent stab	ilization measures listed in t	his section are being	g implemented?				
Existing Vegetation (11/29/22).							
Checklist Questions:							
Are receiving waters adjacent to the project t	free of any significant signs of even	en er odiment thet week	d he conceinted with the construct	tion activity?			
Are receiving waters adjacent to the project to Yes	free of any significant signs of erosi	on or sediment that would	u be associated with the construc	cuon activity r			
Create Corrective Action?							
N/A							
Have disturbed ences been condiction attains	ico stabilizad es remuire 40 List i com	tive portions of the arets	at and if stabilization measure are	adoquate en nonded to	provent erector		
Have disturbed areas been seeded or otherw No	ise stabilized as required? List mac	uve portions of the projec	and it stabilization measure are	auequate of needed to	prevent erosion.		
Create Corrective Action?							
No, See findings section							

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
Yes
Create Corrective Action?
N/A
Are construction entrances and adjacent streets being maintained adequately?
Yes
Create Corrective Action?
N/A
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:
The site was inactive during the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section at this time. 2.) All bare areas on-site that have been inactive for 14 days should be seeded. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	X-11		Removed		
Current Condition:	Removed - Echo Valley pave	d all entrances prior to	the inspection on 12/5/23.			
D1	Diversion	D-8 to K-8	5/23/2023	Active	No	
Current Condition:	Good Condition - HRC Development installed the diversion prior to the inspection on 5/23/23.					
D2	Diversion	East of SB B	5/23/2023	Active	Yes	
Current Condition:	<ul> <li>Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. K2 Construction removed sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23.</li> <li>Diversion should be reinstalled where removed for sanitary installation.</li> <li>K2 Construction was informed to complete by 9/19/23. Not done as of the last inspection. K2 Construction was reminded on 10/18/23, 11/16/23, 2/15/24</li> </ul>					
D3	Diversion	Southeast of SB A	5/23/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Develop				100	
	K2 Construction was informe		23. Not done as of the last i	nspection. K2 Cor	struction and HR	
D4 Current Condition:	Development was reminded of Diversion Fair Condition - HRC Develop sections of the diversion for s	on 11/16/23, 2/15/24 South of SB A pment installed the dive canitary sewer installatio	5/23/2023 rsion prior to the inspection on prior to the inspection on	Active on 5/23/23. K2 Co	Yes	
Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develop sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe reminded on 10/18/23, 11/16	on 11/16/23, 2/15/24 South of SB A pment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons	Yes nstruction remove	
Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develop sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe reminded on 10/18/23, 11/16           Erosion Control Terraces	on 11/16/23, 2/15/24 South of SB A pment installed the dive sanitary sewer installation ed where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active	Yes nstruction remove truction was	
Current Condition: ET 1 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develop sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Devel	on 11/16/23, 2/15/24 South of SB A prent installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the ered	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on	Yes Instruction remove Instruction was No 6/6/23.	
Current Condition: ET 1 Current Condition: ET 2	Development was reminded           Diversion           Fair Condition - HRC Develop sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Devel           Erosion Control Terraces	on 11/16/23, 2/15/24 South of SB A pment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the ero B-9 to I-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active	Yes Instruction remove Instruction was No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develop sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informered reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develop           Erosion Control Terraces           Good Condition - HRC Develop           Erosion Control Terraces           Good Condition - HRC Develop	on 11/16/23, 2/15/24 South of SB A prent installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on	Yes           Instruction remove           Instruction was           No           6/6/23.           No           6/6/23.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	Development was reminded           Diversion           Fair Condition - HRC Develop sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informered reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develop           Erosion Control Terraces	on 11/16/23, 2/15/24 South of SB A prent installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active	Yes Instruction remove Instruction was Instruc	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Development was reminded of           Diversion           Fair Condition - HRC Develop           sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Devel	on 11/16/23, 2/15/24 South of SB A coment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         3. Not done as of the last in 6/6/2023         osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on	Yes           Instruction remove           Instruction was           No           6/6/23.           No           6/6/23.           No           6/6/23.           No           6/6/23.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	Development was reminded           Diversion           Fair Condition - HRC Develop sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Devel	on 11/16/23, 2/15/24 South of SB A prent installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         3. Not done as of the last in 6/6/2023         bsion control terrace prior to 6/6/2023         osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes           Instruction remove           Instruction was           No           6/6/23.           No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develop sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develop	on 11/16/23, 2/15/24 South of SB A pment installed the dive sanitary sewer installation ed where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Cc 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on	Yes           nstruction remove           struction was           No           6/6/23.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: ET 5	Development was reminded of           Diversion           Fair Condition - HRC Develop           sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Devel           Erosion Control Terraces           Good Condition - HRC Devel	on 11/16/23, 2/15/24 South of SB A coment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error Q-10 to Q-8	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         3. Not done as of the last in 6/6/2023         osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes           nstruction remove           struction was           No           6/6/23.           6/6/23.           No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develop sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Devel	on 11/16/23, 2/15/24 South of SB A pment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error Q-10 to Q-8 opment installed the error	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Cc 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on	Yes           Instruction remove           Instruction was           No           6/6/23.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: ET 5	Development was reminded of           Diversion           Fair Condition - HRC Develop           sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informe           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Devel           Erosion Control Terraces           Good Condition - HRC Devel	on 11/16/23, 2/15/24 South of SB A pment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error Q-10 to Q-8 opment installed the error Q-10 to Q-8 opment installed the error R-10 to R-7	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         anitary installation.         3. Not done as of the last in 6/6/2023         bsion control terrace prior to 6/6/2023         osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Cc 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes           Instruction remove           Instruction was           No           6/6/23.	

Current Condition:	Good Condition - HRC Deve	lopment installed the er	osion control terrace prior	to the inspection on	6/6/23.
FT 1	Fuel Tank	On site	12/6/2022	Pending	No
Current Condition:	Pending - Ruff Grading brou from site during the inspection inspection on 4/11/23. Ruff ( 5/2/23.	on on 3/28/23. Ruff Grad	ding installed a fuel tank a	nd secondary contair	nment prior to the
MS 1	Material Storage Area	On site	11/4/2022	Active	No
Current Condition:	Good Condition-Material and		ccurring on-site by Ruff fue	el tanker as of 12/26/	22
PB 1	Portable toilet	On site	4/11/2023	Pending	No
Current Condition:	Pending - Ruff Grading insta secured the portable toilet du subdivision prior to the inspe inspection on 8/29/23. K2 Co Echo Valley installed and se portable toilet from the site p	uring the inspection on 4 ection on 5/2/23. K2 Cor onstruction removed the cured a portable toilet o	4/18/23. Ruff Grading mov astruction installed and sec portable toilet from the sit n site prior to the inspectic	ed the portable toilet cured a portable toile te prior to the inspec	to the Morgan River ton site prior to the tion on 10/24/23.
SB A	Sediment Basin	Z-9	11/14/2023	Active	Yes
Current Condition:	Fair Condition - 20% filled - Development was in the pro Development installed the ris during the inspection on 11/2 Dewatering holes should be HRC Development was infor reminded on 2/15/24	cess of installing the rise ser prior to the inspectio 28/23. installed in the riser.	er and outfall pipe during ti n on 11/14/23. E&A inspe	he inspection on 11/7 ctor painted the clea	7/23. HRC nout mark on the
SB B	Sediment Basin	L-7	3/21/2023	Active	No
Current Condition:	Good Condition - 5% filled -				
	Development repaired the en installed the riser prior to the inspection.	rosion on the outerbank	of the basin prior to the in	spection on 12/12/23	3. HRC Developme
SF 1 Current Condition:	Silt fence Good Condition - HRC Deve	West edge of site	11/29/2022	Active	No
SF 2 Current Condition:	cleaned out the silt fence in silt fence checks in multiple Silt fence Good Condition - HRC Deve	high flow areas prior to West edge of site	the inspection on 3/14/23.	Active	No
Current Condition.	trenched in the silt fence wh prior to the inspection on 3/2 12/12/23.	ere undermined prior to	the inspection on 3/6/23. I	HRC Development re	epaired the silt fen
SF 3	Silt fence	East edge of site	3/14/2023	Active	No
Current Condition:	Good Condition - HRC Deve along the edge of the site ne	•			to the grade silt fe
WO 1	Concrete Washout	On site	11/21/2023	Pending	No
Current Condition:	Pending - Echo Valley instal second concrete washout pi on site and pile up concrete	t with liner prior to the in	spection on 12/5/23. Echo	Valley removed the	
WS 1	Waste Storage Area	On site	11/4/2022	Pending	No
Current Condition:	Pending - There is currently generated or stored on-site;	the E&A inspector will c		ite due to no waste r	materials being
STR	Streets	Bennington Road, N. 168th Street	11/4/2022	Active	No
Current Condition:	Good Condition - HRC Deve				
SWPPP Sign	SWPPP Notification Sign	Adjacent to CE 1	11/4/2022	Active	No
Current Condition:	Good Condition - SWPPP in				
Certification Statement:	"I certify, under penalty of la direction or supervision in ac properly gathered and evalu- persons who manage the sy the information submitted is, am aware that there are sigr of fines and imprisonment for	cordance with a system ated the information sub stem or those persons of to the best of my know ificant penalties for sub	a designed to assure that comitted. Based on my inqu directly responsible for gat ledge and belief, true, acc	ualified personnel iry of the person or hering the informatio urate, and complete.	I

Inspector Signature:

Broga M Wayht

Parto Sul Reviewed By: