

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2019.032.000							
Inspector: Bryce Wright							
Project Name:	Kempten Creek 2 CSW-202106167				1		
For Week Ending:	3/16/2024						
Project Location:	North 168th Street and Bennington Road - Bennington, NE (Douglas County)				68007		
		and Demnigton Road	- Dennington, NE (Doug				
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	90%						
Seeding:	40%						
Utilities:	40 % 0%						
Overall Development:	30%						
	3078						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time		
		Date inspected		Time	Week 1		
Sunday:	0.00"				Week I		
Monday:	0.00"						
Tuesday:	0.00"	3/12/2024	Sunny 61	1:30 PM			
Wednesday:	0.00"		-				
Thursday:	0.40"						
Friday:	0.00"						
Saturday:	0.00"						
Complaints:							
	•						
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began (11/14/23). Paving and construction ceased on site (1/2/24).							
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?							
Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began (11/14/23). Paving and construction ceased on site (1/2/24). What temporary or permanent stabilization measures listed in this section are being implemented?							
Existing Vegetation (11/29/22).							
Checklist Questions:							
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes Create Corrective Action? N/A							
Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. No							
Create Corrective Action?							
No, See findings section							

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
Yes
Create Corrective Action?
N/A
Are construction entrances and adjacent streets being maintained adequately?
Yes
Create Corrective Action?
N/A
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:

The site was inactive during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section at this time. 2.) All bare areas on-site that have been inactive for 14 days should be seeded. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection. K2 Construction was reminded on 2/15/24

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	X-11		Removed		
Current Condition:	Removed - Echo Valley pave	d all entrances prior to t	the inspection on 12/5/23.			
D1	Diversion	D-8 to K-8	5/23/2023	Active	No	
Current Condition:	Good Condition - HRC Devel	Good Condition - HRC Development installed the diversion prior to the inspection on 5/23/23.				
D2	Diversion	East of SB B	5/23/2023	Active	Yes	
Current Condition:	sections of the diversion for s Diversion should be reinstalle K2 Construction was informe	 Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. K2 Construction removed sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23. Diversion should be reinstalled where removed for sanitary installation. K2 Construction was informed to complete by 9/19/23. Not done as of the last inspection. K2 Construction was reminded on 10/18/23, 11/16/23, 2/15/24 				
D3	Diversion	Southeast of SB A	5/23/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Develo				100	
	K2 Construction was informe		23. Not done as of the last i	nspection. K2 Cor	nstruction and HRC	
24	Development was reminded	on 11/16/23, 2/15/24				
D4 Current Condition:	Development was reminded	on 11/16/23, 2/15/24 South of SB A	5/23/2023	Active	Yes	
	Development was reminded	on 11/16/23, 2/15/24 South of SB A pment installed the diver- sanitary sewer installation of where removed for sa d to complete by 9/19/2 /23, 2/15/24	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in	Active on 5/23/23. K2 Cc 8/29/23.	Yes Instruction removed	
Current Condition: ET 1	Development was reminded Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces	on 11/16/23, 2/15/24 South of SB A pment installed the diver- sanitary sewer installation ed where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active	Yes Instruction removed	
Current Condition: ET 1 Current Condition:	Development was reminded Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16	on 11/16/23, 2/15/24 South of SB A pment installed the diver- sanitary sewer installation ed where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the erc	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active	Yes Instruction remove	
Current Condition: ET 1 Current Condition: ET 2	Development was reminded Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	South of SB A South of SB A pment installed the diversanitary sewer installation and where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the erco B-9 to I-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active	Yes Instruction remove Struction was No 6/6/23. No	
Current Condition: ET 1 Current Condition:	Development was reminded Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	South of SB A South of SB A pment installed the diverse anitary sewer installation of the complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active	Yes Instruction remove Instruction was Instruc	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	Development was reminded of Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalled K2 Construction was informered reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Develop Erosion Control Terraces	South of SB A South of SB A pment installed the diversanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the erco B-9 to I-10 opment installed the erco B-7 to K-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active	Yes Instruction remove Struction was No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Development was reminded Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	South of SB A South of SB A pment installed the diversanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the erco B-9 to I-10 opment installed the erco B-7 to K-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active	Yes Instruction remove Struction was No 6/6/23. No 6/6/23. No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	Development was reminded of Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalled K2 Construction was informered reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Develop Erosion Control Terraces	South of SB A South of SB A pment installed the diverse anitary sewer installation of the complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the erco B-9 to I-10 opment installed the erco B-7 to K-10 opment installed the erco I-7 to M-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes Instruction remove Struction was No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Development was reminded of Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	South of SB A South of SB A pment installed the diverse anitary sewer installation of the complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the erco B-9 to I-10 opment installed the erco B-7 to K-10 opment installed the erco I-7 to M-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes Instruction remove Struction was No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	Development was reminded of Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalled K2 Construction was informered reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Develop Erosion Control Terraces	South of SB A South of SB A pment installed the diverse anitary sewer installation of the complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the erco B-9 to I-10 opment installed the erco B-7 to K-10 opment installed the erco I-7 to M-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes Instruction remove Struction was No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Development was reminded of Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalled K2 Construction was informered on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Develop	South of SB A South of SB A pment installed the diver- sanitary sewer installation d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the erco B-9 to I-10 opment installed the erco B-7 to K-10 opment installed the erco I-7 to M-10 opment installed the erco Q-10 to Q-8	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on	Yes onstruction remove struction was No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: ET 5	Development was reminded Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalled K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	South of SB A South of SB A pment installed the diver- sanitary sewer installation d to complete by 9/19/2 /23, 2/15/24 B-9 to G-10 opment installed the erco B-9 to I-10 opment installed the erco B-7 to K-10 opment installed the erco I-7 to M-10 opment installed the erco Q-10 to Q-8	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on	Yes onstruction remove struction was No 6/6/23. No	

ET 7	Erosion Control Terraces	S-7 to U-10	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel	lopment installed the ero	sion control terrace prior t	o the inspection on	6/6/23.
FT 1	Fuel Tank	On site	12/6/2022	Pending	No
Current Condition:	Pending - Ruff Grading broug from site during the inspection inspection on 4/11/23. Ruff G 5/2/23.	on on 3/28/23. Ruff Grad	ing installed a fuel tank an	d secondary contair	nment prior to the
MS 1	Material Storage Area	On site	11/4/2022	Active	No
Current Condition:	Good Condition-Material and	vehicle staging area oc	curring on-site by Ruff fuel	tanker as of 12/26/	22
PB 1	Portable toilet	On site	4/11/2023	Pending	No
Current Condition:	Pending - Ruff Grading instal secured the portable toilet du subdivision prior to the inspe inspection on 8/29/23. K2 Cc Echo Valley installed and sec portable toilet from the site p	uring the inspection on 4 ction on 5/2/23. K2 Cons onstruction removed the cured a portable toilet or	/18/23. Ruff Grading move struction installed and secu portable toilet from the site a site prior to the inspection	ed the portable toilet ured a portable toile e prior to the inspec	to the Morgan Ric t on site prior to th tion on 10/24/23.
SB A	Sediment Basin	Z-9	11/14/2023	Active	Yes
Current Condition:	Fair Condition - 20% filled - H Development was in the proc Development installed the ris during the inspection on 11/2 Dewatering holes should be in HRC Development was inform reminded on 2/15/24	cess of installing the rise ser prior to the inspection 28/23. installed in the riser.	r and outfall pipe during th n on 11/14/23. E&A inspec	e inspection on 11/ tor painted the clea	7/23. HRC nout mark on the r
SB B	Sediment Basin	L-7	3/21/2023	Active	No
Current Condition:	Good Condition - 5% filled - I Development repaired the er installed the riser prior to the inspection.	osion on the outerbank o	of the basin prior to the ins	pection on 12/12/23	3. HRC Developmer
SF 1	Silt fence	West edge of site	11/29/2022	Active	No
Current Condition:	Good Condition - HRC Devel cleaned out the silt fence in r silt fence checks in multiple h	multiple locations prior to	the inspection on 3/6/23.		
SF 2	Silt fence	West edge of site	11/29/2022	Active	No
Current Condition:	Good Condition - HRC Devel trenched in the silt fence whe prior to the inspection on 3/2 12/12/23.	opment installed the silt are undermined prior to t	he inspection on 3/6/23. H	IRC Development re	epaired the silt fend
SF 3	Silt fence	East edge of site	3/14/2023	Active	No
Current Condition:	Good Condition - HRC Devel along the edge of the site ne				to the grade silt fer
WO 1	Concrete Washout	On site	11/21/2023	Pending	No
Current Condition:	Pending - Echo Valley install second concrete washout pit on site and pile up concrete r	with liner prior to the ins	pection on 12/5/23. Echo	Valley removed the	
WS 1	Waste Storage Area	On site	11/4/2022	Pending	No
Current Condition:	Pending - There is currently generated or stored on-site; 1	the E&A inspector will co		te due to no waste i	materials being
STR	Streets	Bennington Road, N. 168th Street	11/4/2022	Active	No
Current Condition:	Good Condition - HRC Devel				
SWPPP Sign	SWPPP Notification Sign	Adjacent to CE 1	11/4/2022	Active	No

Certification Statement:	direction or supervision in acc properly gathered and evaluat persons who manage the syst the information submitted is,	v, that this document and all attachments were prep cordance with a system designed to assure that qu ited the information submitted. Based on my inquiry stem or those persons directly responsible for gather to the best of my knowledge and belief, true, accur ificant penalties for submitting false information incl r knowing violations."	alified personnel y of the person or ering the information, rate, and complete. I
Inspector Signature:	Brya M Zhanght		Reviewed By: