E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha. NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

		Creek 2 106167		Stage 1		
th Street and B	CSW-202 ² 6/8/20	106167				
th Street and B		024				
th Street and B	landinatan Diri		6/8/2024			
	North 168th Street and Bennington Road - Bennington, NE (Douglas County)					
100%		T				
100%						
100%						
90%						
40%						
35%						
30%						
Date	inspected	Weather Conditions	Time	Storm event time		
				Wee		
	6/4/2024	Sunny 74	9:55 PM			

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paying began (11/14/23). Paving and construction ceased on site (1/2/24). Utility installation began on site (4/2/24).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began (11/14/23). Paving and construction ceased on site (1/2/24). Utility installation began on site (4/2/24).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (11/29/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, See findings section Yes Create Corrective Action? N/A Are construction entrances and adjacent streets being maintained adequately? No No, See BMP inspection Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A Comments: Comments: The site was inactive during the last inspection. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section at this time. 2.) All bare areas on-site that have been inactive for 14 days should be seeded. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection. K2 Construction was reminded on 2/15/24, 3/21/24, 5/2/24, Cedar Construction was reminded on 5/30/24

	Type	Location	Projected Install Date	Status	Maintenance
Unique Name CE 1	Construction Entrance	X-11	- 10,00000 motum 2000	Removed	
Current Condition:	Removed - Echo Valley paved all entrances prior to the inspection on 12/5/23.				
D1	Diversion	D-8 to K-8	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develop				
	Diversion should be redefined HRC Development and Ceda	•	rmed to complete by 5/7/24	. Not done as of th	e last inspection.
	Cedar Construction was remi	nded on 5/30/24			
D2	Diversion	East of SB B	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Development Sections of the diversion for sections				nstruction remove
	Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16	d to complete by 9/19/2	3. Not done as of the last in		
D3	Diversion	Southeast of SB A		Removed	
Current Condition:	Removed - Due to paving the	diversion is no longer r	necessary as of the 4/16/24	inspection.	'
D4	Diversion	South of SB A	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Development Sections of the diversion for sections				
	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe	to the inspection on 5/2 ed where removed for said d to complete by 9/19/2	28/24. anitary installation. 3. Not done as of the last in	spection. K2 Cons	struction was
FT 1	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16	to the inspection on 5/2 ed where removed for sa d to complete by 9/19/2 /23, 2/15/24, 3/21/24, 5/	28/24. anitary installation. 3. Not done as of the last in 2/24, 5/22/24 Cedar Consti	spection. K2 Consuction was remind	struction was led on 5/30/24
ET 1 Current Condition:	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces	d to complete by 9/19/2 /23, 2/15/24, 3/21/24, 5/ B-9 to G-10	28/24. anitary installation. 3. Not done as of the last in (2/24, 5/22/24 Cedar Consti	spection. K2 Cons ruction was remind Active	struction was led on 5/30/24 No
	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel	d to complete by 9/19/2 /23, 2/15/24, 3/21/24, 5/ B-9 to G-10	28/24. anitary installation. 3. Not done as of the last in (2/24, 5/22/24 Cedar Consti	spection. K2 Cons ruction was remind Active	struction was led on 5/30/24 No
Current Condition:	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces	d to complete by 9/19/2 /23, 2/15/24, 3/21/24, 5/ B-9 to G-10 opment installed the erc	28/24. anitary installation. 3. Not done as of the last in (2/24, 5/22/24 Cedar Construction) 6/6/2023 assion control terrace prior to 6/6/2023	espection. K2 Construction was remind Active the inspection on Active	struction was led on 5/30/24 No 6/6/23. No
Current Condition: ET 2	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	d to complete by 9/19/2 /23, 2/15/24, 3/21/24, 5/ B-9 to G-10 opment installed the erc	28/24. anitary installation. 3. Not done as of the last in (2/24, 5/22/24 Cedar Construction) 6/6/2023 assion control terrace prior to 6/6/2023	espection. K2 Construction was remind Active the inspection on Active	struction was led on 5/30/24 No 6/6/23. No
Current Condition: ET 2 Current Condition:	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	d to complete by 9/19/2 /23, 2/15/24, 3/21/24, 5/ B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10	28/24. anitary installation. 3. Not done as of the last in (2/24, 5/22/24 Cedar Construction) 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	aspection. K2 Construction was remind Active the inspection on Active the inspection on Active Active	struction was ed on 5/30/24 No 6/6/23. No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	d to complete by 9/19/2 /23, 2/15/24, 3/21/24, 5/ B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10	28/24. anitary installation. 3. Not done as of the last in (2/24, 5/22/24 Cedar Construction) 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	aspection. K2 Construction was remind Active the inspection on Active the inspection on Active Active	struction was ed on 5/30/24 No 6/6/23. No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3 Current Condition:	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	d to complete by 9/19/2/23, 2/15/24, 3/21/24, 5/ B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10	28/24. anitary installation. 3. Not done as of the last in 2/2/4, 5/22/24 Cedar Construction 6/6/2023 asion control terrace prior to 6/6/2023	Active the inspection on Active	struction was ed on 5/30/24 No 6/6/23. No 6/6/23. No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel	d to complete by 9/19/2/23, 2/15/24, 3/21/24, 5/ B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10	28/24. anitary installation. 3. Not done as of the last in 2/2/4, 5/22/24 Cedar Construction 6/6/2023 asion control terrace prior to 6/6/2023	Active the inspection on Active	struction was ed on 5/30/24 No 6/6/23. No 6/6/23. No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel	d to complete by 9/19/2 /23, 2/15/24, 3/21/24, 5/ B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8	28/24. anitary installation. 3. Not done as of the last in 1/2/24, 5/22/24 Cedar Construction 6/6/2023 Desion control terrace prior to 6/6/2023	Active the inspection on Active Active	No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5	reinstalled the diversion prior Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	d to complete by 9/19/2 /23, 2/15/24, 3/21/24, 5/ B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8	28/24. anitary installation. 3. Not done as of the last in 1/2/24, 5/22/24 Cedar Construction 6/6/2023 Desion control terrace prior to 6/6/2023	Active the inspection on Active Active	No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23.

Current Condition:	Good Condition - HRC Devel	lopment installed the ero	osion control terrace prior to	the inspection on	6/6/23.
ET 7	Erosion Control Terraces	S-7 to U-10	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel	lopment installed the ero	osion control terrace prior to	the inspection on	6/6/23.
FT 1	Fuel Tank	On site	12/6/2022	Pending	No
Current Condition:	Pending - Ruff Grading broug from site during the inspectio inspection on 4/11/23. Ruff G 5/2/23. Cedar Construction in Construction removed the fue	on on 3/28/23. Ruff Grad Grading moved the fuel t enstalled a single walled f	ing installed a fuel tank and ank to the Morgan Ridge su uel tank on site prior to the	d secondary containublished by the secondary containuble by the secondary contains and seco	ment prior to the ie inspection on
IF 1-4	Inlet Filter	Street A	5/28/2024	Active	No
Current Condition:	Good Condition - HRC Development installed inlet filters 1-3 prior to the inspection on 5/28/24.				
MS 1	Material Storage Area	On site	11/4/2022	Active	No
Current Condition:	Good Condition-Material and	vehicle staging area oc	curring on-site by Ruff fuel	tanker as of 12/26/	22
PB 1	Portable toilet	On site	4/11/2023	Pending	No No
Current Condition:	Pending - Ruff Grading instal secured the portable toilet du subdivision prior to the inspec inspection on 8/29/23. K2 Co Echo Valley installed and sec portable toilet from the site pi	uring the inspection on 4 ction on 5/2/23. K2 Construction removed the cured a portable toilet or	/18/23. Ruff Grading mover struction installed and secu portable toilet from the site a site prior to the inspection	d the portable toilet red a portable toiled prior to the inspect	to the Morgan Ridge t on site prior to the ion on 10/24/23.
SB A	Sediment Basin	Z-9	11/14/2023	Active	Yes
	Fair Condition - 55% filled - HRC Development began shaping the basin prior to the inspection on 3/21/23. HRC Development was in the process of installing the riser and outfall pipe during the inspection on 11/7/23. HRC Development installed the riser prior to the inspection on 11/14/23. E&A inspector painted the cleanout mark on the during the inspection on 11/28/23. HRC Development installed the dewatering hole prior to the inspection on 5/7/24. Basin should be cleaned out. E&A inspector will send out to bid once SID gives approval.				
SB B	Sediment Basin	L-7	3/21/2023	Activo	No
Current Condition:	Good Condition - 5% filled - H			Active	No 3/21/23 HRC
	Development repaired the erc installed the riser prior to the inspection.	osion on the outer bank inspection on 2/13/24. I	of the basin prior to the ins E&A inspector painted the o	pection on 12/12/23 cleanout mark durin	3. HRC Development g the 2/20/24
SF 1 Current Condition:	Silt fence Good Condition - HRC Devel	West edge of site	11/29/2022	Active	No C Davidanment
Current Condition.	cleaned out the silt fence in r silt fence checks in multiple h	multiple locations prior to	the inspection on 3/6/23.		
SF 2	Silt fence	West edge of site	11/29/2022	Active	No
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 11/29/22. HRC Development trenched in the silt fence where undermined prior to the inspection on 3/6/23. HRC Development repaired the silt fence prior to the inspection on 3/28/23. HRC Development repaired the entire run of silt fence prior to the inspection on 12/12/23.				
SF 3	Silt fence	East edge of site	3/14/2023	Active	No
Current Condition:	Good Condition - HRC Devel	lopment installed the silt	fence prior to the inspection	on 01/1//23 Due	
	along the edge of the site near	ar Daniel Street is no lor	nger necessary as of 5/23/2		to the grade silt fence
WO 1	Concrete Washout	On site	nger necessary as of 5/23/2 11/21/2023	23. Pending	No
WO 1 Current Condition:		On site ed a concrete washout of with liner prior to the ins	nger necessary as of 5/23/2 11/21/2023 on site prior to the inspection spection on 12/5/23. Echo	Pending n on 11/21/23. Ech /alley removed the	No o Valley installed a
Current Condition: WS 1	Concrete Washout Pending - Echo Valley installesecond concrete washout pit on site and pile up concrete r Waste Storage Area	On site ed a concrete washout of with liner prior to the instrubble in preparation for On site	11/21/2023 In site prior to the inspection on 12/5/23. Echo viremoval prior to the inspection on 12/5/23.	Pending on on 11/21/23. Ech /alley removed the tion on 12/12/23. Pending	No o Valley installed a concrete washouts
Current Condition:	Concrete Washout Pending - Echo Valley installesecond concrete washout pit on site and pile up concrete r	On site ed a concrete washout of with liner prior to the instrubble in preparation for On site no need for a designated the E&A inspector will consider the second	11/21/2023 In site prior to the inspection on 12/5/23. Echo verenoval prior to the inspection on 12/5/23. Echo verenoval prior to the inspection on 12/4/2022 It waste storage area on-site.	Pending on on 11/21/23. Ech /alley removed the tion on 12/12/23. Pending	No o Valley installed a concrete washouts
Current Condition: WS 1 Current Condition: STR	Concrete Washout Pending - Echo Valley installesecond concrete washout pit on site and pile up concrete r Waste Storage Area Pending - There is currently regenerated or stored on-site; t	On site ed a concrete washout of with liner prior to the instrubble in preparation for On site no need for a designated the E&A inspector will collaborated Bennington Road, N. 168th Street	11/21/2023 In site prior to the inspection on 12/5/23. Echo verenoval prior to the inspection on 12/5/23. Echo verenoval prior to the inspection on 11/4/2022 It waste storage area on-site ontinue to monitor.	Pending on on 11/21/23. Ech /alley removed the tion on 12/12/23. Pending e due to no waste r Active	No o Valley installed a concrete washouts No naterials being
Current Condition: WS 1 Current Condition:	Concrete Washout Pending - Echo Valley installesecond concrete washout pit on site and pile up concrete r Waste Storage Area Pending - There is currently regenerated or stored on-site; to	On site ed a concrete washout of with liner prior to the instrubble in preparation for On site no need for a designated the E&A inspector will collaborate the E&A inspector will be a second wil	11/21/2023 In site prior to the inspection on 12/5/23. Echo verenoval prior to the inspection on 12/5/23. Echo verenoval prior to the inspection on 12/5/23. Echo verenoval prior to the inspection of the inspect	Pending on on 11/21/23. Ech /alley removed the tion on 12/12/23. Pending e due to no waste r Active s during the inspect	No o Valley installed a concrete washouts No naterials being
Current Condition: WS 1 Current Condition: STR	Concrete Washout Pending - Echo Valley installes second concrete washout pit on site and pile up concrete r Waste Storage Area Pending - There is currently regenerated or stored on-site; to Streets Good Condition - HRC Devel	On site ed a concrete washout of with liner prior to the instrubble in preparation for On site no need for a designated the E&A inspector will color be bennington Road, N. 168th Street lopment was cleaning all interior streets prior to Adjacent to CE 1	11/21/2023 In site prior to the inspection on 12/5/23. Echo is removal prior to the inspection on 12/5/23. Echo is removal prior to the inspection on 11/4/2022 If waste storage area on-site on the inspection on 5/28/24. Interior and exterior street to the inspection on 5/28/24.	Pending on on 11/21/23. Ech /alley removed the tion on 12/12/23. Pending e due to no waste r Active s during the inspect	No o Valley installed a concrete washouts No naterials being

Certification Statement:	direction or supervision in ac properly gathered and evalua persons who manage the sys the information submitted is,	w, that this document and all attachments were preportion of the information submitted. Based on my inquirestem or those persons directly responsible for gathe to the best of my knowledge and belief, true, accurificant penalties for submitting false information incoming violations."	ualified personnel y of the person or ering the informati rate, and complete	e. Í
Inspector Signature:	Brya M Waght		Reviewed Bv:	But Sul